

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 5702J - AXA****ROEL***Not Authorized*  
*Book Value??* *LI Imp 87*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHD 5702J - ROEL**

JTDGJ20W205002783\*

TOYOTA

WISH 2.0 BI-FUEL

24.01.2014

**AXA****PART****LIST**

|    |   |                                        |    |                     |   |
|----|---|----------------------------------------|----|---------------------|---|
| 1  | 1 | Front Bumper                           | \$ | <i>B/L</i> 585.36   | ✓ |
| 2  | 1 | Front Bumper Lower Absorber            | \$ | <i>B/L</i> 130.00   | ✓ |
| 3  | 1 | Front Bumper Reinforcement             | \$ | <i>B/L</i> 318.11   | ✓ |
| 4  | 1 | Front Bumper Side Support LH           | \$ | <i>D/L</i> 76.20    | ✓ |
| 5  | 1 | Front Bumper Side Support RH           | \$ | <i>D/L</i> 76.20    | ✓ |
| 6  | 1 | Front Bumper Retainer RH               | \$ | <i>D/L</i> 102.00   | ✓ |
| 7  | 1 | Front Bumper Retainer LH               | \$ | <i>C/M</i> 102.00   | ✓ |
| 8  | 1 | Front Bumper Bracket RH                | \$ | <i>B/L</i> 108.00   | ✓ |
| 9  | 1 | Front Bumper Bracket LH                | \$ | <i>B/L</i> 108.00   | ✓ |
| 10 | 1 | Front Bumper Centre Grille             | \$ | <i>C/M</i> 139.92   | ✓ |
| 11 | 1 | Front Bumper Lower Grille              | \$ | <i>C/M</i> 129.36   | ✓ |
| 12 | 1 | Front Bumper Fog Lamp RH               | \$ | <i>C/M</i> 208.00   | ✓ |
| 13 | 1 | Front Bumper Fog Lamp Outer Chrome RH  | \$ | <i>B/L</i> 190.00   | ✓ |
| 14 | 1 | Front Bumper Fog Lamp Grille RH        | \$ | <i>D/L</i> 150.00   | ✓ |
| 15 | 1 | Front Bumper Fog Lamp LH               | \$ | <i>B/L</i> 208.00   | ✓ |
| 16 | 1 | Front Bumper Fog Lamp Outer Chrome LH  | \$ | <i>B/L</i> 190.00   | ✓ |
| 17 | 1 | Front Bumper Fog Lamp Grille LH        | \$ | <i>B/L</i> 150.00   | ✓ |
| 18 | 1 | Front Bumper Fog Lamp Protector Grille | \$ | <i>B/L</i> 100.00   | ✓ |
| 19 | 1 | Front Headlamp RH                      | \$ | <i>B/L</i> 672.00   | ✓ |
| 20 | 1 | Headlamp RH inner panel                | \$ | <i>N/S</i> 732.00   | X |
| 21 | 1 | Front Headlamp LH                      | \$ | <i>B/L</i> 672.00   | ✓ |
| 22 | 1 | Headlamp LH inner panel                | \$ | <i>N/S</i> 732.00   | X |
| 23 | 1 | Front Support Panel Assy               | \$ | <i>B/L</i> 1,222.32 | ✓ |
| 24 | 1 | Front Brace Panel                      | \$ | <i>B/L</i> 95.49    | ✓ |
| 25 | 1 | Horn unit                              | \$ | <i>N/S</i> 125.00   | ✓ |
| 26 | 1 | Horn high pitch / low pitch            | \$ | <i>S/L</i> 150.00   | X |
| 27 | 1 | Bonnet                                 | \$ | <i>B/L</i> 1,019.16 | ✓ |
| 28 | 1 | Bonnet Under Weatherstrip Seal         | \$ | <i>C/L</i> 71.99    | ✓ |
| 29 | 1 | Bonnet Hinge RH                        | \$ | <i>B/L</i> 81.60    | ✓ |
| 30 | 1 | Bonnet Hinge LH                        | \$ | <i>B/L</i> 81.60    | ✓ |
| 31 | 1 | Bonnet Moulding                        | \$ | <i>N/S</i> 194.36   | X |
| 32 | 1 | Bonnet Lock                            | \$ | <i>B/L</i> 90.02    | ✓ |
| 33 | 1 | Bonnet Centre 'TOYOTA' Logo Badge      | \$ | <i>N/S</i> 115.44   | ✓ |

**TRANS-CAB AUTO SERVICES PTE LTD****ROEL**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 5702J - AXA**

|    |   |                                         |    |       |          |   |
|----|---|-----------------------------------------|----|-------|----------|---|
| 34 | 1 | Bonnet Insulator                        | \$ | D/S   | 524.06   | ✓ |
| 35 | 1 | Bonnet Damper Stay                      | \$ | Sm    | 239.05   | X |
| 36 | 1 | Front Fender RH                         | \$ | Bu    | 837.60   | ✓ |
| 37 | 1 | Front Fender Liner RH                   | \$ | CM    | 369.14   | ✓ |
| 38 | 1 | Front Fender Indicator Lamp RH          | \$ | Sm    | 95.80    | X |
| 39 | 1 | Front Fender Inner Wheel House Panel RH | \$ |       | 714.86   | ? |
| 40 | 1 | Front Fender LH                         | \$ | Bu    | 369.14   | ✓ |
| 41 | 1 | Front Fender Liner LH                   | \$ | CM    | 369.14   | ✓ |
| 42 | 1 | Front Fender Indicator Lamp LH          | \$ | Sm    | 95.80    | X |
| 43 | 1 | Front Fender Inner Wheel House Panel LH | \$ | Bu    | 714.86   | ✓ |
| 44 | 1 | Room View Mirror                        | \$ | Sm    | 200.04   | X |
| 45 | 1 | Front Windscreen                        | \$ | Sm    | 1,406.64 | X |
| 46 | 1 | Front Windscreen Moulding               | \$ | Sm    | 86.40    | ✓ |
| 47 | 1 | Radiator Assembly                       | \$ | Bu/Bu | 2,268.24 | ✓ |
| 48 | 1 | Radiator Grille                         | \$ | CM    | 462.48   | ✓ |
| 49 | 1 | Radiator Fan Blade                      | \$ | D/S   | 223.95   | ✓ |
| 50 | 1 | Aircon Fan Blade                        | \$ | NSP   | 223.95   | X |
| 51 | 1 | Radiator Cowling                        | \$ | CM    | 221.73   | ✓ |
| 52 | 1 | Radiator Fan Motor                      | \$ | Tr    | 372.76   | ✓ |
| 53 | 1 | Aircon Fan Motor                        | \$ | NSP   | 372.76   | X |
| 54 | 1 | Radiator Expansion Tank                 | \$ | D/S   | 180.76   | ✓ |
| 55 | 1 | Radiator Y - Pipe                       | \$ |       | 98.50    | ? |
| 56 | 1 | Aircon Condenser                        | \$ | Bu/Bu | 1,375.50 | ✓ |
| 57 | 1 | Aircon hose - condenser to compressor   | \$ | D/S   | 389.51   | ✓ |
| 58 | 1 | Aircon hose - compressor to evaporator  | \$ |       | 521.93   | ? |
| 59 | 1 | Aircon hose - condenser to evaporator   | \$ |       | 216.00   | ? |
| 60 | 1 | Aircon compressor - pump                | \$ |       | 3,200.00 | ? |
| 61 | 1 | Aircon compressor bracket               | \$ |       |          |   |
| 62 | 1 | Windscreen Washer Tank - Filler Neck    | \$ | D/S   | 120.76   | ✓ |
| 63 | 1 | Windscreen Washer Tank                  | \$ | D/S   | 166.00   | ✓ |
| 64 | 1 | Windscreen Washer Tank Motor            | \$ | Sm    | 266.86   | X |
| 65 | 1 | Front Door RH                           | \$ | R     | 1,554.00 | X |
| 66 | 1 | Fuse Box Top (Cover)                    | \$ | NSP   | 88.44    | ✓ |
| 67 | 1 | Fuse Box Lower                          | \$ | CM    | 84.24    | ✓ |
| 68 | 1 | Fuse Box Centre                         | \$ | CM    | 254.04   | ✓ |
| 69 | 1 | Fuse Box Centre Cover                   | \$ |       | 238.32   | ? |
| 70 | 1 | Engine Cover ( Top )                    | \$ | CM    | 250.60   | ✓ |
| 71 | 1 | Intake Manifold                         | \$ | CM    | 1,500.08 | ✓ |
| 72 | 1 | Air Cleaner Assembly                    | \$ |       | 1,036.44 | ? |
| 73 | 1 | Air-Cleaner Intake Duct                 | \$ | Sm    | 101.57   | X |
| 74 | 1 | Air-cleaner intake hose                 | \$ | Sm    | 199.42   | X |
| 75 | 1 | Front shock absorber assy LH            | \$ |       | 558.00   | ? |

**TRANS-CAB AUTO SERVICES PTE LTD****ROEL**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 5702J - AXA**

|     |   |                                      |    |               |   |
|-----|---|--------------------------------------|----|---------------|---|
| 76  | 1 | Front shock absorber top mounting LH | \$ | 159.16        | ? |
| 77  | 1 | Front shock absorber assy RH         | \$ | 558.00        | ? |
| 78  | 1 | Front shock absorber top mounting RH | \$ | 159.16        | ? |
| 79  | 1 | Front lower arm RH                   | \$ | Sm 620.57     | X |
| 80  | 1 | Front lower arm LH                   | \$ | Sm 620.57     | X |
| 81  | 1 | Front knuckle arm RH                 | \$ | Sm 490.74     | X |
| 82  | 1 | Front knuckle arm LH                 | \$ | Sm 490.74     | X |
| 83  | 1 | Steering rack & pinion assy          | \$ | R 3,167.33    | X |
| 84  | 1 | Steering rack end                    | \$ | Sm 246.50     | X |
| 85  | 1 | Steering rack & pinion bushing       | \$ | nn 30.00      | X |
| 86  | 1 | Bracket-strg rack no 1 (s10/12)      | \$ | Sm 55.14      | X |
| 87  | 1 | Bracket-strg rack no 2 (s10/12)      | \$ | Sm 37.42      | X |
| 88  | 1 | Steering tie-rod end                 | \$ | Sm 127.44     | X |
| 89  | 1 | Steering wheel air bag               | \$ | Burn 2,480.52 | ✓ |
| 90  | 1 | Steering Wheel air bag sensor        | \$ | nn 522.72     | ✓ |
| 91  | 1 | Steering Wheel air bag control unit  | \$ | nn 522.60     | ✓ |
| 92  | 1 | Power steering pump                  | \$ | NSP 5,664.96  | X |
| 93  | 1 | Power steering belt                  | \$ | NSP 251.33    | X |
| 94  | 1 | Power steering reservoir tank        | \$ | NSP 394.62    | X |
| 95  | 1 | Power steering inlet / outlet pipe   | \$ | NSP 518.04    | X |
| 96  | 1 | Power steering pump pulley           | \$ | NSP 235.68    | X |
| 97  | 1 | Power steering hose - pressure       | \$ | NSP 361.68    | X |
| 98  | 1 | Power steering hose - non pressure   | \$ | NSP 494.28    | X |
| 99  | 1 | Front chassis member/frame           | \$ | B 1,550.70    | ✓ |
| 100 | 1 | Dash Board                           | \$ | CM 869.76     | ✓ |
| 101 | 1 | Dash Board air bag                   | \$ | Burn 3,342.72 | ✓ |
| 102 | 1 | Dash Board air bag sensor            | \$ | nn 323.76     | ✓ |
| 103 | 1 | Dash Board air bag control unit      | \$ | nn 654.96     | ✓ |
| 104 | 1 | Engine splash cover RH               | \$ | 178.20        | ? |
| 105 | 1 | Engine splash cover LH               | \$ | 178.20        | ? |
| 106 | 1 | ECU assy                             | \$ | 4,584.24      | ? |
| 107 | 1 | ABS pump                             | \$ | CM 5,679.60   | ✓ |
| 108 | 1 | ABS pump pipe                        | \$ | 82.08         | ? |
| 109 | 1 | Alternator assembly                  | \$ | 2,657.64      | ? |
| 110 | 1 | Gear box cross member                | \$ | 1,454.28      | ? |
| 111 | 1 | Gear box cross member Center         | \$ | 539.76        | ? |
| 112 | 1 | Gear box mountingRR                  | \$ | 349.68        | ? |
| 113 | 1 | Gear box mounting FRT                | \$ | 189.60        | ? |
| 114 | 1 | Engine mounting side LH              | \$ | 209.58        | ? |
| 115 | 1 | Engine mounting RH                   | \$ | 254.28        | ? |
| 116 | 1 | Front Seat Belt RH                   | \$ | In 862.20     | ✓ |
| 117 | 1 | Front safety belt cover garnish RH   | \$ | D 253.68      | ✓ |

**TRANS-CAB AUTO SERVICES PTE LTD****ROEL**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 5702J - AXA**

|     |   |                                    |    |              |
|-----|---|------------------------------------|----|--------------|
| 118 | 1 | Front Seat Belt tension RH         | \$ | 126.01 ?     |
| 119 | 1 | Front Seat Belt LH                 | \$ | 862.20 ✓     |
| 120 | 1 | Front safety belt cover garnish LH | \$ | 253.68 ✓     |
| 121 | 1 | Front Seat Belt tension LH         | \$ | 126.01 ?     |
| 122 | 1 | Battery                            | \$ | 240.00 50/50 |
| 123 | 1 | Battery tray                       | \$ | 63.48 ✓      |
| 124 | 1 | Battery fastener bracket           | \$ | 37.26 X      |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>75,828.26</b> |
| <b>25%</b>   | <b>\$</b> | <b>18,957.07</b> |
|              | <b>\$</b> | <b>56,871.19</b> |

**Specical Nett**

|       |                                          |    |             |
|-------|------------------------------------------|----|-------------|
| 1 Set | Front Bumper Fastener Clip               | \$ | 40.00 ✓     |
| 1     | CNG Sticker                              | \$ | 15.00 ✓     |
| 1 Set | Front Fender Liner Clip LH               | \$ | 30.00 ✓     |
| 1 Set | Front Fender Liner Clip RH               | \$ | 30.00 ✓     |
| 2     | Bonnet Stopper                           | \$ | 9.60 ✓      |
| 1 Set | Bonnet Under Weatherstrip Seal Clips     | \$ | 21.60 ✓     |
| 1 Set | Bonnet Insulator Clip                    | \$ | 42.00 ✓     |
| 1 Set | Bonnet Damper Stay Clip                  | \$ | 10.00 X     |
| 1 Set | Horn High pitch / Low Pitch              | \$ | 100.00 X    |
| 1 Set | Front Wiper Garnish / Wiper Grille Clips | \$ | 18.50 ✓     |
| 1 Set | Front Wiper Clip                         | \$ | 10.68 ✓     |
| 1 Set | Radiator Grille Clip                     | \$ | 18.00 ✓     |
| 2 Can | Radiator Coolant                         | \$ | 40.00 20/50 |
| 2     | Radiator Top Bracket Mounting            | \$ | 33.84 ✓     |
| 2     | Radiator Lower Mounting Bushing          | \$ | 18.43 ?     |
| 1     | Front Licence Plate                      | \$ | 50.00 25/50 |
| 1     | Front Door Sticker 'Trans-Cab'           | \$ | 60.00 X     |
| 1     | Front Side Rocker Panel Garnish Clips    | \$ | 18.00 X     |
| 1     | Front Windscreen Sealant                 | \$ | 80.00 40/50 |
| 1     | Front Windscreen Inner Sponge Seal       | \$ | 60.00 30/50 |
| 1     | Roof Lining Clips                        | \$ | 25.00 X     |
| 1     | Front ERP Bracket                        | \$ | 50.00 X     |
| 1     | Front ERP Unit                           | \$ | 200.00 X    |
| 2     | ERP Sticker                              | \$ | 10.00 ✓     |
| 1     | Battery                                  | \$ | 240.00 X    |
| 1     | Air Filter                               | \$ | 36.00 ?     |
| 1 Set | Engine splash cover clip RH              | \$ | 12.00 ?     |
| 1 Set | Engine splash cover clip LH              | \$ | 12.00 ?     |

**TRANS-CAB AUTO SERVICES PTE LTD****ROEL**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 5702J - AXA**

|   |                                       |    |                                |
|---|---------------------------------------|----|--------------------------------|
| 1 | Front Fender Advertisement Sticker LH | \$ | <i>nn</i> 250.00 <i>150.00</i> |
| 1 | Front Fender Advertisement Sticker RH | \$ | <i>nn</i> 250.00 <i>150.00</i> |

**TOTAL \$ 1,790.65****TOTAL PARTS \$ 58,661.85**

|                                                                                                                                    |    |                           |
|------------------------------------------------------------------------------------------------------------------------------------|----|---------------------------|
| Panel Beating, Knocking And Straightening<br>The Necessary Portion, Remove And<br>Renewal Of Parts, Adjust And Realign The<br>Same | \$ | 8,400.00 <i>2000</i>      |
| To Check Electrical Lighting Concerned.                                                                                            | \$ | 100.00 <i>300</i>         |
| To Rust-Proofing Of The Affected Areas.                                                                                            | \$ | 200.00 <i>1800</i>        |
| Putty And Spray Painting Of The Affected<br>Portion.                                                                               | \$ | 8,100.00 <i>14000</i>     |
| To Remove And Refit Interior Fittings,<br>Trimings, Garnish, Fittings And Other, To<br>Enable Repair.                              | \$ | <i>nn</i> 350.00 <i>X</i> |
| Labour charge to mount and dismount<br>vehicle on jig bench, to facilitate repair.                                                 | \$ | 380.00 <i>2500</i>        |
| To dismantle and refit front end suspension,<br>undercarriage parts, final checking and<br>testing.                                | \$ | 380.00 <i>2400</i>        |
| To remove and renew engine and gear box<br>mounting.                                                                               | \$ | 380.00                    |
| To dismantle and refit engine cross-member<br>and engine mounting.                                                                 | \$ | 380.00                    |
| To lift-up engine with gear box and refit.                                                                                         | \$ | 440.00                    |
| To remove and renew power steering pump,<br>oil cooler pipe and final checking and<br>testing.                                     | \$ | <i>nn</i> 440.00 <i>X</i> |

**TRANS-CAB AUTO SERVICES PTE LTD****ROEL**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 5702J - AXA**

|                                                                                   |    |          |          |
|-----------------------------------------------------------------------------------|----|----------|----------|
| To check ABS brake efficiency, final checking and testing.                        | \$ | 380.00   | } 801    |
| To remove and refit ABS pump relay to enable repair.                              | \$ | 380.00   |          |
| To remove and refit air bag system and reset.                                     | \$ | 480.00   | 2401     |
| To Remove And Replace Corporate Sticker                                           | \$ | 150.00   | 601      |
| Towing Fees.                                                                      | \$ | 100.00   | 501      |
| To Check Steering Geometry And Computer Wheel Alignment.                          | \$ | 200.00   | 601      |
| To Transfer Of Tire, Rim And On Wheel Balancing.                                  | \$ | ~ 150.00 | X        |
| To Vacuum, Replace, Refix And Recharge Air Condenser                              | \$ | 350.00   | 1001     |
| To Replace, Refix And Top Up Coolant For Radiator                                 | \$ | 150.00   | 501      |
| To Dismantle And Refit Aircon Assy And Attachment, Vacuum And Charge-In-Gas.      | \$ | 350.00   | Repair X |
| To remove and replace corporate sticker                                           | \$ | ~ 330.00 | X        |
| To Remove, Replace And Refit Front W/ Screen Glass To Facilitate Bodywork Repair. | \$ | 150.00   | 1201     |

**TOTAL \$ 22,720.00****Over All Total \$ 81,381.84****Total Repair Days****30 DAYS**

18 days