



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

k

18 JUL 2019

Your Ref : SLR2694Y
Our Ref : TP/11349/FBL9895M/SLR2694Y

BY EMAIL & HAND

ERGO Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

ATTN: Motor Claims Dept

Dear Sir / Madam,

Accident Involving FBL9895M & SLR2694Y on 30/05/2019

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$ 906.93
2. Loss of Use (3 days x \$20)	\$ 60.00
3. GIA Vehicle Insurance Search Fee	\$ 2.00
TOTAL	\$ 968.93

We attached our Tax Invoice and GIA Search Invoice for your perusal.

Your prompt settlement is greatly appreciated.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

Raymond Tan
Manager/Insurance Dept





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000280K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

TAX INVOICE

Customer :

ERGO INSURANCE PTE LTD
302 ORCHARD ROAD
#09-01 TIONG BUILDING
SINGAPORE 238862

MOTOR CLAIMS DEPT

GST Reg No. : M2-0010542-7

Invoice No. : **DLCR40101315-I11349**
Invoice Date : 10/07/2019
Payment Due Date : 09/08/2019

CLAIM NO. : 11349
POLICY NO. :
VEHICLE NO. : FBL9895M
MAKE/MODEL : BAJAJ / PULSAR 200 NS M

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	LABOUR	Supply/Install	1	\$160.00	\$160.00
2	ASLY HUGGER REAR	REPLACE	1	\$35.00	\$31.50
				Disc %: 10%	
3	BALANCER LH/RH	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	
4	BOX REAR (GIVI) E33N W/O LIGHT-BLACK	REPLACE	1	\$155.00	\$139.50
				Disc %: 10%	
5	BRACKET REFLECTOR MTG	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
6	FOG LIGHT	REPLACE	1	\$150.00	\$135.00
				Disc %: 10%	
7	FOOT BRAKE PEDAL	REPLACE	1	\$42.00	\$37.80
				Disc %: 10%	
8	GUARD LEG RH	REPLACE	1	\$25.00	\$22.50
				Disc %: 10%	
9	LEVER BRAKE	REPLACE	1	\$18.00	\$16.20
				Disc %: 10%	
10	LOCK PLATE RH	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
11	MIRROR RH	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	
12	REAR BOX BRACKET (KAPPA)	REPLACE	1	\$138.00	\$124.20
				Disc %: 10%	
13	REFLECTOR	REPLACE	1	\$7.00	\$6.30
				Disc %: 10%	
14	STEP HOLDER PILLION RH	REPLACE	1	\$55.00	\$49.50
				Disc %: 10%	
15	STEP PILLION ASSY COMP	REPLACE	1	\$18.00	\$16.20
				Disc %: 10%	
16	STICKER P PLATE	REPLACE	1	\$18.00	\$16.20
				Disc %: 10%	
17	TUBE REAR HUGGER MTG	REPLACE	1	\$35.00	\$31.50
				Disc %: 10%	



bizSAFE₃



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
		SUB TOTAL			\$847.60
		GST @ 7 %			\$59.33
		GRAND TOTAL			<u>\$906.93</u>

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Printed by : RAYMOND

bizSAFE₃

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-086150
Date of Request: 30/05/2019

Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 30/05/2019
Enquiry By Tan Chok Lok
TP Vehicle No. SLR2694Y
Accident Date 30/05/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLR2694Y	ERGO Insurance Pte. Ltd.	08/08/2018-07/08/2019	6829 9199

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-086150
Date of Request: 30/05/2019

Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 30/05/2019
Enquiry By Tan Chok Lok
TP Vehicle No. SLR2694Y
Accident Date 30/05/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 19700268K
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

ERGO INSURANCE PTE LTD
302 ORCHARD ROAD
#09-01 TIONG BUILDING
SINGAPORE 238862

ERGO INSURANCE PTE LTD

NO. : 34256

DATE : 11/06/2019

CLAIM NO. : 11349

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBL9895M
MAKE/MODEL : BAJAJ / PULSAR 200 NS M

*not Afford
nhr
2/2 ~~847.60~~
327.
1/6/19
2hr, 2h AM-147*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ASLY HUGGER REAR	REPLACE	1.00	\$35.00	De 35.00
2	BALANCER 2 /RH P/N: 62564	REPLACE	1.00	\$28.00	O/S ser 28.00
3	BOX REAR (GIVI) E33N W/O LIGHT-BLACK P/N: 44275	REPLACE	1.00	\$155.00	Cu 155.00
4	BRACKET REFLECTOR MTG P/N: 62557	REPLACE	1.00	\$9.00	nr 9.00
5	FOG LIGHT	REPLACE	1.00	\$150.00	Dye 150.00
6	FOOT BRAKE PEDAL P/N: 62565	REPLACE	1.00	\$42.00	sy 42.00
7	GUARD LEG RH	REPLACE	1.00	\$25.00	nr 25.00
8	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	*	1.00	\$190.00	160 190.00
9	LEVER BRAKE	REPLACE	1.00	\$18.00	S12 18.00
10	LOCK PLATE RH	REPLACE	1.00	\$3.00	nr 3.00
11	MIRROR RH P/N: 62560	REPLACE	1.00	\$28.00	Cu 28.00
12	REAR BOX BRACKET (KAPPA)	REPLACE	1.00	\$138.00	3ul 138.00
13	REFLECTOR	REPLACE	1.00	\$7.00	m-s 7.00



bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
14	STEP HOLDER PILLION RH	REPLACE	1.00	\$55.00	55.00
15	STEP PILLION ASSY COMP	REPLACE	1.00	\$18.00	18.00
16	STICKER P PLATE P/N: 29128	REPLACE	1.00	\$18.00	18.00
17	TUBE REAR HUGGER MTG	REPLACE	1.00	\$35.00	35.00
SUB TOTAL					\$954.00
GST @ 7 %					\$66.78
GRAND TOTAL					\$1,020.78

Divide total amount by 1.07 to get net amount.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

P-764
847.60

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

\$ 764.00
76.40

\$ 687.60
160.00

847.60



bizSAFE₃

