

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9271J****AAD1906-074***Not Authored  
Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHD 9271J**

JTDKB3FU203080009

TOYOTA

PRIUS

8.6.19

**ERGO**

17/5/2019

		<b>PART</b>		<b>LIST</b>		
1	1	REAR BUMPER	\$	<i>Buc</i>	458.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$		318.80	?
3	1	REAR BUMPER TOWING COVER	\$	<i>nd</i>	14.70	✓
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	<i>Buc/Rd</i>	552.60	✓
5	1	REAR BUMPER SIDE RETAINER LH	\$	<i>SL</i>	112.70	} X
6	1	REAR BUMPER SIDE RETAINER RH	\$	<i>SL</i>	112.70	
7	1	REAR TAILGATE	\$	<i>N</i>	1,547.27	
8	1	REAR TAILGATE OUTER GARNISH	\$	<i>SL</i>	905.10	
9	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i>	54.70	
10	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i>	54.70	
11	1	GARNISH, BACK DOOR SIDE, LH	\$	<i>SL</i>	93.60	
12	1	GARNISH, BACK DOOR SIDE, RH	\$	<i>SL</i>	93.60	
13	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>SL</i>	55.40	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>SL</i>	55.40	
15	1	BOARD ASSY, BACK DOOR TRIM	\$	<i>SL</i>	254.40	
16	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>SL</i>	51.20	
17	1	REAR TAILGATE WEATHERSTRIP	\$	<i>SL</i>	365.20	
18	1	REAR END PANEL	\$	<i>N</i>	602.10	
19	1	TAILLAMP LOWER RH	\$	<i>SL</i>	548.40	
20	1	TAILLAMP UPPER RH	\$	<i>SL</i>	557.90	
21	1	REAR BUMPER SIDE RH	\$	<i>SL</i>	232.00	
22	1	REAR BUMPER SIDE LH	\$	<i>SL</i>	232.00	
23	1	TAILLAMP LOWER LH	\$	<i>SL</i>	548.40	
24	1	TAILLAMP UPPER LH	\$	<i>SL</i>	557.90	
25	1	REAR FENDER RH	\$	<i>N</i>	817.50	
26	1	REAR FENDER LH	\$	<i>N</i>	817.50	
27	1	BOARD, BACK DOOR TRIM	\$	<i>SL</i>	220.70	
28	1	PANEL SUB-ASSY, QUARTER, LH	\$	<i>N</i>	836.70	
29	1	PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	<i>N</i>	290.50	

**Trans-cab Auto Services Pte Ltd**

AAD1906-074

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9271J

30	1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>nn</i>	836.70	X
31	1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	\$	<i>nn</i>	290.50	X
<b>TOTAL</b>			\$		<b>12,489.47</b>	
<b>25%</b>			\$		<b>3,122.37</b>	
			\$		<b>9,367.10</b>	

**Special Nett**

1	1SET	PARKING AID	\$	<i>nn</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i>	22.00	
3	2	REAR WINDSCREEN SEALANT	\$	<i>nn</i>	80.00	}
4	1	WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	
6	1	REAR TAILGATE TOYOTA LOGO	\$	<i>nn</i>	47.00	
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>nn</i>	52.90	
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>nn</i>	53.50	
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>nn</i>	80.00	}
10	1	REAR TAILGATE STICKER '6555-3333'	\$	<i>nn</i>	80.00	
11	1	REAR BUMPER PROTECTOR	\$	<i>nn</i>	100.00	<i>3000</i>
12	1	REAR WHEEL RIM	\$	<i>nn</i>	1,570.55	}
13	1	REAR WHEEL RIM COVER	\$	<i>nn</i>	175.80	
14	1	SPARE WHEEL RIM	\$	<i>nn</i>	1,570.55	
15	1	SPARE WHEEL RIM COVER	\$	<i>nn</i>	175.80	
16	1	REAR BUMPER SIDE RETAINER LH	\$	<i>nn</i>	112.70	
17	1	REAR BUMPER SIDE RETAINER RH	\$	<i>nn</i>	112.70	
<b>TOTAL</b>			\$		<b>5,133.50</b>	

**TOTAL PARTS \$ 14,500.60****LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *nn* 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 4,500.00 *200*

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ *nn* 170.00X

**Trans-cab Auto Services Pte Ltd****AAD1906-074**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9271J**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	2201
To Rust-Proofing Of The Affected Areas.	\$	na 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	101
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00	X
<b>TOTAL</b>	<b>\$</b>	<b>12,100.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>26,600.60</b>	

LKK Auto Consultants hence notify the Repairer of the following:  
**(PART-BY-PART) Repair Days**  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary items to be resurveyed and is subject to final settlement from Insurance Company

Acknowledged by P. [Signature]

Signature:

Date:

**15 Days**

2 days