

ASS. REC. BY:

Surveyor: Kenneth

RHP: CS/MSG19010415/Krd302

Special Instruction:

From (Person): merimeh Pauline Tham

ASSIGNMENT (Office)

of Melia

Date/Time: 12/6/19 @ 10-18am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 5778R

Insured:

SLR 8656T

at Workshop m/s

ThursLab

Tel:

52130998

of

No. 2 Amk St. 63

Policy No: 1000764450

Claim No:

228013

Sum Insured:

Excess:

6

Make of Veh:

(Client's Record)

D.O.A. 08/08/2019

CA / REV / REP. / REV 24 HRS

Date/Time:

11/11am @ 12/6/19

Person Contacted:

Candy

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction

13/11/19

SHD 5778R - CE3

III / 5018266 / Kw63n2

JVA: 23/10/15

SLR 8656T - x

13/6/19

Send preli. revised via merimeh

1/7

85467.15 to Summ. (Reel 27,967.38, 84B)

ASS. REC. BY:

REF: MSG/

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

08

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

1-B1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S140 578RYr Regn: 12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Ruv

c.c

1788Colour MR White / R

A/C:

Insured / Std / NI / NA

Sp. Reading 39674

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTD KB 31-U 703078577Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

195/65R15BS / DUN / EXNOVA / SY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 8/6/19D.O.I. 12/6/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Acc o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 02 JUL 2019

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

1/2 - typistReport Format: Mr. menLump Sum / I.B.I. (\$) 5467.15Days Of Repair: 8Resurvey No. of Trip: 1Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

30011311

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2019		12 Jun 2019 12:01 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N, Email: ida@hcspl.com.sg		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD5778R	Date of Loss:	08/06/2019 19:00 - :59 [5 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 228013	Policy/Cover Note No.:	1000764450 (Comprehensive) Coverage: 30/08/2018 - 29/08/2019
Vehicle Reg. No. (Insured):	SLR8656T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Trans-cab Auto Services Pte Ltd ( ) No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by <b>Pauline Tham</b> - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/06/2019]		
Driver/Custodian (Insured):	TESHIMA KOKI ( ), NRIC: G6071871M, Tel: +6592713560 Email:		
Adj Asg. Remarks:	(Manual assigned) on WP, VEH IN, Liab: 100%. Contact: Candy @ 6213 0998. Do not assign AIS.		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Ong Zi Hui <zihui\_ong@sg.msig-asia.com>  
**Sent:** Wednesday, 12 June 2019 10:18 AM  
**To:** assignments@lkkauto.com; admin-d@lkkauto.com  
**Cc:** Crystal Lee  
**Subject:** Survey Request - Manual Assigned  
**Attachments:** 5778.pdf; 9798.pdf

PRI OF SHD5778R (TP) and SHB9798S (TP)

### Manual Assigned

Dear LKK

Refer to the attachment, please survey **both** vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you.

Ong Zi Hui  
Admin Officer, Claims Services  
D: +65 6643 1320 | F: +65 6225 7402 | [zihui\\_ong@sg.msig-asia.com](mailto:zihui_ong@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

#### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn:	Pauline Tham	Date:	13 Jun 2019
-------	--------------	-------	-------------

**Preliminary Advice**

Insured Vehicle No	: SLR8656T	Accident Date	: 08/06/2019
TP Vehicle No	: SHD5778R	Assignment Date	: 12/06/2019
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 8
Date of Inspection	: 12/6/2019		
Inspection At	: TRANS-CAN AUTO SERVICES PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,434.53
Revised Amount	:S\$	5,467.15
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,467.15
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

**Vehicle Details**

Vehicle No.: SHD5778R

Vehicle to be Exported: Yes

Intended Deregistration Date: 10 Jun 2019

Vehicle Make: TOYOTA

Vehicle Model: PRIUS 5DR HATCHBACK (AUTO)

Primary Colour: Red

Manufacturing Year: 2018

Engine No.: 2ZR2B92770

Chassis No.: JTDKB3FU703078577

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$26,605.00

Original Registration Date: 19 Dec 2018

First Registration Date: 19 Dec 2018

Transfer Count: 0

Actual ARF Paid: \$14,247.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Dec 2026

PARF Rebate Amount: \$10,685.00

**Intended COE Rebate Details**

COE Expiry Date: 18 Dec 2026

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$22,057.00

COE Rebate Amount: \$17,645.00

**Total Rebate Amount: \$28,330.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Jun 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/06/2019 10:45
Date Of Accident	08/06/2019 19:20
Exact Location Of Accident	COMMONWEALTH AVE WEST TOWARDS COMMONWEALTH AVE 2
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD5778R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
<b>Driver</b>	
Name of Driver	SYED MASHOR BIN SYED ABU BAKAR
NRIC No	S2171340F
Date Of Birth	11/05/1958
Occupation	OUTDOOR
Date Of Driving Pass	13/08/1985
Driving Experience	33 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	+65-98171760
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 123 BEDOK RESERVOIR ROAD #02-1003
Postcode	470123
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20190609/2073

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO LARGE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR8656T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	



Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name SYED MASHOR BIN SYED ABU BAKAR

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHD5778R

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

## Sketch Plan Pg. 1

### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

### SKETCH PLAN

Refer to attached Sketch Plan.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T/20190609/2073-

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SINGAPORE POLICE FORCE



T/20190609/2073

1 of 3

Police Station Of Origin:  
Changkat NPP  
109 Tampines Street 11 #01-261  
SINGAPORE 521109  
Tel No: 1800-7819999

Report No. T/20190609/2073

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 09/06/2019 14:26		Vide Report No.:		Station Diary No.: 9	
<b>Informant's Particulars</b>					
Name of Informant: SYED MASHOR BIN SYED ABU BAKAR			Address: APT BLK 123 BEDOK RESERVOIR ROAD #02-1003 SINGAPORE 470123		
ID Type / ID No.: NRIC NO / S2171340F			Contact No.: Home/Office: Mobile: 98171760		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 61	Date of Birth: 11/05/1958	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 08/06/2019 19:20	Type of Location: FILTER LANE
Location: Junction of Road 1 and Road 2 COMMONWEALTH AVENUE WEST CLEMENTI AVENUE 2 FILTER LANE FROM COMMONWEALTH AVENUE WEST TO CLEMENTI AVENUE 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD5778R	Car				Slightly Damaged	2
SLR8656T	Car					0

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:  
Changkat NPP  
109 Tampines Street 11 #01-261  
SINGAPORE 521109  
Tel No: 1800-7819999

Report No. T/20190609/2073

**CONTINUATION OF REPORT**

<b>Driver</b>				
Name	SYED MASHOR BIN SYED ABU BAKAR		ID No.	S2171340F
Related Vehicle	SHD5778R (Car)		Contact No.	98171760
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	09/06/2019		Date Discharge	NIL
No. of Days granted Medical Leave	05		Degree of Injury	Slight
<b>Driver</b>				
Name	TESHIMA KOKI		ID No.	G6071871M
Related Vehicle	SLR8656T (Car)		Contact No.	92713560
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

**Brief Details.**

On the 08/06/2019 at about 1918hrs, I was driving my taxi SHD5778R along Commonwealth Ave West towards Commonwealth Ave. I turned left into the filter lane towards Clementi Ave 2. I stopped before the give way lines to check for traffic when suddenly another car SLR8656T had hit my taxi from the rear. At that point of time, both my passengers, myself and the other driver did not complaint of any injury. We did not call for police or ambulance.

I have in-vehicle camera installed inside my taxi however the view was to the front portion only. Today I felt pain on my hands, legs and back thus went to seek medical attention at Mount Alvernia Hospital and received 05 days of medical leave. My medical certificate number M19000016181.



**SINGAPORE  
POLICE FORCE**



T/20190609/2073

Police Station Of Origin:  
Changkat NPP  
109 Tampines Street 11 #01-261  
SINGAPORE 521109  
Tel No: 1800-7819999

3 of 3

Report No. T/20190609/2073

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
G /  
Sr Staff Sgt MUHAMMAD HAFIDZ BIN ABDUL  
RAHMAN

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
09/06/2019 14:26

Officer In Charge Of Case:  
TP / AEIT /  
Sgt 3 KOH CHEE SENG, KEVIN  
Contact No.: 65472073

Classification Of Case:

Authentication Stamp  
NP168



**SINGAPORE  
POLICE FORCE**

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5778R****AAD1906-081**

*14/6/19 Not Authored*  
*Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHD 5778R**

JTDKB3FU703078577

TOYOTA

PRIUS

8.6.19

**MSIG**

19/12/2018

		<b>PART</b>	<b>LIST</b>	
1	1	REAR BUMPER	\$ CM 458.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$ N 318.80	X
3	1	REAR BUMPER TOWING COVER	\$ SN 14.70	X
4	1	REAR BUMPER UNDER COVER (BLACK)	\$ NALDI 552.60	✓
5	1	REAR BUMPER SIDE RETAINER LH	\$ SN 112.70	X
6	1	REAR BUMPER SIDE RETAINER RH	\$ DI 112.70	✓
7	1	REAR TAILGATE	\$ N 1,547.27	X
8	1	REAR TAILGATE OUTER GARNISH	\$ NALDI 905.10	✓
9	1	COVER, REAR COMBINATION LAMP, RH	\$ SN 54.70	X
10	1	COVER, REAR COMBINATION LAMP, RH	\$ SN 54.70	X
11	1	GARNISH, BACK DOOR SIDE, LH	\$ SN 93.60	} X
12	1	GARNISH, BACK DOOR SIDE, RH	\$ SN 93.60	
13	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$ SN 55.40	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$ SN 55.40	
15	1	BOARD ASSY, BACK DOOR TRIM	\$ SN 254.40	
16	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$ SN 51.20	} X
17	1	REAR TAILGATE WEATHERSTRIP	\$ SN 365.20	
18	1	REAR END PANEL	\$ BI 602.10	
19	1	TAILLAMP LOWER RH	\$ CM 548.40	✓
20	1	TAILLAMP UPPER RH	\$ SN 557.90	X
21	1	REAR BUMPER SIDE RH	\$ CM 232.00	✓
22	1	REAR BUMPER SIDE LH	\$ SN 232.00	X
23	1	TAILLAMP LOWER LH	\$ SN 548.40	X
24	1	TAILLAMP UPPER LH	\$ SN 557.90	X
25	1	REAR FENDER RH	\$ BI 817.50	} X
26	1	REAR FENDER LH	\$ N 817.50	
27	1	BOARD, BACK DOOR TRIM	\$ SN 220.70	
28	1	PANEL SUB-ASSY, QUARTER, LH	\$ N 836.70	} X
29	1	PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$ N 290.50	

**Trans-cab Auto Services Pte Ltd**

AAD1906-081

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5778R

30	1	PANEL SUB-ASSY, QUARTER, RH	\$	n	836.70	}	X	
31	1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	\$	sn	290.50			
32	1	PAN, REAR FLOOR	\$	n	572.10			
33	1	EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	n	77.00			
34	1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	n	192.90			
35	1	EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	n	77.00			
36	1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	n	192.90			
TOTAL			\$		13,601.37			
25%			\$		3,400.34			
			\$		10,201.03			

**Special Nett**

1	1SET	PARKING AID	\$	sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	22.00	✓
3	2	REAR WINDSCREEN SEALANT	\$	na	80.00	X
4	1	WINDSCREEN MOULDING	\$	na	100.00	X
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	✓
6	1	REAR TAILGATE TOYOTA LOGO	\$	na	47.00	X
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90	✓
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50	✓
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00	30sn
10	1	REAR TAILGATE STICKER '6555-3333'	\$	na	80.00	30sn
11	1	REAR BUMPER PROTECTOR	\$	na	100.00	30sn
12	1	REAR WHEEL RIM	\$	sn	1,570.55	} X
13	1	REAR WHEEL RIM COVER	\$	sn	175.80	
14	1	SPARE WHEEL RIM	\$	sn	1,570.55	
15	1	SPARE WHEEL RIM COVER	\$	sn	175.80	
16	1	REAR BUMPER SIDE RETAINER LH	\$	Replacement	112.70	
17	1	REAR BUMPER SIDE RETAINER RH	\$	✓	112.70	
TOTAL			\$		5,133.50	

**TOTAL PARTS \$ 15,334.53****LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ nn 170.00 X



**Trans-cab Auto Services Pte Ltd****AAD1906-081**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5778R**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1200 7,500.00 <del>300</del>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	na 170.00 X
Putty And Spray Painting Of The Affected Portion.	\$	7,500.00 <del>600</del>
To Rust-Proofing Of The Affected Areas.	\$	na 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <del>500</del>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00 X
To check steering geometry and computer wheel alignment	\$	na 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <del>200</del>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 380.00 <del>1000</del>
To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00 X
<b>TOTAL</b>	<b>\$</b>	<b>18,100.00</b>

**Trans-cab Auto Services Pte Ltd****AAD1906-081**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5778R**

Over All Total	\$	<u>33,434.53</u>
----------------	----	------------------

**(PART-BY-PART) Repair Days**~~25 Days~~

3 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey on "Without Prejudice" basis
- No illegal modification is allowed
- Surplus money received must be destroyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Monday, 1 July 2019 4:54 PM  
**To:** Ng Wai Yin; 'calvin.er@transcab.com.sg'  
**Cc:** SUR; jasminetan@transcab.com.sg  
**Subject:** FINALIZE (3 VEHICLES)  
**Attachments:** SHC 5804D (MARKING) .pdf; SHD 5778R (MARKING).pdf; SHD 9884R (MARKING).pdf

Dear Wai Yin,

WITHOUT PREJUDICE

- 1) SHC 5804D-DOA:10/6/19, Lump Sum \$4700 @ 3 working days
- 2) SHD 5778R-DOA:8/6/19 , Finalize amount \$5467.15 @ 3 working days
- 3) SHD 9884R-DOA:28/5/19, Lump Sum \$9400 @ 4 working days (Provides us after paint photos)

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jun 2019		12 Jun 2019 12:01 <a href="#">Edit Adj Rpt</a>	<b>S\$5,467.15</b> <a href="#">Edit Estimates</a>	<b>S\$5,467.15</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N, Email: ida@hcspl.com.sg								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHD5778R	Date of Loss:	08/06/2019 19:00 - :59 [5 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 228013	Policy/Cover Note No.:	1000764450 (Comprehensive) Coverage: 30/08/2018 - 29/08/2019						
Vehicle Reg. No. (Insured):	SLR8656T	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Trans-cab Auto Services Pte Ltd ( ) No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/07/2019]								
Driver/Custodian (Insured):	TESHIMA KOKI ( ), NRIC: G6071871M, Tel: +6592713560 Email:								
Adj Asg. Remarks:	(Manual assigned) on WP. VEH IN. Liab: 100%. Contact: Candy @ 6213 0998. Do not assign AIS.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SHD5778R (228013)**  
**[SLR8656T]**  
**TP**  
**TRANS-CAB SERVICES PTE LTD**  
**Jun 8 2019 7:00PM**  
**[HITACHI CAPITAL ASIA PACIFIC PTE LTD]**  
**Trans-cab Auto Services Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	12/06/19 11:41	<b>Accident Statement</b> From:OD - Reg. No: SLR8656T, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	13/06/19 15:54	<b>Adjuster Immediate Advice</b>		Load HTM
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
2	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
3	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
4	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
5	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
6	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
7	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
8	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
9	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
10	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
11	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
12	01/07/19 16:03	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
13	01/07/19 16:03	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
14	01/07/19 16:03	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
15	01/07/19 16:03	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
16	01/07/19 16:03	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
17	01/07/19 16:03	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
18	01/07/19 16:03	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
19	01/07/19 16:05	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
20	01/07/19 16:05	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
21	01/07/19 16:05	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	12/06/19 11:41	<b>estimate repair</b>		Load PDF
2	12/06/19 11:41	<b>TP GIA report-SHD5778R</b> From:OD - Reg. No: SLR8656T, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD		Load PDF
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail Print
1	12/06/19 11:57	<b>email - manual assign</b>		Load PDF

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
----------------------------	-----------------------	----------------------	-----------------------

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010415/KVD3E2

Date: 09/07/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000764450

Claimant Vehicle No : SHD5778R

Insured Vehicle No : SLR8656T

Date of Loss: 08/06/2019

Nature of Claim: TP

Claim No: 228013

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHD5778R

Make &amp; Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZR2B92770

Reg. Date: 19/12/2018 (Man. Year: 2018)

Chassis No: JTDKB3FU703078577

Colour: Metallic Red

Odometer: 39674 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Goodyear 7 mm

Rear Left Side: Goodyear 7 mm

Front Right Side: Goodyear 7 mm

Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,334.53	3,437.15	11,897.38	77.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,100.00	2,030.00	16,070.00	88.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>33,434.53</b>	<b>5,467.15</b>	<b>27,967.38</b>	<b>83.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,340.42</b>	<b>382.70</b>	<b>1,957.72</b>	<b>83.65</b>
<b>Nett Amount (S\$)</b>	<b>35,774.95</b>	<b>5,849.85</b>	<b>29,925.10</b>	<b>83.65</b>

## INSPECTION

Date of Assignment: 12/06/2019

Date Inspected: 12/06/2019 Inspected At:

Trans-cab Auto Services Pte Ltd  
No 2 Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2019)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD5778R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	458.60 FL	*458.60 FL
2	1		*REAR BUMPER RE-INFORCEMENT	Repair	318.80 FL	*- FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	14.70 FL	*- FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Dented / Distorted	552.60 FL	*552.60 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Distorted	112.70 FL	*112.70 FL
7	1		*REAR TAILGATE	Repair	1,547.27 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Dented / Cut	905.10 FL	*905.10 FL
9	1		*COVER, REAR COMBINATION LAMP, RH	Serviceable	54.70 FL	*- FL
10	1		*COVER, REAR COMBINATION LAMP, RH	Serviceable	54.70 FL	*- FL
11	1		*GARNISH, BACK DOOR SIDE, LH	Serviceable	93.60 FL	*- FL
12	1		*GARNISH, BACK DOOR SIDE, RH	Serviceable	93.60 FL	*- FL
13	1		*MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	Serviceable	55.40 FL	*- FL
14	1		*MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	Serviceable	55.40 FL	*- FL
15	1		*BOARD ASSY, BACK DOOR TRIM	Serviceable	254.40 FL	*- FL
16	1		*PANEL ASSY, BACK DOOR TRIM, UPPER	Serviceable	51.20 FL	*- FL
17	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	365.20 FL	*- FL
18	1		*REAR END PANEL	Bent	602.10 FL	*602.10 FL
19	1		*TAILLAMP LOWER RH	Cracked	548.40 FL	*548.40 FL
20	1		*TAILLAMP UPPER RH	Serviceable	557.90 FL	*- FL
21	1		*REAR BUMPER SIDE RH	Cracked	232.00 FL	*232.00 FL
22	1		*REAR BUMPER SIDE LH	Serviceable	232.00 FL	*- FL
23	1		*TAILLAMP LOWER LH	Serviceable	548.40 FL	*- FL
24	1		*TAILLAMP UPPER LH	Serviceable	557.90 FL	*- FL
25	1		*REAR FENDER RH	Bent	817.50 FL	*817.50 FL
26	1		*REAR FENDER LH	Repair	817.50 FL	*- FL
27	1		*BOARD, BACK DOOR TRIM	Serviceable	220.70 FL	*- FL
28	1		*PANEL SUB-ASSY, QUARTER, LH	Repair	836.70 FL	*- FL
29	1		*PANEL, QUARTER WHEEL HOUSE, OUTER LH	Repair	290.50 FL	*- FL
30	1		*PANEL SUB-ASSY, QUARTER, RH	Repair	836.70 FL	*- FL
31	1		*PANEL, QUARTER WHEEL HOUSE, OUTER RH	Serviceable	290.50 FL	*- FL
32	1		*PAN, REAR FLOOR	Repair	572.10 FL	*- FL
33	1		*EXTENSION, REAR FLOOR SIDE PANEL, RH	Repair	77.00 FL	*- FL
34	1		*EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	Repair	192.90 FL	*- FL
35	1		*EXTENSION, REAR FLOOR SIDE PANEL, LH	Repair	77.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	Repair	192.90 FL	*- FL
37	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
38	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
39	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
41	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
42	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.00 FS	*47.00 FS
43	1		*REAR TAILGATE WORDING PRIUS	Necessary	52.90 FS	*52.90 FS
44	1		*REAR TAILGATE WORDING HYBRID	Necessary	53.50 FS	*53.50 FS
45	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
46	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
47	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*30.00 FS
48	1		*REAR WHEEL RIM	Serviceable	1,570.55 FS	*- FS
49	1		*REAR WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
50	1		*SPARE WHEEL RIM	Serviceable	1,570.55 FS	*- FS
51	1		*SPARE WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
52	1		*REAR BUMPER SIDE RETAINER LH	Repeated	112.70 FS	*- FS
53	1		*REAR BUMPER SIDE RETAINER RH	Repeated	112.70 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 18,734.87 4,494.40  
 - List Item Discount on L Items 25.00/25.00% (\$\$) 3,400.34 1,057.25

Total Parts (\$\$) 15,334.53 3,437.15

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	7,500.00	1,200.00
3	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	660.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
7	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	100.00
13	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
14	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
15	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>18,100.00</b>	<b>2,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >