

2/03/2003

ASS. REC. BY:

REF:

C8/MSA196/0417/Kvc302

Special Instruction:

Supervisor: Kenneth

Merimen

## ASSIGNMENT (Office)

From (Person):

Fivel Poo

of

MS/G

Date/Time:

12/6/12 10:18am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 9798S

Insured:

SLX 4829G

at Workshop m/s

Thunacub

Tel:

62876666

of

No. 2 Amcst-63

Policy No:

A29077313ARW

Claim No:

596152

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11/11/2012 12/6/12

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time

Action/Instruction

1/1/2013

SHB 9798S - CC3/AIT 4000778/Kyn 3n2-1

DOA: 11/01/2014

SLX 4829G-X

13/6/19

Send preli revised via merimen

ASS. REC. BY:

REF: MSG/

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

02 days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

201.45 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time

Action / Instruction

/ File pass to

14/6/19

11 by @ 2450/

(Red

22,476.21, 909)

RECEIVED 14 JUN 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

14/6- typist

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_

MR. imen

2450/2

Days Of Repair: 2

Resurvey No. of Trlp: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

Tech Invs (\$ \_\_\_\_\_)

☐

Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Fees \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

300

11

311

Veh No: S14B 9798SYr Regn: 11, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: PeugeotC.C. 1995Colour: M. White / Red

A/C: \_\_\_\_\_

Insured / Std / NI / NA

Sp. Reading: 587205

T/Radio: \_\_\_\_\_

Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C/No: VIFIABL 15 AUG 283371Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NT / S/Rlm / STD A/Rlm or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Goodyear

Front

Rear

R/Bal. 7 mmR/Bal. 6 mmL/Bal. 7 mmL/Bal. 6 mmD.O.A. 9/16/19D.O.I. 12/6/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
Rear o/s

The UIC / Chassis frame / Body Structure affected due to collision.

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2019		12 Jun 2019 15:34 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	CHIA SOO PING, SHARON, ID: S7239304Z, Tel: +6592214377			
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K			
Vehicle Reg. No.:	SHB9798S	Date of Loss:	09/06/2019 18:00 - :59 [70 Months and 9 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 596152	Policy/Cover Note No.:	A29077313AVW (Comprehensive) Coverage: 28/03/2019 - 27/03/2020	
Vehicle Reg. No. (Insured):	SLX4829G	Policy No. (Claimant):		
		Excess:	S\$3,500.00	
Repairer:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/06/2019]			
Driver/Custodian (Insured):	MARIA BELLE LEE SHU MIN (), NRIC: S9826144C, Tel: +6591906981 Email:			
Adj Asg. Remarks:	on WP, VEH IN/ Liab: 100%. Contact: Amanda @ 6213 0998. Manually assigned to LKK via email on 12/06/2019			

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Ong Zi Hui <zihui\_ong@sg.msig-asia.com>  
**Sent:** Wednesday, 12 June 2019 10:18 AM  
**To:** assignments@lkkauto.com; admin-d@lkkauto.com  
**Cc:** Crystal Lee  
**Subject:** Survey Request - Manual Assigned  
**Attachments:** 5778.pdf; 9798.pdf

PRI OF SHD5778R (TP) and SHB9798S (TP)

### Manual Assigned

Dear LKK

Refer to the attachment, please survey **both** vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you.

Ong Zi Hui  
Admin Officer, Claims Services  
D: +65 6643 1320 | F: +65 6225 7402 | [zihui\\_ong@sg.msig-asia.com](mailto:zihui_ong@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

#### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn: Fievel Foo Wen Yao Date: 13 Jun 2019

## Preliminary Advice

Insured Vehicle No	: SLX4829G	Accident Date	: 09/06/2019
TP Vehicle No	: SHB9798S	Assignment Date	: 12/06/2019
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 2
Date of Inspection	: 12/6/2019		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,926.21
Revised Amount	:S\$	3,083.59
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,083.59
Lump Sum Repair	:S\$	

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHB97985
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000300
Chassis No.:	VF1ABL15AUC273443
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Jul 2013
First Registration Date:	31 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2021
PARF Rebate Amount:	\$8,748.00

**Intended COE Rebate Details**

COE Expiry Date:	30 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$51,810.00
COE Rebate Amount:	\$13,840.00
<b>Total Rebate Amount:</b>	<b>\$22,588.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Jun 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/06/2019 11:46
Date Of Accident	09/06/2019 18:25
Exact Location Of Accident	TPE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHB9798S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN YEOW SENG
NRIC No	S1275189C
Date Of Birth	09/12/1957
Occupation	OUTDOOR
Date Of Driving Pass	19/07/1979
Driving Experience	39 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90362496
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 831 TAMPINES STREET 83 #04-46
Postcode	520831
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SELINA - 98444718 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 09.06.2019 at about 1827hours, I was travelling slowly on the second lane along TPE due to congestion ahead. Suddenly, I felt an impact. Vehicle B (SLX4829G) hit onto my taxi rear portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX4829G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MARIA BELLE
NRIC/Passport Number	
Contact Number	91906981
Address	
Postcode	



Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please see the attach G/A report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9798S**

AAD1906-083

*12/6/19*  
*Not Notified*  
*Repair Bk paint*  
*61 Sing & 2450/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHB 9798S**

VF1ABL15AUC273443

RENAULT

LATITUDE

9.6.19

**MSIG**

31/7/2013

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bua</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>nd 10.11</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1 BUMPER RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>cm</i> 43.61 ✓
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Sn</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>n</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95 X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>n</i> 1,471.77
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56
15	1 TAILLAMP RH	\$	<i>Sn</i> 552.55
16	1 TAILLAMP PANEL RH	\$	<i>n</i> 986.70
17	1 TAILLAMP LH	\$	<i>Sn</i> 552.55
18	1 TAILLAMP PANEL LH	\$	<i>n</i> 986.70
19	1 BOOT REAR	\$	<i>n</i> 2,872.68
20	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
21	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
24	1 BOOT BADGE 'RENAULT'	\$	<i>nn</i> 225.36
25	1 BOOT BADGE	\$	<i>nn</i> 225.36
26	1 BOOT STRUT LH	\$	<i>Seq</i> 276.08
27	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08
28	1 BOOT HINGE LH	\$	<i>n</i> 367.84
29	1 BOOT HINGE RH	\$	<i>n</i> 367.84

**Trans-cab Auto Services Pte Ltd**

AAD1906-083

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9798S**

30	1	BOOT INNER TRIM	\$	586.45	X
31	1	BOOT SWITCH	\$	168.13	X
32	1	BOOT LOCK	\$	202.67	X
33	1	BOOT LOCK CATCH	\$	74.40	X
<b>TOTAL</b>			<b>\$</b>	<b>16,046.87</b>	
<b>10%</b>			<b>\$</b>	<b>1,604.69</b>	
			<b>\$</b>	<b>14,442.19</b>	

**Special Nett**

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	
10	1	BOOT STICKER "Trans-cab"	\$	30.00	} X
11	1	BOOT STICKER "6555-3333"	\$	30.00	
12	1	EXHAUST MOUNTING REAR	\$	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	80.00	
14	1	WINDSCREEN MOULDING	\$	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
16	1	BOOT INNER TRIM CLIP	\$	45.00	
17	1SET	BOOT FINISHER CLIP	\$	24.20	
18	1	TAILLAMP CLIP LH	\$	5.00	
19	1	TAILLAMP CLIP RH	\$	5.00	
<b>TOTAL</b>			<b>\$</b>	<b>1,384.02</b>	

<b>TOTAL PARTS</b>	<b>\$</b>	<b>15,826.21</b>
--------------------	-----------	------------------

**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	10/
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	X

**Trans-cab Auto Services Pte Ltd****AAD1906-083**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9798S**

To reinstall rear bumper parking sensor.	\$	170.00	601
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	4 380.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4 380.00	X

**TOTAL \$ 9,100.00****Over All Total \$ 24,926.21****LUMP SUM (REPAIR DAY)****10 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supersession part(s) must be approved by the Insurance Company

Approved by Repairer

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jun 2019		12 Jun 2019 15:34 <a href="#">Edit Adj Rpt</a>	<b>S\$2,450.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,450.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>CHIA SOO PING, SHARON</b> , ID: S7239304Z, Tel: +6592214377								
Main Claimant:	<b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	<b>SHB9798S</b>	Date of Loss:	09/06/2019 18:00 - :59 [70 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 596152</b>	Policy/Cover Note No.:	A29077313AVW (Comprehensive) Coverage: 28/03/2019 - 27/03/2020						
Vehicle Reg. No. (Insured):	<b>SLX4829G</b>	Policy No. (Claimant):							
		Excess:	S\$3,500.00						
Repairer:	<b>Trans-Cab Services Pte Ltd (HQ)</b> 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Fievel Foo Wenyao</b> - 6643 1316]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 12/07/2019]								
Driver/Custodian (Insured):	MARIA BELLE LEE SHU MIN (), NRIC: S9826144C, Tel: +6591906981 Email:								
Adj Asg. Remarks:	on WP. VEH IN/ Liab: 100%. Contact: Amanda @ 6213 0998. Manually assigned to LKK via email on 12/06/2019								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHB9798S (596152)  
[SLX4829G]  
TP  
TRANS-CAB SERVICES PTE LTD  
Jun 9 2019 6:00PM  
[CHIA SOO PING, SHARON]  
Trans-Cab Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <span style="border: 1px solid black; padding: 0 5px;">View in Browser</span>	
<b>Assessment Reports</b>						1 per page <span style="border: 1px solid black; padding: 0 5px;">v</span> <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print
1	12/06/19 13:37	<b>Accident Statement</b> <small>From: OD - Reg. No: SLX4829G, Claimant: CHIA SOO PING, SHARON</small>				Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	13/06/19 15:45	<b>Adjuster Immediate Advice</b>				Load HTM	
<b>Photos/Images</b>						3 per page <span style="border: 1px solid black; padding: 0 5px;">v</span> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
2	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
3	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
4	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
5	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
6	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
7	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
8	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
9	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
10	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
11	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
12	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
13	08/07/19 08:51	<b>General View</b>				Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>						1 per page <span style="border: 1px solid black; padding: 0 5px;">v</span> <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print
1	12/06/19 13:37	<b>REPAIR EST</b>				Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)				Thumbnail	Print
1	12/06/19 15:33	<b>Survey Request - Manual Assigned</b>				Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>				
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				





# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010417/KVD3E2

Date: 08/07/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29077313AVW

Claimant Vehicle No : SHB9798S

Insured Vehicle No : SLX4829G

Date of Loss: 09/06/2019

Nature of Claim: TP

Claim No: 596152

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB9798S

Make &amp; Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Engine No: M9R8839C000300

Reg. Date: 31/07/2013 (Man. Year: 2013)

Chassis No: VF1ABL15AUC273443

Colour: Metallic White/Red

Odometer: 587265 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Giti 7 mm Rear Left Side: Giti 6 mm

Front Right Side: Giti 7 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,826.19	2,593.59	13,232.60	83.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,100.00	490.00	8,610.00	94.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,926.19</b>	<b>3,083.59</b>	<b>21,842.60</b>	<b>87.63</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,450.00</b>		
<b>(S\$)</b>	<b>24,926.19</b>	<b>2,450.00</b>	<b>22,476.19</b>	<b>90.17</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,744.83</b>	<b>171.50</b>	<b>1,573.33</b>	<b>90.17</b>
<b>Nett Amount (S\$)</b>	<b>26,671.02</b>	<b>2,621.50</b>	<b>24,049.52</b>	<b>90.17</b>

### INSPECTION

Date of Assignment: 12/06/2019

Date Inspected: 12/06/2019 Inspected At:

Trans-Cab Services Pte Ltd (HQ)  
2 Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2019)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB9798S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Distorted	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Cracked	43.61 FL	*43.61 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
19	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
20	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
21	1		*BOOT WHEATHERSTRIP	Serviceable	323.05 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
24	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
25	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
26	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
27	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
28	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
29	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
30	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
31	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
32	1		*BOOT LOCK	Repair	202.67 FL	*- FL
33	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
34	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
35	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
36	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
37	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
38	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
39	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
41	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
42	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
43	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
44	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
45	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*- FS
46	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
47	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
48	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
49	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
50	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
51	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
52	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>17,430.88</b>	<b>2,863.43</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,604.69</b>	<b>269.84</b>
<b>Total Parts (\$\$)</b>	<b>15,826.19</b>	<b>2,593.59</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
2	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
7	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	3,000.00	200.00
9	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
10	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
11	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
14	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
15	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,100.00</b>	<b>490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >