

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0739/2019/KK/KS
Date : 11-Jun-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no. : SDG 9595 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Cheng Chuan
Address : 6 Jalan Hussein
Singapore 419402
Telephone : (HP) +65 96302114
Type of Claim : Third Party Claims
Policy No. : 2018-V0094286-VAW-R004
Vehicle No : **SKD 1203 Z**
Model Code : Audi A4 1.8 TFSI MU
Model / Year : Oct-11
Engine No : CDH 146593
Chassis No. : WAUZZZ8K1CA050618
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Jun-19
Place of Accident : Aljunied Ave 2 Multi Storey Car park

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKD 1203 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlight, horns outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. Inspect front lock carrier for further damages. Re-organise crash management components. Reinstall all parts removed.	\$ 3,150.00 750	
3	✓ To respray front bumper, bonnet and lhs front fender. ✗	\$ 2,800.00 1100	✓
4	To carry out diagnostic check	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>6,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 1203 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>deformed</i>	\$ 2,041.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 234.00	X
3	FRONT REINFORCEMENT BEAM <i>?</i>	\$ 802.00	?
4	FRONT BUMPER BRACKET <i>new</i>	\$ 207.00	+
5	FRONT BUMPER REINFORCEMENT SUPPORT LH / RH <i>new</i> 2	\$ 52.00	+
6	FRONT BUMPER GUIDE LH <i>no one</i>	\$ 40.00	+
7	FRONT BUMPER TOP COVER <i>cancel</i>	\$ 116.00	✓
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 160.00	X.
9	FOAM FILLER PIECE <i>?</i>	\$ 113.00	?
10	FRONT AIR GUIDE GRILLE LH <i>new</i>	\$ 156.00	+
11	FRONT REINFORCEMENT BEAM COVER <i>new</i>	\$ 89.00	+
12	"CAUTION" STICKER <i>2 new</i>	\$ 13.00	✓
13	AIR COND STICKER	\$ 18.00	✓
14	SIGNAL HORN LH <i>2 new</i>	\$ 184.00	+
15	SIGNAL HORN BRACKET LH	\$ 23.00	+
16	FRONT FENDER LH <i>Regis</i>	\$ 904.00	+
17	FRONT FENDER ATTACHMENTS	\$ 52.00	+
18	FRONT FENDER BRACKET <i>new</i>	\$ 48.00	+
19	FRONT FENDER BRACKET - LONG <i>new</i>	\$ 46.00	+
20	FRONT FENDER CLOSING ELEMENT	\$ 45.00	+
SUB - TOTAL SPARE PARTS CHARGES		\$ 5,343.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 1203 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER BRACE LH <i>NEC</i>	\$ 107.00	+
22	FRONT WHEEL HOUSING LINER LH	\$ 223.00	+
23	FRONT WHEEL HOUSING LINER ATTACHMENTS <i>green</i>	\$ 41.00	+
24	BONNET	\$ 1,788.00	+
25	BONNET ATTACHMENTS PARTS	\$ 153.00	+
26	BONNET HINGE LH / RH	2 \$ 136.00	+
27	BONNET CATCH HOOK	\$ 127.00	+
28	BONNET STRUT	\$ 109.00	+
29	BONNET EDGE PROTECTION	\$ 50.00	+
30	BONNET LOCK WITH MIRCO SWITCH <i>NEC</i>	\$ 196.00	+
31	BONNET LOCK COVER	\$ 21.00	+
32	MICRO SWITCH	\$ 67.00	+
33	BONNET LOCK CABLE	\$ 44.00	+
34	BONNET LOCK CABLE	\$ 67.00	+
35	HEADLIGHT MOUNTING LH	\$ 107.00	+
36	HEADLIGHT LH <i>checked</i>	\$ 994.00	✓
37	HEADLIGHT BRACKET LH <i>NEC</i>	\$ 71.00	+
38	HALAGEN FOG LAMP LH <i>NEC</i>	\$ 238.00	+
39	WASH WATER RESERVOIR <i>NEC</i>	\$ 200.00	+
40	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 10,382.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *12/06/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *04 days.*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant