

ASS. REC. BY:

REF:

CS/AWA/1010422/USD3

n2

Special Instruction:

Supervisor:

Menas

ASSIGNMENT (Office)

From (Person):

Hew Lee Fung

of

AWAC

Date/Time:

11/6/19 @ 3:33pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKM 4165H

Insured:

FBL 2268U

at Workshop in/s

Dico 60 Auto

Tel:

9187 8064

of

Pikaki Bulut Ave #02-24

Policy No:

AVFM SBO 000591803

Claim No:

NSV 1900285/BP

Sum Insured:

Excess:

Make of Veh:

D.O.A.

7/6/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:27am @ 12/6/19

Person Contacted:

Shenelle

Vehicle IN / OUT

Date/Time	Action/Instruction	
	SKM 4165H - NA / CTI 19010119 / 24	DOA: 7/6/2019
	FBL 2268 U - NA / CTI 19010119 / 24	DOA: 7/6/2019

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

AWAC/
ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bar. or Market Value:

DAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A 40 458

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKM 4165H

Yr Regn:

214

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Citroen C3

c.c 1397

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

103934

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF75C8FP0DA503351

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

7/6/19

D.O.I.

12/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/6/19 confirmed 2/5 \$1700 with John.

(\$ 16,019.39 Red - 90%)

RECEIVED 18 JUN 2019

Date/Time, File Pass to?

18/06/19

1) Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) S + RS, SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$ 1,700/- 4/5)

TOTAL

250

Nivitha (LKK Auto)

From: Hew, Lee Fong <LeeFong.Hew@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Tuesday, 11 June 2019 3:33 PM
To: assignments
Cc: SUR; 'Enquiry'
Subject: TP Survey assignment for SKM 4165 H DOA:07/06/2019 Our ref: NSV1900285/BT

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of Mr Mohamad Taufikh as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SKM 4165 H
Insured Vehicle	:	FBL 2268 U
Policy Number	:	AVFMSB0000591803
Name of Workshop	:	Rico 60 Auto Services Pte Ltd
Contact Number	:	9187 8064/6826 6060
Person to Contact	:	Ms Shanelle Lim
Estimated Cost of repairs	:	\$ NA

Regards,
Claims Division

Copy to Rico 60 Auto Services Pte Ltd (Your Ref: SKM 4165 H) via Email.

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

SUPREME

NEW CARS | PRE-LOVED CARS | INSURANCE | FINANCING

Citroen

Price Range

Depreciation

Year Reg

Hatchback



Advanced Search

Home » Used Cars » V-Kar Traders Pte Ltd » Citroen C3 1.6A Moonroof

Citroen C3 1.6A Moonroof

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$16,888		
Depreciation	\$7,250 /yr View models with similar depre	Reg Date	22-Sep-2010 (1yr 3mths 14days COE left)
Mileage	124,000 km (14.2k /yr)	Manufactured	2010
Road Tax	\$742 /yr	Transmission	Auto
Dereg Value	\$10,977 as of today (change)	OMV	\$15,023
COE	\$20,993	ARF	\$15,023
Engine Cap	1,598 cc	Power	88.0 kW (118 bhp)
Curb Weight	1,145 kg	No. of Owners	4
Type of Vehicle	Hatchback		

Features

Panoramic Roof. View specs of the Citroen C3 (2010-2011)

Description

Well Maintained. Excellent Interior And Exterior Condition.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company	V-Kar Traders Pte Ltd » dealer's pricelist » 14 vehs sold 5 vehs available	
Address	35 The Inglewood Search cars nearby this location	
Office No	67197301	
Contact Person(s)	Ray Kish	96367367 96741114


Posted on: 01-Jun-2019 | Last Updated on: 03-Jun-2019

Upfront Payment

» more Financial info

Transfer Fee	\$25	
Down Payment	\$5,066 (change)	Maximum 70% Loan
1st Instalment	\$817	Based on 2.98% interest rate
Insurance	\$1,331 onwards Not at fault? No upfront payment required! (Get a quote) Quote assumes a standard profile. "Get a quote" for exact figure.	
Total Upfront Payment	\$7,239	Check with seller for exact figure

Powered by



Compare

es

» View All

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 8202Z

Vehicle Details

Vehicle No.: SKM4165H

Vehicle to be Exported: No

Intended Deregistration Date: 12 Jun 2019

Vehicle Make: CITROEN

Vehicle Model: C3 1.4 EGS SMT ABS D/AB 2WS 5DR

Primary Colour: Black

Manufacturing Year: 2013

Engine No.: 10FGAS1707601

Chassis No.: VF7SC8FP0DA503351

Maximum Power Output: 70.0 kW (93 bhp)

Open Market Value: \$15,888.00

Original Registration Date: 27 Feb 2014

First Registration Date: 27 Feb 2014

Transfer Count: 0

Actual ARF Paid: \$5,888.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Feb 2024

PARF Rebate Amount: \$4,121.00

Intended COE Rebate Details

COE Expiry Date: 26 Feb 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$77,201.00

COE Rebate Amount: \$36,337.00

Total Rebate Amount: \$40,458.00

The information contained herein is correct as at 12 Jun 2019

OK

> Back to OneMotoring

Singapore

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8202Z

Vehicle Details

Vehicle No.: SKM4165H
Vehicle to be Exported: No
Intended Deregistration Date: 07 Jun 2019
Vehicle Make: CITROEN
Vehicle Model: C3 1.4 EGS SMT ABS D/AB 2WS 5DR
Primary Colour: Black
Manufacturing Year: 2013
Engine No.: 10FGAS1707601
Chassis No.: VF7SC8FP0DA503351
Maximum Power Output: 70.0 kW (93 bhp)
Open Market Value: \$15,888.00
Original Registration Date: 27 Feb 2014
First Registration Date: 27 Feb 2014
Transfer Count: 0
Actual ARF Paid: \$5,888.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Feb 2024
PARF Rebate Amount: \$4,121.00

Intended COE Rebate Details

COE Expiry Date: 26 Feb 2024
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$77,201.00
COE Rebate Amount: \$36,448.00
Total Rebate Amount: \$40,569.00

The information contained herein is correct as at 07 Jun 2019

OK

1	FRONT WINDSCREEN SEALANT	11	1	S	120.00	X
2	FRONT BONNET INNER TRIM CLIPS	11	10	S	100.00	X
3	FRONT BUMPER STICKER (WEBSITE)	11	1	S	500.00	150
4	FRONT BUMPER STICKER (CITROEN)	11	1	S	400.00	80
5	FRONT BUMPER STICKER (LOWER)	11	1	S	400.00	X
6	FRONT CARPLATE	11	1	S	120.00	X
7	FRONT FENDER COWLING CLIPS	11	10	S	100.00	X
				SPECIAL NETT TOTAL		S 1,740.00
LABOUR			QTY	PRICE		
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	200	1	S	2,400.00	
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	400	1	S	2,400.00	
3	TO RUST PROOF ACCIDENT AFFECTED AREA	11	1	S	250.00	X
4	TO RNR REAR WINDSCREEN	11	1	S	400.00	X
5	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	11	1	S	400.00	X
6	TO RNR UNDERCARRAIGE SYSTEM	11	1	S	250.00	X
7	TO CHECK WHEEL ALIGNMENT	11	1	S	200.00	X
8	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	11	1	S	120.00	X
9	TO RNR TYRE AND WHEEL BALANCING	11	1	S	200.00	X
10	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11	1	S	120.00	X
11	TO DO WATER LEAK TEST .	11	1	S	80.00	X
				TOTAL		S 6,820.00
				GRAND TOTAL COST		S 17,719.39

PAGE 2 OF 2

I, the undersigned, hereby notify
 the Insurer of the following:
 • To rectify the above spray painting
 • To replace damaged part(s) during resurvey
 • To rectify the above defect to confirmation
 • To rectify the above defect on a "Without Prejudice" basis
 • To rectify the above defect to approval
 • To rectify the above defect to approval and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

P-1466.80
 10%
 P-1320.12
 S.N 230.00
 Labor - 600.00
 2150.12
 202
 1720.09



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA19010422/Usd3n2

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

MAPLETREE ANSON

SINGAPORE 079914

Date : 25-06-2019



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBL 2268U	Veh. Inspected	SKM 4165H
Policy No.	AVFMSB0000591803	Coverage (\$)	0.00
Claim No.	NSV1900285/BT	Excess (\$)	0.00
Assign From	HEW LEE FONG	Assign Date	11/06/2019

2. Vehicle Particulars & Condition

Make & Model	CITROEN C3 (A)	c.c	1397
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF7SC8FP0DA503351	Colour	BLACK
Odometer	103934	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	6 mm
L/H Front Tyre	205/55 R16	MICHELIN	6 mm
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/06/2019	Inspection Date	12/06/2019
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 4165H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	280.40	-
1	BONNET	NOT NECESSARY	1,460.50	-
1	BONNET LOCK	NOT NECESSARY	314.50	-
1	BONNET CATCH (NPA)	NOT NECESSARY	-	-
1	BONNET INNER TRIM (NPA)	NOT NECESSARY	-	-
2	BONNET HINGE (L+R)	NOT NECESSARY	220.60	-
2	BONNET STOPPER (L+R) (NPA)	NOT NECESSARY	-	-
1	BONNET RUBBER STRIP (NPA)	NOT NECESSARY	-	-
2	HEADLAMP (L+R)	NOT NECESSARY	3,520.80	-
2	HEADLAMP BRACKET (L+R)	NOT NECESSARY	140.60	-
1	FRONT BUMPER	DEEP CUT	2,345.60	1,325.00
2	FRONT BUMPER RETAINER (L+R)	N/S BENT	113.60	56.80
1	FRONT BUMPER LOGO (CITROEN)	NECESSARY	85.00	85.00
2	FRONT BUMPER FOG LAMP (L+R) (NPA)	NOT NECESSARY	-	-
2	FRONT BUMPER FOG LAMP BRACKET (L+R) (NPA)	NOT NECESSARY	-	-
1	FRONT CENTER GRILLE	NOT NECESSARY	398.00	-
1	FRONT CENTER GRILLE FRAME CHROME (NPA)	NOT NECESSARY	-	-
1	FRONT CENTER GRILLE GARNISH	NOT NECESSARY	521.00	-
1	FRONT CENTER GRILLE GARNISH NOZZLE CAP (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER REINFORCEMENT BAR	NOT NECESSARY	478.00	-
1	FRONT BUMPER REINFORCEMENT ABSORBER	NOT NECESSARY	298.50	-
1	FRONT BUMPER BEAM (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER SPONGE (NPA)	NOT NECESSARY	-	-
2	FRONT BUMPER BRACKET (L+R)(NPA)	NOT NECESSARY	-	-
2	FRONT FENDER (L+R)(NPA)	TO REPAIR SEE LABOUR	-	-
2	FRONT FENDER COWLING (L+R)(NPA)	NOT NECESSARY	-	-
1	FRONT SUPPORT PANEL (NPA)	NOT NECESSARY	-	-
1	FRONT SUPPORT PANEL TOP GARNISH (NPA)	NOT NECESSARY	-	-
2	FRONT ABSORBER (L+R)(NPA)	NOT NECESSARY	-	-
2	FRONT LOWER ARM (L+R)(NPA)	NOT NECESSARY	-	-
2	FRONT KNUCKLE (L+R)(NPA)	NOT NECESSARY	-	-
2	FRONT KNUCKLE BEARING (L+R)(NPA)	NOT NECESSARY	-	-
2	FRONT BEARING HUB (L+R)(NPA)	NOT NECESSARY	-	-

Report Ref No. CS/AWA19010422/Usd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT CROSSMEMBER (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-1,017.71	-146.68
			9,159.39	1,320.12
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	120.00	-
10	FRONT BONNET INNER TRIM CLIPS (SN)	NOT NECESSARY	100.00	-
1	FRONT BUMPER STICKER (WEBSITE)(SN)	NECESSARY	500.00	150.00
1	FRONT BUMPER STICKER (CITRIEN)(SN)	NECESSARY	400.00	80.00
1	FRONT BUMPER STICKER (LOWER)(SN)	NOT NECESSARY	400.00	-
1	FRONT CARPLATE (SN)	NOT NECESSARY	120.00	-
10	FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	100.00	-
			1,740.00	230.00
	<u>LABOUR</u>			
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD,KNOCK & REALIGN.INCLUSIVE OF THE REPAIR OF FRONT FENDER (L+R).		2,400.00	200.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		2,400.00	400.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.	NOT NECESSARY	250.00	-
	TO RNR REAR WINDSCREEN.	NOT NECESSARY	400.00	-
	TO RNR UPHOLSTERY,GARNISH AND ATTACHMENT PARTS.	NOT NECESSARY	400.00	-
	TO RNR UNDERCARRIAGE SYSTEM.	NOT NECESSARY	250.00	-
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	200.00	-
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS.	NOT NECESSARY	120.00	-
	TO RNR TYRE AND WHEEL BALANCING.	NOT NECESSARY	200.00	-
	TO DO DIAGNOSIS AND RESET,REPROGRAM OR CODING FAULT CODE.	NOT NECESSARY	120.00	-
	TO DO WATER LEAK TEST.	NOT NECESSARY	80.00	-
			6,820.00	600.00
	GRAND TOTAL		17,719.39	2,150.12
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00

Report Ref No. CS/AWA19010422/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.