


Thiam Heng Huat

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA VELLFIRE
 Engine/Chassis No.: AGH300019520
 Date of accident:
 Damaged area: Front

Date: 06/08/2019
 Claim Type: TP
 VRN: SLV3345C



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front grille	1	\$ 674.00	\$ 674.00
2	Front grille chrome moulding	1	\$ 498.00	\$ 498.00
3	Front grille base	1	\$ 175.00	\$ 175.00
4	Front grille top moulding	1	\$ 195.00	\$ 195.00
5	Front grille lower moulding	1	\$ 215.00	\$ 215.00
6	Front bumper	1	\$ 1,657.00	\$ 1,657.00
7	Front bumper top grille	1	\$ 169.00	\$ 169.00
8	Front bumper top grille moulding	1	\$ 161.00	\$ 161.00
9	Front bumper lower grille	1	\$ 221.00	\$ 221.00
10	Front bumper lower lip	1	\$ 847.00	\$ 847.00
11	Front fog lamp n/s	1	\$ 425.00	\$ 425.00
12	Front fog lamp chrome garnish n/s	1	\$ 349.00	\$ 349.00
13	Front fog lamp grille n/s	1	\$ 258.00	\$ 258.00
14	Headlamp n/s	1	\$ 3,073.00	\$ 3,073.00
15	Headlamp outer garnish n/s	1	\$ 437.00	\$ 437.00
16	Front bumper reinforcement	1	\$ 583.00	\$ 583.00
17	Front grille bracket	1	\$ 76.00	\$ 76.00
18	Front bumper side retainer	2	\$ 141.00	\$ 282.00
19	Front bumper lower lip chrome moulding	1	\$ 576.00	\$ 576.00
20	Front bumper impact absorber	1	\$ 275.00	\$ 275.00
Subtotal				\$ 11,146.00
List discount				25.00%
Total				\$ 8,359.50

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front grille clip	4	\$ 6.50	\$ 26.00
2	Front bumper clip	10	\$ 6.50	\$ 65.00
3	Front bumper top grille clip	4	\$ 6.50	\$ 26.00
4	Front bumper lower grille clip	4	\$ 6.50	\$ 26.00
5	Front bumper distance sensors	2	\$ 295.00	\$ 590.00
6	Front bumper distance sensors holder	2	\$ 63.00	\$ 126.00
7	Front licence plate & frame	1	\$ 65.00	\$ 65.00
8	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 974.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	Supply spray paint material and necessary items to respray front bumper, top grille, n/s front fender and other affected area / panel.	5	\$ 1,000.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,150.00

Estimate Grand Total	\$ 11,483.50
-----------------------------	---------------------