

**CROWN ASIA BUS BUILDER PTE. LTD.** (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667

Tel: (65) 6469 3319, Fax: (65) 6902 6758

GST ID No : 201023449R

**Repair Estimate****No. : QT-000048**

FWD SINGAPORE PTE. LTD.

C/O LKK AUTO CONSULTANTS PTE LTD  
6 TEMASEK BOULEVARD,  
#18-01 SUNTEC TOWER FOUR,  
SINGAPORE 038986

TEL :

FAX :

Your Ref. :

Our D/O No. :

Terms : C.O.D.

Date : 13-06-2019

Page : 1 of 2

Item	Tax Code	Description	Qty	UOM	U/ Price S\$	Disc. S\$	Total S\$
OS		THIRD PARTY CLAIM - REPAIR ESTIMATE FOR PC760J Traffic accident on 10/06/2019 involving PC 760 J and SGL 3412 D at junction of Yishun Ave 1 & Yishun st 41					
<b>Parts Required:</b>							
1.	OS	REAR CENTRE BUMPER ASSY BUC✓	1.00		2,900.00	1500✓	2,900.00
2.	OS	REAR CENTRE BUMPER STRUCTURAL FRAME ASSY	1.00	BT✓	1,200.00	1000✓	1,200.00
3.	OS	REAR RIGHT CORNER BUMPER ASSY BUC✓	1.00		1,400.00	1100✓	1,400.00
4.	OS	REAR RIGHT CORNER BUMPER STRUCTURAL FRAME ASSY	1.00	BT✓	900.00	700✓	900.00
5.	OS	REAR ENGINE COMPARTMENT DOOR ASSY BUC✓	1.00		2,700.00	2300✓	2,700.00
6.	OS	REAR RIGHT TAIL LAMP CRA✓	1.00		960.00	750✓	960.00
7.	OS	REAR RIGHT AIRCON COMPARTMENT DOOR BUC✓	1.00		1,700.00	1500✓	1,700.00
8.	OS	REAR COMPARTMENT DOOR RUBBER STOPPER BT✓	1.00		25.00		25.00
		SubTotal					11,785.00
9.	OS	LESS: 10% TRADE DISCOUNT	1.00		-1,178.50		-1,178.50
<b>Nett Items:</b>							
10.	OS	REAR STICKER "60KM/H" WCC✓	1.00		15.00		15.00
11.	OS	REAR NUMBER PLATE CRA✓	1.00		50.00	30✓	50.00
12.	OS	REAR REVERSE SENSOR started✓	3.00	245	80.00	200✓	240.00
<b>Labour Charge:</b>							
13.	OS	LABOUR CHARGES - TO KNOCK AND REPAIR ALL NECESSARY PARTS INCLUDING CHANGING OF ALL DAMAGED PARTS	1.00		3,200.00	1800	3,200.00
14.	OS	LABOUR CHARGES TO PUTTY AND SPRAY PAINTING FOR REAR BUMPER, REAR STRUCTURE ASSY AND REAR RIGHT LID COVER (THREE COLOUR)	1.00		2,450.00	2000	2,450.00





# CROWN ASIA BUS BUILDER PTE. LTD. (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667

Tel: (65) 6469 3319, Fax: (65) 6902 6758

GST ID No : 201023449R

## Repair Estimate

No. : QT-000048

FWD SINGAPORE PTE. LTD.

C/O LKK AUTO CONSULTANTS PTE LTD  
6 TEMASEK BOULEVARD,  
#18-01 SUNTEC TOWER FOUR,  
SINGAPORE 038986

TEL :

FAX :

Your Ref. :

Our D/O No. :

Terms : C.O.D.

Date : 13-06-2019

Page : 2 of 2

Item	Tax Code	Description	Qty	UOM	U/ Price	Disc.	Total
					S\$		S\$

NOTE: THIS ESTIMATE IS BASED ON VISIBLE DAMAGE ONLY. SHOULD ANY HIDDEN PARTS AND/OR LABOUR CHARGES REQUIRED DURING WORKS IN PROGRESS, IT WILL BE NOTIFIED ACCORDINGLY.

PRICE QUOTED IS SUBJECT TO 7% GST.

15.	OS	LABOUR CHARGES TO REPLACE, CHECK THE WIRING OF SENSOR, REAR TAILLAMP AND OTHER ELECTRICAL RELATED ITEMS	1.00		220.00		80 220.00
-----	----	--	------	--	--------	--	-----------

P- 7965  
N- 245  
L- 3880  
12,090  
L/S- 9672  
= 9650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

SINGAPORE DOLLAR SIXTEEN THOUSAND SEVEN HUNDRED EIGHTY ONE AND CENTS FIFTY ONLY

Sub Total (Excluding GST) 16,781.50

GST payable @ 7% on 0.00 0.00

Total (Inclusive of GST) 16,781.50

### Notes :

1. All cheques should be crossed and made payable to CROWN ASIA BUS BUILDER PTE. LTD.
2. Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

### GST Summary

Amount(S\$) Tax(S\$)

Huee Jie - LKK  
13/6/19  
L/S 12 days

Authorised Signature