

| Qty | Parts Description/ Labour                          | Type | Unit Price | Amount        |
|-----|----------------------------------------------------|------|------------|---------------|
|     | Front Bumper Cover <i>distorted / windy broken</i> |      | \$         | 1,052.20 ✓    |
|     | Front Bumper Grille (RH) NH                        |      | \$         | 93.60 X       |
|     | Front Bumper Grille Airduct (RH) NH                |      | \$         | 26.20 X       |
|     | Front Bumper Bracket Top (RH) NH                   |      | \$         | 22.40 X       |
|     | Front Bumper Bracket (RH) SVC                      |      | \$         | 24.60 X       |
|     | Headlamp Support Panel Assy CRACK                  |      | \$         | 907.40 ✓      |
|     | Headlamp (RH) <i>windy crack</i>                   |      | \$         | 1,388.00 ✓    |
|     | Front Fender (RH) Dentin                           |      | \$         | 663.00 ✓      |
|     | Front Fender Shield (RH) SVC                       |      | \$         | 174.90 X      |
|     | Front Fender Retainer NH                           |      | \$         | 24.60 X       |
|     | Front Door Glass (RH) Scratched                    |      | \$         | 228.20 ✓      |
|     | Front Door Outer Moulding (RH) cut                 |      | \$         | 47.10 ✓       |
|     | Front Door Mirror Assy (RH) broken                 |      | \$         | 670.00 ✓      |
|     | Front Wheel Rim (RH) <i>distorted</i>              |      | \$         | 325.30 Z ✓    |
|     | Front Wheel Hub Cap (RH) cut   W                   |      | \$         | 107.10 ✓      |
|     | Front Wheel Bearing <i>Z Dam</i>                   |      | \$         | 540.50 Z ✓    |
|     | Front Shock Absorber (Assy) (RH) <i>distorted</i>  |      | \$         | 342.20 Z ✓    |
|     | Front Shock Absorber Mounting (RH) NH              |      | \$         | 108.80 X      |
|     | Front Drive Shaft (RH) <i>Dam</i>                  |      | \$         | 1,030.80 X ✓  |
|     | Rack & Pinion Assy <i>Dam</i>                      |      | \$         | 1,191.30 X ✓  |
|     | STG Tie End <i>distorted</i>                       |      | \$         | 62.60 Z ✓     |
|     | Stabilizer Bar <i>distorted</i>                    |      | \$         | 252.30 Z ✓    |
|     | Stabilizer Bar Bush (RH) NH                        |      | \$         | 16.40 X       |
|     | Stabilizer Bar Link <i>distorted</i>               |      | \$         | 61.10 Z ✓     |
|     | Stabilizer Bracket NH                              |      | \$         | 24.00 X       |
|     | Front Suspension Lower Arm (RH) <i>distorted</i>   |      | \$         | 529.30 Z ✓    |
|     | Knuckle Arm (RH) <i>distorted</i>                  |      | \$         | 552.00 Z ✓    |
|     | Engine Under Cover NH                              |      | \$         | 334.60 X      |
|     | Engine Crossmember NH                              |      | \$         | 2,094.40 X    |
|     | ABS Sensor (RH) NH                                 |      | \$         | 234.00 X      |
|     | SUB TOTAL                                          |      | \$         | 13,128.90     |
|     | LESS 20%                                           |      | \$         | 2,625.78      |
|     | DISCOUNTED TOTAL                                   |      | \$         | 10,503.12     |
|     | Front Door Comfort Logo (RH) <i>Nuc</i>            |      | \$         | 75.00 Nett ✓  |
|     | Front Tyre (RH) SVC                                |      | \$         | 216.00 Nett X |
|     |                                                    |      | \$         | 291.00        |

SHC 8428L

| Qty | Parts Description/ Labour                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | Type | Unit Price | Amount            |
|-----|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------|-------------------|
|     | <b>Labour Charge</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |      |            |                   |
|     | Panel Beating                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |      |            | \$ 1,600.00 600/- |
|     | Spray Painting Charge                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |      |            | \$ 200.00 600/-   |
|     | Wiring Charge                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |      |            | \$ 50.00 30/-     |
|     | Tuff Kote                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |      |            | \$ 50.00 40/-     |
|     | Towing Charge                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |      |            | \$ 50.00 40/-     |
|     | Remove/Refix Undercarriage (FRT)                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |      |            | \$ 200.00 150/-   |
|     | FRT Wheel Alignment                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |      |            | \$ 120.00 60/-    |
|     | Remove/Refix Aircon & Refill Gas                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |      |            | \$ 150.00 40/-    |
|     | Re-set Frt ABS System                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |      |            | \$ 200.00 3150/-  |
|     | Diagnostic & Resetting To Erase Fault Code                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |      |            | \$ 480.00         |
|     | <b>TOTAL LABOUR</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |      |            | \$ 3,800.00       |
|     | <b>ESTIMATE TOTAL</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |      |            | \$ 14,594.12      |
|     | <p>12/06/2019 @ 1015m</p> <p>N/A Antimal</p> <p>2/5m 6 days</p> <p>ryan</p> <p>2kk Auto</p>                                                                                                                                                                                                                                                                                                                                                                                                   |      |            |                   |
|     | <p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> |      |            |                   |
|     | This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.                                                                                                                                                                                                                                                                                                                                                                   |      |            |                   |