

INS. CASE OWNER:

Loh Ah Heng CC 4, MG 190 10442, Kfa3

LKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

24/6/2019

Date / Time:

11-6-19

Registered in Merimen:

12-6-19

Pre-assign / CCU / FTE



Insured Vehicle No.:

Soy 3292A

Name of Insured:

Neo Chee Keng

Insured Tel No.:

HP:

Excess Sec II : S\$

D.O.A.:

21/6/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SMF 1526H



INSRS:

WSP:

Tel:

Liability:

RMKS:

Esteem Pmc



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SMF 1526H. X ; soy 3292A. X
+ pending video. a video uploaded.
File pass to mk to close.24/6/2019
Kenneth

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: WhatsApp e-mail only

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: P11 S\$ 2,364.20 (4 days) Reduction: 73%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27

Repair Cost: (w/GST) S\$ 2,529.69

Loss of Rental (LOR): S\$ 420 (5 days) x \$84

Loss of Use (LOU): S\$ - (\$ - x - days)

Loss of Income (LOI): S\$ - (\$ - x - days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S\$ 7.45

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost S\$ -

Total: S\$ 2,957.14 Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: S\$ 2,957.14

Payee 2:

ESTEEM PERFORMANCE PTELTO

Payee 3: (Strike if N/A) S\$ -

Payee 4:

Payee 5: (Strike if N/A) S\$ -

Payee 6:

If NO or B 28 Ass. Lia: (01 REAR END TP)

COPY SENT
24/6/2019

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320

ASS. REC. BY:

REF: 1161

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.8.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMF 15264 Regn: 10, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Honda Civic cc 1496

Colour: M. Green A/C: Insured / Std / NI / NA

Sp. Reading: 63919 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GBT 1075520

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 5 mm

L/Bal: 6 mm L/Bal: 5 mm

D.O.A. 2/6/19 D.O.I. 24/6/19

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

(PIP \$ 2,864.20 / Red \$ 6,284.20 / 73%)

4 days + 1 PPS = 5 days

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$

Fuel

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I. (\$ _____)



**ESTEE
PERFORMANCE**

ESTEE PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/252, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempart.com.sg

Repair Estimates

SMF 1526 H

Finalised

ts (a) Cost / List Price Items	\$ 1486.50	6,460.50
Plus/Less 20%	\$ 287.30	1,292.10
Total of Cost / List	\$ 1184.20	5,168.40
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	250.00
il Parts Cost	\$	5,418.40
sur	\$ 1255.40	3,230.00
I	\$ 2144.20	8,648.40

\$ 2364.20

above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

CKK

Survey conducted on

24/6/19

at

Remarks By Surveyor

) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

) Recommended Days of Repair : 04 day(s)

) Resurvey : Required / Not Required

) Excess : \$

) Signature of surveyor

Re

Date: 24/6/19

Not authorized
Resurvey B4 paint



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569535.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SMF 1526 H

HONDA FREED
GB71075520

Submit By :
Year Manufacture :
Engine No. :
Cost / List

Carmen Lim
2018

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	X
2	Rear bumper	1	\$955.00		X
3	Rear bumper clip	10	\$35.00		X
4	Rear bumper side retainer LH	1	\$34.90		X
5	Rear bumper side retainer RH	1	\$34.90		X
6	Rear bumper beam centre	1	\$105.00		X
7	Rear bumper reflector LH	1	\$42.80		X
8	Rear bumper reflector RH	1	\$42.80		X
9	Rear windscreen moulding	1	\$125.00		✓
10	Rear windscreen sealant	1	\$50.00	S.N	For S.N
11	Tail door	1	\$1,193.00		✓
12	Tail door lock	1	\$189.50		X
13	Tail door emblem	1	\$38.50		✓
14	Wording "FREED"	1	\$55.00		✓
15	Wording "HYBRID"	1	\$75.00		✓
16	Tail door trim	1	\$288.00		X
17	Tail door trim clip	8	\$36.00		X
18	Tail door reflector LH	1	\$360.00		X
19	Tail door reflector RH	1	\$360.00		X
20	Tail lamp LH	1	\$580.00		X
21	Tail lamp RH	1	\$580.00		X
22	Tail door chrome	1	\$320.40		X
23	Tail end panel	1	\$653.70		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / UST No. 20-0005485-N

1486.50

Spare Parts

Vehicle No. : SMF 1526 H
Make & Model : HONDA FREED
Chassis No. : GB71075520

Submit By : Carmen Lim
Year Manufacture : 2018
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish <i>SL</i>	1	\$115.00		<i>X</i>
25	Tail end panel garnish clip <i>NR</i>	8	\$28.00		<i>X</i>
26	Boot weatherstrip <i>SL</i>	1	\$168.00		<i>X</i>
27	Rear number plate <i>SL</i>	1	\$45.00		<i>X</i>
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 6033 Ang Mo Kio, Ind Park 2 #01-251/259, 668536.
Tel: +65-6484 1221 Fax: +65-6484 7879 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SMF 1526 H**
Make & Model : **HONDA FREED**

Submit By : **Carmen Lim**
Year of Manufacture : **2018**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (TAILDOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (TAILDOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	440
3	To check wiring	\$50.00	15
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	X
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$150.00	⑦ 300
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMF 1526 H

Parts	(a) Cost / List Price Items	\$	6,460.50
	Plus/Less 20%	\$	1,292.10
	Total of Cost / List	\$	5,168.40
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	250.00
Total Parts Cost		\$	5,418.40
Labour		\$	3,230.00
Total		\$	8,648.40

The above total will be subjected to 7% G.S.T.

Not Not have
Resurvey B4 paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after repair/painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Written Procedure' basis
- No illegal modification is allowed
- Supplementary work must be submitted and is subject to prior approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 24/6/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 24/6/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperv.com.sg

Spare Parts

Vehicle No. : **SMF 1526 H**
Make & Model : **HONDA FREED**
Chassis No. : **GB71075520**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	?
2	Rear bumper	1	\$955.00		?
3	Rear bumper clip	10	\$35.00		?
4	Rear bumper side retainer LH	1	\$34.90		X
5	Rear bumper side retainer RH	1	\$34.90		X
6	Rear bumper beam centre	1	\$105.00		?
7	Rear bumper reflector LH	1	\$42.80		X
8	Rear bumper reflector RH	1	\$42.80		X
9	Rear windscreen moulding	1	\$125.00		✓
10	Rear windscreen sealant	1	\$50.00	S.N	4012
11	Tail door	1	\$1,193.00		✓
12	Tail door lock	1	\$189.50		?
13	Tail door emblem	1	\$38.50		✓
14	Wording "FREED"	1	\$55.00		✓
15	Wording "HYBRID"	1	\$75.00		✓
16	Tail door trim	1	\$288.00		X
17	Tail door trim clip	8	\$36.00		X
18	Tail door reflector LH	1	\$360.00		X
19	Tail door reflector RH	1	\$360.00		X
20	Tail lamp LH	1	\$580.00		X
21	Tail lamp RH	1	\$580.00		X
22	Tail door chrome	1	\$320.40		X
23	Tail end panel	1	\$653.70		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SMF 1526 H**

Make & Model : **HONDA FREED**

Chassis No : **GB71075520**

Submit By : **Carmen Lim**

Year Manufacture : **2018**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish	1	\$115.00		?
25	Tail end panel garnish clip	8	\$28.00		?
26	Boot weatherstrip	1	\$168.00		X
27	Rear number plate	1	\$45.00		X
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SMF 1526 H** Submit By : **Carmen Lim**
Make & Model : **HONDA FREED** Year of Manufacture : **2018**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (TAILDOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (TAILDOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	440
3	To check wiring	\$50.00	15
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$150.00	?
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

PRE-REPAIR INSPECTION REQUEST – SMF1526H vs SDY3292A (OJ) on D.O.A.: 02/06/2019

From: Hor, Yinnul
To: 'assigments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaut, Baljit, Abu Kassim, Noor Mariess, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithosingh, Aashweenjeetkaur, Suhrmanam, Divyashni, Tor
Sent: 6/11/2019 4:42:23 PM
Attachments: 201906111601073772.pdf

Hi,

Please refer to the enclosed request from Esteem Performance Pte Ltd.

Claim no : 6334259778SG003
Case Owner : Loh Chee Heng

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
Claim Adjuster II, Singapore FNOI, Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

12.36pm 12/6/19
Carmen
VNI

From: Carmen Lim [mailto:carmen@esteemperf.com.sg]
Sent: Tuesday, June 11, 2019 4:09 PM
To: AIG SGP, Claims-Survey
Cc: Jenny chong; serence etc
Subject: [EXTERNAL] REQUEST FOR PRI SURVEY SMF1526H

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)

We act for Esteem Leasing Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no.SMF 1526 H.

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : 385, Sin Ming Drive (Inside Vicom) S 575718

Tel : 8799 0066
Fax : 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

We will email GIA report once receive from MARS.

We are prefer **LKK Auto Consultants Pte Ltd- KENNETH** to survey the car.

Freundliche Grüsse / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066
P: 6484 1221
E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259 (Head Office)

385 Sin Ming Drive Vicom Inspection Centre (Showroom)

www.esteemperformance.com



Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 14 January 2020 9:53 AM
To: Carmen Lim
Cc: Admin A
Subject: DV - SMF1526H (TP-AIG)
Attachments: AIG DV.pdf

Without Prejudice

Dear Sir/Madam,

We refer to the above matter and your e-mail below.

We confirm settlement as per your LOD on this matter.

We attach herewith a copy of the DV for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Wishing you a Happy and Prosperous Lunar New Year"



Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carmen Lim <carmen@esteemperf.com.sg>

Sent: Monday, 14 October 2019 6:58 PM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; coleen kwok <coleen21@esteemperf.com.sg>; serence etc <serence@esteemperf.com.sg>; jenny chong <jenny@esteemperf.com.sg>

Subject: LOD SMF1526H (TP-AIG)

Dear Khanchna,

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2019 Edit Reg		11 Jun 2019 00:00 Edit Adj Rpt	S\$2,364.20 Edit Estimates	S\$2,364.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: NEO CHEE KIONG , ID: S6928309H									
Main Claimant: ESTEEM LEASING PTE LTD , Co. Reg. No.: 201807215D									
Vehicle Reg. No.: SMF1526H		Date of Loss: 02/06/2019 13:00 - :59 [127 Months and 4 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6334259778SG		Policy/Cover Note No.: 2100439511 (Comprehensive)							
Vehicle Reg. No. (Insured): SDY3292A		Policy No. (Claimant): 5101728862							
Excess:									
Repairer: Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel: 64841221									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/06/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (26/06/2019): Re: Request for OI GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMF1526H (6334259778SG)
[SDY3292A]
TP
ESTEEM LEASING PTE LTD
Jun 2 2019 1:00PM
[NEO CHEE KIONG]
Esteem Performance Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Video					1 per page	☒
No	Finalized On			Thumbnail	Print	
1	18/10/19 16:59	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Video - Other		Load MP4	
2	18/10/19 16:59	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Video - Accident		Load MP4	

Letters/Correspondences					1 per page	☒
No	Finalized On			Thumbnail	Print	
1	(Draft)	LKK Auto Consultants Pte Ltd (HQ)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images					3 per page	☒
No	Relabel/Reorder			Thumbnail	Print	
1	17/02/20 10:09	LKK Auto Consultants Pte Ltd (HQ)	General View		Load JPG	☒
2	17/02/20 10:09	LKK Auto Consultants Pte Ltd (HQ)	General View		Load JPG	☒
3	17/02/20 10:09	LKK Auto Consultants Pte Ltd (HQ)	General View		Load JPG	☒
4	17/02/20 10:09	LKK Auto Consultants Pte Ltd (HQ)	General View		Load JPG	☒
5	17/02/20 10:09	LKK Auto Consultants Pte Ltd (HQ)	General View		Load JPG	☒
6	17/02/20 10:09	LKK Auto Consultants Pte Ltd (HQ)	General View		Load JPG	☒
7	17/02/20 10:09	LKK Auto Consultants Pte Ltd (HQ)	General View		Load JPG	☒
8	17/02/20 10:09	LKK Auto Consultants Pte Ltd (HQ)	General View		Load JPG	☒
9	17/02/20 10:09	LKK Auto Consultants Pte Ltd (HQ)	General View		Load JPG	☒
10	17/02/20 10:09	LKK Auto Consultants Pte Ltd (HQ)	General View		Load JPG	☒

Documentation					1 per page	☒
No	Relabel/Reorder			Thumbnail	Print	
1	12/06/19 20:27	LKK Auto Consultants Pte Ltd (HQ)	EMAIL FROM AIG DD 11.06.2019		Load PDF	
2	12/06/19 20:27	LKK Auto Consultants Pte Ltd (HQ)	ACKNOWLEDGEMENT EMAIL TO AIG DD 12.06.2019		Load PDF	
3	12/06/19 20:27	LKK Auto Consultants Pte Ltd (HQ)	TP ESTIMATE + TP GIA REPORT		Load PDF	
4	26/06/19 10:36	LKK Auto Consultants Pte Ltd (HQ)	TP ESTIMATE - MARKED		Load PDF	
5	05/12/19 11:24	LKK Auto Consultants Pte Ltd (HQ)	EMAIL TO OI		Load PDF	
6	18/02/20 11:13	LKK Auto Consultants Pte Ltd (HQ)	WORKSHOP INVOICE		Load PDF	
7	18/02/20 11:13	LKK Auto Consultants Pte Ltd (HQ)	AUTHORISATION TO ACT FORM		Load PDF	
8	18/02/20 11:13	LKK Auto Consultants Pte Ltd (HQ)	Release Voucher		Load PDF	
9	18/02/20 11:13	LKK Auto Consultants Pte Ltd (HQ)	RENTAL RECEIPT		Load PDF	
10	18/02/20 11:13	LKK Auto Consultants Pte Ltd (HQ)	LTA SEARCH		Load PDF	
11	18/02/20 11:13	LKK Auto Consultants Pte Ltd (HQ)	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	13/06/19 10:18	AIG Asia Pacific Insurance Pte. Ltd. (SG)	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SDY3292A (Insd veh)	Model:	HONDA FREED HYBRID 1.5
	SMF1526H (TP veh)		G (A)
Date of Accident:	02/06/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,253.79
Final Repair Cost	:	\$	2,529.69
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	420.00 5 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,957.14

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Esteem Performance Pte Ltd	:	\$ 2,957.14
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

18 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19010442/KKA3Q2

Date: 18/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100439511
Claimant
Vehicle No : SMF1526H **Insured Vehicle No :** SDY3292A
Date of Loss: 02/06/2019 **Nature of Claim:** TP **Claim No:** 6334259778SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMF1526H
 Make & Model: HONDA FREED HYBRID, 1.5 G (A) Engine No: LEB5610727
 Reg. Date: 29/10/2008 (Man. Year: 2008) Chassis No: GB71075520
 Colour: Metallic Green Odometer: 63919 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,418.40	1,229.20	4,189.20	77.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,135.00	2,095.00	64.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,648.40	2,364.20	6,284.20	72.66
+ GST 7.00/7.00% (S\$)	605.39	165.49	439.90	72.66
Nett Amount (S\$)	9,253.79	2,529.69	6,724.10	72.66
+ Car Rental (5.0 x S\$84.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,957.14		

INSPECTION

Date of Assignment: 11/06/2019
 Date Inspected: 24/06/2019 Inspected At: ESTEEM PERFORMANCE PTE LTD
 BLK 5033
 ANG MO KIO INDUSTRIAL PARK 2
 #01-259
 SINGAPORE 569536
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS
2	1		*REAR BUMPER	Serviceable	955.00 FL	*- FL
3	10		*REAR BUMPER CLIP	Not Necessary	35.00 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	34.90 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	34.90 FL	*- FL
6	1		*REAR BUMPER BEAM CENTRE	Serviceable	105.00 FL	*- FL
7	1		*REAR BUMPER REFLECTOR LH	Serviceable	42.80 FL	*- FL
8	1		*REAR BUMPER REFLECTOR RH	Serviceable	42.80 FL	*- FL
9	1		*REAR WINDSCREEN MOULDING	Necessary	125.00 FL	*125.00 FL
10	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
11	1		*TAIL DOOR	Bent	1,193.00 FL	*1,193.00 FL
12	1		*TAIL DOOR LOCK	Repair	189.50 FL	*- FL
13	1		*TAIL DOOR EMBLEM	Necessary	38.50 FL	*38.50 FL
14	1		*WORDING FREED	Necessary	55.00 FL	*55.00 FL
15	1		*WORDING HYBRID	Necessary	75.00 FL	*75.00 FL
16	1		*TAIL DOOR TRIM	Serviceable	288.00 FL	*- FL
17	8		*TAIL DOOR TRIM CLIP	Not Necessary	36.00 FL	*- FL
18	1		*TAIL DOOR REFLECTOR LH	Serviceable	360.00 FL	*- FL
19	1		*TAIL DOOR REFLECTOR RH	Serviceable	360.00 FL	*- FL
20	1		*TAIL LAMP LH	Serviceable	580.00 FL	*- FL
21	1		*TAIL LAMP RH	Serviceable	580.00 FL	*- FL
22	1		*TAIL DOOR CHROME	Serviceable	320.40 FL	*- FL
23	1		*TAIL END PANEL	Repair	653.70 FL	*- FL
24	1		*TAIL END PANEL GARNISH	Serviceable	115.00 FL	*- FL
25	8		*TAIL END PANEL GARNISH CLIP	Not Necessary	28.00 FL	*- FL
26	1		*BOOT WEATHERSTRIP	Serviceable	168.00 FL	*- FL
27	1		*REAR NUMBER PLATE	Serviceable	45.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,710.50	1,526.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,292.10	297.30
Total Parts (\$\$)	5,418.40	1,229.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (TAILDOOR ,REAR BUMPER ,END PANEL,SPARE TYRE WELL PANEL)	New	1,200.00	400.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (TAILDOOR ,REAR BUMPER ,END PANEL,SPARE TYRE WELL PANEL)	New	1,200.00	440.00
3	TO CHECK WIRING	New	50.00	15.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
5	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	0.00
6	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
7	TO TUFF COAT	New	150.00	30.00
8	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	60.00
9	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	20.00
Gross Labour Cost (S\$)			3,230.00	1,135.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >