

Ace Auto Solution
Registration number : 53228991M
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 11/6/2019

Reference: SLX7962J
OPEL INSIGNIA
Make: GRANDSPORT
B15XHT

7PA19
Vic

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLX7962J
CHASSIS NO.:W0VZT6EB9J1071744
ENGINE NO.:B1172908HAKX0246

Name of insured :Sheng Li Ching
Date of accident.: 04/08/2013

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Bootlid weatherstrip <i>fit</i>	\$ 190.00
2	1	Bootlid latch <i>for new</i>	\$ 152.00
3	1	Bootlid striker	\$ 53.00
4	1	Rear Bumper Upper <i>Rehd</i>	\$ 1,588.00
5	1	Rear Bumper Lower Moulding <i>Rehd</i>	\$ 450.00
6	1	Rear Bumper Towing Cover <i>new</i>	\$ 102.00
7	1	Rear Bumper LH Reflector <i>Rehd</i>	\$ 54.00
8	1	Rear Bumper RH Reflector <i>Rehd</i>	\$ 54.00
9	2	Number plate lamp <i>Rehd</i>	\$ 62.00
10	1	LHR Taillamp <i>for</i>	\$ 793.00
11	1	RHR Taillamp <i>for</i>	\$ 793.00
12	1	LHR Bumper Bracket, Guide <i>for</i>	\$ 90.00
13	1	RHR Bumper Bracket, Guide	\$ 90.00
14	1	LHR Bumper bracket <i>for</i>	\$ 55.00
15	1	RHR Bumper bracket	\$ 55.00
16	1	Rear Centre Bumper bracket <i>Rehd</i>	\$ 65.00
17	1	Reverse sensor wire harness <i>for new</i>	\$ 450.00

<u>18</u>	1	Rh Rear Bumper Absorber <i>3 new</i>	\$ 69.00	+
<u>19</u>	1	Lh Rear Bumper Absorber <i>new</i>	\$ 69.00	+
<u>20</u>	1	Rear Bumper Reinforcement Bar <i>Best</i>	\$ 670.00	✓
<u>21</u>	1	Rear end panel <i>Repairs</i>	\$ 545.00	+
<u>22</u>	1	Rear end panel trim <i>He m</i>	\$ 280.00	+
<u>23</u>	1	LHR Bumper Air Ventilator <i>3 new</i>	\$ 80.00	+
<u>24</u>	1	RHR Bumper Air Ventilator	\$ 80.00	+
<u>25</u>	1	LHR Bumper Blind Spot Active Sensor Module <i>could</i>	\$ 724.00	✓
<u>26</u>	1	RHR Bumper Blind Spot Active Sensor Module <i>could</i>	\$ 724.00	✓

4871

4383.50

Parts Total: \$ 8,337.00

Less 10%: \$ 833.70

Total: \$ 7,503.30

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>	
Rear portion			
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 per day)	\$ 1,000.00	500
<u>2</u>	Carry out spray painting on accident affected area (\$200 per panel)	\$ 800.00	400
<u>3</u>	To conduct anti rust of under carriage tuff coat	\$ 120.00	x
<u>4</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
<u>5</u>	To remove and refix reverse sensor and conduct test	\$ 80.00	50
<u>6</u>	To remove and refix reverse camera and conduct test	\$ 80.00	50

1030

Labour Total: \$ 2,110.00

Others

<u>No.</u>	<u>Qty</u>	<u>Other Description</u>	<u>Price (SGD)</u>	
Rear portion				
1	1	Rear number plate <i>could</i>	\$ 45.00	✓
2	10	Rear bumper clip <i>new</i>	\$ 65.00	30
3	6	Rear Fender Liner Clip <i>3 new</i>	\$ 39.00	+
4	5	Rear end panel trim clip <i>3 new</i>	\$ 32.50	+
5	1	Reverse sensor (4pcs) <i>2 new</i>	\$ 320.00	200
6	1	Reverse camera <i>2 new</i>	\$ 480.00	380

7	1	Rear end panel insulation seal <i>the new</i>	\$ 80.00
---	---	---	----------

655 Other Total: \$ 1,061.50

GRAND TOTAL: \$ 10,674.80

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully




Service Advisor

Suhaimi

HP : 9189 2617 Email - aceautosolution@gmail.com

*Adrian Lim
P/P 11/06/15*

APPROVER DETAILS

SURVEYOR : _____

CONTACT NO : _____

PART BY PART / LUMP SUM

04 Days

total: 6068.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

To pass Admin for final check

Ace Auto Solution

Registration number : 53228991M

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

INVOICE

To : AIG Asia Pacific Insurance Pte. Ltd
78 SHENTON WAY
#07-16
SINGAPORE 079120

Invoice No: ACC-2015001
Invoice Date:

Vehicle No: SLX7962J
Chasis No : W0VZT6EB9J1071744
Engine No: B1172908HAKX0246

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.		Price (SGD)
<u>1</u>	1	Bootlid weatherstrip	\$ 190.00
<u>2</u>	1	Rear Bumper Upper	\$ 1,588.00
<u>3</u>	1	Rear Bumper Lower Moulding	\$ 450.00
<u>4</u>	1	Rear Bumper LH Reflector	\$ 54.00
<u>5</u>	1	Rear Bumper RH Reflector	\$ 54.00
<u>6</u>	2	Number plate lamp	\$ 62.00
<u>7</u>	1	LHR Bumper Bracket, Guide	\$ 90.00
<u>8</u>	1	RHR Bumper Bracket, Guide	\$ 90.00
<u>9</u>	1	LHR Bumper bracket	\$ 55.00
<u>10</u>	1	RHR Bumper bracket	\$ 55.00
<u>11</u>	1	Rear Centre Bumper bracket	\$ 65.00
<u>12</u>	1	Rear Bumper Reinforcement Bar	\$ 670.00
<u>13</u>	1	LHR Bumper Blind Spot Active Sensor Module	\$ 724.00
<u>14</u>	1	RHR Bumper Blind Spot Active Sensor Module	\$ 724.00

Total: \$ 4,871.00
Less 10%: \$ 487.10
Parts Total : \$ 4,383.90

Labour

No.		Price (SGD)
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 per day)	\$ 500.00
<u>2</u>	Carry out spray painting on accident affected area (\$200 per panel)	\$ 400.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>4</u>	To remove and refix reverse sensor and conduct test	\$ 50.00
<u>5</u>	To remove and refix reverse camera and conduct test	\$ 50.00

Labour Total : \$ 1,030.00

Other

<u>No.</u>			<u>Price (SGD)</u>
1	1	Rear number plate	\$ 45.00
2	10	Rear bumper clip	\$ 30.00
3	1	Reverse sensor (4pcs)	\$ 200.00
4	1	Reverse camera	\$ 380.00

Other Total : \$ 655.00

Total : \$ 6,068.90

Grand Total: \$ 6,068.90

Yours Faithfully


Suhaimi

Service Executive

Tel: 9189 2617 Fax:6844 5185

Email : aceautosolution@gmail.com

E & O E

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "**ACE AUTO SOLUTION**".

PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice