

AXA / Kenneth 13/6



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SDS 84 K

Parts	(a) Cost / List Price Items	\$	4,053.15
	Plus/Less 10%	\$	405.32
	Total of Cost / List	\$	3,647.84
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	3,692.84
Labour		\$	2,520.00
Total		\$	6,212.84

The above total will be subjected to 7% G.S.T.

Not Authorized

Resurvey After Paint
11 Sep 87

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 13/6/18 at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : Date: 13/6/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SDS 84 K**
Make & Model : **VOLKSWAGEN GOLF A7**
Chassis No : **WVWZZZAUZEW059331**

Submit By : **SERENCE**
Year Manufacture : **2013**
Engine No. : **CHP009895**
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sn</i>	4	\$855.40		X
2	Rear number plate <i>Ref</i>	1	\$45.00	S.N	✓
3	Rear bumper <i>Bur / Ref</i>	1	\$1,056.55		✓
4	Rear bumper clip <i>Sn</i>	10	\$30.00		✓
5	Rear bumper side retainer LH <i>Sn</i>	1	\$48.15		X
6	Rear bumper side retainer RH <i>Sn</i>	1	\$48.15		X
7	Rear bumper reinforcement	1	\$555.95		?
8	Rear bumper reflector LH <i>Sn</i>	1	\$66.55		X
9	Rear bumper reflector RH <i>Sn</i>	1	\$66.55		X
10	Rear bumper tow cover <i>Sn</i>	1	\$23.65		X
11	Tail end panel <i>Ref</i>	1	\$793.75		X
12	Tail end panel garnish <i>Sn</i>	1	\$161.05		X
13	Tail end panel garnish clip <i>Sn</i>	4	\$10.00		X
14	Boot weatherstrip <i>Sn</i>	1	\$337.40		X
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.