

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 3320L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEAD LAMP LH (CONSISTENT)	CRACKED	980.00	786.00
1	SET HEAD LAMP RH (CONSISTENT)	NECESSARY	20.00	20.00
1	FRONT DOOR LH (CONSISTENT)	DISTORTED	1,415.00	1,415.00
1	FRONT DOOR UPPER HINGE LH (CONSISTENT)	NOT NECESSARY	48.00	-
1	FRONT DOOR LOWER HINGE LH (CONSISTENT)	BENT	39.00	39.00
1	FRONT STEP LH (CONSISTENT)	DEFORMED	165.00	165.00
1	FRONT BUMPER (CONSISTENT)	DISTORTED	681.80	681.80
2	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	NECESSARY	430.00	65.00
1	SET FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	50.00	30.00
1	FRONT BUMPER FOG COVER LH (CONSISTENT)	DEFORMED	242.80	48.00
1	FRONT BUMPER TOP REINFORCEMENT (CONSISTENT)	BENT	342.70	342.70
1	SUPPORT PANEL (CONSISTENT)	NOT NECESSARY	482.80	-
1	BRACE PANEL (CONSISTENT)	NOT NECESSARY	89.00	-
	LESS 25% DISCOUNT		-1,246.53	-898.13
			3,739.57	2,694.37
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE WITH COVER (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	RADIATOR COOLANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
			220.00	-
	<u>LABOUR</u>			
	TO KNOCK,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA.		1,400.00	400.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		1,200.00	600.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.	NOT NECESSARY	120.00	-
	TO R&R AIR CON AND RADIATOR.	NOT NECESSARY	350.00	-
			3,070.00	1,000.00
	GRAND TOTAL		7,029.57	3,694.37

RECOMMENDED COST OF LUMP SUM REPAIRS		2,900.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM19010449/Aga3q2





Report Ref No. CC4/ASM19010449/Aga3q2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.