

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 8 Raffles Quay #18-00 Singapore 048520
 Tel (65) 6224 9018 Fax (65) 6224 0010
 Operating Hours: Monday to Friday, 09:00 - 17:00
 65th 360000206 / 671 Bug No. 3600017723

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MPA 119 06968 Vehicle Registration No: 982 7730 A
 Name (as shown in NRIC): Runi Jus Asia Pacific Ins Ltd NRIC/FIN/Passport No: 199501508k
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: 15 International Business Park Gateway Centre #01-22/25 Singapore (609916)
 Contact (Tel): 65628412 Mobile No.: 97525455
 Email Address: sewingap@singnet.sg
 Date of Accident: 28/5/2019 Time of Accident: 11:50 AM
 Place of Accident: Along Bukit Batok East Ave 2
 Insurance Company: AGI Asia Pacific Insurance Pte Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To Comment on Damage Recovery



Policyholder / Driver's Signature
 Date:



Reporting Centre Personnel's Signature
 Name: Victor Wong
 NRIC/FIN No.: 68468405L
 Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0695/2019/DY/TF
Date : 30-May-19

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no. : **SJZ 7730 A**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Reint Jes Asia Pacific Pte Ltd
Address : 25 International Business Park
German Centre
#01-22/25
Singapore 609916
Telephone : (Office) +65 628812
(HP) 97525655 (Driver. Dr Chen)
Type of Claim : Own Damage Claims
Policy No. : 2100441060-03
Vehicle No : **SJZ 7730 A**
Model Code : Audi A6 2.0 TFSI S tronic
Model / Year : Dec-15
Engine No : CYP 005790
Chassis No : WAUZZZ4G5GN074971
Mileage : 49834
Date In : 28-May-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-May-19
Place of Accident : Along Bukit Batok East Ave 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJZ 7730 A

<u>S/N</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To tow and recover vehicle from scene of accident.	S/N WAIVED /	
2	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 <i>all ✓</i>	
3	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00 <i>7Xm</i>	
4	To dismantle and renew front bumper, bonnet, rhs front fender and both headlights. Cut out and reweld rhs fender support, closing element. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 9,600.00 <i>1750</i>	
5	To respray front bumper, rhs front fender, bonnet, rhs upper A-pillar, hinges, rhs fender top support and rhs front door. To carry out joint sealant work and stone chip treatment.	\$ 6,200.00 <i>1650</i>	
SUB-TOTAL LABOUR CHARGES		: \$ 17,680.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax**Estimated Labour Charges for Accident Vehicle. SJZ 7730 A**

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
6	To renew rhs front rim and carry out wheel alignment. Inspect for front suspension damages.	S/N \$	280.00	✓
7	To carry out diagnostic check.	S/N \$	384.00	✓
TOTAL LABOUR CHARGES		:	<u><u>\$ 18,344.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 7730 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,549.00	de ✓
2	FRONT BUMPER CENTER LOWER GRILLE	\$ 598.00	de ✓
3	FRONT BUMPER LOCKING CLIP	\$ 65.00	? m ✓
4	FRONT BUMPER CHROME TRIM	\$ 276.00	? m ✓
5	FRONT BUMPER FIXING PARTS	\$ 45.00	? m ✓
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	\$ 199.00	de X m
7	FRONT BUMPER SPOILER	\$ 227.00	X m
8	RADIATOR GRILLE	\$ 1,766.00	car ✓
9	RADIATOR GRILLE CAMERA COVER	\$ 53.00	m ✓
10	RADIATOR GRILLE LOGO REAR COVER	\$ 33.00	? dis ✓
11	RADIATOR GRILLE CAMERA BRACKET	\$ 84.00	? x m
12	RADIATOR GRILLE CAMERA SECURING PLATE	\$ 76.00	? x m
13	RADIATOR GRILLE CAMERA	\$ 902.00	x m
14	RADIATOR GRILLE SENSOR SUPPORT	2 \$ 122.00	acc ✓
15	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	319 \$ 638.00	LH X, RH m ✓
16	FRONT BUMPER AIR GRILLE REAR COVER - LH / RH	46 \$ 92.00	LH X, RH m ✓
17	FRONT WHEEL SPOILER - RH	\$ 242.00	de ✓
18	FRONT HEADLIGHT WASHER COVER - LH / RH	52 \$ 104.00	LH X, RH m ✓
19	FRONT REINFORCEMENT BAR	\$ 754.00	X m
20	FOAM FILLER PIECE	\$ 215.00	X m
SUB-TOTAL SPARE PARTS		\$ 9,040.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 7730 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT BUMPER TOP COVER	\$ 112.00	de✓
22	FRONT BUMPER HOLDER BRACKET - RH	\$ 237.00	Xnn
23	FRONT BUMPER BRACE - RH	\$ 27.00	bt✓
24	FRONT BUMPER GUIDE PIECE - RH	\$ 34.00	over✓
25	A/C STICKER	\$ 18.00	nee✓
26	CAUTION STICKER	\$ 13.00	nee✓
27	FRONT FENDER - RH	\$ 1,269.00	bt✓
28	FRONT FENDER ATTACHMENT PARTS - RH	\$ 92.00	Xnn
29	FRONT FENDER STONE GUARD FILM - RH	\$ 110.00	nee✓
30	FRONT FENDER BRACE - RH	\$ 75.00	?bt✓
31	FRONT WHEEL HOUSING LINER - RH	\$ 256.00	de✓
32	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 66.00	nee✓
33	FRONT WHEEL HOUSING LINER STONE CHIP GUARD	\$ 66.00	?de✓
34	ADHESIVE TAPE	\$ 50.00	Xnn
35	FRONT FENDER BRACKET - RH	\$ 15.00	?bt✓
36	BONNET	\$ 4,965.00	bt✓
37	BONNET ATTACHMENT PARTS	\$ 161.00	Xnn
38	BONNET HINGE - LH / RH	\$ 292.00	Xnn
39	BONNET LOCK BAR	2 \$ 90.00	Xnn
40	BONNET CATCH - TOP	\$ 127.00	Xnn
SUB-TOTAL SPARE PARTS		\$ 8,075.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 7730 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	BONNET ABSORBER	2 \$ 217.00	X
42	BONNET CATCH - LOWER	\$ 16.00	X
43	BONNET CATCH COVER	\$ 3.00	X
44	BONNET LOCK	2 \$ LH X 391.00	RH - X 195.50
45	BONNET LOCK SWITCH	2 \$ LH X 133.00	? RH X 66.50
46	BONNET LOCK SWITCH CONNETOR	2 \$ LH X 18.00	RH - X 9.00
47	BONNET BOWDEN CABLE	\$ 53.00	X
48	BONNET BOWDEN CABLE COVER	\$ 9.00	X
49	BONNET LOCK CABLE	\$ 67.00	X
50	HEADLIGHT MOUNTING - LH / RH	\$ 214.00	LH X RH - ?
51	LED HEADLIGHT - LH / RH	2 \$ 22,640.00	LH X RH - ?
52	HEADLIGHT POWER MODULE - MATRIX LIGHTS	\$ 1,726.00	X
53	HEADLIGHT POWER MODULE - DAY DRIVING LIGHTS	\$ 520.00	X
54	HEADLIGHT FAN - RH	\$ 363.00	X
55	HEADLIGHT POWER MODULE - DIPPED BEAM	\$ 508.00	X
56	HEADLIGHT LIFT CYLINDER - RH	\$ 216.00	one
57	HEADLIGHT LIFT CYLINDER HOSE	\$ 413.00	dis
58	HEADLIGHT HOSE JOINT	\$ 35.00	dis
59	FRONT BUMPER SENSOR - INNER	2 \$ 462.00	X
60	FRONT BUMPER SENSOR - SIDE	\$ 231.00	X
SUB-TOTAL SPARE PARTS		: \$ 28,235.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 7730 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	FRONT BUMPER SENSOR SEAL	\$ 5.00	OK
62	FRONT BUMPER WIRING SET	\$ 532.00	X
63	HORN - HIGH TONE	\$ 215.00	X
64	HORN BRACKET - RH	\$ 43.00	X
65	FRONT FENDER CLOSING ELEMENT	\$ 136.00	X
66	FRONT FENDER CONNECTING PLATE	\$ 683.00	X
67	FRONT FENDER NOISE INSULATION	\$ 30.00	X
68	FRONT FENDER RIVET	\$ 12.00	OK
69	LOCK CARRIER	\$ 1,140.00	X
70	A/C CONDENSER	\$ 689.00	X
71	A/C REFRIGERANT HOSE	2 \$ 468.00	X
72	RADIATOR	\$ 775.00	X
73	COOLANT	\$ 84.00	X
74	INTERCOOLER	\$ 1,220.00	X
75	PRESSURE HOSE	\$ 413.00	X
76	RADIATOR TWIN FAN RING	\$ 237.00	X
77	RADIATOR FAN	2 \$ 1,511.00	X
78	RADIATOR AIR GUIDE - LH / RH	\$ 50.00	X
79	RADIATOR COVER - UPPER	\$ 27.00	X
80	RADIATOR COVER SEALING STRIP	\$ 21.00	X
SUB-TOTAL SPARE PARTS		\$ 8,291.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 7730 A

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
81	INTAKE AIR DUCT AIR GUIDE - RH	\$ 24.00	X3 NN
82	INTAKE AIR DUCT - RH	\$ 79.00	X3
83	AIR FILTER	\$ 266.00	XNN
84	INTAKE AIR DUCT HOSE	\$ 150.00	XNN
85	FRONT RIM - RH	\$ 1,162.00	oil
86	FRONT TYRE - RH	PRICE TBC	XNN
87	RUBBER VALVE	\$ 13.00	new
88	ACRYLIC SEALANT	S/N \$ 180.00	X } paint
89	CRAVITY WAX	S/N \$ 140.00	X }
90	STONE CHIP TREATMENT	S/N \$ 180.00	X }
91	FRONT NO. PLATE	S/N \$ 40.00	new
92	SUNDRIES	\$ 400.00	7.100 new
TOTAL SPARE PARTS		:	\$ 56,275.00
TOTAL LABOUR CHARGES		:	\$ 18,344.00
GRAND TOTAL		:	\$ 74,619.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Tan Kah 97495749
12/6/11 @ 545pm
Not Authorise, Revert.
Resurvey before paint.
Exp! to be advise.
08 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SJZ 7730 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0695/2019/NH

21st JAN 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SJZ 7730 A, Audi A6 2.0 TFSI S TRONIC.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SJZ 7730 A**, claimant, **Reint Jes Asia Pacific Pte Ltd**, please find the related document per attached.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

1. A copy of the Original invoice no. 85014764 – S\$ 18,618.00.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SJZ 7730 A

Premium Automobiles Pte Ltd



Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service

Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:54

Company Reg.No.199902271W

GST Reg.No.199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014764 Date : 20/01/2020 Order: SJZ7730A Term : 30	Account : A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	---

Regn No: SJZ7730A (V 27872)

Regn Date: 21/12/2015

Mileage: 54257

WIP No : 54894

Model : A6 2.0 TFSI S tronic

Chassis: WAUZZZ4G5GN074971

Engine: CYP 005790

DEPT : U

You have been assisted by: UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
S	SUBLET	To carry out contractual LUMP SUM repair basis as agreed	20,000.00	1.00	20,000.00
Q	EXC	Insurance Excess/Liability	2600.00	1.00	2600.00

Parts 0.00
Labour 0.00
Sublet 20,000.00
Menus 0.00
Lubricant 0.00

Sub- Total 17,400.00

7% GST 1,218.00

Grand Total 18,618.00



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SJZ 7730 A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0695/2019/KK
27 June 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 2.0 TFSI S TRONIC
Vehicle Chassis No. : WAUZZZ4G5GN074971
Vehicle Regn No. : **SJZ 7730 A**
Vehicle Mileage : 49835 KM
Vehicle Owner : Reint Jes Asia Pacific Pte Ltd
Certificate No : 2100441060-03
Own Damage Excess : \$2,782.00 (Incl. 7% GST)
Accident Date : 28 May 2019
Place : Along Bukit Batok East Ave 2
Repair Cost : \$ 18,618.00
WIP No. : 54894
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.



Owner / Insured Signature : _____
Time : _____
Date : _____ 28/6

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt.	Adj. Submitted	Ins. Auth'd	Status
Main	31 May 2019		13 Jun 2019 12:03 Edit Adj Rpt	S\$20,000.00 Edit Estimates	S\$20,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	REINT JES ASIA PACIFIC PTE LTD, Co. Reg. No.: 199301508K, Tel: +6597525655		
Vehicle Reg. No.:	SJZ7730A	Date of Loss:	28/05/2019 11:00 - :59 [41 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 2509809313SG	Policy/Cover Note No.:	2100441060 (Comprehensive)
		Excess:	S\$2,600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Yap, Weijoe] Weijoe.Yap@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/06/2019]		
Driver/Custodian:	CHEN WEI NGIAP (54 / Male) , NRIC: S1687307A, Tel: +6597525655 Email: SCWNGIAP@SINGNET.COM.SG		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (14/06/2019): Alert - Adj Mandate Approved (S\$20000.00) - SJZ7730A - Claim Handler: Yap, Weijo...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	13/06/19 14:02	General View	 Load JPG	☒
35	13/06/19 14:02	General View	 Load JPG	☒
36	13/06/19 14:02	General View	 Load JPG	☒
37	13/06/19 14:02	General View	 Load JPG	☒
38	13/06/19 14:02	General View	 Load JPG	☒
39	13/06/19 14:02	General View	 Load JPG	☒
40	13/06/19 14:02	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/19 14:01	Certificate of Insurance, driving license and nirc	 Load PDF	
2	13/06/19 14:01	ESTIMATE	 Load PDF	
3	13/06/19 14:01	Singapore Accident Statement	 Load PDF	
4	13/06/19 16:04	Log card (if available)	 Load PDF	
5	13/06/19 16:04	SG CAR MART	 Load PDF	
6	05/02/20 09:42	DISCHARGE VOUCHER	 Load PDF	
7	05/02/20 09:42	WORKSHOP INVOICE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print		
1	11/06/19 13:27	Addendum Sheet	 Load JPG	☒		
2	04/09/19 01:11	Accident Statement	 Load HTM			
3	04/09/19 01:26	Accident Statement	 Load HTM			
Photos/Images			3 per page	☒		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print		
1	28/05/19 18:45	Accident Photo	 Load JPG	☒		
2	28/05/19 18:45	Accident Photo	 Load JPG	☒		
3	28/05/19 18:45	Accident Photo	 Load JPG	☒		
4	28/05/19 18:45	Accident Photo	 Load JPG	☒		
5	28/05/19 18:45	Accident Photo	 Load JPG	☒		
6	28/05/19 18:45	Accident Photo	 Load JPG	☒		
7	28/05/19 18:45	Accident Photo	 Load JPG	☒		
8	28/05/19 18:45	Accident Photo	 Load JPG	☒		
9	28/05/19 18:45	Accident Photo	 Load JPG	☒		
10	28/05/19 18:45	Accident Photo	 Load JPG	☒		
11	28/05/19 18:45	Accident Photo	 Load JPG	☒		
12	28/05/19 18:45	Accident Photo	 Load JPG	☒		
13	28/05/19 18:45	Accident Photo	 Load JPG	☒		
14	28/05/19 18:45	Accident Photo	 Load JPG	☒		
15	28/05/19 18:45	Accident Photo	 Load JPG	☒		
16	28/05/19 18:45	Accident Photo	 Load JPG	☒		
Documentation			1 per page	☒		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print		
1	28/05/19 18:38	Sketch Plan	 Load JPG	☒		
2	28/05/19 18:38	Sketch Plan #2	 Load JPG	☒		

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19010461/T1TD3S2

Date: 05/02/2020

REFERENCE

Insured/Claimant:	REINT JES ASIA PACIFIC PTE LTD	Policy No:	2100441060
Date of Loss:	28/05/2019	Nature of Claim:	OD Claim No: 2509809313SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ7730A	Engine No:	CYP005790
Make & Model:	AUDI A6, 2.0 TFSI (A)	Chassis No:	WAUZZZ4G5GN074971
Reg. Date:	21/12/2015 (Man. Year: 2015)	Odometer:	49834 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$104,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	56,275.00	27,117.00	29,158.00	51.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,344.00	4,544.00	13,800.00	75.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	74,619.00	31,661.00	42,958.00	57.57
Approved Total (Overridden) (S\$)		20,000.00		
- Excess (S\$)	2,600.00	2,600.00	0.00	0.00
(S\$)	72,019.00	17,400.00	54,619.00	75.84
+ GST 7.00/7.00% (S\$)	5,041.33	1,218.00	3,823.33	75.84
Nett Amount (S\$)	77,060.33	18,618.00	58,442.33	75.84

INSPECTION

Date of Assignment:	13/06/2019	
Date Inspected:	12/06/2019	Inspected At: 24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,549.00 FS	*2,549.00 FS
2	1		*FRONT BUMPER CENTER LOWER GRILLE	Deformed	598.00 FS	*598.00 FS
3	1		*FRONT BUMPER LOCKING CLIP	Necessary	65.00 FS	*65.00 FS
4	1		*FRONT BUMPER CHROME TRIM	Cracked	276.00 FS	*276.00 FS
5	1		*FRONT BUMPER FIXING PARTS	Necessary	45.00 FS	*45.00 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	199.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Not Necessary	227.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	1,766.00 FS	*1,766.00 FS
9	1		*RADIATOR GRILLE CAMERA COVER	Missing	53.00 FS	*53.00 FS
10	1		*RADIATOR GRILLE LOGO REAR COVER	Distorted	33.00 FS	*33.00 FS
11	1		*RADIATOR GRILLE CAMERA BRACKET	Not Necessary	84.00 FS	*- FS
12	1		*RADIATOR GRILLE CAMERA SECURING PLATE	Not Necessary	76.00 FS	*- FS
13	1		*RADIATOR GRILLE CAMERA	Not Necessary	902.00 FS	*- FS
14	2		*RADIATOR GRILLE SENSOR SUPPORT	Necessary	122.00 FS	*122.00 FS
15	1		*FRONT BUMPER AIR GUIDE GRILLE - LH/RH	N/s Not Necessary/O/s Missing	638.00 FS	*319.00 FS
16	1		*FRONT BUMPER AIR GRILLE REAR COVER - LH/RH	N/s Not Necessary/O/s Missing	92.00 FS	*46.00 FS
17	1		*FRONT WHEEL SPOILER - RH	Deformed	242.00 FS	*242.00 FS
18	1		*FRONT HEADLIGHT WASHER COVER - LH/RH	N/s Not Necessary/O/s Missing	104.00 FS	*52.00 FS
19	1		*FRONT REINFORCEMENT BRACKET	Not Necessary	754.00 FS	*- FS
20	1		*FOAM FILLER PIECE	Not Necessary	215.00 FS	*- FS
21	1		*FRONT BUMPER TOP COVER	Deformed	112.00 FS	*112.00 FS
22	1		*FRONT BUMPER HOLDER BRACKET - RH	Not Necessary	237.00 FS	*- FS
23	1		*FRONT BUMPER BRACE - RH	Bent	27.00 FS	*27.00 FS
24	1		*FRONT BUMPER GUIDE PIECE - RH	Cracked	34.00 FS	*34.00 FS
25	1		*A/C STICKER	Necessary	18.00 FS	*18.00 FS
26	1		*CAUTION STICKER	Necessary	13.00 FS	*13.00 FS
27	1		*FRONT FENDER - RH	Bent	1,269.00 FS	*1,269.00 FS
28	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	92.00 FS	*- FS
29	1		*FRONT FENDER STONE GUARD FILM - RH	Necessary	110.00 FS	*110.00 FS
30	1		*FRONT FENDER BRACE - RH	Bent	75.00 FS	*75.00 FS
31	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	256.00 FS	*256.00 FS
32	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	66.00 FS	*66.00 FS
33	1		*FRONT WHEEL HOUSING LINER STONE CHIP GUARD	Deformed	66.00 FS	*66.00 FS
34	1		*ADHESIVE TAPE	Not Necessary	50.00 FS	*- FS
35	1		*FRONT FENDER BRACKET - RH	Bent	15.00 FS	*15.00 FS
36	1		*BONNET	Bent	4,965.00 FS	*4,965.00 FS
37	1		*BONNET ATTACHMENT PARTS	Not Necessary	161.00 FS	*- FS
38	1		*BONNET HINGE - LH/RH	Not Necessary	292.00 FS	*- FS
39	2		*BONNET LOCK BAR	Not Necessary	90.00 FS	*- FS
40	1		*BONNET CATCH - TOP	Not Necessary	127.00 FS	*- FS
41	2		*BONNET ABSORBER	Not Necessary	217.00 FS	*- FS
42	1		*BONNET CATCH - LOWER	Not Necessary	16.00 FS	*- FS
43	1		*BONNET CATCH COVER	Not Necessary	3.00 FS	*- FS
44	1		*BONNET LOCK	N/s Not Necessary / O/s Bent	391.00 FS	*195.50 FS
45	1		*BONNET LOCK SWITCH	N/s Not Necessary / O/s Bent	133.00 FS	*66.50 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*BONNET LOCK SWITCH CONNECTOR	N/s NotNecessary/O/s Distorted	18.00 FS	*9.00 FS
47	1		*BONNET BOWDEN CABLE	Not Necessary	53.00 FS	*-FS
48	1		*BONNET BOWDEN CABLE COVER	Not Necessary	9.00 FS	*-FS
49	1		*BONNET LOCK CABLE	Not Necessary	67.00 FS	*-FS
50	1		*HEADLIGHT MOUNTING - LH/RH	N/s NotNecessary/O/s Distorted	214.00 FS	*107.00 FS
51	1		*LED HEADLIGHT - LH/RH	N/s Not Necessary/O/s Cracked	22,640.00 FS	*11,320.00 FS
52	1		*HEADLIGHT POWER MODULE - MATRIX LIGHTS	Not Necessary	1,726.00 FS	*-FS
53	1		*HEADLIGHT POWER MODULE - DAY DRIVING LIGHTS	Not Necessary	520.00 FS	*-FS
54	1		*HEADLIGHT FAN - RH	Not Necessary	363.00 FS	*-FS
55	1		*HEADLIGHT POWER MODULE - DIPPED BEAM	Not Necessary	508.00 FS	*-FS
56	1		*HEADLIGHT LIFT CYLINDER - RH	Cracked	216.00 FS	*216.00 FS
57	1		*HEADLIGHT LIFT CYLINDER HOSE	Distorted	413.00 FS	*413.00 FS
58	1		*HEADLIGHT HOSE JOINT	Distorted	35.00 FS	*35.00 FS
59	2		*FRONT BUMPER SENSOR - INNER	Not Necessary	462.00 FS	*-FS
60	1		*FRONT BUMPER SENSOR - SIDE	Not Working	231.00 FS	*231.00 FS
61	1		*FRONT BUMPER SENSOR SEAL	Necessary	5.00 FS	*5.00 FS
62	1		*SET FRONT BUMPER WIRING	Not Necessary	532.00 FS	*-FS
63	1		*HORN - HIGH TONE	Not Necessary	215.00 FS	*-FS
64	1		*HORN BRACKET - RH	Not Necessary	43.00 FS	*-FS
65	1		*FRONT FENDER CLOSING ELEMENT	Not Necessary	136.00 FS	*-FS
66	1		*FRONT FENDER CONNECTING PLATE	Not Necessary	683.00 FS	*-FS
67	1		*FRONT FENDER NOISE INSULATION	Not Necessary	30.00 FS	*-FS
68	1		*FRONT FENDER RIVET	Necessary	12.00 FS	*12.00 FS
69	1		*LOCK CARRIER	Not Necessary	1,140.00 FS	*-FS
70	1		*A/C CONDENSER	Not Necessary	689.00 FS	*-FS
71	2		*A/C REFRIGERANT HOSE	Not Necessary	468.00 FS	*-FS
72	1		*RADIATOR	Not Necessary	775.00 FS	*-FS
73	1		*COOLANT	Not Necessary	84.00 FS	*-FS
74	1		*INTERCOOLER	Not Necessary	1,220.00 FS	*-FS
75	1		*PRESSURE HOSE	Not Necessary	413.00 FS	*-FS
76	1		*RADIATOR TWIN FAN RING	Not Necessary	237.00 FS	*-FS
77	2		*RADIATOR FAN	Not Necessary	1,511.00 FS	*-FS
78	1		*RADIATOR AIR GUIDE - LH/RH	Not Necessary	50.00 FS	*-FS
79	1		*RADIATOR COVER - UPPER	Not Necessary	27.00 FS	*-FS
80	1		*RADIATOR COVER SEALING STRIP	Not Necessary	21.00 FS	*-FS
81	1		*INTAKE AIR DUCT AIR GUIDE - RH	Not Necessary	24.00 FS	*-FS
82	1		*INTAKE AIR DUCT - RH	Not Necessary	79.00 FS	*-FS
83	1		*AIR FILTER	Not Necessary	266.00 FS	*-FS
84	1		*INTAKE AIR DUCT HOSE	Not Necessary	150.00 FS	*-FS
85	1		*FRONT RIM - RH	Cut	1,162.00 FS	*1,162.00 FS
86	1		*FRONT TYRE - RH (NPA)	Not Necessary	0.00 FS	*-FS
87	1		*RUBBER VALVE	Necessary	13.00 FS	*13.00 FS
88	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*-FS
89	1		*CRAVIRY WAX	Not Necessary	140.00 FS	*-FS
90	1		*STONE CHIP TREATMENT	Not Necessary	180.00 FS	*-FS
91	1		*FRONT NO. PLATE	Necessary	40.00 FS	*40.00 FS
92	1		*SUNDRIES	Necessary	400.00 FS	*100.00 FS

F=Franchise part, S=SpcNett.

Total Parts (S\$) 56,275.00 27,117.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT. (NPA)	New	0.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS, FRONT FENDER AND BOTH HEADLIGHTS. CUT OUT AND REWELD RHS FENDER SUPPORT, CLOSING ELEMENT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED.	New	9,600.00	1,750.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS UPPER A-PILLAR, HINGES, RHS FENDER TOP SUPPORT AND RHS FRONT DOOR. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.	New	6,200.00	1,650.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT. INSPECT FOR FRONT SUSPENSION DAMAGES.	New	280.00	280.00
7	TO CARRY DIAGNOSTIC CHECK.	New	384.00	384.00
Gross Labour Cost (S\$)			18,344.00	4,544.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >