

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0695/2019/DY/TF
Date : 30-May-19

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no. : **SJZ 7730 A**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Reint Jes Asia Pacific Pte Ltd
Address : 25 International Business Park
German Centre
#01-22/25
Singapore 609916
Telephone : (Office) +65 628812
: (HP) 97525655 (Driver: Dr Chen)
Type of Claim : Own Damage Claims
Policy No. : 2100441060-03
Vehicle No : **SJZ 7730 A**
Model Code : Audi A6 2.0 TFSI S tronic
Model / Year : Dec-15
Engine No : CYP 005790
Chassis No : WAUZZZ4G5GN074971
Mileage : 49834
Date In : 28-May-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-May-19
Place of Accident : Along Bukit Batok East Ave 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax**Estimated Labour Charges for Accident Vehicle. SJZ 7730 A**

<u>S/N</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To tow and recover vehicle from scene of accident.	S/N WAIVED /	
2	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ^{nee} ✓	
3	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00 ?	
4	To dismantle and renew front bumper, bonnet, rhs front fender and both headlights. Cut out and reweld rhs fender support, closing element. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 9,600.00 ¹⁷⁵⁰	
5	To respray front bumper, rhs front fender, bonnet, rhs upper A-pillar, hinges, rhs fender top support and rhs front door. To carry out joint sealant work and stone chip treatment.	\$ 6,200.00 ¹⁶⁵⁰	
SUB-TOTAL LABOUR CHARGES		: \$ 17,680.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax**Estimated Labour Charges for Accident Vehicle. SJZ 7730 A**

S/N	Nature of Jobs	Estimated Charges	Surveyor's recommendation
6	To renew rhs front rim and carry out wheel alignment. Inspect for front suspension damages.	S/N \$ 280.00	✓
7	To carry out diagnostic check.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 18,344.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 7730 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,549.00	de ✓
2	FRONT BUMPER CENTER LOWER GRILLE	\$ 598.00	?
3	FRONT BUMPER LOCKING CLIP	\$ 65.00	?
4	FRONT BUMPER CHROME TRIM	\$ 276.00	?
5	FRONT BUMPER FIXING PARTS	\$ 45.00	?
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	\$ 199.00	de X nn
7	FRONT BUMPER SPOILER	\$ 227.00	X nn
8	RADIATOR GRILLE	\$ 1,766.00	ca ✓
9	RADIATOR GRILLE CAMERA COVER	\$ 53.00	nn ✓
10	RADIATOR GRILLE LOGO REAR COVER	\$ 33.00	?
11	RADIATOR GRILLE CAMERA BRACKET	\$ 84.00	?
12	RADIATOR GRILLE CAMERA SECURING PLATE	\$ 76.00	?
13	RADIATOR GRILLE CAMERA	\$ 902.00	X
14	RADIATOR GRILLE SENSOR SUPPORT	2 \$ 122.00	de ✓
15	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	319 \$ 638.00	LH X, RH nn ✓
16	FRONT BUMPER AIR GRILLE REAR COVER - LH / RH	46 \$ 92.00	LH X, RH nn ✓
17	FRONT WHEEL SPOILER - RH	\$ 242.00	de ✓
18	FRONT HEADLIGHT WASHER COVER - LH / RH	52 \$ 104.00	LH X, RH nn ✓
19	FRONT REINFORCEMENT BAR	\$ 754.00	X nn
20	FOAM FILLER PIECE	\$ 215.00	X nn
SUB-TOTAL SPARE PARTS		\$ 9,040.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 7730 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT BUMPER TOP COVER	\$ 112.00	de ✓
22	FRONT BUMPER HOLDER BRACKET - RH	\$ 237.00	X nn ✓
23	FRONT BUMPER BRACE - RH	\$ 27.00	bt ✓
24	FRONT BUMPER GUIDE PIECE - RH	\$ 34.00	over ✓
25	A/C STICKER	\$ 18.00	ner ✓
26	CAUTION STICKER	\$ 13.00	ner ✓
27	FRONT FENDER - RH	\$ 1,269.00	bt ✓
28	FRONT FENDER ATTACHMENT PARTS - RH	\$ 92.00	X nn ✓
29	FRONT FENDER STONE GUARD FILM - RH	\$ 110.00	ner ✓
30	FRONT FENDER BRACE - RH	\$ 75.00	?
31	FRONT WHEEL HOUSING LINER - RH	\$ 256.00	de ✓
32	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 66.00	ner ✓
33	FRONT WHEEL HOUSING LINER STONE CHIP GUARD	\$ 66.00	?
34	ADHESIVE TAPE	\$ 50.00	X nn ✓
35	FRONT FENDER BRACKET - RH	\$ 15.00	?
36	BONNET	\$ 4,965.00	bt ✓
37	BONNET ATTACHMENT PARTS	\$ 161.00	X nn ✓
38	BONNET HINGE - LH / RH	\$ 292.00	X nn ✓
39	BONNET LOCK BAR	2 \$ 90.00	?
40	BONNET CATCH - TOP	\$ 127.00	X nn ✓
SUB-TOTAL SPARE PARTS		\$ 8,075.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 7730 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	BONNET ABSORBER	2 \$ 217.00	X
42	BONNET CATCH - LOWER	\$ 16.00	X
43	BONNET CATCH COVER	\$ 3.00	X
44	BONNET LOCK	2 \$ LH X 391.00	RH-? 195.5
45	BONNET LOCK SWITCH	2 \$ LH X 133.00	? RH 66.5
46	BONNET LOCK SWITCH CONNETOR	2 \$ LH X 18.00	RH-? 9
47	BONNET BOWDEN CABLE	\$ 53.00	X
48	BONNET BOWDEN CABLE COVER	\$ 9.00	X
49	BONNET LOCK CABLE	\$ 67.00	X
50	HEADLIGHT MOUNTING - LH / RH	\$ 214.00	LH X RH-? 101
51	LED HEADLIGHT - LH / RH	2 \$ 22,640.00	LH X RH-? 11320
52	HEADLIGHT POWER MODULE - MATRIX LIGHTS	\$ 1,726.00	?
53	HEADLIGHT POWER MODULE - DAY DRIVING LIGHTS	\$ 520.00	?
54	HEADLIGHT FAN - RH	\$ 363.00	?
55	HEADLIGHT POWER MODULE - DIPPED BEAM	\$ 508.00	?
56	HEADLIGHT LIFT CYLINDER - RH	\$ 216.00	OK
57	HEADLIGHT LIFT CYLINDER HOSE	\$ 413.00	OK?
58	HEADLIGHT HOSE JOINT	\$ 35.00	?
59	FRONT BUMPER SENSOR - INNER	2 \$ 462.00	X
60	FRONT BUMPER SENSOR - SIDE	\$ 231.00	OK
SUB-TOTAL SPARE PARTS		\$ 28,235.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 7730 A

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
61	FRONT BUMPER SENSOR SEAL	\$ 5.00	ad ✓
62	FRONT BUMPER WIRING SET	\$ 532.00	?
63	HORN - HIGH TONE	\$ 215.00	X nm
64	HORN BRACKET - RH	\$ 43.00	X nm
65	FRONT FENDER CLOSING ELEMENT	\$ 136.00	?
66	FRONT FENDER CONNECTING PLATE	\$ 683.00	?
67	FRONT FENDER NOISE INSULATION	\$ 30.00	X nm
68	FRONT FENDER RIVET	\$ 12.00	ad ✓
69	LOCK CARRIER	\$ 1,140.00	?
70	A/C CONDENSER	\$ 689.00	?
71	A/C REFRIGERANT HOSE	2 \$ 468.00	?
72	RADIATOR	\$ 775.00	?
73	COOLANT	\$ 84.00	?
74	INTERCOOLER	\$ 1,220.00	?
75	PRESSURE HOSE	\$ 413.00	?
76	RADIATOR TWIN FAN RING	\$ 237.00	?
77	RADIATOR FAN	2 \$ 1,511.00	?
78	RADIATOR AIR GUIDE - LH / RH	\$ 50.00	X } nm
79	RADIATOR COVER - UPPER	\$ 27.00	X }
80	RADIATOR COVER SEALING STRIP	\$ 21.00	X }
SUB-TOTAL SPARE PARTS		\$ 8,291.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 7730 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	INTAKE AIR DUCT AIR GUIDE - RH	\$ 24.00	X? NN
82	INTAKE AIR DUCT - RH	\$ 79.00	X? NN
83	AIR FILTER	\$ 266.00	?
84	INTAKE AIR DUCT HOSE	\$ 150.00	X? NN
85	FRONT RIM - RH	\$ 1,162.00	cut
86	FRONT TYRE - RH	PRICE TBC	?
87	RUBBER VALVE	\$ 13.00	new
88	ACRYLIC SEALANT	S/N \$ 180.00	?
89	CAVITY WAX	S/N \$ 140.00	?
90	STONE CHIP TREATMENT	S/N \$ 180.00	?
91	FRONT NO. PLATE	S/N \$ 40.00	new
92	SUNDRIES	\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 56,275.00
TOTAL LABOUR CHARGES		:	\$ 18,344.00
GRAND TOTAL		:	\$ 74,619.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tan Kah 97495749
12/6/11 @ 545pm
Not Authorise, Revert.
Resurvey before paint.
Exp: to be advise
08 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 May 2019		13 Jun 2019 12:03 Edit Adj Rpt	S\$29,562.00 Edit Estimates	S\$29,562.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:	REINT JES ASIA PACIFIC PTE LTD, Co. Reg. No.: 199301508K, Tel: +6597525655		
Vehicle Reg. No.:	SJZ7730A	Date of Loss:	28/05/2019 11:00 - :59 [41 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 2509809313SG	Policy/Cover Note No.:	2100441060 (Comprehensive)
		Excess:	S\$2,600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Yap, Weijoe] Weijoe.Yap@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/06/2019]		
Driver/Custodian:	CHEN WEI NGIAP (54 / Male) , NRIC: S1687307A, Tel: +6597525655 Email: SCWNGIAP@SINGNET.COM.SG		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (14/06/2019): Alert - Adj Mandate Approved (S\$20000.00) - SJZ7730A - Claim Handler: Yap, Weijo...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJZ7730A (2509809313SG)**
OD
May 28 2019 11:00AM
[REINT JES ASIA PACIFIC PTE LTD]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/19 16:52	Adjuster Immediate Advice	 Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/19 14:02	General View	 Load JPG	☒
2	13/06/19 14:02	General View	 Load JPG	☒
3	13/06/19 14:02	General View	 Load JPG	☒
4	13/06/19 14:02	General View	 Load JPG	☒
5	13/06/19 14:02	General View	 Load JPG	☒
6	13/06/19 14:02	General View	 Load JPG	☒
7	13/06/19 14:02	General View	 Load JPG	☒
8	13/06/19 14:02	General View	 Load JPG	☒
9	13/06/19 14:02	General View	 Load JPG	☒
10	13/06/19 14:02	General View	 Load JPG	☒
11	13/06/19 14:02	General View	 Load JPG	☒
12	13/06/19 14:02	General View	 Load JPG	☒
13	13/06/19 14:02	General View	 Load JPG	☒
14	13/06/19 14:02	General View	 Load JPG	☒
15	13/06/19 14:02	General View	 Load JPG	☒
16	13/06/19 14:02	General View	 Load JPG	☒
17	13/06/19 14:02	General View	 Load JPG	☒
18	13/06/19 14:02	General View	 Load JPG	☒
19	13/06/19 14:02	General View	 Load JPG	☒
20	13/06/19 14:02	General View	 Load JPG	☒
21	13/06/19 14:02	General View	 Load JPG	☒
22	13/06/19 14:02	General View	 Load JPG	☒
23	13/06/19 14:02	General View	 Load JPG	☒
24	13/06/19 14:02	General View	 Load JPG	☒
25	13/06/19 14:02	General View	 Load JPG	☒
26	13/06/19 14:02	General View	 Load JPG	☒
27	13/06/19 14:02	General View	 Load JPG	☒
28	13/06/19 14:02	General View	 Load JPG	☒
29	13/06/19 14:02	General View	 Load JPG	☒
30	13/06/19 14:02	General View	 Load JPG	☒
31	13/06/19 14:02	General View	 Load JPG	☒
32	13/06/19 14:02	General View	 Load JPG	☒
33	13/06/19 14:02	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	13/06/19 14:02	General View	 Load JPG	☒
35	13/06/19 14:02	General View	 Load JPG	☒
36	13/06/19 14:02	General View	 Load JPG	☒
37	13/06/19 14:02	General View	 Load JPG	☒
38	13/06/19 14:02	General View	 Load JPG	☒
39	13/06/19 14:02	General View	 Load JPG	☒
40	13/06/19 14:02	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/19 14:01	Certificate of Insurance, driving license and nirc	 Load PDF	
2	13/06/19 14:01	ESTIMATE	 Load PDF	
3	13/06/19 14:01	Singapore Accident Statement	 Load PDF	
4	13/06/19 16:04	Log card (if available)	 Load PDF	
5	13/06/19 16:04	SG CAR MART	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/05/19 18:48	Accident Statement	 Load HTM	
2	11/06/19 13:27	Addendum Sheet	 Load JPG	☒
3	11/06/19 13:27	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/05/19 18:45	Accident Photo	 Load JPG	☒
2	28/05/19 18:45	Accident Photo	 Load JPG	☒
3	28/05/19 18:45	Accident Photo	 Load JPG	☒
4	28/05/19 18:45	Accident Photo	 Load JPG	☒
5	28/05/19 18:45	Accident Photo	 Load JPG	☒
6	28/05/19 18:45	Accident Photo	 Load JPG	☒
7	28/05/19 18:45	Accident Photo	 Load JPG	☒
8	28/05/19 18:45	Accident Photo	 Load JPG	☒
9	28/05/19 18:45	Accident Photo	 Load JPG	☒
10	28/05/19 18:45	Accident Photo	 Load JPG	☒
11	28/05/19 18:45	Accident Photo	 Load JPG	☒
12	28/05/19 18:45	Accident Photo	 Load JPG	☒
13	28/05/19 18:45	Accident Photo	 Load JPG	☒
14	28/05/19 18:45	Accident Photo	 Load JPG	☒
15	28/05/19 18:45	Accident Photo	 Load JPG	☒
16	28/05/19 18:45	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/05/19 18:38	Sketch Plan	 Load JPG	☒
2	28/05/19 18:38	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19010461/T1TD3S2

Date: 19/06/2019

REFERENCE

Insured/Claimant: REINT JES ASIA PACIFIC PTE LTD

Policy No: 2100441060

Date of Loss: 28/05/2019

Nature of Claim: OD

Claim No: 2509809313SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ7730A**

Make & Model: AUDI A6, 2.0 TFSI (A)

Reg. Date: 21/12/2015 (Man. Year: 2015)

Colour: Grey

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$104,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CYP005790

Chassis No: WAUZZZ4G5GN074971

Odometer: 49834 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R18

Rear Tyre Size:

245/45R18

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	56,275.00	25,018.00	31,257.00	55.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,344.00	4,544.00	13,800.00	75.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	74,619.00	29,562.00	45,057.00	60.38
+ GST 7.00/7.00% (S\$)	5,223.33	2,069.34	3,153.99	60.38
Nett Amount (S\$)	79,842.33	31,631.34	48,210.99	60.38

INSPECTION

Date of Assignment: 13/06/2019

Date Inspected: 12/06/2019

Inspected At:

24 Benoi Sector

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$104,000.00
OMV :	\$49,511.00
PARF Rebate (1) :	\$45,987.00
Quota Premium Paid :	\$58,190.00
COE Rebate (2) :	\$37,932.00
Total Rebate (1) + (2) = :	\$83,919.00

The total amount incurred will be Market Value \$104,000.00 minus Total Rebate \$83,919.00 = \$20,081.000 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,549.00 FS	*2,549.00 FS
2	1		*FRONT BUMPER CENTER LOWER GRILLE	*Check	598.00 FS	*- FS
3	1		*FRONT BUMPER LOCKING CLIP	*Check	65.00 FS	*- FS
4	1		*FRONT BUMPER CHROME TRIM	*Check	276.00 FS	*- FS
5	1		*FRONT BUMPER FIXING PARTS	*Check	45.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	199.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Not Necessary	227.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	1,766.00 FS	*1,766.00 FS
9	1		*RADIATOR GRILLE CAMERA COVER	Missing	53.00 FS	*53.00 FS
10	1		*RADIATOR GRILLE LOGO REAR COVER	*Check	33.00 FS	*- FS
11	1		*RADIATOR GRILLE CAMERA BRACKET	*Check	84.00 FS	*- FS
12	1		*RADIATOR GRILLE CAMERA SECURING PLATE	*Check	76.00 FS	*- FS
13	1		*RADIATOR GRILLE CAMERA	Not Necessary	902.00 FS	*- FS
14	2		*RADIATOR GRILLE SENSOR SUPPORT	Necessary	122.00 FS	*122.00 FS
15	1		*FRONT BUMPER AIR GUIDE GRILLE - LH/RH	N/s Not Necessary/O/s Missing	638.00 FS	*319.00 FS
16	1		*FRONT BUMPER AIR GRILLE REAR COVER - LH/RH	N/s Not Necessary/O/s Missing	92.00 FS	*46.00 FS
17	1		*FRONT WHEEL SPOILER - RH	Deformed	242.00 FS	*242.00 FS
18	1		*FRONT HEADLIGHT WASHER COVER - LH/RH	N/s Not Necessary/O/s Missing	104.00 FS	*52.00 FS
19	1		*FRONT REINFORCEMENT BRACKET	Not Necessary	754.00 FS	*- FS
20	1		*FOAM FILLER PIECE	Not Necessary	215.00 FS	*- FS
21	1		*FRONT BUMPER TOP COVER	Deformed	112.00 FS	*112.00 FS
22	1		*FRONT BUMPER HOLDER BRACKET - RH	Not Necessary	237.00 FS	*- FS
23	1		*FRONT BUMPER BRACE - RH	Bent	27.00 FS	*27.00 FS
24	1		*FRONT BUMPER GUIDE PIECE - RH	Cracked	34.00 FS	*34.00 FS
25	1		*A/C STICKER	Necessary	18.00 FS	*18.00 FS
26	1		*CAUTION STICKER	Necessary	13.00 FS	*13.00 FS
27	1		*FRONT FENDER - RH	Bent	1,269.00 FS	*1,269.00 FS
28	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	92.00 FS	*- FS
29	1		*FRONT FENDER STONE GUARD FILM - RH	Necessary	110.00 FS	*110.00 FS
30	1		*FRONT FENDER BRACE - RH	*Check	75.00 FS	*- FS
31	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	256.00 FS	*256.00 FS
32	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	66.00 FS	*66.00 FS
33	1		*FRONT WHEEL HOUSING LINER STONE CHIP GUARD	*Check	66.00 FS	*- FS
34	1		*ADHESIVE TAPE	Not Necessary	50.00 FS	*- FS
35	1		*FRONT FENDER BRACKET - RH	*Check	15.00 FS	*- FS
36	1		*BONNET	Bent	4,965.00 FS	*4,965.00 FS
37	1		*BONNET ATTACHMENT PARTS	Not Necessary	161.00 FS	*- FS
38	1		*BONNET HINGE - LH/RH	Not Necessary	292.00 FS	*- FS
39	2		*BONNET LOCK BAR	*Check	90.00 FS	*- FS
40	1		*BONNET CATCH - TOP	Not Necessary	127.00 FS	*- FS
41	2		*BONNET ABSORBER	Not Necessary	217.00 FS	*- FS
42	1		*BONNET CATCH - LOWER	Not Necessary	16.00 FS	*- FS
43	1		*BONNET CATCH COVER	Not Necessary	3.00 FS	*- FS
44	2		*BONNET LOCK	N/s Not Necessary / O/s *Check	391.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*BONNET LOCK SWITCH	N/s Not Necessary / O/s *Check	133.00 FS	*- FS
46	2		*BONNET LOCK SWITCH CONNECTOR	N/s Not Necessary / O/s *Check	18.00 FS	*- FS
47	1		*BONNET BOWDEN CABLE	Not Necessary	53.00 FS	*- FS
48	1		*BONNET BOWDEN CABLE COVER	Not Necessary	9.00 FS	*- FS
49	1		*BONNET LOCK CABLE	Not Necessary	67.00 FS	*- FS
50	1		*HEADLIGHT MOUNTING - LH/RH	N/s Not Necessary / O/s *Check	214.00 FS	*- FS
51	1		*LED HEADLIGHT - LH/RH	N/s Not Necessary / O/s Cracked	22,640.00 FS	*11,320.00 FS
52	1		*HEADLIGHT POWER MODULE - MATRIX LIGHTS	*Check	1,726.00 FS	*- FS
53	1		*HEADLIGHT POWER MODULE - DAY DRIVING LIGHTS	*Check	520.00 FS	*- FS
54	1		*HEADLIGHT FAN - RH	*Check	363.00 FS	*- FS
55	1		*HEADLIGHT POWER MODULE - DIPPED BEAM	*Check	508.00 FS	*- FS
56	1		*HEADLIGHT LIFT CYLINDER - RH	Cracked	216.00 FS	*216.00 FS
57	1		*HEADLIGHT LIFT CYLINDER HOSE	*Check	413.00 FS	*- FS
58	1		*HEADLIGHT HOSE JOINT	*Check	35.00 FS	*- FS
59	2		*FRONT BUMPER SENSOR - INNER	Not Necessary	462.00 FS	*- FS
60	1		*FRONT BUMPER SENSOR - SIDE	Not Working	231.00 FS	*231.00 FS
61	1		*FRONT BUMPER SENSOR SEAL	Necessary	5.00 FS	*5.00 FS
62	1		*SET FRONT BUMPER WIRING	*Check	532.00 FS	*- FS
63	1		*HORN - HIGH TONE	Not Necessary	215.00 FS	*- FS
64	1		*HORN BRACKET - RH	Not Necessary	43.00 FS	*- FS
65	1		*FRONT FENDER CLOSING ELEMENT	*Check	136.00 FS	*- FS
66	1		*FRONT FENDER CONNECTING PLATE	*Check	683.00 FS	*- FS
67	1		*FRONT FENDER NOISE INSULATION	Not Necessary	30.00 FS	*- FS
68	1		*FRONT FENDER RIVET	Necessary	12.00 FS	*12.00 FS
69	1		*LOCK CARRIER	*Check	1,140.00 FS	*- FS
70	1		*A/C CONDENSER	*Check	689.00 FS	*- FS
71	2		*A/C REFRIGERANT HOSE	*Check	468.00 FS	*- FS
72	1		*RADIATOR	*Check	775.00 FS	*- FS
73	1		*COOLANT	*Check	84.00 FS	*- FS
74	1		*INTERCOOLER	*Check	1,220.00 FS	*- FS
75	1		*PRESSURE HOSE	*Check	413.00 FS	*- FS
76	1		*RADIATOR TWIN FAN RING	*Check	237.00 FS	*- FS
77	2		*RADIATOR FAN	*Check	1,511.00 FS	*- FS
78	1		*RADIATOR AIR GUIDE - LH/RH	Not Necessary	50.00 FS	*- FS
79	1		*RADIATOR COVER - UPPER	Not Necessary	27.00 FS	*- FS
80	1		*RADIATOR COVER SEALING STRIP	Not Necessary	21.00 FS	*- FS
81	1		*INTAKE AIR DUCT AIR GUIDE - RH	Not Necessary	24.00 FS	*- FS
82	1		*INTAKE AIR DUCT - RH	Not Necessary	79.00 FS	*- FS
83	1		*AIR FILTER	*Check	266.00 FS	*- FS
84	1		*INTAKE AIR DUCT HOSE	Not Necessary	150.00 FS	*- FS
85	1		*FRONT RIM - RH	Cut	1,162.00 FS	*1,162.00 FS
86	1		*FRONT TYRE - RH (NPA)	*Check	0.00 FS	*- FS
87	1		*RUBBER VALVE	Necessary	13.00 FS	*13.00 FS
88	1		*ACRYLIC SEALANT	*Check	180.00 FS	*- FS
89	1		*CRAVIRY WAX	*Check	140.00 FS	*- FS
90	1		*STONE CHIP TREATMENT	*Check	180.00 FS	*- FS
91	1		*FRONT NO. PLATE	Necessary	40.00 FS	*40.00 FS
92	1		*SUNDRIES	*Check	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 56,275.00 25,018.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT. (NPA)	New	0.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. (*Check)	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS, FRONT FENDER AND BOTH HEADLIGHTS. CUT OUT AND REWELD RHS FENDER SUPPORT, CLOSING ELEMENT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED.	New	9,600.00	1,750.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS UPPER A-PILLAR, HINGES, RHS FENDER TOP SUPPORT AND RHS FRONT DOOR. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.	New	6,200.00	1,650.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT. INSPECT FOR FRONT SUSPENSION DAMAGES.	New	280.00	280.00
7	TO CARRY DIAGNOSTIC CHECK.	New	384.00	384.00
Gross Labour Cost (S\$)			18,344.00	4,544.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >