

22/02/2019

ASS. REC. BY:

REF: CS/C12 19010463/kt+d3

112

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of C11 Date/Time: 13/6/19 @ 11am

Estimated Cost: Bill to:

CD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJF 7011Y Insured: SKQ 89982

at Workshop in/s Kang Auto Tel: 6556 0103

of 160 Sin Ming Drive #02-16

Policy No: DM HCSN1816 201800

Claim No: SNM 190 202567 (02)

Sum Insured: Excess:

Make of Veh: D.O.A. 9/6/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 11.17am @ 13/6/19 Person Contacted: May Vehicle ☒ IN / OUT

Date/Time Action/Instruction

SJF 7011Y - NA / INC 10012059 / r DOA - 12/06/2010

SKQ 89982 - X

2d6 L1 Sy 8235d Cabin (Red: 1793.121 43%)

ASS. REC. BY:

REF:

CT1

ASSIGNMENT

From:

Date:

13/6/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJF 70114

at Workshop in/s

Gartines Key Ave

of

160 Sin Ming Drive # 02-04

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Date:

6/23

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJF 70114

Regn:

06, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

A1

C.C.

133P

Colour:

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

141856

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GEB 1076235

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

9/6/19

D.O.I.

13/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Area N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 21 JUN 2019

Date/Time, File Pass to?

1) 21/6 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L&L: C

TP

23501

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invt (\$)



Week-end (\$)

Survey Fee:

Transportation:

3 + RS. \$

Photos:

Others:

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2019		13 Jun 2019 11:05 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	ONG GUANG ZHENG, ID: S83345481		
Main Claimant:	SJF7011Y		
Vehicle Reg. No.:	TP / SNM19D202567C02	Date of Loss:	09/06/2019 19:00 - :59
Claim Type:	SKQ8998Z	Policy/Cover Note No.:	DMHCSN1816201800
Vehicle Reg. No. (Insured):		Policy No. (Claimant):	5103352455
		Excess:	S\$0.00
Repairer:	Kang Auto Engineering Pte Ltd () 160 Sin Ming Drive, #02-16, Sin Ming AutoCity, 575722 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Thursday, 13 June 2019 11:00 AM
To: kangauto@singnet.com.sg; assignments@lkkauto.com
Subject: RE: Resent - Pre Repair Inspection - SJF7011Y

WITHOUT PREJUDICE

Dear May,

We refer to your email of 13.06.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: kangauto@singnet.com.sg [mailto:kangauto@singnet.com.sg]
Sent: Thursday, 13 June, 2019 10:40 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: Resent - Pre Repair Inspection - SJF7011Y

Tan,
Please assign kenneth Kong (LKK Auto)
Car Is in.

Regards
May Ang

On Thu Jun 13 2019 09:00:32 GMT+0800 (Singapore Standard Time) Tan Kah Leong
<KahLeong.Tan@sg.cntaiping.com> wrote:
----- Original Message -----

Without Prejudice

Dear Sirs,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING

LOW SAR HUEI

SEE CHEW SENG

MOHD FADHILAH BIN OSMAN

XING QUO QIANG

KENNETH KONG

HONG FOOK CHOY

CHUA WEIJIE

MARCUS CHUA

HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From:

Claims Dept of CTI

Sent: Wednesday, 12 June, 2019 4:18 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; kangauto@singnet.com.sg

Cc: Angie Foo <angie.foo@sg.cntaiping.com>

Subject: FW: Resent - Pre Repair Inspection - SJF7011Y

Dear Kah Leong,

Please conduct PRS – TP: SJF7011Y (SNM19D202567) soonest possible.
File with OIC – Kah Leong - 63896193

From:

kangauto@singnet.com.sg [mailto:kangauto@singnet.com.sg]

Sent: Wednesday, 12 June 2019 4:04 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Resent - Pre Repair Inspection - SJF7011Y

Motor Claims Dept

Accident involving SJF7011Y & SKQ8998Z on 09/06/2019 along Yishun Street 22.

Please find attached relevant Document from my client for your retention.

Please assign your surveyor to survey Vehicle SJF7011Y.

Please revert Claim Handler in-Charge.

Yours Sincerely,

May Ang

Kang Auto Engineering Pte Ltd

Tel: 6556 0103


On Tue Jun 11 2019 14:43:18 GMT+0800 (Singapore Standard Time) Kang Auto Engineering Pte Ltd
<kangauto@singnet.com.sg> wrote:

----- Original Message -----

Scanned from BD034080
Date: 11/06/2019 14:43
Pages: 9
Resolution: 200x200 DPI

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.



For more information please visit <http://www.symanteccloud.com>

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SKQ8998Z	09 Jun 2019 / 23:00:00	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD



SINGAPORE POLICE FORCE



T/20190610/2141

1 of 4

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

Report No. T/20190610/2141

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/06/2019 15:51		Vide Report No.:		Station Diary No.: 81	
Informant's Particulars					
Name of Informant: ONG GUANG ZHENG			Address: APT BLK 108 ANG MO KIO AVENUE 4 #03-94 SINGAPORE 560108		
ID Type / ID No.: NRIC NO / S8334548I			Contact No.: Home/Office: Mobile: 91182781		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 35	Date of Birth: 28/10/1983	Type of Informant: Driver		
Race: Chinese		Language:		Institution / School Name:	
Occupation: SALES EXECUTIVE		Driving Licence Information: Class: 3 Date of Expiry:			

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 09/06/2019 19:45	Type of Location: Straight Road
Location: Along Road 1 YISHUN STREET 22 Along Yishun Street 22				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Pedestrian Crossing		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJF7011Y	Car	HONDA	FIT 1.3G A	Black	Slightly Damaged	1
SKQ8998Z	Car	BMW		Black	Slightly Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJF7011Y	NTUC Income Insurance Co-Operative Limited	5103352455	31/08/2018	05/12/2019



Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

Report No. T/20190610/2141

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ONG GUANG ZHENG	ID No.	S8334548I
Related Vehicle	SJF7011Y (Car)	Contact No.	91182781
Hospital/Clinic	ONECARE CLINIC YISHUN	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	10/06/2019	Date Discharge	10/06/2019
No. of Days granted Medical Leave	03	Degree of Injury	Serious
Driver			
Name	LIM BOON TAI	ID No.	S8915196A
Related Vehicle	NIL	Contact No.	94879978
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 09/06/2019 at about 7.45pm, I was driving along Yishun Street 22, near a zebra crossing. I was about to turn into a carpark when a car, SKQ8998Z hit my car, SJF7011Y from behind. I was with one other passenger and I could not see whether the other car has any passengers.

Due to the impact, the rear left of my car's bumper was dented and about to come out. For the other car, the middle right front of the car was slightly dented.

From the impact, I suffered from back and neck injury. I had received a 3day MC from 10/06/2019 to 12/06/2019 from OneCare Clinic Yishun MC no.: MC/377448. My girlfriend who was the passenger and the witness of the accident at that point of time, had not seen the doctor yet but she also felt pain in the neck.

I do not know if the other driver suffered any injury from the impact.

No police or ambulance attended to us and no government property was damaged.



**SINGAPORE
POLICE FORCE**



T/20190610/2141

3 of 4

Report No. T/20190610/2141

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190610/2141

4 of 4

Report No. T/20190610/2141

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

Sgt 2 NURSYAFIQAH AMIRA BINTE
MOHAMED ZULKIFFLI

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

10/06/2019 15:51

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG HOCK

Contact No.: 65476436

Classification Of Case:

CN 085

Authentication Stamp

NP168



Signature:

Singapore Police Force

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5103352455

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle : **SJF7011Y**
Chassis Number : **GE61076235**
2. Name of Policyholder : **ONG GUANG ZHENG**
3. Effective Date of Insurance : **31 Aug 2018**
4. Expiry Date of Insurance : **05 Dec 2019**
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

- (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: ONG GUANG ZHENG
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: TECK WEI CREDIT PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : TECK WEI CREDIT PTE. LTD. (00000572499)

Date of Issue : 31 Aug 2018 11:01 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

REPUBLIC OF SINGAPORE DRIVING LICENCE


License Number: S83345481

Name: ONG GUANG ZHENG (WANG GUANGZHENG)

Birth Date: 28 Oct 1983

Issue Date: 23 Sep 2011

002003013K



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S83345481

Name: ONG GUANG ZHENG (WANG GUANGZHENG)

王光正

Race: CHINESE

Date of birth: 28-10-1983

Sex: M

Country of birth: SINGAPORE

S83345481





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg

EFFECTIVE DATE: 03 Apr 2006

NP 428A

Licence No. S83345481



4731316

NRIC No. S83345481

Date of Issue: 20-05-2011

APT BLK 108 ANG MO KIO AVENUE 4 #03-94
SINGAPORE 560108

NRIC No. S83345481 Date: 23/09/2011 No: 6937104




CHINA

KANG**AUTO ENGINEERING PTE LTD****Sin Ming Auto City**

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015

Email: kangauto@singnet.com.sg



M/S ONG GUANG ZHENG
BLK108 ANG MO KIO AVENUE 4
#03-94
SINGAPORE 560108

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP19/06/1138
VEHICLE NO : SJF7011Y
MAKE/MODEL : HONDA FIT 1.3
DATE OF ACCIDENT : 09.06.2019

1	PC	TAILGATE		S\$	\$	552.00	✓
1	PC	TAILGATE LOCK	1/1		\$	85.00	X
1	PC	TAILGATE 'HONDA' BADGE			\$	25.00	✓
1	PC	TAILLAMP (LEFT)		mgm	\$	225.00	✓
1	PC	REAR BUMPER			\$	462.40	✓
1	SET	REAR BUMPER CLIPS			\$	35.00	✓
1	PC	REAR BUMPER REINFORCEMENT		nsp	\$	115.00	X
2	PCS	REAR BUMPER BRACKETS			\$	22.00	EA \$ 44.00 X
2	PCS	REAR BUMPER SIDE RETAINER	mgm		\$	12.00	EA \$ 24.00 4
1	PC	REAR BUMPER TOWING COVER			\$	48.00	X
1	PC	REAR END PANEL		B1	\$	248.50	✓
3	PCS	REAR END PANEL TOP GARNISH			\$	55.00	EA \$ 165.00 X
1	PC	REAR WINDSCREEN MOULDING		re	\$	125.00	✓
					\$	2,153.90	
					LESS 20%	\$	430.78
					\$	1,723.12	

1 PC REVERSE SENSOR

sher \$ 200.00 S'NETT ✓

TO CHECK WIRING SYSTEM
TO TRANSFER TAILGATE MECHANISM TO NEW TAILGATE
TO REMOVE & REFIT REAR WINDSCREEN GLASS
TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL
TO PUTTY AND SPRAY PAINT CHARGES
LABOUR CHARGE

S\$ \$ 40.00 201
\$ 120.00 601
\$ 80.00 ✓
\$ 80.00 601
\$ 1,100.00 6001
\$ 800.00 601
\$ 4,143.12

SGD FOUR THOUSAND ONE HUNDRED FORTY-THREE AND CENTS TWELVE ONLY.

YOURS FAITHFULLY,

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a 'Without Prejudice' basis
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

KANG AUTO ENGINEERING PTE LTD

Acknowledged by Repairer
Signature:
Date:

Not Notarised
C/Lump & 2350h
Murney After Rain
5 day

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119010463/KTD3N2

Date: 26/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1816201800		
Claimant Vehicle No :	SJF7011Y	Insured Vehicle No :	SKQ8998Z		
Date of Loss:	09/06/2019	Nature of Claim:	TP	Claim No:	SNM19D202567C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF7011Y	Engine No:	L13A4085618
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61076235
Reg. Date:	06/06/2008 (Man. Year: 2008)	Odometer:	141856 km
Colour:	Metallic Black		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,923.12	1,547.92	375.20	19.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,420.00	800.00	36.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,143.12	2,967.92	1,175.20	28.37
Approved Total (Overridden) (\$\$)		2,350.00		
Nett Amount (\$\$)	4,143.12	2,350.00	1,793.12	43.28

INSPECTION

Date of Assignment:	13/06/2019	
Date Inspected:	13/06/2019 Inspected At:	Kang Auto Engineering Pte Ltd 160 Sin Ming Drive, #02-16, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2019)
Parts: 144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJF7011Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	552.00 FL	*552.00 FL
2	1		*TAILGATE LOCK	Repair	85.00 FL	*- FL
3	1		*TAILGATE FIT BADGE	Necessary	25.00 FL	*25.00 FL
4	1		*TAILLAMP (LEFT)	Mtg Cracked	225.00 FL	*225.00 FL
5	1		*REAR BUMPER	Bent	462.40 FL	*462.40 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
7	1		*REAR BUMPER REINFORCEMENT	No Such Part	115.00 FL	*- FL
8	2		*REAR BUMPER BRACKETS	Repair	44.00 FL	*- FL
9	2		*REAR BUMPER SIDE RETAINER	N/s CRacked	24.00 FL	*12.00 FL
10	1		*REAR BUMPER TOWING COVER	Serviceable	48.00 FL	*- FL
11	1		*REAR END PANEL	Bent	248.50 FL	*248.50 FL
12	3		*REAR END PANEL TOP GARNISH	Serviceable	165.00 FL	*- FL
13	1		*REAR WINDSCREEN MOULDING	Necessary	125.00 FL	*125.00 FL
14	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNetL. L=ListItemDisc.

Sub Total (S\$)	2,353.90	1,884.90
- List Item Discount on L Items 20.00/20.00% (S\$)	430.78	336.98
Total Parts (S\$)	1,923.12	1,547.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM.	New	40.00	20.00
2	TO TRANSFER TAILGATE MECHANISM TO NEW TAILGATE.	New	120.00	60.00
3	TO REMOVE & REFIT REAR WINDSCREEN GLASS.	New	80.00	80.00
4	TO APPLY RUST PROOFING ON REPLACED / REPAIRED PANEL.	New	80.00	60.00
5	TO PUTTY AND SPRAY PAINT CHARGES.	New	1,100.00	600.00
6	LABOUR CHARGE.	New	800.00	600.00
Gross Labour Cost (S\$)			2,220.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >