

2/03/2002

ASS. REC. BY:

REF: CS/CT1190104691Jd3n2

Special Instruction:

Surveyor: Hwa Jie

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of C12

Date/Time: 13.6.19 10.56a.m

Estimated Cost:

Bill to:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SMJ 9260A

Insured: PC 1513A

at Workshop m/s CYS Auto Mobile

Tel: 649 2098

of 38 Woodland Industrial Park East 1 #07-14

Policy No: DMB15N3008981900

Claim No: SNM1910202580002

Sum Insured:

Excess:

Make of Veh:

D.O.A. 12.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"rwp"

H.O.D. Endorsement:

Date/Time: 13.6.19 11.08a.m

Person Contacted:

Ah Jeng

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMJ 9260A-x
	PC 1513A-x

(08/11/13)

REF

CT1

ASS. REC. BY: Hue Jie

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$58k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMJ 9260A Yr Regn: 28 Sep 2009Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598Colour: White A/C: Insured / Std / NI / NASp. Reading: 153038 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0532EE106154769Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or hexen

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/6/19 D.O.I. 13/6/19Survey held at CYS AutoDes. of Damages: (Fr) / Rear / (O/S) NIS / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
11/8/19	Amount \$7190, 8 days. cred: 9435.06! 57%
6/8/19 @ 9.54am	amount confirm by repayer.

RECEIVED 06 AUG 2019

Date/Time, File Pass to?

1) 6/8 Typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: 8Resurvey No. of Trip: 2

Survey Fee:

Transportation:

____ \$ + RS ____ \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

220

Report Format : tpLump Sum / I.B.I: (\$ 7100f)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jun 2019		13 Jun 2019 10:56 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant:	CHIA KOK KIAN, ID: S1829599G
----------------	------------------------------

Vehicle Reg. No.:	SMJ9260A
-------------------	-----------------

Date of Loss:	12/06/2019 09:00 - :59
---------------	------------------------

Claim Type:	TP / SNM19D202580C02
-------------	----------------------

Policy/Cover Note No.:	DMB1SN3008981900
------------------------	------------------

Vehicle Reg. No. (Insured):	PC1513A
-----------------------------	---------

Policy No. (Claimant):

Excess:	S\$2,000.00
---------	-------------

Repairer: **CYS Automobile Services Pte Ltd (Woodlands)** 38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park. 757700 Woodlands - Tel: 6219 2098

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]
-------------------	---

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... **[Final Rpt due 24/06/2019]**

ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Denise Tay (LKKAUTO)

From: CYSAUTO <cysauto@singnet.com.sg>
Sent: Tuesday, 6 August 2019 9:54 AM
To: Denise Tay (LKKAUTO)
Subject: RE: FINALISATION & PHOTOS FOR SMJ9260A - CONFIRMED

Dear Ms Denise Tay,

WITHOUT PREJUDICE

Confirmed with thanks

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Friday, August 02, 2019 2:50 PM
To: CYSAUTO <cysauto@singnet.com.sg>
Subject: RE: FINALISATION & PHOTOS FOR SMJ9260A

Dear Wee Sin,

We have check with our surveyor, there was no damage photo to the Engine cross member & Steering Rack & Pinion.

We will offer at lump sum \$7100/-

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CYSAUTO <cysauto@singnet.com.sg>
Sent: Friday, 2 August 2019 11:26 AM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: RE: FINALISATION & PHOTOS FOR SMJ9260A
Importance: High

Dear Ms Denise Tay,

WITHOUT PREJUDICE

Attached herewith photos for your attention.

The photo can showed the Engine cross member & Steering Rack & Pinion.

Denise Tay (LKKAUTO)

From: CYSAUTO <cysauto@singnet.com.sg>
Sent: Friday, 2 August 2019 11:26 AM
To: Denise Tay (LKKAUTO)
Subject: RE: FINALISATION & PHOTOS FOR SMJ9260A
Attachments: AFTER REPAIR PHOTO 4.jpg

Importance: High

Dear Ms Denise Tay,

WITHOUT PREJUDICE

Attached herewith photos for your attention.

The photo can showed the Engine cross member & Steering Rack & Pinion.

So we have re-calculate the repair cost at \$9,150 based on lump sum.

Kindly confirm. Thanks and look forward for your reply.

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Friday, August 02, 2019 9:26 AM
To: CYSAUTO <cysauto@singnet.com.sg>
Subject: RE: FINALISATION & PHOTOS FOR SMJ9260A

Dear Sir/Madam

Re offer at lump sum \$7100/-, 8days.

Please check and confirm.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CYSAUTO <cysauto@singnet.com.sg>
Sent: Wednesday, 24 July 2019 9:50 AM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: FW: FINALISATION & PHOTOS FOR SMJ9260A

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9599G
Vehicle Details	
Vehicle No.:	SMJ9260A
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	3ZZ4930920
Chassis No.:	MR053ZEE106154769
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	28 Sep 2009
First Registration Date:	28 Sep 2009
Transfer Count:	1
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2019
PARF Rebate Amount:	\$8,926.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$26,175.00
COE Rebate Amount:	\$25,862.00
Total Rebate Amount:	\$34,788.00

The information contained herein is correct as at 13 Jun 2019

OK



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR CHIA KOK KIAN
BLK. 412 SAUJANA ROAD
#02-64 SINGAPORE 670412

POLICY NO :
YOUR REF :
OUR REF :
VECHICLE NO :
MAKE/MODEL :
DATE OF ACCIDENT :
THIRD PARTY CLAIMS :
PC 1513 A (CHINA)
TP 6036
SMJ 9062-A SMJ 9260A
TOYOTA ALTIS
12.06.19

SURVEY BY

DATE : 13.06.19

1	PC	FRONT BUMPER	DEF ✓		S\$	520.40 ✓
1	PC	FRONT BUMPER REINFORCEMENT	DD ✓			346.31 298.40 ✓
2	PCS	FRONT BUMPER SIDE RETAINERS	rel ✓	51.90		103.80 ✓
1	PC	FRONT BUMPER TOP RUBBER	scr ✓			44.30 ✓
1	PCS	HEADLAMP ASSY	CRA-LH ✓	813.80 ✓		1,627.60
1	PC	FRONT FENDER RH	Buc ✓			652.40 598.10 ✓
1	PC	FRONT FENDER "VTI" EMBLEM	rel ✓			42.10 ✓
1	PC	FRONT FENDER GARNISH (TRIANGLE)	mis ✓			39.80 ✓
1	PC	FRONT FENDER INNER GARNISH RH	DEF ✓			85.40 ✓
1	PC	FRONT FENDER INNER SHIELD RH	DEF ✓			186.10 ✓
1	PC	WASHER TANK	nn x			121.60 X
1	PC	FRONT WINDSCREEN GLASS MOULDING	rel ✓			112.40 ✓
1	PC	FRONT WINDSCREEN GLASS PILLAR RH	Repair X			334.80 X
1	PC	FRONT DOOR RH	Buc ✓			881.90 ✓
1	PC	FRONT DOOR SIDE MIRROR RH	CRA ✓			981.10 866.10 ✓
1	PC	FRONT DOOR OUTER MOULDING RH	rel ✓			130.30 ✓
2	PCS	FRONT DOOR HINGES	BT ✓	87.50		175.00 ✓
1	PC	FRONT DOOR PROTECTOR RH	DEF ✓			154.30 ✓
1	PC	FRONT DOOR CHECKER RH	nn x			138.30 X
1	PC	FRONT DOOR WEATHERSTRIP RH	nn x			187.70 X
1	PC	FRONT DOOR GLASS	nn x			454.70 X
1	PC	FRONT DOOR REGULATOR GEAR RH	nn x			235.10 X
1	PC	FRONT DOOR PILLAR RH	Repair X			386.60 X
1	PC	ROCKER PANEL GARNISH RH	DEF ✓			695.20 565.70 ✓
1	PC	FRONT SHOCK ABSORBER RH	? / BT			396.90 ✓
1	PC	FRONT KNUCKLE ARM RH	? / BT			461.40 ✓
1	PC	FRONT KNUCKLE ARM BEARING RH	? / BT			159.40 ✓
1	PC	FRONT LOWER ARM RH	? / BT			459.30 ✓
1	PC	FRONT LOWER ARM BALL JOINT	? / BT			197.80 95 ✓
1	PC	ANTI ROLL BAR RH	? X / BT			357.50 X
1	PC	ANTI ROLL BAR LINK RH	? X / BT			180.50 110 ✓
1	PC	ENGINE CROSS MEMBER	? X			1,925.30 X
1	PC	DRIVE SHAFT RH	? X			1,633.20 X
1	PC	STEERING RACK & PINION	? X			1,524.90 X
						7299.90
						- 25%
						5474.92 ✓
						S\$ 15,933.41
LESS 25%						3,983.35
						S\$ 11,950.06

----- CONT PAGE-2



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

CON'T FROM PAGE-1

- 1 SET FRONT BUMPER CLIPS *rel ✓*
- 1 SET FRONT FENDER INNER SHIELD CLIPS RH *rel ✓*
- 1 PC FRONT WINDSCREEN GLASS SEALANT *rel ✓*
- 1 PC TYRE *cut ✓*
- 1 SET TYRE RIM *scr ✓*

S\$ 11,950.06

S\$	30.00	S/ NETT
	20 35.00	"
	40.00	"
	160.00	"
	350 500.00	"
S\$	765.00	

TO TOWING CHANGES

S\$ 50.00 ✓

TO REMOVE AND REFIX FRONT WINDSCREEN GLASS

~~140.00~~ 120

TO DISMANTLE AND REFIX DASHBOARD FITTING

~~300.00~~ 120

TO TRANSFER DOOR FITTING

~~80.00~~ 50

TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE

~~300.00~~ 100

TO CHECK AND ADJUST COMPUTER ALIGNMENT

~~150.00~~ 60

TO CHECK WIRING FUNCTION

~~50.00~~ 30

TO APPLY RUSTING AND PROOFING ON REPLACED AND REPAIR PANEL

~~150.00~~ 40

LABOUR CHARGES

~~1,200.00~~ 1000

TO PUTTY AND SPRAY PAINTING CHARGES

~~1,400.00~~ 1200

S\$ 16,535.06

SIN DOLLARS: SIXTEEN THOUSAND FIVE HUNDRED THIRTY-FIVE AND CENTS SIX ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700
Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

2770 ✓

*P- 5474.92
N- 600
L- 2770
8844.92*

*L/S- 7075.93
= 7100*

*Huee Jia - LKK
13/6/19*

L/S 8 days.

[Signature]

*[Signature]
17/6/19*



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

MR CHIA KOK KIAN
BLK. 412 SAUJANA ROAD
#02-64 SINGAPORE 670412

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : PC 1513 A (CHINA)
OUR REF : TP 6036
VEHICLE NO : SMJ 9060A
MAKE/MODEL : TOYOTA ALTIS
DATE OF ACCIDENT : 12.06.19

SURVEY BY

DATE : 13.06.19

1	PC	FRONT BUMPER	DEF /		S\$	520.40
1	PC	FRONT BUMPER REINFORCEMENT	DD /			346.31
2	PCS	FRONT BUMPER SIDE RETAINERS	rel /	51.90		103.80
1	PC	FRONT BUMPER TOP RUBBER	scr /			44.30
1	PCS	HEADLAMP ASSY	CRA-LH /	813.80		1,627.60
1	PC	FRONT FENDER RH	Buc /			652.40
1	PC	FRONT FENDER "VTI" EMBLEM	rel /			42.10
1	PC	FRONT FENDER GARNISH (TRIANGLE)	mis /			39.80
1	PC	FRONT FENDER INNER GARNISH RH	DEF /			85.40
1	PC	FRONT FENDER INNER SHIELD RH	DEF /			186.10
1	PC	WASHER TANK	nn x			121.60
1	PC	FRONT WINDSCREEN GLASS MOULDING	rel /			112.40
1	PC	FRONT WINDSCREEN GLASS PILLAR RH	Repair x			334.80
1	PC	FRONT DOOR RH	Buc /			881.90
1	PC	FRONT DOOR SIDE MIRROR RH	CRA /			981.10
1	PC	FRONT DOOR OUTER MOULDING RH	rel /			130.30
2	PCS	FRONT DOOR HINGES	BT /	87.50		175.00
1	PC	FRONT DOOR PROTECTOR RH	DEF /			154.30
1	PC	FRONT DOOR CHECKER RH	nn x			138.30
1	PC	FRONT DOOR WEATHERSTRIP RH	nn x			187.70
1	PC	FRONT DOOR GLASS	nn x			454.70
1	PC	FRONT DOOR REGULATOR GEAR RH	nn x			235.10
1	PC	FRONT DOOR PILLAR RH	Repair x	11270.11		386.60
1	PC	ROCKER PANEL GARNISH RH	DEF /			695.20
1	PC	FRONT SHOCK ABSORBER RH	? / BT			396.90
1	PC	FRONT KNUCKLE ARM RH	? / BT	8452.58		461.40
1	PC	FRONT KNUCKLE ARM BEARING RH	? / OPC			159.40
1	PC	FRONT LOWER ARM RH	? / BT			459.30
1	PC	FRONT LOWER ARM BALL JOINT	? / BT			197.80
1	PC	ANTI ROLL BAR RH	? X NAI			357.50
1	PC	ANTI ROLL BAR LINK RH	? X			180.50
1	PC	ENGINE CROSS MEMBER	? X			1,925.30
1	PC	DRIVE SHAFT RH	? X			1,633.20
1	PC	STEERING RACK & PINION	? X			1,524.90
						S\$ 15,933.41
LESS 25%						3,983.35
						S\$ 11,950.06

----- CONT PAGE-2



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

CONT FROM PAGE-1

		S\$	11,950.06	
1 SET FRONT BUMPER CLIPS	rel /	S\$	30.00	S/ NETT
1 SET FRONT FENDER INNER SHIELD CLIPS RH	rel /	20	35.00	"
1 PC FRONT WINDSCREEN GLASS SEALANT	rel /		40.00	"
1 PC TYRE	cut /		160.00	"
1 SET TYRE RIM	scr /	350	500.00	"
		S\$	765.00	
TO TOWING CHANGES		S\$	50.00	/
TO REMOVE AND REFIX FRONT WINDSCREEN GLASS			140.00	120
TO DISMANTLE AND REFIX DASHBOARD FITTING			300.00	120
TO TRANSFER DOOR FITTING			80.00	50
TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE			300.00	100
TO CHECK AND ADJUST COMPUTER ALIGNMENT			150.00	60
TO CHECK WIRING FUNCTION			50.00	30
TO APPLY RUSTING AND PROOFING ON REPLACED AND REPAIR PANEL			150.00	40
LABOUR CHARGES			1,200.00	1000
TO PUTTY AND SPRAY PAINTING CHARGES			1,400.00	1200
		S\$	16,535.06	

SIN DOLLARS: SIXTEEN THOUSAND FIVE HUNDRED THIRTY-FIVE AND CENTS SIX ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

LS = \$9450

Huee Jie - CLKK

13/6/19

4/5 8 days.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19010469/JTD3N2

Date: 07/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN3008981900
Claimant Vehicle No :	SMJ9260A	Insured Vehicle No :	PC1513A
Date of Loss:	12/06/2019	Nature of Claim:	TP
		Claim No:	SNM19D202580C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ9260A	Engine No:	3ZZ4930920
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106154769
Reg. Date:	28/09/2009 (Man. Year: 2009)	Odometer:	153038 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,715.06	6,074.92	6,640.14	52.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	2,770.00	1,050.00	27.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,535.06	8,844.92	7,690.14	46.51
Approved Total (Overridden) (S\$)		7,100.00		
(S\$)	16,535.06	7,100.00	9,435.06	57.06
+ GST 7.00/7.00% (S\$)	1,157.45	497.00	660.45	57.06
Nett Amount (S\$)	17,692.51	7,597.00	10,095.51	57.06

INSPECTION

Date of Assignment:	13/06/2019	
Date Inspected:	13/06/2019 Inspected At:	CYS Automobile Services Pte Ltd (Woodlands) 38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park Singapore 757700

Estimated Period of Repair: 8.0 days

Adjuster: ONG HWEE JIE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Aug 2019)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ9260A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	520.40 FL	*520.40 FL
2	1		*FRONT BUMPER REINFORCEMENT	Dented	346.31 FL	*298.40 FL
3	2		*FRONT BUMPER SIDE RETAINERS	Necessary	103.80 FL	*103.80 FL
4	1		*FRONT BUMPER TOP RUBBER	Scratched	44.30 FL	*44.30 FL
5	1		*HEADLAMP ASSY	N/s Cracked	1,627.60 FL	*813.80 FL
6	1		*FRONT FENDER RH	Buckled	652.40 FL	*598.10 FL
7	1		*FRONT FENDER VVTI EMBLEM	Necessary	42.10 FL	*42.10 FL
8	1		*FRONT FENDER GARNISH (TRIANGLE)	Missing	39.80 FL	*39.80 FL
9	1		*FRONT FENDER INNER GARNISH RH	Deformed	85.40 FL	*85.40 FL
10	1		*FRONT FENDER INNER SHIELD RH	Deformed	186.10 FL	*186.10 FL
11	1		*WASHER TANK	Not Necessary	121.60 FL	*- FL
12	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	112.40 FL	*112.40 FL
13	1		*FRONT WINDSCREEN GLASS PILLAR RH	Repair	334.80 FL	*- FL
14	1		*FRONT DOOR RH	Buckled	881.90 FL	*881.90 FL
15	1		*FRONT DOOR SIDE MIRROR RH	Cracked	981.10 FL	*866.10 FL
16	1		*FRONT DOOR OUTER MOULDING RH	Necessary	130.30 FL	*130.30 FL
17	2		*FRONT DOOR HINGES	Bent	175.00 FL	*175.00 FL
18	1		*FRONT DOOR PROTECTOR RH	Deformed	154.30 FL	*154.30 FL
19	1		*FRONT DOOR CHECKER RH	Not Necessary	138.30 FL	*- FL
20	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	187.70 FL	*- FL
21	1		*FRONT DOOR GLASS	Not Necessary	454.70 FL	*- FL
22	1		*FRONT DOOR REGULATOR GEAR RH	Not Necessary	235.10 FL	*- FL
23	1		*FRONT DOOR PILLAR RH	Repair	386.60 FL	*- FL
24	1		*ROCKER PANEL GARNISH RH	Deformed	695.20 FL	*565.70 FL
25	1		*FRONT SHOCK ABSORBER RH	Bent	396.90 FL	*396.90 FL
26	1		*FRONT KNUCKLE ARM RH	Bent	461.40 FL	*461.40 FL
27	1		*FRONT KNUCKLE ARM BEARING RH	Necessary	159.40 FL	*159.40 FL
28	1		*FRONT LOWER ARM RH	Bent	459.30 FL	*459.30 FL
29	1		*FRONT LOWER ARM BALL JOINT	Bent	197.80 FL	*95.00 FL
30	1		*ANTI ROLL BAR RH	Not Necessary	357.50 FL	*- FL
31	1		*ANTI ROLL BAR LINK RH	Bent	180.50 FL	*110.00 FL
32	1		*ENGINE CROSS MEMBER	Not Necessary	1,925.30 FL	*- FL
33	1		*DRIVE SHAFT RH	Not Necessary	1,633.20 FL	*- FL
34	1		*STEERING RACK & PINION	Not Necessary	1,524.90 FL	*- FL
35	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
36	1		*SET FRONT FENDER INNER SHIELD CLIPS RH	Necessary	35.00 FS	*20.00 FS
37	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
38	1		*TYRE	Cut	160.00 FS	*160.00 FS
39	1		*SET TYRE RIM	Scratched	500.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,698.41	7,899.90
- List Item Discount on L Items 25.00/25.00% (S\$)	3,983.35	1,824.98
Total Parts (S\$)	12,715.06	6,074.92

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOWING CHARGES	New	50.00	50.00
2	TO REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	140.00	120.00
3	TO DISMANTLE AND REFIX DASHBOARD FITTING	New	300.00	120.00
4	TO TRANSFER DOOR FITTING	New	80.00	50.00
5	TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE	New	300.00	100.00
6	TO CHECK AND ADJUST COMPUTER ALIGNMENT	New	150.00	60.00
7	TO CHECK WIRING FUNCTION	New	50.00	30.00
8	TO APPLY RUSTING AND PROOFING ON REPLACED AND REPAIR PANEL	New	150.00	40.00
9	LABOUR CHARGES	New	1,200.00	1,000.00
10	TO PUTTY AND SPRAY PAINTING CHARGES	New	1,400.00	1,200.00
Gross Labour Cost (\$\$)			3,820.00	2,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >