

ASS. REC. BY:

REF:

TMI / C31 TMI 190104761 Kvd302


Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: SKV 197U  
 Policy No. MT 109028  
 Claims No. M1904264  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: 873,400  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repair: 07 days Res.: Yes or No  
 Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S140 5838B Yr Regn: 11, 18  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Traller or \_\_\_\_\_  
 Make: Toy Prow c.c. 1798  
 Colour M. #. White / Red A/C: Insured / Std / NI / NA  
 Sp. Reading 72773 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTDK B 31-4 9.03 076871  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modl: Nil / S/Rlm / STD / Rlm or  
 Tyre Size: F: 195/65R15  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / SY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front R/Bal. 7 mm  
 Rear R/Bal. 6 mm  
 L/Bal. 7 mm  
 L/Bal. 6 mm  
 D.O.A. 8/6/19 D.O.I. 12/6/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
 & m  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/17/19 File pass to

SHD 5838B - A / IN C17010374/114

SKV 197U - X

D.O.A. - 08/06/2019

13/6/19 Email GIA to TMI

RECEIVED 1 JUL 2019

11/7/19 817994.89 (Red 38,256.87, 689)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

11/7 typist

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

250

11

261

Report Format:

merimen

Lump Sum / I.B.I. (\$

17,994.89

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2019		13 Jun 2019 17:21 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KHAIRUL ANWAR BIN KAMARUDIN, ID: S8736455J		
Main Claimant:	TRANS-CAB SERVICES PTE LTD (3/5), Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD5838B	Date of Loss:	08/06/2019 20:00 - :59
Claim Type:	TP / M1904264	Policy/Cover Note No.:	MT109028 (Comprehensive) Coverage: 25/10/2018 - 24/10/2019
Vehicle Reg. No. (Insured):	SKV197U	Policy No. (Claimant):	VPX/P1680520
		Excess:	S\$0.00
Repairer:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ho Teng Boon Eliza]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/06/2019]		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 13 June 2019 3:33 PM  
**To:** SUR; motorclaims@tokiomarine.com.sg  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 8/6/2019, SHD 5838B (TP VEHICLE), SKV 197U (OI VEHICLE)  
**Attachments:** EST.pdf; GIA.pdf; POLICE REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHB 5838B at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 12/6/2019

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	3878K
<b>Vehicle Details</b>	
Vehicle No.:	SHD5838B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B75675
Chassis No.:	JTDKB3FU903076877
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	22 Nov 2018
First Registration Date:	22 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Nov 2026
PARF Rebate Amount:	\$10,685.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	21 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,736.00
COE Rebate Amount:	\$18,988.00
<b>Total Rebate Amount:</b>	<b>\$29,673.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Jun 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/06/2019 09:52
Date Of Accident	08/06/2019 20:40
Exact Location Of Accident	BKE TOWARDS SLE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD5838B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
<b>Driver</b>	
Name of Driver	QUEK WEE TEN
NRIC No	S1135022D
Date Of Birth	04/04/1955
Occupation	OUTDOOR
Date Of Driving Pass	10/07/1975
Driving Experience	43 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90258580
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 709 WOODLANDS DRIVE 70 #10-05
Postcode	730709
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	QT5828 (PRIVATE CAR)
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS EAST N.P.C
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Please see the attach Police Report T/20190609/2011.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV197U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBE1694R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

GOODS VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLE8610T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

QT5828

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name

QUEK WEE TEN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHD5838B

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode



## Sketch Plan Pg. 1

### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN

A: SHD 5838B  
B: SKV 197U  
C: GBE 1694R  
D: SLE 8610T  
E: QT5828  
DKE towards SLE

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please see the attach police report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Amanda  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190609/2011

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

3 of 3

Report No. T/20190609/2011

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

L/  
ON ZHI WEI, ROGER

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
09/06/2019 01:06

Officer In Charge Of Case:

TP / GIT /  
SI T. ABAGESH JEYATHESH  
Contact No: 65476232

SN 130

Authentication Stamp  
NP168

Signature :

**Singapore Police Force**

Classification Of Case:

## Police Report Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190609/2011

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

1 of 3

Report No. T/20190609/2011

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/06/2019 01:06			Vide Report No.:		Station Diary No.: 37
Name of Informant: QUEK WEE TEN			Address: APT BLK 709 WOODLANDS DRIVE 70 #10-05 SINGAPORE 730709		
ID Type / ID No.: NRIC NO / S1135022D			Contact No.: Home/Office: Mobile: 90258580		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 64	Date of Birth: 04/04/1955	Type of Informant: Driver		
Race: Chinese			Language: Chinese	Institution / School Name:	
Occupation: Taxi driver			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 08/06/2019 20:40	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY BKE TOWARDS SLE AFTER MANDAI EXIT				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: CHAINED COLLISION			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Vehicle	Make	Model	Color	Condition	No. of Passenger
GBE1694R	Lorry				Slightly Damaged	0
QT5828 (Not Accurate)	Car				Seriously Damaged	2
SHD5838B	Car				Seriously Damaged	0
SKV197U	Car				Seriously Damaged	0
SLE8610T	Car				Seriously Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20190609/2011

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

2 of 3  
Report No. T/20190609/2011

**CONTINUATION OF REPORT**

**Brief Details.**

I am commonly known as Mr Quek. I am working as a taxi driver. I am currently residing in Blk 709 Woodlands Dr 70 #10-05.

On 08/06/2019 at about 2040 hrs, I was travelling along BKE towards SLE after Mandai exit. There was a multiple-chained collision involving 5 vehicles. The first vehicle which was a car with vehicle plate number SLE8610T collided with another car with vehicle plate number SKV197U from the front to the rear. This resulted in the second car front to collide with the third vehicle which was my vehicle with car plate number SHD5838B on my rear. My car as a result then collided a lorry in front of me with plate number GBE1694R. The lorry's front as a result collided with the vehicle in front of him which was a foreign vehicle with car plate number QT5828.

The front and rear of my vehicle were seriously scratched and dented inwards. I had no passengers in my vehicle. I am unsure of the exact details of the damage assessment of other vehicles clearly.

I was prescribed with 5 days of MC via Intermedical 24 Hr Clinic due to pain on the rear of my neck, my back area and left side of the leg as a result of the collision. Police and ambulance had attended to the scene however no one was conveyed. There is CCTV installed in my taxi front which recorded the incident.

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5838B****AAD1906-075**

*Not Authorised*  
*Mercury B4 paint*  
*@17994.89*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHD 5838B**

JTDKB3FU903076877

TOYOTA

PRIUS

8.6.2019

**TOKIO MARINE**

22/11/2018

**PART****LIST**

1	1 REAR BUMPER	\$	<i>Acc 10M</i> 458.60	✓
2	1 REAR BUMPER RE-INFORCEMENT	\$	<i>R</i> 318.80	✓
3	1 REAR BUMPER TOWING COVER	\$	<i>SL</i> 14.70	X
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>R</i> 552.60	✓
5	1 REAR BUMPER SIDE RETAINER LH	\$	<i>SL</i> 112.70	X
6	1 REAR BUMPER SIDE RETAINER RH	\$	<i>SL</i> 112.70	X
7	1 REAR TAILGATE	\$	<i>Bu</i> 1,547.27	✓
8	1 REAR TAILGATE OUTER GARNISH	\$	<i>Acc</i> 905.10	✓
9	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i> 54.70	X
10	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i> 54.70	X
11	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>SL</i> 93.60	X
12	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>SL</i> 93.60	X
13	1 BOARD ASSY, BACK DOOR TRIM	\$	<i>SL</i> 254.40	X
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>SL</i> 51.20	X
15	1 REAR TAILGATE WEATHERSTRIP	\$	<i>SL</i> 365.20	X
16	1 REAR END PANEL	\$	<i>R</i> 602.10	✓
17	1 TAILLAMP LOWER RH	\$	<i>SL</i> 548.40	X
18	1 TAILLAMP UPPER RH	\$	<i>SL</i> 557.90	X
19	1 REAR BUMPER SIDE RH	\$	<i>SL</i> 232.00	X
20	1 REAR BUMPER SIDE LH	\$	<i>ngem</i> 232.00	✓
21	1 TAILLAMP LOWER LH	\$	<i>SL</i> 548.40	X
22	1 TAILLAMP UPPER LH	\$	<i>SL</i> 557.90	X
23	1 PAN, REAR FLOOR	\$	<i>R</i> 572.10	X
24	1 EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	<i>R</i> 77.00	X
25	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	<i>R</i> 192.90	X
26	1 EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	<i>R</i> 77.00	X
27	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	<i>R</i> 192.90	X
28	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	<i>R</i> 290.50	X

**Trans-cab Auto Services Pte Ltd**

AAD1906-075

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5838B**

29	1 REAR FENDER LH	\$	R	817.50	X
30	1 REAR FENDER RH	\$	R	817.50	X
31	1 FRONT BUMPER	\$	B	499.90	✓
32	1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	R	101.20	X
33	1 REINFORCEMENT, FRONT BUMPER	\$	R	696.40	X
34	1 ABSORBER, FRONT BUMPER, LOWER	\$	R	130.20	X
35	1 ABSORBER, FRONT BUMPER ENERGY	\$	D	78.10	✓
36	1 FRONT BUMPER SIDE RETAINER RH	\$	D	78.00	✓
37	1 FRONT BUMPER SIDE RETAINER LH	\$	D	78.00	✓
38	1 FRONT BUMPER SUPPORT	\$	C	81.70	✓
39	1 EXTENSION, FRONT BUMPER, RH	\$	R	117.80	X
40	1 EXTENSION, FRONT BUMPER, LH	\$	R	117.80	X
41	1 FRONT LED LAMP (LOWER) RH	\$	R	907.75	X
42	1 FRONT LED LAMP (LOWER) LH	\$	R	907.75	X
43	1 FRONT HEADLAMP RH	\$	B	2,909.04	✓
44	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	R	492.30	X
45	1 MOTOR, HEADLAMP LEVELING, RH	\$	R	413.10	X
46	1 FRONT HEADLAMP LH	\$	B	2,909.04	✓
47	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	m	492.30	✓
48	1 MOTOR, HEADLAMP LEVELING, RH	\$	R	413.10	X
49	1 FRONT BONNET	\$	B	950.50	✓
50	1 SEAL, HOOD TO FRONT END PANEL	\$	R	25.30	X
51	1 INLET, AIR CLEANER, NO.1	\$	D	132.80	✓
52	1 INLET, AIR CLEANER, NO.2	\$	R	95.90	X
53	1 INLET, AIR CLEANER, NO.3	\$	R	35.90	X
54	1 CAP SUB-ASSY, AIR CLEANER	\$	C	459.50	✓
55	1 COVER, RADIATOR SUPPORT OPENING	\$	D	232.10	✓

	\$	24,661.45
25%	\$	6,165.36
	\$	18,496.09

**Special Nett**

1	1SET PARKING AID	\$	Shan	700.00	250sn
2	1SET REAR BUMPER CLIP	\$	R	22.00	✓
3	2 REAR WINDSCREEN SELANT	\$	R	80.00	60sn
4	1 WINDSCREEN MOULDING	\$	R	100.00	✓

**Trans-cab Auto Services Pte Ltd**

AAD1906-075

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5838B

5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	<i>30sn</i>
6	1 REAR TAILGATE TOYOTA LOGO	\$	<i>nn</i> 47.00	<i>—</i>
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>nn</i> 52.90	<i>—</i>
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>nn</i> 53.50	<i>—</i>
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00	<i>30sn</i>
10	1 REAR TAILGATE STICKER '6555-3333'	\$	<i>nn</i> 80.00	<i>30sn</i>
11	1 REAR BUMPER PROTECTOR	\$	<i>nn</i> 100.00	<i>X</i>
12	1 FRONT NUMBER PLATE WITH MOULDING	\$	<i>nn</i> 200.00	<i>45sn</i>

TOTAL \$ 1,615.40

TOTAL PARTS \$ 20,111.49

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	<i>1500</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	<i>900</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>60</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>50</i>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	<i>60</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>



37755.62

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5838B****AAD1906-075**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHD 5838B**

JTDKB3FU903076877

TOYOTA

PRIUS

8.6.2019

**TOKIO MARINE**

22/11/2018

**SUPPLEMENTARY ESTIMATE**

		<b>PART</b>	<b>LIST</b>	
1	1	HINGE ASSY, HOOD, LH	\$	<i>DIT</i> 58.00 —
2	1	HINGE ASSY, HOOD, RH	\$	<i>DIT</i> 58.00 —
3	1	LOCK ASSY, HOOD	\$	<i>R</i> 133.30 ✓
4	1	CABLE ASSY, HOOD LOCK CONTROL	\$	<i>Sm</i> 54.20 X
5	1	CAP SUB-ASSY, AIR CLEANER	\$	<i>CM</i> 459.50 —
6	1	FENDER SUB-ASSY, FRONT LH	\$	<i>Bu</i> 963.80 —
7	1	FENDER SUB-ASSY, FRONT RH	\$	<i>Bu</i> 963.80 —
8	1	LINER, FRONT FENDER, LH	\$	<i>Sm</i> 200.00 X
9	1	LINER, FRONT FENDER, RH	\$	<i>Sm</i> 204.20 X
10	1	RETAINER, FRONT FENDER LINER	\$	<i>Sm</i> 16.10 X
11	1	RETAINER, FRONT FENDER LINER	\$	<i>Sm</i> 16.10 X
12	1	RADIATOR ASSY	\$	<i>R</i> 1,892.40 ✓
13	1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>R</i> 101.20 X
14	1	REINFORCEMENT, FRONT BUMPER	\$	<i>Reinforce</i> 696.40 X
15	1	MOTOR SUB-ASSY, BLOWER W/FAN	\$	<i>Sm</i> 1,029.60 X
16	1	SUPPORT SUB-ASSY, RADIATOR, UPPER	\$	<i>R</i> 371.80 ✓
17	1	SUPPORT SUB-ASSY, RADIATOR, LOWER	\$	<i>R</i> 404.50 X
18	1	SUPPORT, RADIATOR, UPPER LH	\$	<i>DIT</i> 78.00 —
19	1	SUPPORT, RADIATOR, UPPER RH	\$	<i>DIT</i> 78.00 —
			\$	<b>7,778.90</b>
25%			\$	<b>1,944.73</b>
			\$	<b>5,834.18</b>

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 11 July 2019 12:27 PM  
**To:** Ng Wai Yin  
**Cc:** jasminetan@transcab.com.sg; SUR  
**Subject:** SHD 5838B-DOA: 8/6/2019  
**Attachments:** MARKING.pdf

Dear Wai Yin,

WITHOUT PREJUDICE

Final amount \$17,994.89 before GST @ 7 working days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jun 2019		13 Jun 2019 17:21 <a href="#">Edit Adj Rpt</a>	<b>S\$17,994.89</b> <a href="#">Edit Estimates</a>	<b>S\$17,994.89</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



























  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>KHAIRUL ANWAR BIN KAMARUDIN</b> , ID: S87364553								
Main Claimant:	<b>TRANS-CAB SERVICES PTE LTD (3/5)</b> , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	<b>SHD5838B</b>	Date of Loss:	08/06/2019 20:00 - :59 [6 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / M1904264</b>	Policy/Cover Note No.:	MT109028 (Comprehensive) Coverage: 25/10/2018 - 24/10/2019						
Vehicle Reg. No. (Insured):	<b>SKV197U</b>	Policy No. (Claimant):	VPX/P1680520						
		Excess:	S\$0.00						
Repairer:	<b>Trans-Cab Services Pte Ltd (HQ)</b> 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Ho Teng Boon Eliza</b> ]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 24/06/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									













## Claim Documents






**\*SHD5838B (M1904264)**  
**[SKV197U]**  
**TP**  
**TRANS-CAB SERVICES PTE LTD (3/5)**  
**Jun 8 2019 8:00PM**  
**[KHAIRUL ANWAR BIN KAMARUDIN]**  
**Trans-Cab Services Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	11/06/19 11:05	<b>Accident Statement</b> From: SC - Reg. No: SKV197U, Claimant: KHAIRUL ANWAR BIN KAMARUDIN	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
2	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
20	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
21	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
22	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
23	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
24	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
25	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
26	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
27	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
28	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
29	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
30	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
31	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>
33	11/07/19 12:39	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
34	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/07/19 12:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	13/06/19 17:18	13.06.19 - SHD5838B POLICE REPORT	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/07/19 11:47	Supplementary	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)	Thumbnail	Print
1	10/06/19 11:25	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)	Thumbnail	Print
1	10/06/19 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	10/06/19 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	10/06/19 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	10/06/19 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	10/06/19 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	10/06/19 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	10/06/19 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	10/06/19 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	10/06/19 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	10/06/19 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	10/06/19 10:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)	Thumbnail	Print
1	10/06/19 10:17	Sketch Plan	 Load TIF	
2	10/06/19 10:17	Sketch Plan #2	 Load TIF	
3	10/06/19 10:17	Police Report	 Load TIF	
4	10/06/19 10:17	Police Report	 Load TIF	
5	10/06/19 10:17	Police Report	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19010476/KVD3E2

Date: 12/07/2019

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MT109028

Claimant Vehicle No : SHD5838B

Insured Vehicle No : SKV197U

Date of Loss: 08/06/2019

Nature of Claim: TP

Claim No: M1904264

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHD5838B

Make &amp; Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZR2B75675

Reg. Date: 22/11/2018 (Man. Year: 2018)

Chassis No: JTDKB3FU903076877

Colour: Metallic White/Red

Odometer: 72773 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Goodyear 7 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 7 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,945.66	15,114.89	10,830.77	41.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,810.00	2,880.00	8,930.00	75.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>37,755.66</b>	<b>17,994.89</b>	<b>19,760.77</b>	<b>52.34</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,642.90</b>	<b>1,259.64</b>	<b>1,383.26</b>	<b>52.34</b>
<b>Nett Amount (S\$)</b>	<b>40,398.56</b>	<b>19,254.53</b>	<b>21,144.03</b>	<b>52.34</b>

## INSPECTION

Date of Assignment: 13/06/2019

Date Inspected: 12/06/2019 Inspected At:

Trans-Cab Services Pte Ltd (HQ)

2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2019)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD5838B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	458.60 FL	*458.60 FL
2	1		*REAR BUMPER RE-INFORCEMENT	Bent	318.80 FL	*318.80 FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	14.70 FL	*- FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Bent	552.60 FL	*552.60 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
7	1		*REAR TAILGATE	Buckled	1,547.27 FL	*1,547.27 FL
8	1		*REAR TAILGATE OUTER GARNISH	Dented	905.10 FL	*905.10 FL
9	1		*COVER, REAR COMBINATION LAMP, RH	Serviceable	54.70 FL	*- FL
10	1		*COVER, REAR COMBINATION LAMP, RH	Serviceable	54.70 FL	*- FL
11	1		*GARNISH, BACK DOOR SIDE, LH	Serviceable	93.60 FL	*- FL
12	1		*GARNISH, BACK DOOR SIDE, RH	Serviceable	93.60 FL	*- FL
13	1		*BOARD ASSY, BACK DOOR TRIM	Serviceable	254.40 FL	*- FL
14	1		*PANEL ASSY, BACK DOOR TRIM, UPPER	Serviceable	51.20 FL	*- FL
15	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	365.20 FL	*- FL
16	1		*REAR END PANEL	Bent	602.10 FL	*602.10 FL
17	1		*TAILLAMP LOWER RH	Serviceable	548.40 FL	*- FL
18	1		*TAILLAMP UPPER RH	Serviceable	557.90 FL	*- FL
19	1		*REAR BUMPER SIDE RH	Serviceable	232.00 FL	*- FL
20	1		*REAR BUMPER SIDE LH	Mtg Cracked	232.00 FL	*232.00 FL
21	1		*TAILLAMP LOWER LH	Serviceable	548.40 FL	*- FL
22	1		*TAILLAMP UPPER LH	Serviceable	557.90 FL	*- FL
23	1		*PAN, REAR FLOOR	Repair	572.10 FL	*- FL
24	1		*EXTENSION, REAR FLOOR SIDE PANEL, RH	Repair	77.00 FL	*- FL
25	1		*EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	Repair	192.90 FL	*- FL
26	1		*EXTENSION, REAR FLOOR SIDE PANEL, LH	Repair	77.00 FL	*- FL
27	1		*EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	Repair	192.90 FL	*- FL
28	1		*PANEL, QUARTER WHEEL HOUSE, OUTER LH	Repair	290.50 FL	*- FL
29	1		*REAR FENDER LH	Repair	817.50 FL	*- FL
30	1		*REAR FENDER RH	Repair	817.50 FL	*- FL
31	1		*FRONT BUMPER	Bent	499.90 FL	*499.90 FL
32	1		*BRACKET, FRONT BUMPER EXTENSION MOUNTING	Repair	101.20 FL	*- FL
33	1		*REINFORCEMENT, FRONT BUMPER	Bent	696.40 FL	*696.40 FL
34	1		*ABSORBER, FRONT BUMPER, LOWER	Serviceable	130.20 FL	*- FL
35	1		*ABSORBER, FRONT BUMPER ENERGY	Distorted	78.10 FL	*78.10 FL
36	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	78.00 FL	*78.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	78.00 FL	*78.00 FL
38	1		*FRONT BUMPER SUPPORT	Cracked	81.70 FL	*81.70 FL
39	1		*EXTENSION, FRONT BUMPER, RH	Serviceable	117.80 FL	*- FL
40	1		*EXTENSION, FRONT BUMPER, LH	Serviceable	117.80 FL	*- FL
41	1		*FRONT LED LAMP (LOWER) RH	Serviceable	907.75 FL	*- FL
42	1		*FRONT LED LAMP (LOWER) LH	Serviceable	907.75 FL	*- FL
43	1		*FRONT HEADLAMP RH	Broken	2,909.04 FL	*2,909.04 FL
44	1		*COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	Serviceable	492.30 FL	*- FL
45	1		*MOTOR, HEADLAMP LEVELING, RH	Serviceable	413.10 FL	*- FL
46	1		*FRONT HEADLAMP LH	Broken	2,909.04 FL	*2,909.04 FL
47	1		*COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	Mtg Cracked	492.30 FL	*492.30 FL
48	1		*MOTOR, HEADLAMP LEVELING, RH	Serviceable	413.10 FL	*- FL
49	1		*FRONT BONNET	Bent	950.50 FL	*950.50 FL
50	1		*SEAL, HOOD TO FRONT END PANEL	Serviceable	25.30 FL	*- FL
51	1		*INLET, AIR CLEANER, NO.1	Dented	132.80 FL	*132.80 FL
52	1		*INLET, AIR CLEANER, NO.2	Serviceable	95.90 FL	*- FL
53	1		*INLET, AIR CLEANER, NO.3	Serviceable	35.90 FL	*- FL
54	1		*CAP SUB-ASSY, AIR CLEANER	Cracked	459.50 FL	*459.50 FL
55	1		*COVER, RADIATOR SUPPORT OPENING	Distorted	232.10 FL	*232.10 FL
56	1		*SET PARKING AID	Shorted	700.00 FS	*250.00 FS
57	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
58	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
59	1		*WINDSCREEN MOULDING	Necessary	100.00 FS	*100.00 FS
60	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
61	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.00 F	*47.00 FN
62	1		*REAR TAILGATE WORDING PRIUS	Necessary	52.90 F	*52.90 FN
63	1		*REAR TAILGATE WORDING HYBRID	Necessary	53.50 F	*53.50 FN
64	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
65	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
66	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	*- FS
67	1		*FRONT NUMBER PLATE	Bent	200.00 FS	*45.00 FS
68	1		*HINGE ASSY, HOOD, LH	Distorted	58.00 FL	*58.00 FL
69	1		*HINGE ASSY, HOOD, RH	Distorted	58.00 FL	*58.00 FL
70	1		*LOCK ASSY, HOOD	Bent	133.30 FL	*133.30 FL
71	1		*CABLE ASSY, HOOD LOCK CONTROL	Serviceable	54.20 FL	*- FL
72	1		*CAP SUB-ASSY, AIR CLEANER	Cracked	459.50 FL	*459.50 FL
73	1		*FENDER SUB-ASSY, FRONT LH	Buckled	963.80 FL	*963.80 FL
74	1		*FENDER SUB-ASSY, FRONT RH	Buckled	963.80 FL	*963.80 FL
75	1		*LINER, FRONT FENDER, LH	Serviceable	200.00 FL	*- FL
76	1		*LINER, FRONT FENDER, RH	Serviceable	204.20 FL	*- FL
77	1		*RETAINER, FRONT FENDER LINER	Serviceable	16.10 FL	*- FL
78	1		*RETAINER, FRONT FENDER LINER	Serviceable	16.10 FL	*- FL
79	1		*RADIATOR ASSY	Bent	1,892.40 FL	*1,892.40 FL
80	1		*BRACKET, FRONT BUMPER EXTENSION MOUNTING	Repair	101.20 FL	*- FL
81	1		*REINFORCEMENT, FRONT BUMPER	Repeated	696.40 FL	*- FL
82	1		*MOTOR SUB-ASSY, BLOWER W/FAN	Serviceable	1,029.60 FL	*- FL
83	1		*SUPPORT SUB-ASSY, RADIATOR, UPPER	Bent	371.80 FL	*371.80 FL
84	1		*SUPPORT SUB-ASSY, RADIATOR, LOWER	Repair	404.50 FL	*- FL
85	1		*SUPPORT, RADIATOR, UPPER LH	Distorted	78.00 FL	*78.00 FL
86	1		*SUPPORT, RADIATOR, UPPER RH	Distorted	78.00 FL	*78.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$) 34,055.75 19,970.85

- List Item Discount on L Items 25.00/25.00% (\$\$) 8,110.09 4,817.61

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- Nett Item Discount on N Items 0.00/25.00% (S\$)					0.00	38.35
Total Parts (S\$)					25,945.66	15,114.89

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	1,540.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,200.00	900.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
5	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	120.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
12	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
13	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
14	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
15	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
16	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER	New	380.00	100.00
17	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	50.00
18	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00
19	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>11,810.00</b>	<b>2,880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >