

ESTIMATE TO REPAIR

VEHICLE NO. : SKN 3549 K
 MAKE : TOYOTA
 MODEL : COROLLA ALTIS 1.6L CVT
 YEAR : 2014
 CHASSIS NO : MR053REH104509548

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 10-Jun-19
 DATE OF ACCIDENT : 8-Jun-19
 THIRD PARTY REF : SKA 3353 B / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 486.50
2 pcs	Rear Bumper Retainer		\$ 88.50		\$ 177.00
2 pcs	Rear Bumper Bracket		\$ 56.30		\$ 112.60
1 pc	Rear End Panel				\$ 789.70
1 pc	Rear End Panel Garnish				\$ 189.20
1 pc	Rear Boot				\$ 784.60
1 pc	Rear Boot Lock				\$ 458.70
1 pc	Rear Boot Rubber				\$ 85.64
1 pc	Rear Boot Centre Emblem				\$ 58.70
1 pc	Rear Boot COROLLA Emblem				\$ 88.50
1 pc	Rear Boot ALTIS Emblem				\$ 85.90
2 pcs	Taillamps		\$ 381.90		\$ 763.80
1 pc	Rear Spare Tyre Top Cover				\$ 324.11
					\$ 4,404.95
	Less 25%				\$ 1,101.24
					\$ 3,303.71
1 set	Rear Bumper Sensor	S.Nett			\$ 200.00
1 pc	Rear Number Plate	S.Nett			\$ 40.00
	To putty and spray painting				\$ 800.00
	To anti-rust				\$ 80.00
	Labour charges				\$ 650.00
TG/RA-	Total				\$ 5,073.71

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd