

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 783M

DATE : 12.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

India / CPL 1

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid Wt <i>st</i>			\$ 2,174.90
	Boot Lid Rubber <i>Nuc</i>			\$ 96.50
	Boot Lid Lock Upper <i>NH</i>			\$ 102.60
	Boot Lid Lock Lower <i>NH</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>NH Nuc</i>			\$ 28.70
	Boot Lid CRDI Plate <i>NH Nuc</i>			\$ 27.90
	Boot Lid Lamp (LH) <i>NH</i>			\$ 565.60
	Boot Lid Trimboard <i>NH</i>			\$ 116.40
	Boot Lid Trimboard Clips (10pcs) <i>NH</i>			\$ 11.00
	Bootlid Moulding <i>NH</i>			\$ 85.00
	Bootlid i40 Emblem <i>NH</i>			\$ 27.90
	Bootlid Lower Garnish <i>NH</i>			\$ 227.90
	Rear Bumper <i>distal</i>			\$ 553.00
	Rear Bumper Reinforcement <i>crack / Wt</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>N/S</i>	<i>Wt o/s</i>	\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>Nuc</i>	<i>NH</i>		\$ 22.00
	Rear Bumper Bracket <i>NH</i>		\$ 35.60	\$ 71.20
	Rear Bumper Sponge <i>trim</i>			\$ 118.40
	Rear Bumper Under Cover <i>distal</i>			\$ 228.00
	Rear Bumper Reflector Lamp (LH) <i>NH</i>			\$ 30.60
	Tail Lamp (LH) <i>crack</i>			\$ 697.80
	Tail Lamp Quarter Panel (LH) <i>NH</i>			\$ 226.50
	Rear Panel <i>Distal</i>			\$ 526.70
	Rear Panel Garnish <i>NH</i>			\$ 57.70
	Rear Panel Lower Panel <i>Distal</i>			\$ 495.50
	Spare Tyre Holder <i>NH</i>			\$ 223.10
	Spare Tyre Panel <i>NH</i>			\$ 852.80
	Spare Tyre Panel Cushion <i>NH</i>			\$ 209.05
	Rear Towing Hook <i>NH</i>			\$ 94.60
	Member Assy- Rear Floor Centre <i>NH</i>			\$ 570.40
	Exhaust Pipe Insulator, LH <i>NH</i>			\$ 58.55
	Exhaust Silencer, LH <i>st</i>			\$ 967.70
	Exhaust Pipe Hanger, LH <i>NH</i>			\$ 58.55
	Exhaust Pipe Centre <i>NH</i>			\$ 730.10
	Rear Fender With Housing (LH) <i>Distal</i>			\$ 4,736.80
	Rear Fender Inner Lining (LH) <i>NH</i>			\$ 169.30
	Rear Fender Air-Duct, LH <i>NH</i>			\$ 51.60
	Rear Windscreen Moulding <i>Nuc</i>			\$ 28.30
				\$ 15,863.35
				\$ 3,172.67
				\$ 12,690.68

Handwritten checkmarks and 'photo' note on the right side of the table.

SUB TOTAL
LESS 20%
DISCOUNTED TOTAL

SHC 783M

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker 1 Hec			\$ 30.00	Nett * ✓
	Boot Lid Advertisement Logo 1 Hec			\$ 100.00	Nett * ✓
	Rear Bumper Reverse Sensor 1 Down			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo Hec			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat Hec			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) Hec		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant Hec			\$ 46.00	Nett ✓
				\$ 611.70	
	Labour Charge				
	Panel Beating			\$ 1,800.00	700/-
	Spray Painting Charge			\$ 1,250.00	600/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	40/-
	Towing Fee			\$ 50.00	44
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Fuel Tank			\$ 150.00	44
	Remove/Refix Exhaust Pipe			\$ 200.00	60/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	44
				\$ 4,470.00	
	ESTIMATE TOTAL			\$ 17,772.38	
	<p>13/06/19 @ 1400w N/A Actual 45min 6 days. [Signature] JKK Auto</p>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.