

Date: _____
Signature: _____
Acknowledged by Repairer: _____

VEHICLE NO : FBF 231U

Yamaha YZF-R15

Nett Items

Front 1	Number plate <i>HN</i>	15.00 ✓
2	Towing fee	40.00 30/-
3	Labour to remove & replace necessary parts, align & etc	280.00 150/-
4	Remove & replace fork tube & top up fork oil	120.00 80/-
5	Putty & respray paint where necessary	250.00 120/-
		395.00

Special Nett Items

1	Meter Assy <i>HN</i>	650.00 X
---	----------------------	----------

Sub-Total 1,355.00


Nett Total 4,905.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

3311.00

4/5 2600/-

Kindly revert upon completion. Thank you



SG 98 MOTOR PTE LTD

12/06/2019 @ 1800 hrs

NA Antun

2/5mm

gn 4 days

2 KK Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: