

ASS. REC. BY:

REF:

CS/FCT19010508/T14 d3/n2

Special Instruction:

Survey: Tan Heng

ASSIGNMENT (Office)

PWS

From (Person): Karen Tan

of

FCL

Date/Time: 4:06pm @ 13/6/19

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC1491D

Insured:

SHD 3766M

at Workshop in/s

Yi Heng Motor

Tel:

65090052

of

Blk 11 Kuli Bukit Ave 6 #02-19

Policy No:

Claim No:

D19003838 MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/06/2019

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

4:48pm @ 13/6/19

Person Contacted:

Wan ping

Vehicle IN/OUT

Date/Time

Action/Instruction

Tobin /

PC1491D-x

SHD 3766M-CS/FCT1 7011249/Ked 3s2

DUA: 7/6/17

8/7 @ 4:07pm revised via email preli advise.

REG. BY: Tautich

REF: FCI

ASSIGNMENT

From: Date: 26/6/19

Veh No: PC1491D Yr Regn: 2013, Feb.

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: PC 1491D

Make: MAN 18.240 C.C. 6871

at Workshop m/s

Colour: Maroon A/C: Insured / Std / NI / NA

of 154 Gul Circle - 629611

Sp. Reading: 26400 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No: WMAA69221CC017534

Policy No.

C/No:

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: Pls call Louis before going

Modi: Nil / S/Rim / STD A/Rim or

81886626

Tyre Size: F: 275 / 70R22.5

(Policy Condition)

R: 4 -

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 8 mm

R/Bal. 8/8 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 8 mm

L/Bal. 8/8 mm

Est. Repairs: days Res.: Yes or No

D.O.A. D.O.I. 26/6/19

Lum Sum: % 3 Val.: Yes or No

Survey held at 154 Gul Circle

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Finalized lump sum \$1500t (Red: 5500t : 78%)
	RECEIVED 19 JUL 2019

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 3

1) IAH Typist

☒ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

145

2)

Add Fee: ☐ : Site Insp (\$

Transportation:

50

☐ : Interview (\$

3+PS, SI

50

☐ : Tech. Inve (\$

Photos:

20

☐ : West end (\$

Others:

TOTAL

265

Report Format:

TP

Lump Sum / L.B. 1500t



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003838MFSH

Date: 8/7/2019

Our Ref: CS/FCI19010508/T1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. PC 1491D

Please be informed that we had conducted the inspection of the abovementioned vehicle 26/6/2019 at the premises of M/s Yi Heng Motor have the following to report: -

Workshop Estimate Amount	: S\$ 7,000.00
Revised Estimate Amount	: S\$ 1,900.00
"Check" Items Amount	: S\$ 0.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
Front o/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	12-06-2019	Our Ref No. D19003838MFSH
Accident Date	09-06-2019	Claim Type. Third Party
Insured Vehicle	SHD3766M	Third Party Vehicle. PC1491D
Survey Location	BLK 1 KAKI BUKIT AVENUE 6 #02-19 AUTOBAY @KAKIBUKIT	
Contact Person.	WAN PING	
Contact No.	65090052/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YI HENG MOTOR WORKSHOP	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Yong Patric Yong <yihengmotorworkshop@yahoo.com.sg>
Sent: Thursday, 18 July 2019 10:20 AM
To: SUR
Subject: Finalise of PC 1491D Doa : 09-06-19

To Taufikh,

We agree to finalise on lump sum \$1500.00 and 3 working days repair.

From,
Wan Ping

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5678G

Vehicle Details

Vehicle No.:	PC1491D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Jun 2019
Vehicle Make:	MAN
Vehicle Model:	18.240 HOCL-NL (A69)
Primary Colour:	Multi-Colour
Manufacturing Year:	2012
Engine No.:	21432226113242
Chassis No.:	WMAA69ZZ1CC017534
Maximum Power Output:	-
Open Market Value:	\$155,294.00
Original Registration Date:	05 Feb 2013
First Registration Date:	05 Feb 2013
Transfer Count:	0
Actual ARF Paid:	\$7,765.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	04 Feb 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$59,111.00
COE Rebate Amount:	\$21,569.00
Total Rebate Amount:	\$21,569.00

The information contained herein is correct as at 11 Jun 2019

OK

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 8 July 2019 4:07 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003838MFSH/1
Attachments: PRELI ADVISED PC 1491D.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **PC 1491D**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 13 June 2019 4:50 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003838MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 13 June 2019 4:06 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003838MFSH/1

Thank you.

Q



Dave Ng



YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

26-06-19

OUR REF NO. PC 1491D

SINGAPORE DUCKTOURS PTE. LTD.
82, AMOY STREET
#03-00
SINGAPORE 069901

ESTIMATE BILL FOR VEHICLE NO. PC 1491D

MODEL : MAN 18.240 HOCL-NL (A69)

SPECIAL NETT ITEM

1) FRONT BUMPER CUSTOMISE	1500.00	Rx
2) FRONT SIDE PANEL	1000.00	Rx
		2500.00

LABOUR CHARGE

1) TO SUPPLY LASER GRAPHIC ADVERTISEMENT STICKER	1500.00	1000
2) TO REMOVE AND RESPASTE ADVERTISEMENT STICKER	1000.00	300
3) TO RESPRAY ON AFFECTED AREAS	1000.00	300
4) TO REPLACE NEW PARTS ETC	1000.00	300
		4500.00
GRAND TOTAL		<u>7000.00</u>

Tan Jiahua 97495749
26/6/19
03 days
Resurvey after repair.
sur@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19010508/T1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3766M	Veh. Inspected	PC 1491D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003838MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	13/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAN 18.240	c.c	6871	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WMAA69ZZ1CC017534	Colour	MAROON	
Odometer	216400	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm	
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm	
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/06/2019	Inspection Date	26/06/2019	
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 1491D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER CUSTOMISE (SN)	TO REPAIR SEE LABOUR	1,500.00	-
1	FRONT SIDE PANEL (SN)	TO REPAIR SEE LABOUR	1,000.00	-
			2,500.00	-
LABOUR				
	TO SUPPLY LASER GRAPHIC ADVERTISEMENT STICKER.		1,500.00	1,000.00
	TO REMOVE AND RESPASTE ADVERTISEMENT STICKER.		1,000.00	300.00
	TO RESPRAY ON AFFECTED AREAS.		1,000.00	300.00
	TO REPLACE NEW PARTS ETC. INCLUSIVE OF THE REPAIR OF FRONT BUMPER CUSTOMISE AND FRONT SIDE PANEL.		1,000.00	300.00
			4,500.00	1,900.00
GRAND TOTAL			7,000.00	1,900.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/FCI19010508/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.