

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

not allowed
able

13/6/19

Whaybe AH-12p
Total 1055

max rep- SL

M/S : NORIAH BINTE MOHAMED NOOR
BLK 468A FERNVALE LINK #14-539
SINGAPORE 791468

Estimate No: EST1504937
Date: 12 Jun 2019
Policy No: P10081714R00
Veh Reg No: SGL6019L
Make/Model: TOYOTA ESTIMA 2.4 A
Chassis No: ACR507028526
Engine No: 2AZC046236
Reg. Date: 22/09/2006

ATTN: QBE
Your Ref No: TP 0619-5550
Claim Type: Third Party
Accident Date: 10/06/2019
TP Veh Reg No: SKU 6272 B

Estimate Repair Cost to Vehicle No :SGL6019L

Description	U/Price	Quantity	Price	Amount
			SS	SS
List Price				
1 REAR BOOT	1,087.96	1 PC	1,087.96	—
2 REAR BOOT RUBBER	378.91	1 PC	378.91	?
3 REAR BOOT TOP LOCK	375.86	1 PC	375.86	—
4 REAR BOOT BOTTOM LOCK	77.44	1 PC	77.44	X
5 REAR BOOT TOYOTA LOGO	77.44	1 PC	77.44	—
6 REAR BOOT ESTIMA WORDING	96.16	1 PC	96.16	—
7 REAR BOOT X WORDING	96.16	1 PC	96.16	—
8 REAR BOOT OUTER REFLECTOR - CENTRE	376.84	1 PC	376.84	X
9 REAR BOOT OUTER REFLECTOR - LH	355.60	1 PC	355.60	?
10 REAR BOOT OUTER REFLECTOR - RH	355.60	1 PC	355.60	?
11 REAR BOOT TRIM - LOWER	896.90	1 PC	896.90	?
12 REAR BOOT TRIM - TOP	396.70	1 PC	396.70	?
13 REAR BOOT TRIM - LH	377.70	1 PC	377.70	X
14 REAR BOOT TRIM - RH	377.70	1 PC	377.70	X
15 REAR BOOT OUTER GARNISH	266.52	1 PC	266.52	?
16 REAR BOOT WIPER MOTOR	789.90	1 PC	789.90	X
17 REAR BOOT WIPER LINK	0.00	1 PC	0.00	X
18 REAR BOOT GLASS MOULDING	127.51	1 SET	127.51	—
19 REAR BOOT NUMBER PLATE LAMP - LH	69.84	1 PC	69.84	X
20 REAR BOOT NUMBER PLATE LAMP - RH	69.84	1 PC	69.84	X
21 REAR BOOT LOCK SWITCH	181.60	1 PC	181.60	X
22 REAR BUMPER	897.24	1 PC	897.24	—
23 REAR BUMPER CLIPS	4.90	10 PC	49.00	—
24 REAR BUMPER SIDE HOLDER - LH	98.98	1 PC	98.98	—
25 REAR BUMPER SIDE HOLDER - RH	98.98	1 PC	98.98	X
26 REAR BUMPER CENTRE BRACKET - LH	90.42	1 PC	90.42	—
27 REAR BUMPER CENTRE BRACKET - RH	90.42	1 PC	90.42	—
28 REAR BUMPER FOAM	107.86	2 PC	215.72	?
29 REAR BUMPER REFLECTOR - LH	66.84	1 PC	66.84	—
30 REAR BUMPER REFLECTOR - RH	66.84	1 PC	66.84	X
31 REAR BUMPER TOWING - LH	76.81	1 PC	76.81	—
32 REAR BUMPER TOWING - RH	76.81	1 PC	76.81	X
33 REAR FENDER - LH	987.90	1 PC	987.90	X
34 REAR FENDER GLASS - LH	485.16	1 PC	485.16	X
35 REAR FENDER INNER TRIM - LH	996.70	1 PC	996.70	?
36 TAIL LAMP UNIT - LH	427.12	1 PC	427.12	?
37 TAIL LAMP LOWER - LH	18.70	1 PC	18.70	?
38 TAIL LAMP LOWER - RH	18.70	1 PC	18.70	?

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S: NORIAH BINTE MOHAMED NOOR
BLK 468A FERNVALE LINK #14-539
SINGAPORE 791468

Estimate No: EST1504937
Date: 12 Jun 2019
Policy No: P10081714R00
Veh Reg No: SGL6019L
Make/Model: TOYOTA ESTIMA 2.4 A
Chassis No: ACR507028526
Engine No: 2AZC046236
Reg. Date: 22/09/2006

ATTN: QBE
Your Ref No: TP 0619-5550
Claim Type: Third Party
Accident Date: 10/06/2019
TP Veh Reg No: SKU 6272 B

Estimate Repair Cost to Vehicle No :SGL6019L

Description	U/Price	Quantity	Price	Amount
			SS	SS
39 REAR EXHAUST PIPE	957.90	1 PC 11	957.90	X
40 REAR EXHAUST PIPE TOP PLATE	0.00	1 PC 11	0.00	X
41 REAR EXHAUST PIPE MOUNTING	85.21	3 PC 11	255.63	X
42 REAR PANEL	587.50	1 PC 3.05m	587.50	—
43 REAR PANEL TOP GARNISH	285.69	1 PC	285.69	?
44 REAR PANEL INNER LOWER GARNISH	276.51	1 PC	276.51	?
45 TAIL LAMP PANEL - RH	275.50	1 PC 2	275.50	X
46 REAR SPARE FLOOR PANEL	957.86	1 PC 1.1m	957.86	?
47 REAR SPARE TYRE BOARD	815.20	1 PC	815.20	—
48 FRONT BUMPER	588.60	1 PC 1.1	588.60	—
49 FRONT BUMPER CLIPS	4.90	10 PC 2m	49.00	—
50 FRONT BUMPER SIDE HOLDER - LH	108.70	1 PC 3.0m	108.70	—
51 FRONT BUMPER SIDE HOLDER - RH	108.70	1 PC 3.0	108.70	—
52 FRONT BUMPER TOWING COVER - LH	66.25	1 PC 1.1	66.25	X
53 FRONT BUMPER TOWING COVER - RH	66.25	1 PC 1.1	66.25	X
54 FRONT BUMPER CENTRE LOWER GRILLE	0.00	1 PC 1.0m	0.00	—
55 FRONT BUMPER CENTRE LOWER GRILLE CHROME	0.00	1 PC 1.0m	0.00	—
56 FRONT BUMPER FOAM	198.54	1 PC	198.54	?
57 FRONT BUMPER TOP BEAM	218.80	1 PC	218.80	?
58 FRONT BUMPER REINFORCEMENT	371.54	1 PC	371.54	?
59 GRILLE ASSY	585.90	1 PC 1.0m	585.90	—
60 GRILLE LOGO	127.64	1 PC 2m	127.64	—
61 GRILLE SIDE STOPPER - LH	48.70	1 PC 2m	48.70	—
62 GRILLE SIDE STOPPER - RH	48.70	1 PC 2m	48.70	—
63 GRILLE CLIP	18.90	10 PCS 2m	189.00	—
64 SUPPORT PANEL TOP GARNISH CLIP	7.80	10 PCS 1.0m	78.00	—
65 SUPPORT PANEL TOP GARNISH	489.67	1 PC 1.1	489.67	—
66 SUPPORT PANEL - TOP	422.31	1 PC 3.0	422.31	—
67 BRACE PANEL	0.00	1 PC	0.00	?
68 HEAD LAMP TOP PANEL - LH	269.80	1 PC	269.80	?
69 HEAD LAMP TOP PANEL - RH	269.80	1 PC	269.80	?
70 HEAD LAMP PANEL, SIDE - LH	0.00	1 PC	0.00	?
71 HEAD LAMP PANEL, SIDE - RH	0.00	1 PC	0.00	?
72 RADIATOR	1,487.70	1 PC	1,487.70	?
73 RADIATOR FAN MOTOR	486.27	1 PC	486.27	?
74 RADIATOR FAN COWLING	278.90	1 PC	278.90	?
75 RADIATOR TOP HOSE	79.78	1 PC	79.78	?
76 RADIATOR BOTTOM HOSE	79.78	1 PC	79.78	?
77 CONDENSER	1,487.62	1 PC 1.0m	1,487.62	—

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : NORIAH BINTE MOHAMED NOOR
 BLK 468A FERNVALE LINK #14-539
 SINGAPORE 791468

Estimate No: EST1504937
Date: 12 Jun 2019
Policy No: P10081714R00
Veh Reg No: SGL6019L
Make/Model: TOYOTA ESTIMA 2.4 A
Chassis No: ACR507028526
Engine No: 2AZC046236
Reg. Date: 22/09/2006

ATTN: QBE
Your Ref No: TP 0619-5550
Claim Type: Third Party
Accident Date: 10/06/2019
TP Veh Reg No: SKU 6272 B

Estimate Repair Cost to Vehicle No :SGL6019L

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
78 CONDENSER FAN MOTOR	378.90	1 PC	378.90 ?	
79 CONDENSER FAN COWLING	0.00	1 PC	0.00 ?	
80 AIRCON DISCHARGE PIPE	485.60	1 PC	485.60 ?	
81 AIRCON LIQUID TUBE	754.87	1 PC	754.87 ?	
82 TEMP SENSOR	126.82	1 PC	126.82 ?	
83 HORN - LH	185.60	1 PC	185.60 ?	
84 HORN - RH	185.60	1 PC	185.60 ?	
85 HEAD LAMP UNIT - LH	988.51	1 PC <i>cm</i>	988.51 //	
86 HEAD LAMP UNIT - RH	988.51	1 PC <i>cm</i>	988.51 //	
87 HEAD LAMP LOWER RETAINER - LH	62.70	1 PC <i>34</i>	62.70 //	
88 HEAD LAMP LOWER RETAINER - RH	62.70	1 PC <i>34</i>	62.70 //	
89 FRONT FENDER - LH	485.80	1 PC <i>2</i>	485.80 X	
90 FRONT FENDER COWLING - LH	396.92	1 PC <i>11</i>	396.92 X	
91 FRONT FENDER COWLING CLIPS - LH	4.80	10 PC <i>12</i>	48.00 X	
92 FRONT BONNET	487.86	1 PC <i>54</i>	487.86 //	
93 FRONT BONNET RUBBER	99.45	1 PC <i>24</i>	99.45 //	
94 FRONT BONNET LOCK	129.57	1 PC <i>74</i>	129.57 //	
95 FRONT BONNET INSULATOR	375.80	1 PC	375.80 ?	
96 FRONT BONNET INSULATOR CLIP	6.50	5 PCS	32.50 ?	
97 FRONT BONNET HINGE - LH	98.57	1 PC <i>34</i>	98.57 //	
98 FRONT BONNET HINGE - RH	98.57	1 PC <i>34</i>	98.57 //	
99 WIPER TANK ASSY	166.52	1 PC	166.52 ?	
100 RADIATOR SPARE TANK	218.57	1 PC	218.57 ?	
			31,070.20	
		Less 25%	7,767.55	23,302.65

Special Net

101 REAR BUMPER SENSOR	220.00	1 SET <i>shld</i>	220.00 200	
102 REAR BOOT CAMERA	350.00	1 SET	350.00 ?	
103 REAR NUMBER PLATE WITH CASING	35.00	1 SET	35.00 ?	
104 FRONT NUMBER PLATE WITH CASING	35.00	1 SET <i>cm</i>	35.00 40	
105 SEALANT <i>Ren</i>	20.00	4 PC <i>ru</i>	80.00 30	
106 SPONGE TAPE	20.00	3 PC <i>ren</i>	60.00 30	
			780.00	780.00

Labour

107 TO KNOCK OUT DENTS, REAR CHASSIS, REAR FLOOR PANEL, CUT/WELD REAR PANEL, RH REAR FENDER, SUPPORT PANEL, REMOVE, REPLACE ACCIDENT PARTS	2,800.00	1 JOB	2,800.00 2200	
108 TO RESPRAY PAINT ON ACCIDENT PORTIONS	2,500.00	1 JOB	2,500.00 1800	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : NORIAH BINTE MOHAMED NOOR
BLK 468A FERNVALE LINK #14-539
SINGAPORE 791468

Estimate No: EST1504937
Date: 12 Jun 2019
Policy No: P10081714R00
Veh Reg No: SGL6019L
Make/Model: TOYOTA ESTIMA 2.4 A
Chassis No: ACR507028526
Engine No: 2AZC046236
Reg. Date: 22/09/2006

ATTN: QBE
Your Ref No: TP 0619-5550
Claim Type: Third Party
Accident Date: 10/06/2019
TP Veh Reg No: SKU 6272 B

Estimate Repair Cost to Vehicle No :SGL6019L

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
109 TO CHECK WIRING	50.00	1 JOB	50.00	30
110 TO REMOVE, REFIX CONDENSER AND REFILL GAS	100.00	1 JOB	100.00	✓
111 TO REMOVE, REFIX REAR GARNISH, CARPET, CUSHION AND RELATED PARTS	300.00	1 JOB	300.00	100
112 TO REMOVE REAR BUMPER SENSOR	100.00	1 JOB	100.00	50
113 TO REMOVE, REPLACE REAR EXHAUST PIPE	100.00	1 JOB	100.00	X
114 TO REMOVE, REPLACE REAR BOOT GLASS	150.00	1 JOB	150.00	120
115 TO REMOVE, REFIX REAR FENDER GLASS - LH	60.00	1 JOB	60.00	X
116 TO REMOVE, REFIX REAR FENDER GLASS - RH	60.00	1 JOB	60.00	X
117 TO REMOVE, REFIX REAR WINDSCREEN	150.00	1 JOB	150.00	X
118 TO 4 WHEEL ALIGNMENT	100.00	1 JOB	100.00	X
119 TO CAR-O-LINER CHASSIS	250.00	1 JOB	250.00	X
120 TO REMOVE, REFIX, REAR UNDERCARRIAGE	400.00	1 JOB	400.00	X
121 TO TUFF-KOTE	120.00	1 JOB	120.00	✓
122 TO REMOVE, REFIX PETROL TANK	150.00	1 JOB	150.00	60
			7,390.00	7,390.00

Total S\$ 31,472.65

Add GST @ 7% 2,203.09

Total Amount Payable S\$ 33,675.74

TOTAL: SINGAPORE DOLLAR THIRTY THREE THOUSAND SIX HUNDRED SEVENTY FIVE AND CENTS SEVENTY FOUR ONLY

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party's survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE