



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102191

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 05/04/2021
Reference CC6/CTI19010517/Ara3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKP 8379R
Insured Veh. SJJ 600Y
Claim No. SNM19D202651
Policy No. DMPCSN3068321801
Accident Date 02/06/2019
Inspection Date 20/11/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI19010517/Ara3q2	
			Date: 05/04/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJJ 600Y	Veh. Inspected	SKP 8379R	
Policy No.	DMPCSN3068321801	Coverage (\$)	0.00	
Claim No.	SNM19D202651	Excess (\$)	0.00	
Assign From		Assign Date	20/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	BMW 525I	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	WBANU52080CZ87477	Colour	GREY	
Odometer	151600 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	MICHELIN	6 mm	
L/H Front Tyre	225/50 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/50 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/50 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/06/2019	Inspection Date	20/11/2019	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 8379R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,468.00	-
1	SET FRONT BUMPER CLIPS	NOT NECESSARY	50.00	-
1	FRONT BUMPER SIDE HOLDER-LH	NOT NECESSARY	65.00	-
1	FRONT FENDER-LH	TO REPAIR SEE LABOUR	845.00	-
1	HEAD LAMP-LH	CUT	2,620.00	2,620.00
	LESS 10% DISCOUNT		-504.80	-262.00
			4,543.20	2,358.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER SENSOR-LH (SN)	NOT NECESSARY	260.00	-
1	FRONT WHEEL RIM-LH (SN)	NOT NECESSARY	1,450.00	-
			1,710.00	-
<u>LABOUR</u>				
	TO KNOCKING OUT FRONT PORTION & RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT FENDER-LH.		500.00	250.00
	TO PUTTY & SPRAY UP PAINT WORKS.		600.00	400.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO REMOVE FRONT BUMPER SENSOR.		100.00	50.00
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			1,400.00	730.00
GRAND TOTAL			7,653.20	3,088.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CC6/CT119010517/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKP 8379R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

