

CCG/CTI19010517/Ad63

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

**CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**

3 Anson Road #16-00  
 Springleaf Tower  
 Singapore 079909  
 Tel : 6389 - 6111  
 Fax : 6224 - 7478 / 7175

**Quotation**  
 DATE : 20.11.2019  
 VEH NO : SKP8379R  
 MODEL : BMW 523i  
 D O A : 02.06.2019  
 YR REF : SJJ600Y

Jiale.

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SKP8379R (BMW 523i)**

| <u>Item</u> | <u>Description</u>                                | <u>Qty</u> | <u>Amt</u>                |
|-------------|---------------------------------------------------|------------|---------------------------|
| <b>NO</b>   | <b>LIST ITEMS</b>                                 |            |                           |
| 1           | Front Bumper : Reps                               | 1          | 1,468.00 X                |
| 2           | Front Bumper Clips Reps                           | 1 set      | 50.00 X                   |
| 3           | Front Bumper Side Holder - LH Reps 2620           | 1          | 65.00 X                   |
| 4           | Front Fender - LH Reps 2358                       | 1          | 845.00 X                  |
| 5           | Head Lamp - LH cut                                | 1          | 2,620.00 ✓                |
|             |                                                   |            | <u>\$ 5,048.00</u>        |
|             | Less 10%                                          |            | (504.80)                  |
|             |                                                   |            | <u>\$ 4,543.20</u>        |
|             | <b>S/NET ITEMS</b>                                |            |                           |
| 1           | Front Bumper Sensor - LH Reps                     | 1          | 260.00 X                  |
| 2           | Front Wheel Rim - LH Reps                         | 1          | 1,450.00 X                |
|             |                                                   |            | <u>\$ 1,710.00</u>        |
|             | <b>Total parts</b>                                |            | <u><b>\$ 6,253.20</b></u> |
|             | <b>LABOUR CHARGE</b>                              |            |                           |
| 1           | To knocking out front portion & renew above parts |            | \$ 500.00 250             |
| 2           | To putty & spray up paint works                   |            | \$ 600.00 400             |
| 3           | To check wiring system                            |            | \$ 50.00 30               |
| 4           | To remove front bumper sensor                     |            | \$ 100.00 50              |
| 5           | To perform wheel alignment                        |            | \$ 150.00 X               |
|             | <b>Total Labour</b>                               |            | <u>\$ 1,400.00</u>        |
|             | <b>Grand Total</b>                                |            | <u><b>\$ 7,653.20</b></u> |

LKK Auto Centre to confirm the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3088  
 C/s 2450  
 03 Days