

ASS. REC. BY:

REF:

CS/FCI17610518/Ktd3n2

Special Instruction:

Coverage: Kenneth

ASSIGNMENT (Office)

From (Person):

Hunny Kuo

of

FCI

Date/Time:

3:57pm @ 13/6/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 5497G

Insured:

SHB 48362

at Workshop m/s

Trung Cab

Tel:

62876666

of

No. 2 AMIC8-63

Policy No:

Claim No:

D19003798MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/6/2019

CA / REV / REP. / REV 24 HRS

lap

H.O.D. Endorsement:

Date/Time:

4:09pm @ 13/6/19

Person Contacted:

Candy

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	
	SHC 5497G-CC3/AXA/2014431/chc3	DOA: 23/07/2012
	SHC 48362-CS/FCI/5607262/Rq bdi	DOA: 6/5/2015

ASS. REC. BY:

REF: FC21

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

03 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: S17C 34976Yr Regn: 07, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitude

C.C

1995Colour M. White / Red

A/C: _____

Insured / Std / NI / NA

Sp. Reading 371461

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: V1=1 ABL 15 AUG 278810Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: MT / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 9/6/19D.O.I. 13/6/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass toL1 By 82600h confirm with wai yin (Red: 32844 93, 92%)

RECEIVED 19 JUN 2019

Date/Time, File Pass to?



: Prel. Report

1) 19/6/19 Typist

: Final Report

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS. \$

Fees: _____

Others: _____

TOTAL

350Report Format: TPLump Sum / I.B.I: (\$ 2600+)

MOTOR SURVEY ASSIGNMENT

Date	11-06-2019	Our Ref No. D19003798MFSH
Accident Date	09-06-2019	Claim Type. Third Party
Insured Vehicle	SHB4836Z	Third Party Vehicle. SHC5497G
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 19 June 2019 11:53 AM
To: Denise Tay (LKKAuto)
Subject: FW: SHC 5497G / TP / FIRST CAPITAL / DOA: 9/6/2019 -- AAD1906-093
Attachments: SHC 5497G ESTIMATE.pdf

Hi Denise

We confirmed COR amount \$2600 (b4 GST)

Will u photo after I receive from our workshop.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Wednesday, 19 June, 2019 10:08 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: RE: SHC 5497G / TP / FIRST CAPITAL / DOA: 9/6/2019

Dear Wai Yin,

Lump Sum \$2600, 3days.

Please check and confirm

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Friday, 14 June 2019 9:44 AM

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5497G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001847
Chassis No.:	VF1ABL15AUC278810
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	11 Jul 2014
First Registration Date:	11 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jul 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	10 Jul 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$53,269.00
COE Rebate Amount:	\$20,530.00
Total Rebate Amount:	\$29,903.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Jun 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5497G

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC

VF1.

REN

LAT

9.6.

FIR:

11/

0*c

1,108*46+

768*84+

552*55+

=

2,429*85*

2,429*85x

90*%

2,186*865*

0*c

5*+

66*+

33*+

66*+

=

170*+

0*c

400*+

440*+

20*+

60*+

=

920*+

0*c

2,186*865+

170*+

920*+

=

3,276*865*

3,276*865x

80*%

2,621*492*

TOTAL \$**10% \$****\$****PART**

- 1 DOOR PANEL REAR RH
- 1 BOOT REAR
- 1 BOOT REFLECTOR LAMP RH
- 1 FENDER PANEL REAR RH
- 1 FENDER PANEL INNER TRIM REAR RH
- 1 WHEELARCH REAR RH
- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER REFLECTOR RH
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 TAILLAMP RH
- 1 TAILLAMP PANEL RH
- 1 EXHAUST REAR
- 1 EXHAUST CAP REAR

Special Nett

- 1 REAR DOOR STICKER '6555-3333'
- 1 FENDER INNER TRIM CLIP RH
- 1 TAILLAMP CLIP RH
- 1SET FENDER WHEELARCH REAR RH CLIP
- 2 REAR WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING

\$

\$

\$

\$

\$

\$

~ 80.00 X

~ 28.00 X

~ 5.00 ✓

~ 35.00 X

~ 80.00 X

~ 100.00 X

Trans-cab Auto Services Pte Ltd**AAD1906-093**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5497G

1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	X
1	REAR RIGHT TYRE	\$	<i>nn</i>	300.00	X
1	REAR RIGHT TYRE RIM	\$	<i>nn</i>	380.00	X
1SET	PARKING AID	\$	<i>nn</i>	700.00	X
1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00	—
1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	—
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	X
1SET	BUMPER RETAINER CLIP RH RR	\$	<i>nn</i>	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	✓
1	EXHAUST MOUNTING REAR	\$	<i>nn</i>	17.82	X
TOTAL		\$		2,042.82	
TOTAL PARTS		\$		22,924.93	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$

4000
4,500.00

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$

nn 380.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$

nn 380.00 X

To check steering geometry and computer wheel alignment

\$

nn 220.00 X

To transfer of Rear door fittings, attachment and perform water seepage test.

\$

nn 380.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$

nn 170.00 X

To transfer of Rear fender fittings, attachment and perform water seepage test.

\$

nn 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1906-093

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5497G

To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To rust-proofing of the affected areas.	\$	nn 170.00 X
Putty and spray painting of the affected portion.	\$	4401 4,500.00 4401
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To reinstall rear bumper parking sensor.	\$	170.00 601
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00 X
TOTAL	\$	12,520.00
Over All Total	\$	35,444.93

LUMP SUM (REPAIR DAY)**15 DAYS**

3 day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance

Acknowledged by Repairer
Signature:
Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19010518/Ktd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4836Z	Veh. Inspected	SHC 5497G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003798MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	13/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC278810	Colour	METALLIC WHITE / RED	
Odometer	371461	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/06/2019	Inspection Date	13/06/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5497G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	TAILLAMP RH	CRACKED	552.55	552.55
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-2,320.23	-242.99
			20,882.11	2,186.86
SPECIAL NETT ITEMS				
1	REAR DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NECESSARY	5.00	5.00
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-

Report Ref No. CS/FCI19010518/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	REAR RIGHT TYRE (SN)	NOT NECESSARY	300.00	-
1	REAR RIGHT TYRE RIM (SN)	NOT NECESSARY	380.00	-
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP RH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
			2,042.82	170.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL REAR RH,BOOT REAR,FENDER PANEL REAR RH,BUMPER BEAM REAR,BUMPER BEAM BRACKET RH REAR,TAILLAMP PANEL RH,EXHAUST REAR AND EXHAUST CAP REAR.		4,500.00	400.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	440.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO APPLY PAINT PROTECTION (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			12,520.00	920.00
GRAND TOTAL			35,444.93	3,276.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/FCI19010518/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.