



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/06/2019

User ID : GohKK2

Section A - Accident Details

Registration Number

SG1030U

Case Reference Number

BUS/06/19/1028

Registration Date

15/8/2016

Company Type

SMRT Buses Ltd

Make

MERCEDES

Model

MBOC530

Name of Driver

Tan Siok Lay

Type of Accident

Head To Side

Accident Date and Time

10/6/2019 9:43 PM

Accident Reported Date and Time

11/6/2019 5:15 PM

Is Surveyor Required?

No

Survey by

Vehicle is Towed Back?

No

Towed Back Date and Time

Replacement Vehicle issued?

No

Job Card Number

Special Instruction to ARC,if any

SG1030U - FRONT PORTION  
SJL2666J (TP) - INSURED WITH AXA

Prepared Date and Time

12/6/2019 1:35 PM

Chassis Number

WEB62808323130284

Mileage

Work Shop

Repair Completion Date and Time

Section B - Summary of Repair Estimates

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Cost

\$2,650.00

\$0.00

Total Spray Cost

\$616.00

\$0.00

Total Spare Part Cost

\$9,908.17

\$0.00

Total Other Cost

\$200.00

\$0.00

TOTAL COST

\$13,374.17

\$0.00

Lump Sum Total

\$0.00

\$0.00

Number of Repair Days

7.0


Prepared / Adjusted By

Boon Chew Tay

ARC / Surveyor Sign Off Date

12/06/2019 2:16 PM

Signature



Remarks

Section C - Quotation and Accident Invoice Details

Quotation Number

Invoice Number

Quotation Date

Invoice Date

Invoice Amount

Prepared Date



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/06/2019

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$2,650.00					
Total Labour				\$2,650.00					
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$616.00					
Total Spray Painting & Panel Beating				\$616.00					
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
TOWING CHARGE				\$200.00					
Total Other Costs				\$200.00					
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012457			WIPER ARM COVER	1.00	\$19.50	0.00	\$19.50	Replace	
			FRONT NUMBER PLATE	1.00	\$75.00	0.00	\$75.00	Replace	
			STICKER IU	1.00	\$35.00	0.00	\$35.00	Replace	
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	
6009895	GLASS	6286712210	WINDSCREEN:FRONT,F OR MB CITARO O530	1.00	\$3,887.85	10.00	\$3,499.07	Replace	
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE:DIRECT GLAZING	10.00	\$37.00	0.00	\$370.00	Replace	
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	
6009901	Body	6283850401	BUMPER:FRONT,CENT RE,FOR MB CITARO O530	1.00	\$1,663.80	10.00	\$1,497.42	Replace	
6009904	Body	6288850526	FLAP:FRONT,CENTRE,F OR MB CITARO O530	1.00	\$1,513.05	10.00	\$1,361.74	Replace	
6010189	Body	0007501250	LOCK:FRT BUMPER,FOR MB CITARO BUS	2.00	\$66.00	10.00	\$118.80	Replace	
6010339	BODY RH	6288210244	ARM,WIPER:RH,FOR MB O530 CITARO BUS	1.00	\$567.00	10.00	\$510.30	Replace	
6010340	BODY LH	6288210144	ARM,WIPER:LH,FOR MB O530 CITARO BUS	1.00	\$567.00	10.00	\$510.30	Replace	
6010341	Body		WIPER ARM ASSEMBLY:FOR MBO530 CITARO BUS	1.00	\$1,029.00	10.00	\$926.10	Replace	
6010541	Body		BLADE,WIPER:FOR MB CITARO O530	2.00	\$113.80	10.00	\$204.84	Replace	
6010399			COVERING ;W/SCREEN EDGE,BOTTOM (CITARO)	1.00	\$545.10	0.00	\$545.10	Replace	
Total					\$10,354.10		\$9,908.17		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									