



ASS. REC. BY:

REF: CS/CI 19010540/R14/27

Special Instruction:

rumun

SUNVAJOT Rusu ASSIGNMENT (Office)

From (Person): Ong Chin Kiat of CT2 Date/Time: 14.6.19 9:50.19

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 9BH 6712 Insured: Sam

at Workshop m/s Yong Sing Motor Tel: 91820027 / 90292092 Jooon
of NO 10 Batu Lane

Policy No: DMPCSA 1825731800 Claim No: SAM1AD202032001

Sum Insured: _____ Excess: \$ 350.00

Make of Veh: _____ D.O.A. 6-6-19
(Client's Record)

CA / (REV) / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 14.6.19 10:40am Person Contacted: Sam Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate Inspection: 53 Batu Lane 12
	9BH 6712-x *P/S revert on brake & tyre efficiency and obtain last servicing record.

17/6/19 @ 2:00pm revert to Ong Chin Kiat via Message

20/6/19 @ 10:08am Wong Tay informed via Message.

20/6/19 @ 10:23am Informed Jason c/o S excess \$350 by email.

14/8/19 @ 11:22am re-finalised with Zhi Yang final fig to 4423.05 by email
(Cost to 4091.95, 48%)


REF: 32049

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBH 6712Z
 at Workshop m/s YONK SMK MOTOR
 of S3, DEPAWANE RD
 Insured: CPI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 380
 (Client's Record)
 Make of Veh: _____

Veh No: GBH 6712Z Yr Regn: 2018 / AUG
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA DYNA 1505MT C.C. 2982
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 2296 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFAT 35410K21165
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/75R15
 R: 155R12C

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 62K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 9 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>5/5</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>5/5</u> mm
D.O.A. <u>06/06/19</u>		D.O.I. <u>14/06/19</u>

 Survey held at YONK SMK MOTOR
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TYRE CONDITION checked in good condition
	CHECKED BRAKE CONDITION IS GOOD
	RECEIVED 19 JUL 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 19/7/2019
 Date/Time, File Return to?
 2) _____
 Report Format: REP-01
 Lump Sum / I.B.I.: (\$) 4423.05

Days Of Repair: 9
 Resurvey No. of Trip: 1
 Add Fee: Site Inap (\$))
 Interview (\$))
 Tech. Invs (\$))
 Weekend (\$))

Survey Fee:	<u>220</u>
Transportation:	_____
Photos	_____
Others	_____
TOTAL:	<u>220</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jun 2019		14 Jun 2019 09:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	KIANPLUS GENERAL CONTRACTOR PTE LTD, Co. Reg. No.: 200723284D			[Created by insurer]					
Vehicle Reg. No.:	GBH6712Z	Date of Loss:	06/06/2019 15:00 - :59 [9 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D202532C01	Policy/Cover Note No.:	DMPCSN1825731800 (Comprehensive)						
Repairer:	Yong Sing Motor Works (HQ) No. 10 Defu Lane Singapore 539315, 539315 Defu Lane - Tel: 82677782			Excess: S\$350.00					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/06/2019]								
Driver/Custodian:	TITU MD ABDUR ROB (34 / Male) , NRIC: G7545984Q, Tel: +6581154153 Email: MOHANATITU@YAHOO.COM.SG								
Adj Asg. Remarks:	pls revert on brake & tyre efficiency and obtain last servicing record. thank you.								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
• CHINA_TAIPING (14/06/2019): Cancellation of Assignment: GBH6712Z									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>
Sent: Friday, 19 July 2019 11:37 AM
To: Shiau Chan (LKKAuto); Rasul (LKKAuto)
Cc: Yong Sing; Jason Sim
Subject: RE: Finalise for GBH 6712Z

Hi Shiau Chan,

We accept the finalise amount of \$4,423.05.

With Regards,

Phua Zhi Yang

Operation Supervisor
Mobile: 9101 7563 Fax: 6284 2798
No: 53, Defu Lane 12 Singapore 539144 (Head Office)
No: 10, Defu Lane 8 Singapore 539315



From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Friday, July 19, 2019 11:22:28 AM
To: Rasul (LKKAuto); Zhi Yang Phua
Cc: Yong Sing; Jason Sim
Subject: RE: Finalise for GBH 6712Z

Dear Zhi Yang,

As spoken with you earlier.

Re-finalise final fig \$4,423.05 instead of \$4,467.90.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, 18 July 2019 6:00 PM
To: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>
Cc: Yong Sing <yongsingmotors@gmail.com>; Jason Sim <Jasonsim@yongsingmotor.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: Finalise for GBH 6712Z

Hi Zhi Yang,

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 19 July 2019 11:22 AM
To: Rasul (LKKAuto); Zhi Yang Phua
Cc: Yong Sing; Jason Sim
Subject: RE: Finalise for GBH 6712Z

Dear Zhi Yang,

As spoken with you earlier.

Re-finalise final fig \$4,423.05 instead of \$4,467.90.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, 18 July 2019 6:00 PM
To: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>
Cc: Yong Sing <yongsingmotors@gmail.com>; Jason Sim <Jasonsim@yongsingmotor.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: Finalise for GBH 6712Z

Hi Zhi Yang,

Finalised amount of \$ 4467.90 / 9 days part by part is confirmed


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 *Save the Earth. Print only when necessary.*

From: Zhi Yang Phua [<mailto:ZhiYangPHUA@yongsingmotor.com>]
Sent: Thursday, 18 July, 2019 5:32 PM
To: Rasul (LKKAuto); Admin-D (LKKAuto)
Cc: Yong Sing; Jason Sim
Subject: RE: Finalise for GBH 6712Z

Hi LKK

Shiau Chan (LKKAuto)

From: Rasul (LKKAuto)
Sent: Thursday, 18 July 2019 6:00 PM
To: Zhi Yang Phua
Cc: Yong Sing; Jason Sim; Shiau Chan (LKKAuto)
Subject: RE: Finalise for GBH 6712Z

Hi Zhi Yang,

Finalised amount of \$ 4467.90 / 9 days part by part is confirmed


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

From: Zhi Yang Phua [mailto:ZhiYangPHUA@yongsingmotor.com]
Sent: Thursday, 18 July, 2019 5:32 PM
To: Rasul (LKKAuto); Admin-D (LKKAuto)
Cc: Yong Sing; Jason Sim
Subject: RE: Finalise for GBH 6712Z

Hi LKK

Our COR for the above mentioned vehicle is \$4467.90/- excluding GST.

Part by Part repair job and 09 repair days were given.

Please take note that we are registered with GST.

Please refer to the attachment.

We hope to hear from your confirmation soon. Thank you.

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315

 **YONG SING**
榮興 MOTOR WORKS

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 20 June 2019 10:23 AM
To: jasons@yongsingmotor.com
Cc: SUR
Subject: OD VEHICLE GBH 6712Z (DOA: 06/06/2019)

Dear Jason,

As instructed by our client, please proceed to repair the insured vehicle **GBH 6712Z** at repair cost on part by part basis (Excess \$350/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	14 Jun 2019 09:47	Cim Veh Model Changed	(205738) TOYOTA DYNA 150 3.0 D SMT (M).	[I] Ong Chin Kiat
2	14 Jun 2019 09:47	Cim Created	Reg No: GBH6712Z, Policy No: DMPCSN1825731800, Acct Date: 2019/06/06, Claim Type: OD, Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Yong Sing Motor Works (HQ), Ins.Status => Incoming Claim. Created from SAS: MJAS19074322	[I] Ong Chin Kiat
3	14 Jun 2019 09:53	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[I] Ong Chin Kiat
4	14 Jun 2019 09:53	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/25	[I] Ong Chin Kiat
5	14 Jun 2019 09:53	Adj Mandate Set	Approved:0.00.	[I] Ong Chin Kiat
6	14 Jun 2019 09:54	Adj Assignment Cancelled		[I] Ong Chin Kiat
7	14 Jun 2019 09:54	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Ong Chin Kiat
8	14 Jun 2019 09:55	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):pls revert on brake & tyre efficiency and obtain last servicing record. thank you.	[I] Ong Chin Kiat
9	14 Jun 2019 09:55	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/25	[I] Ong Chin Kiat
10	14 Jun 2019 09:55	Adj Mandate Set	Approved:0.00.	[I] Ong Chin Kiat
11	14 Jun 2019 10:33	Assignment 1st Accessed		[A] LEE SU THING
12	14 Jun 2019 11:37	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] LEE SU THING
13	17 Jun 2019 14:14	Adj Rpt Initiated		[A] SHIAU CHAN
14	17 Jun 2019 14:23	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/06/25	[A] SHIAU CHAN
15	17 Jun 2019 14:24	Adj Mandate Request	Cur.Req:6365.40:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. According to our surveyor, his static tests on the braking system reveal no abnormality. The condition of the tyres were also in serviceable condition with a remaining tread depth of ap	[A] SHIAU CHAN
16	20 Jun 2019 10:08	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/25	[I] Irene Tay Hui Ping
17	20 Jun 2019 10:08	Adj Mandate Set	Approved:6365.40.	[I] Irene Tay Hui Ping

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2179829	17/06/2019 14:14	Motor	LKK Auto Consultants Pte	LKK Auto Consultants Pte	GBH6712Z		11.77

Part 4 - Spare Parts / Material Usage

Item	Part Name	Part No	Qty	Cost Price (\$)	Cost Plus (15%)	Final Price (\$)	Repair @ Replace (/) (Yong Sing Request)	Repair @ Replace (/) (Sueyng Recommendation)
1	FRONT WINDSCREEN	5611137120	1	\$ 450.00	15%	\$ 517.50	Replace	X
2	FRONT WINDSCREEN MOULDING	5612125040	1	\$ 95.00	15%	\$ 109.25	Replace	X
3	WINDSCREEN SEALANT		2	\$ 50.00	15%	\$ 57.50	Replace	X
4	IJ BRACKET		1	\$ 15.00	15%	\$ 17.25	Replace	X
5	FRONT BUMPER	5210125911	1	\$ 210.00	15%	\$ 241.50	Replace	cut /
6	FRONT BUMPER CLIPS	9010608008	10	\$ 10.00	15%	\$ 11.90	Replace	re /
7	FRONT BUMPER REINFORCEMENT		1	\$ 180.00	15%	\$ 207.00	Replace	X
8	COVER, FOG LAMP LH	8148237040	1	\$ 28.00	15%	\$ 32.20	Replace	X
9	FRONT GRILLE	5311137A01B1	1	\$ 180.00	15%	\$ 207.00	Replace	cut /
10	FRONT GRILLE CLIPS	6777137040	10	\$ 25.00	15%	\$ 28.75	Replace	re /
11	FRONT GRILLE EMBLEM		1	\$ 28.00	15%	\$ 32.20	Replace	re /
12	FRONT LH FENDER PANEL	5380237021	1	\$ 85.00	15%	\$ 97.75	Replace	cut /
13	FRONT LH FENDER PANEL CLIPS		4	\$ 4.00	15%	\$ 4.60	Replace	re /
14	FRONT LH DOOR ASSY	6700237322	1	\$ 500.00	15%	\$ 575.00	Replace	blue /
15	FRONT LH OUTER MOULDING	8816237011	1	\$ 35.00	15%	\$ 40.25	Replace	?
16	FRONT LH DOOR SEAL	5380737031	1	\$ 250.00	15%	\$ 287.50	Replace	?
17	FRONT LH DOOR, CHECK ASSY	6861037030	1	\$ 55.00	15%	\$ 63.25	Replace	?
18	FRONT LH DOOR, BRACKET CHECK ASSY	6861837020	1	\$ 40.00	15%	\$ 46.00	Replace	?
19	FRONT LH DOOR UPPER HINGE	6873037010	1	\$ 35.00	15%	\$ 40.25	Replace	?
20	FRONT LH DOOR LOWER HINGE	6871037020	1	\$ 35.00	15%	\$ 40.25	Replace	?
21	FRONT LH DOOR UPPER HINGE BOLT	9011908892	2	\$ 3.00	15%	\$ 3.45	Replace	X
22	FRONT LH DOOR LOWER HINGE BOLT	9011908892	2	\$ 3.00	15%	\$ 3.45	Replace	X
23	FRONT LH DOOR INNER WEATHERSTRIP	6231437040B0	1	\$ 55.00	15%	\$ 63.25	Replace	re /
24	FRONT LH DOOR LOCK ASSY	6932037050	1	\$ 90.00	15%	\$ 103.50	Replace	X
25	FRONT LH DOOR WINDOW REGULATOR ASSY	6880237052	1	\$ 90.00	15%	\$ 103.50	Replace	?
26	FRONT LH INNER DOOR TRIM BOARD	6762037180B5	1	\$ 130.00	15%	\$ 149.50	Replace	?
27	FRONT LH INNER DOOR TRIM CLIPS	9046707071B0	10	\$ 10.00	15%	\$ 11.50	Replace	re /
28	FRONT LH HEADLAMP ASSY	8115025221	1	\$ 290.00	15%	\$ 333.50	Replace	sea /
29	REAR LHS BODY DECK PANEL	6560020061	1	\$ 1,500.00	15%	\$ 1,725.00	Replace	blue /
30	REAR LHS BODY DECK LATCH	6615428010	1	\$ 40.00	15%	\$ 46.00	Replace	X
31	REAR LHS BODY DECK SUPPORT	6601425010	1	\$ 35.00	15%	\$ 40.25	Replace	X
33	STICKER COMPANY UNDERTAKING		2	\$ 15.00	15%	\$ 17.25	Replace	re /
34	PLATE, FRONT DYNA EMBLEM	7531125070	1	\$ 25.00	15%	\$ 28.75	Replace	re /
35	PLATE, DOOR TOYOTA D4D EMBLEM	7536235090	1	\$ 24.00	15%	\$ 27.60	Replace	re /
36	FRONT LHS MIRROR ASSY		1	\$ 180.00	15%	\$ 189.75	Replace	cut /
				TOTAL MATERIALS	\$ 4,785.00	\$ 5,502.75		

* -> pls ensure parts replaced brand new. Most likely replaced used with condition 80-90%. Parts price will be much more cheaper, Two Sides and One Rear Deck Support cost less than \$500/-.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 17 Jun 2019

Preliminary Advice

Vehicle No	: GBH6712Z	Accident Date	: 06/06/2019
Make	: TOYOTA DYNA 150	Policy No.	: DMPCSN1825731800
Assignment Date	: 14/06/2019	Excess	: S\$350.00
Date of Inspection	: 14/06/2019	Est. Duration of Repair	: 9.00
Inspection At	: YONG SING MOTOR WORKS (HQ) NO. 10 DEFU LANE SINGAPORE 539315 SINGAPORE 539315		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,515.00
Revised Amount	:S\$	5,594.90
Check Items (Estimated)	:S\$	770.50
Total	:S\$	6,365.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	23,808.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,192.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : According to our surveyor, his static tests on the braking system reveal no abnormality. The condition of the tyres were also in serviceable condition with a remaining tread depth of approximately 6/6mm of front tyres and 5/5/5 of rear tyres. We are pending for servicing record from repairer.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details

Owner ID Type:	Company
Owner ID:	3284D

Vehicle Details

Vehicle No.:	GBH6712Z
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2814436
Chassis No.:	JTFAT35Y10K211165
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	20 Aug 2018
First Registration Date:	20 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$1,355.00

Income Tax Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	19 Aug 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$25,958.00
COE Rebate Amount:	\$23,808.00
Total Rebate Amount:	\$23,808.00

The information contained herein is correct as at 17 Jun 2019

OK

62,000
23,808

38,192

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/06/2019 15:27
Date Of Accident	06/06/2019 15:55
Exact Location Of Accident	AYE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH6712Z
Insured/Policyholder	
Name Of Registered Owner	KIANPLUS GENERAL CONTRACTOR PTE LTD
Co Reg No	200723284D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94573068
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1825731800
Cover Note Number	
Driver	
Name of Driver	TITU MD ABDUR ROB
Passport No/FIN	G7545984Q
Date Of Birth	25/03/1985
Occupation	OUTDOOR
Date Of Driving Pass	23/07/2010
Driving Experience	8 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81154153
Fax Number	
Contact Number	
E-Mail Address	MOHANATITU@YAHOO.COM.SG

Address	31B LOR 22 GEYLANG
Postcode	398688
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEHICLE B WAS ON MY LEFT. VEHICLE INFRONT OF ME SUDDENLY STOPPED. I BRAKED AND MY LORRY SKIDDED AND HIT VEHICLE B'S RIGHT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN561C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3



Passenger 1

NAME: :
GENDER: : MALE

Passenger 2

NAME: :
GENDER: : MALE

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **regulate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will and be collected and used to compile claims history for the purpose of fraud detection, investigation and management in respect and of future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
 Date & Time: 7-6-19 14:20 hr




Driver's Signature
 (if driver is not the policyholder)
 Date & Time: 7-6-19 14:20 hr

Reporting Centre Personnel's Signature
 Name: [Signature]
 NRIC/PPN No.:

Sketch Plan #2

SKETCH PLAN



DOA - 6-6-19

A: GEM 67123

E: JNEBIC

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

VEHICLE B WAS IN MY LEFT.

VEHICLE IN FRONT OF ME (SUDDENLY) STOPPED.
BRAKED

I BRAKED AND MY LORRY SKIDED AND HIT VEHICLE B'S
RIGHT PORTION.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



 Police Officer's Signature
 Date & Time: 7-6-19 14:20 hr


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 7-6-19 14:20 hr


 Reporting Centre Personnel's Signature
 Name: JODI KARA JAIN
 RHC/TIN No.:

Yong Sing Estimate Repair

Vehicle Registration Number	GBH6712Z	Case Ref No.	YS/19/0055
Make / Model	Toyota Dyna 150 5MT	The damages on the vehicle are as indicated in the following diagram:	
Chassis No	JTFAT35Y10K211'05		
Year of Manufacture	2018		
Registration Date	20-Aug-18		
Type of Repair (TP/OD/WS)	OD		
Date/Time of Accident	6 June 2019 / 15:55 hrs		
Rental Vehicle	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Remark	OD, China Importing under Any Workshop		

	Yong Sing estimate breakdown cost	Adjusted by Surveyor, if applicable
Total Labour Cost	\$ 1,800.00	\$ -
Total Spray Painting Cost	\$ 1,050.00	\$ -
Total Spare Parts Cost	\$ 4,785.00	\$ 5,502.75
Other Charges	\$ 880.00	\$ -
TOTAL	\$ 8,515.00	\$ 5,502.75
Lump Sum Repair, if any		
No. of Repair Days	[5] days	[5] days

SURVEYOR'S Remark

RASUL
HP 90010068
9 days
P/P
14/06/19 @ 1445 hrs
EXCESS: 350
Reveal
Resing before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey only after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Part 1 - Labour & Panel Beating Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO PROVIDE LABOUR FOR PANEL BEAT AT LHS ACCIDENT PORTION. TO REMOVE AND REFIT REAR DECK PANEL. STRAIGHTEN AND ALIGN ALL DAMAGE PARTS	\$1,800.00	1100
Total Labour Cost	\$1,800.00	\$0.00

Part 2 - Spray Painting Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
SPRAY PAINT FRONT GRILLE	\$150.00	100
SPRAY PAINT FRONT BUMPER	\$300.00	200
SPRAY PAINT FRONT LH DOOR	\$300.00	200
SPRAY PAINT REAR LHS DECK PANEL	\$300.00	200
Total Spray Painting Cost	\$1,050.00	\$0.00

Part 3 - Other Costs - Accident Repair Related Expenses

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO REPLACE FRONT WINDSCREEN	\$250.00	X 11
TO REMOVE AND REFIT DOOR MECHANISM	\$250.00	80
TO PROVIDE ANTI RUST COATING	\$150.00	60
TO CONDUCT WIRE CHECKING	\$50.00	30
TO VACCUMM AND CLEAN ON INTERIOR	\$80.00	X 11
TO CHECK WATER LEAKAGE ON INSTALLED PARTS	\$100.00	30
Total Other Costs	\$880.00	\$0.00

Part 4 - Spare Parts / Material Usage

Item	Part Name	Part No	Qty	Cost Price (\$)	Cost Plus (15%)	Final Price (\$)	Repair @ Replace (/) (Yong Sing Request)	Repair @ Replace (/) (Surveyor's Recommendation)
1	FRONT WINDSCREEN	5611137120	1	\$ 450.00	15%	\$ 517.50	Replace	X
2	FRONT WINDSCREEN MOULDING	5612125040	1	\$ 95.00	15%	\$ 109.25	Replace	X
3	WINDSCREEN SEALANT		2	\$ 50.00	15%	\$ 57.50	Replace	X } m
4	IU BRACKET		1	\$ 15.00	15%	\$ 17.25	Replace	X } m
5	FRONT BUMPER	5210125911	1	\$ 210.00	15%	\$ 241.50	Replace	cut /
6	FRONT BUMPER CLIPS	9010608008	10	\$ 10.00	15%	\$ 11.50	Replace	no / X FROM
7	FRONT BUMPER REINFORCEMENT		1	\$ 180.00	15%	\$ 207.00	Replace	X } aa
8	COVER, FOG LAMP LH	8148237040	1	\$ 28.00	15%	\$ 32.20	Replace	X } aa
9	FRONT GRILLE	5311137A01B1	1	\$ 180.00	15%	\$ 207.00	Replace	cut /
10	FRONT GRILLE CLIPS	6777137040	10	\$ 25.00	15%	\$ 28.75	Replace	no /
11	FRONT GRILLE EMBLEM		1	\$ 28.00	15%	\$ 32.20	Replace	no /
12	FRONT LH FENDER PANEL	5380237021	1	\$ 85.00	15%	\$ 97.75	Replace	cut /
13	FRONT LH FENDER PANEL CLIPS		4	\$ 4.00	15%	\$ 4.60	Replace	no / m
14	FRONT LH DOOR ASSY	6700237322	1	\$ 500.00	15%	\$ 575.00	Replace	bucc /
15	FRONT LH OUTER MOULDING	6816237011	1	\$ 35.00	15%	\$ 40.25	Replace	?
16	FRONT LH DOOR SEAL	5386737031	1	\$ 250.00	15%	\$ 287.50	Replace	?
17	FRONT LH DOOR, CHECK ASSY	6861037030	1	\$ 55.00	15%	\$ 63.25	Replace	?
18	FRONT LH DOOR, BRACKET CHECK ASSY	6861837020	1	\$ 40.00	15%	\$ 46.00	Replace	?
19	FRONT LH DOOR UPPER HINGE	6873037010	1	\$ 35.00	15%	\$ 40.25	Replace	?
20	FRONT LH DOOR LOWER HINGE	6871037020	1	\$ 35.00	15%	\$ 40.25	Replace	?
21	FRONT LH DOOR UPPER HINGE BOLT	9011908892	2	\$ 3.00	15%	\$ 3.45	Replace	X } m
22	FRONT LH DOOR LOWER HINGE BOLT	9011908892	2	\$ 3.00	15%	\$ 3.45	Replace	X } m
23	FRONT LH DOOR INNER WEATHERSTRIP	6231437040B0	1	\$ 55.00	15%	\$ 63.25	Replace	no /
24	FRONT LH DOOR LOCK ASSY	6932037060	1	\$ 90.00	15%	\$ 103.50	Replace	X succ
25	FRONT LH DOOR WINDOW REGULATOR ASSY	6980237062	1	\$ 90.00	15%	\$ 103.50	Replace	?
26	FRONT LH INNER DOOR TRIM BOARD	6762037180B5	1	\$ 130.00	15%	\$ 149.50	Replace	?
27	FRONT LH INNER DOOR TRIM CLIPS	9046707071B6	10	\$ 10.00	15%	\$ 11.50	Replace	no / m
28	FRONT LH HEADLAMP ASSY	8115025221	1	\$ 290.00	15%	\$ 333.50	Replace	succ /
29	REAR LHS BODY DECK PANEL	6560028061	1	\$ 1,500.00	15%	\$ 1,725.00	Replace	bucc /
30	REAR LHS BODY DECK LATCH	6615426010	1	\$ 40.00	15%	\$ 46.00	Replace	X } succ
31	REAR LHS BODY DECK SUPPORT	6601425010	1	\$ 35.00	15%	\$ 40.25	Replace	X } succ
33	STICKER COMPANY UNDERTAKING		2	\$ 15.00	15%	\$ 17.25	Replace	no / m
34	PLATE, FRONT DYNA EMBLEM	7531125070	1	\$ 25.00	15%	\$ 28.75	Replace	no /
35	PLATE, DOOR TOYOTA D4D EMBLEM	7536235090	1	\$ 24.00	15%	\$ 27.60	Replace	no /
36	FRONT LHS MIRROR ASSY		1	\$ 185.00	15%	\$ 189.75	Replace	cut /
				TOTAL MATERIALS \$ 4,785.00		\$ 5,502.75		

Yong Sing Estimate Repair

Vehicle Registration Number	: <u>GBH6712Z</u>	Case Ref. No.	: <u>YS/19/0055</u>
Make / Model	: <u>Toyota Dyna 150 SMT</u>	The damages on the vehicle are as indicated in the following diagram :	
Chassis No	: <u>JTFAT35Y10K211165</u>		
Year of Manufacture	: <u>2018</u>		
Registration Date	: <u>20-Aug-18</u>		
Type of Repair (TP/OD/WS)	: <u>OD</u>		
Date/Time of Accident	: <u>6 June 2019 / 15:55 hrs</u>		
Rental Vehicle	: Yes <input type="radio"/> No <input checked="" type="radio"/>		
Remark	: <u>OD, China Taiping under Any Workshop</u>		

	Yong Sing estimate breakdown cost	Adjusted by Surveyor, if applicable
Total Labour Cost	\$ <u>1,800.00</u>	\$ <u>1,100.00</u>
Total Spray Painting Cost	\$ <u>1,050.00</u>	\$ <u>700.00</u>
Total Spare Parts Cost	\$ <u>3,735.00</u>	\$ <u>2,467.90</u>
Other Charges	\$ <u>880.00</u>	\$ <u>200.00</u>
TOTAL	\$ <u>7,465.00</u>	\$ <u>4,467.90</u>
Lump Sum Repair, if any : _____		
No. of Repair Days	: [10] days	[9] days

SURVEYOR'S Remark

Rasul (LKK)
 hp: 90010068
 part by part
 14/6/19 1445hrs
 resurvey before paint

Steve (resurvey)
 21/6/19 1530hrs

Part 1 - Labour & Panel Beating Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO PROVIDE LABOUR FOR PANEL BEAT AT LHS ACCIDENT PORTION. TO REMOVE AND REFIT REAR DECK PANEL, STRAIGHTEN AND ALIGN ALL DAMAGE PARTS	\$1,800.00	\$1,100.00
Total Labour Cost	\$1,800.00	\$1,100.00

Part 2 - Spray Painting Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
SPRAY PAINT FRONT GRILLE	\$150.00	\$100.00
SPRAY PAINT FRONT BUMPER	\$300.00	\$200.00
SPRAY PAINT FRONT LH DOOR	\$300.00	\$200.00
SPRAY PAINT REAR LHS DECK PANEL	\$300.00	\$200.00
Total Spray Painting Cost	\$1,050.00	\$700.00

Part 3 - Other Costs - Accident Repair Related Expenses

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO REPLACE FRONT WINDSCREEN	\$250.00	\$0.00
TO REMOVE AND REFIT DOOR MECHANISM	\$250.00	\$80.00
TO PROVIDE ANTI RUST COATING	\$150.00	\$60.00
TO CONDUCT WIRE CHECKING	\$50.00	\$30.00
TO VACCUMM AND CLEAN ON INTERIOR	\$80.00	\$0.00
TO CHECK WATER LEAKAGE ON INSTALLED PARTS	\$100.00	\$30.00
Total Other Costs	\$880.00	\$200.00

Part 4 - Spare Parts / Material Usage

Item	Part Name	Part No	Qty	Cost Price (\$)	Cost Plus (15%)	Final Price (\$)	Repair @ Replace (/) (Yong Sing Request)	Repair @ Replace (/) (Surveyor Recommend)
1	FRONT WINDSCREEN	5611137120	1	\$ 450.00	15%	\$ 517.50	Replace	Not Given
2	FRONT WINDSCREEN MOULDING	5612125040	1	\$ 95.00	15%	\$ 109.25	Replace	Not Given
3	WINDSCREEN SEALANT		2	\$ 50.00	15%	\$ 57.50	Replace	Not Given
4	IU BRACKET		1	\$ 15.00	15%	\$ 17.25	Replace	Not Given
5	FRONT BUMPER	5210125911	1	\$ 210.00	15%	\$ 241.50	Replace	Replace
6	FRONT BUMPER CLIPS	9010608008	10	\$ 10.00	15%	\$ 11.50	Replace	Replace
7	FRONT BUMPER REINFORCEMENT		1	\$ 180.00	15%	\$ 207.00	Replace	Not Given
8	COVER, FOG LAMP LH	8148237040	1	\$ 28.00	15%	\$ 32.20	Replace	Not Given
9	FRONT GRILLE	5311137AD1B1	1	\$ 180.00	15%	\$ 207.00	Replace	Replace
10	FRONT GRILLE CLIPS	6777137040	10	\$ 25.00	15%	\$ 28.75	Replace	Replace
11	FRONT GRILLE EMBLEM		1	\$ 28.00	15%	\$ 32.20	Replace	Replace
12	FRONT LH FENDER PANEL	5380237021	1	\$ 85.00	15%	\$ 97.75	Replace	Replace
13	FRONT LH FENDER PANEL CLIPS		4	\$ 4.00	15%	\$ 4.60	Replace	Replace
14	FRONT LH DOOR ASSY	6700237322	1	\$ 500.00	15%	\$ 575.00	Replace	Replace
15	FRONT LH OUTER MOULDING	6816237011	1	\$ 35.00	15%	\$ 40.25	Replace	Not Given
16	FRONT LH DOOR SEAL	5386737031	1	\$ 250.00	15%	\$ 287.50	Replace	Not Given
17	FRONT LH DOOR, CHECK ASSY	6861037030	1	\$ 55.00	15%	\$ 63.25	Replace	Not Given
18	FRONT LH DOOR, BRACKET CHECK ASSY	6861837020	1	\$ 40.00	15%	\$ 46.00	Replace	Not Given
19	FRONT LH DOOR UPPER HINGE	6873037010	1	\$ 35.00	15%	\$ 40.25	Replace	Replace
20	FRONT LH DOOR LOWER HINGE	6871037020	1	\$ 35.00	15%	\$ 40.25	Replace	Replace
21	FRONT LH DOOR UPPER HINGE BOLT	9011908892	2	\$ 3.00	15%	\$ 3.45	Replace	Not Given
22	FRONT LH DOOR LOWER HINGE BOLT	9011908892	2	\$ 3.00	15%	\$ 3.45	Replace	Not Given
23	FRONT LH DOOR INNER WEATHERSTRIP	6231437040B0	1	\$ 55.00	15%	\$ 63.25	Replace	Replace
24	FRONT LH DOOR LOCK ASSY	6932037060	1	\$ 90.00	15%	\$ 103.50	Replace	Not Given
25	FRONT LH DOOR WINDOW REGULATOR ASSY	6980237062	1	\$ 90.00	15%	\$ 103.50	Replace	Not Given
26	FRONT LH INNER DOOR TRIM BOARD	6762037180B5	1	\$ 130.00	15%	\$ 149.50	Replace	Not Given
27	FRONT LH INNER DOOR TRIM CLIPS	9046707971B5	10	\$ 10.00	15%	\$ 11.50	Replace	Replace
28	FRONT LH HEADLAMP ASSY	8115025221	1	\$ 290.00	15%	\$ 333.50	Replace	Replace
29	REAR LHS BODY DECK PANEL	6560026061	1	\$ 450.00	15%	\$ 517.50	Replace	Replace
30	REAR LHS BODY DECK LATCH	6615426010	1	\$ 40.00	15%	\$ 46.00	Replace	Not Given
31	REAR LHS BODY DECK SUPPORT	6601425010	1	\$ 35.00	15%	\$ 40.25	Replace	Not Given
33	STICKER COMPANY UNDERTAKING		2	\$ 15.00	15%	\$ 17.25	Replace	Replace
34	PLATE, FRONT DYNA EMBLEM	7531125070	1	\$ 25.00	15%	\$ 28.75	Replace	Replace
35	PLATE, DOOR TOYOTA D4D EMBLEM	7536235090	1	\$ 24.00	15%	\$ 27.60	Replace	Replace
36	FRONT LHS MIRROR ASSY		1	\$ 165.00	15%	\$ 189.75	Replace	Replace
				TOTAL MATERIALS	\$ 3,735.00	\$ 4,295.25	\$2,467.90	



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
 48A SUNGEI KADUT AVE SINGAPORE 729672
 TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
 GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
 Dept Direct: 6417 9791 / 8748 8828



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
 Forch (Made in Germany)
 Spark plug: Nippon Denso, NGK (Made in Japan)

CASH SALES

CASH

TAX INVOICE : AR201906-0967
 DATE : 20/06/2019
 CUSTOMER ID : CAS00
 VEH REG. NO. : GBH6712
 TERMS : CAS
 PO NO. :
 PAGE NO. : Page 1 of
 CURR : SGI

ATTN : JASON 90292277
 NO.53 DEFU LANE 12

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUN
1	T52101-37985 KDY231 17"	FRT BUMPER	CC C13-F2-5B	1	210.00	210.00
2	T53111-37A01-A0 KDY231 17"	FRT GRILLE	CC CC12-I-01D	1	180.00	180.00
3	T67771-37040 KDY231 17"	FRT GRILLE CLIP	CC CC12-N-1B10	10	2.50	25.00
4	T75315-37080 KDY231 17"	FRT EMBLEM	CC CC12-O-3B10	1	28.00	28.00
5	T53814-37100-A0 KDY231 17"	FRT SIDE PANEL LH	CC CC12-O-04C2	1	85.00	85.00
6	T67002-37322 LY235 KDY231	FRT DOOR LH	CC CC12-A-09A	1	500.00	500.00
7	T67862-37020/1 KDY231 LY235	DOOR RUBBER LH	CC CC12-O-10B3	1	55.00	55.00

CONTINUE NEXT PAGE

[P] 20/06/2019 12:07:05

[E] 20/06/2019 11:57:01A

Goods Sold are not refundable for Cash.
 Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6742 9031



Wiper blade: NWS (Nippon Wiper blade), Silper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

CASH SALES

CASH

TAX INVOICE : AR201906-096
DATE : 20/06/20
CUSTOMER ID : CAS0
VEH REG. NO. : GBH671
TERMS : CAS
PO NO. :
PAGE NO. : Page 2 of
CURR : SC

ATTN : JASON 90292277
NO.53 DEFU LANE 12

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8.	T81170-37660 KDY231 17"	HEAD LAMP LH	CC CC12-H-02C	1	290.00	290.
9.	T75311-25100 KDY231 17"	FRT PANEL (DYNA) EMBLEM	CC CC12-N-03B1	1	25.00	25.

891360

TO COLLECT : 1,495.86

SUB-TOTAL : 1,398.00
ADD GST 7.00 % 97.86

E. & O.E TOTAL AMOUNT SGD : 1,495.86

[P] 20/06/2019 12:07:05

[E] 20/06/2019 11:57:01AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.
Sales Executive: STEVEN



This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL

日美汽車私人有限公司


JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
 48A SUNGEI KADUT AVE SINGAPORE 729672
 TEL: 6385 1255 FAX: 6385 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
 Forch (Made in Germany)
 Spark plug: Nippon Denso, NGK (Made in Japan)

CASH SALES

CASH

ATTN : JASON 9029 2277
 NO.53 DEFU LANE 12

TAX INVOICE : AR201906-0968
 DATE : 20/06/2019
 CUSTOMER ID : CAS001
 VEH REG. NO. : GBH67122
 TERMS : CASE
 PO NO. :
 PAGE NO. : Page 1 of 1
 CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	T75362-35090 KDY231	EMBLEM (D4-D) ✓	U1 L2-ZZ-10	1	24.00	24.00
2	T87905-37122 KDY231 17"	SIDE MIRROR I.H ✓	U1	1	165.00	165.00
SUPPLIER						

TO COLLECT : 202.23

SUB-TOTAL : 189.00
 ADD GST 7.00 % 13.20

E. & O.E TOTAL AMOUNT SGD : 202.20

[P] 20/06/2019 12:09:31PM

[E] 20/06/2019 12:02:29PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte. Ltd.
 Sales Executive STEVEN



This is computer generated document.
 No signature is required.

Goods Received in Good Order

Signature / Co. Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Kor
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

CASH SALES

ATTN : JASON 90292277
NO.53 DEFU LANE 12

TAX INVOICE : AR201906-104
DATE : 21/06/2019
CUSTOMER ID : CASO
VEH REG. NO. : GBH671
TERMS : CA
PO NO. :
PAGE NO. : Page 1 o
CURR. : S

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOU
1.	T65600-26060/61 LY235	SIDE GATE LH	WH W	1	450.00	450
2.	T68730-37010 LY235 DYNA'02	DR HINGE LWR RH/UPPER LH	WH W	1	35.00	35
3.	T68710-37020 LY235 DYNA'02	FRT DOOR UPPER HINGE RH	WH W	1	35.00	35

TO COLLECT : 556.40

SUB-TOTAL : 520.00
ADD GST 7.00% : 36.40

E. & O.E TOTAL AMOUNT SGD : 556.40

[P] 21/06/2019 2:25:56PM [E] 21/06/2019 2:20:45PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : STEVEN



Goods Received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jun 2019		14 Jun 2019 09:55 Edit Adj Rpt	S\$4,423.05 Edit Estimates	S\$4,423.05 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KIANPLUS GENERAL CONTRACTOR PTE LTD , Co. Reg. No.: 200723284D								
Vehicle Reg. No.:	GBH6712Z	Date of Loss:	06/06/2019 15:00 - :59 [9 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D202532C01	Policy/Cover Note No.:	DMPCSN1825731800 (Comprehensive)						
		Excess:	S\$350.00						
Repairer:	Yong Sing Motor Works (HQ) No. 10 Defu Lane Singapore 539315, 539315 Defu Lane - Tel: 82677782								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 25/06/2019]								
Driver/Custodian:	TITU MD ABDUR ROB (34 / Male) , NRIC: G7545984Q, Tel: +6581154153 Email: MOHANATTITU@YAHOO.COM.SG								
Adj Asg. Remarks:	pls revert on brake & tyre efficiency and obtain last servicing record. thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • CHINA_TAIPING (20/06/2019): Alert - Adj Mandate Approved (S\$6365.40) - GBH6712Z - Claim Handler: Ong Chin Ki... • CHINA_TAIPING (14/06/2019): Cancellation of Assignment: GBH6712Z 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH6712Z (SNM19D202532C01)
 OD
 Jun 6 2019 3:00PM
 [KIANPLUS GENERAL CONTRACTOR PTE LTD]
 Yong Sing Motor Works

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Assessment Reports									1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)						Thumbnail	Print		
1	07/06/19 15:54	Accident Statement						Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	17/06/19 14:23	Adjuster Immediate Advice						Load HTM			
Photos/Images									3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	17/06/19 14:05	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>		
2	17/06/19 14:05	Chassis Number						Load JPG	<input checked="" type="checkbox"/>		
3	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
4	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
5	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
6	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
7	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
8	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
9	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
10	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
11	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
12	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
13	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
14	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
15	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
16	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
17	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
18	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
19	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
20	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
21	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
22	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
23	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
24	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
25	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
26	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
27	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
28	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
29	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
30	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
31	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
32	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
33	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		
34	17/06/19 14:05	General View						Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
36	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
37	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
38	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
39	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
40	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
41	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
42	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
43	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
44	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
45	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
46	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
47	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
48	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
49	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
50	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
51	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
52	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
53	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
54	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
55	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
56	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
57	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
58	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
59	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
60	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
61	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
62	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
63	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
64	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
65	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
66	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
67	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
68	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
69	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
70	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
71	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
72	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
73	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
74	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
75	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
76	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
77	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
78	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
79	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
80	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
81	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
82	17/06/19 14:05	General View	Load JPG	<input checked="" type="checkbox"/>
83	19/06/19 15:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
84	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
85	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
86	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
87	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
88	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
89	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
90	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
91	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
92	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
93	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
94	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
95	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
96	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
97	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
98	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
99	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
100	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
101	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
102	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
103	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
104	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
105	19/06/19 15:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	14/06/19 09:49	Estimate - GBH6712Z	1	Load PDF	
2	14/06/19 09:53	PARF_COE Rebate - GBH6712Z	1	Load PDF	
3	18/06/19 12:35	Revised Estimate	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/06/19 14:08	ESTIMATE	1	Load PDF	
2	18/06/19 13:41	AMENDMENT GIA REPORT	1	Load PDF	
3	22/07/19 09:39	Parts Invoice	1	Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	07/06/19 15:54	Accident Statement	1	Load HTM	
2	17/06/19 15:18	Addendum Sheet	1	Load JPG	<input checked="" type="checkbox"/>
3	17/06/19 15:19	Accident Statement Addm. #1	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	07/06/19 15:51	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	07/06/19 15:51	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	07/06/19 15:51	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	07/06/19 15:51	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	07/06/19 15:51	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	07/06/19 15:51	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	07/06/19 15:51	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	07/06/19 15:51	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	07/06/19 15:51	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
				<input checked="" type="checkbox"/>
10	07/06/19 15:51	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	07/06/19 15:51	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	07/06/19 15:51	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	07/06/19 15:51	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	07/06/19 15:51	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	07/06/19 15:51	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	07/06/19 15:51	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	07/06/19 15:50	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	07/06/19 15:50	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	07/06/19 15:50	Sketch Plan #3	Load JPG	<input checked="" type="checkbox"/>
4	07/06/19 15:50	Sketch Plan #4	Load JPG	<input checked="" type="checkbox"/>
5	07/06/19 15:50	Sketch Plan #5	Load JPG	<input checked="" type="checkbox"/>
6	07/06/19 15:53	AUTHORISATION LETTER	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119010540/R1QD3E2

Date: 22/07/2019

REFERENCE

Insured/Claimant:	KIANPLUS GENERAL CONTRACTOR PTE LTD	Policy No:	DMPCSN1825731800
Date of Loss:	06/06/2019	Nature of Claim:	OD
		Claim No:	SNM19D202532C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH6712Z	Engine No:	1KD2814436
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y10K211165
Reg. Date:	20/08/2018 (Man. Year: 2018)	Odometer:	22996 km
Colour:	Grey		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$62,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12C (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 5/5 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,785.00	2,423.05	2,361.95	49.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	2,000.00	1,730.00	46.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,515.00	4,423.05	4,091.95	48.06
- Excess (S\$)	350.00	350.00	0.00	0.00
(S\$)	8,165.00	4,073.05	4,091.95	50.12
+ GST 7.00/7.00% (S\$)	571.55	285.11	286.44	50.12
Nett Amount (S\$)	8,736.55	4,358.16	4,378.39	50.12

INSPECTION

Date of Assignment:	14/06/2019	Inspected At:	Yong Sing Motor Works (HQ) 10 DEFU LANE 8 DEFU INDUSTRIAL ESTATE SINGAPORE 539315
Date Inspected:	14/06/2019		
Estimated Period of Repair:	9.0 days		

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Jul 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH6712Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Not Necessary	450.00 F	*- F
2	1		*FRONT WINDSCREEN MOULDING	Not Necessary	95.00 F	*- F
3	2		*WINDSCREEN SEALANT	Not Necessary	50.00 F	*- F
4	1		*IU BRACKET	Not Necessary	15.00 F	*- F
5	1		*FRONT BUMPER	Cut	210.00 F	*210.00 F
6	10		*FRONT BUMPER CLIPS	Not Necessary	10.00 F	*- F
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	180.00 F	*- F
8	1		*COVER, FOG LAMP LH	Not Necessary	28.00 F	*- F
9	1		*FRONT GRILLE	Cracked	180.00 F	*180.00 F
10	10		*FRONT GRILLE CLIPS	Necessary	25.00 F	*25.00 F
11	1		*FRONT GRILLE EMBLEM	Necessary	28.00 F	*28.00 F
12	1		*FRONT LH FENDER PANEL	Cracked	85.00 F	*85.00 F
13	4		*FRONT LH FENDER PANEL CLIPS	Not Necessary	4.00 F	*- F
14	1		*FRONT LH DOOR ASSY	Buckled	500.00 F	*500.00 F
15	1		*FRONT LH OUTER MOULDING	Not Necessary	35.00 F	*- F
16	1		*FRONT LH DOOR SEAL	Not Necessary	250.00 F	*- F
17	1		*FRONT LH DOOR, CHECK ASSY	Not Necessary	55.00 F	*- F
18	1		*FRONT LH DOOR, BRACKET CHECK ASSY	Not Necessary	40.00 F	*- F
19	1		*FRONT LH DOOR UPPER HINGE	Bent	35.00 F	*35.00 F
20	1		*FRONT LH DOOR LOWER HINGE	Bent	35.00 F	*35.00 F
21	2		*FRONT LH DOOR UPPER HINGE BOLT	Not Necessary	3.00 F	*- F
22	2		*FRONT LH DOOR LOWER HINGE BOLT	Not Necessary	3.00 F	*- F
23	1		*FRONT LH DOOR INNER WEATHERSTRIP	Necessary	55.00 F	*55.00 F
24	1		*FRONT LH DOOR LOCK ASSY	Serviceable	90.00 F	*- F
25	1		*FRONT LH DOOR WINDOW REGULATOR ASSY	Serviceable	90.00 F	*- F
26	1		*FRONT LH INNER DOOR TRIM BOARD	Serviceable	130.00 F	*- F
27	10		*FRONT LH INNER DOOR TRIM CLIPS	Not Necessary	10.00 F	*- F
28	1		*FRONT LH HEADLAMP ASSY	Scratched	290.00 F	*290.00 F
29	1		*REAR LHS BODY DECK PANEL	Buckled	1,500.00 F	*450.00 F
30	1		*REAR LHS BODY DECK LATCH	Serviceable	40.00 F	*- F
31	1		*REAR LHS BODY DECK SUPPORT	Serviceable	35.00 F	*- F
32	2		*STICKER COMPANY UNDERTAKING	Not Necessary	15.00 F	*- F
33	1		*PLATE, FRONT DYNA EMBLEM	Necessary	25.00 F	*25.00 F
34	1		*PLATE, DOOR TOYOTA D4D EMBLEM	Necessary	24.00 F	*24.00 F
35	1		*FRONT LHS MIRROR ASSY	Cut	165.00 F	*165.00 F

F=Franchise part.

Sub Total (S\$)	4,785.00	2,107.00
+ Margin on L,N Items 0.00/15.00% (S\$)	0.00	316.05
Total Parts (S\$)	4,785.00	2,423.05

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE LABOUR FOR PANEL BEAT AT LHS ACCIDENT PORTION. TO REMOVE AND REFIT REAR DECK PANEL, STRAIGHTEN AND ALIGN ALL DAMAGE PARTS.	New	1,800.00	1,100.00
2	SPRAY PAINT FRONT GRILLE.	New	150.00	100.00
3	SPRAY PAINT FRONT BUMPER.	New	300.00	200.00
4	SPRAY PAINT FRONT LH DOOR.	New	300.00	200.00
5	SPRAY PAINT REAR LHS DECK PANEL.	New	300.00	200.00
6	TO REPLACE FRONT WINDSCREEN.	New	250.00	0.00
7	TO REMOVE AND REFIT DOOR MECHANISM.	New	250.00	80.00
8	TO PROVIDE ANTI RUST COATING.	New	150.00	60.00
9	TO CONDUCT WIRE CHECKING.	New	50.00	30.00
10	TO VACUUM AND CLEAN ON INTERIOR	New	80.00	0.00
11	TO CHECK WATER LEAKAGE ON INSTALLED PARTS.	New	100.00	30.00
Gross Labour Cost (S\$)			3,730.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >