

ASS. REC. BY:

REF: CS/FCI 1900552/J's d302 Special Instruction:

Surveyor: Hwz Jix

ASSIGNMENT (Office)

From (Person): Gilken Lee of rei Date/Time: 5:22pm @ 13/6/19

Estimated Cost: _____ Bill to: _____

OP / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMH 3445J Insured: SHC 2698Mat Workshop m/s Kah Motor Tel: 8288 6302of 6 * Mendai EstatePolicy No: _____ Claim No: D19003800MPSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 8/5/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 10:23am @ 14/6/19 Person Contacted: Thilken Vehicle: IN/OUT

Date/Time	Action/Instruction
	<u>Estimate</u> ✓
	<u>SMH 3445J - x</u>
	<u>SHC 2698M - x</u>
<u>18/06/19</u>	<u>@ 14:49 pm revised PA to Gilken via email.</u>

ASS. REC. BY:

Husee Jie

REF: FCI

ASSIGNMENT

From

Date:

17/6/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMH 3445J

at Workshop m/s

Kah Motor

of

GA Mondai Estate

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

After 10cm

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

'DS'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMH3445J

Yr Regn:

10 Feb 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

C.C

1318

Colour

Gray

A/C

Insured / Std / NI / NA

Sp. Reading

18083

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMGK3850HX200216

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

8/6/19

D.O.I.

17/6/19

Survey held at

Kah motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Confirmed P/P \$8627.13/- 6days of repair.
(\$ 7,166.52 Red - 45%)

RECEIVED 03 JUL 2019

[Signature]
27/7/2019

Date/Time, File Pass to?

03/07/19

1) Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B. / P.P.

8,627.13 P/P



: Preli. Report



: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

5x15 = 75

170 + 75

50

50

34

349

MOTOR SURVEY ASSIGNMENT

Date	11-06-2019	Our Ref No. D19003800MFSH
Accident Date	08-06-2019	Claim Type. Third Party
Insured Vehicle	SHC2698M	Third Party Vehicle. SMH3445J
Survey Location	6A MANDAI ESTATE BODY REPAIR & PAINT CENTRE	
Contact Person.	ANIKKA LAI	
Contact No.	65145248/ 82886302	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO. SDN. BHD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9280E
Vehicle Details	
Vehicle No.:	SMH3445J
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L13B11020136
Chassis No.:	JHMGK3850HX200216
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,855.00
Original Registration Date:	10 Feb 2017
First Registration Date:	10 Feb 2017
Transfer Count:	1
Actual ARF Paid:	\$10,855.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Feb 2027
PARF Rebate Amount:	\$8,141.00
Intended COE Rebate Details	
COE Expiry Date:	09 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$36,696.00
Total Rebate Amount:	\$44,837.00

The information contained herein is correct as at 18 Jun 2019

OK

Shirley Hiew (LKK Auto)

From: Hwee Jie (LKK Auto) <hweejie@lkkauto.com>
Sent: Friday, 28 June 2019 10:34 AM
To: Anikka Lai
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SMH3445J - FINALIZATION

Hi,

Finalized P/P \$8,627.13/- 6days of repair.

Best Regards,
Hwee Jie | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai [mailto:anikkalai@honda.com.sg]
Sent: Monday, 24 June, 2019 7:07 PM
To: Veron Chen (LKKAuto); Hwee Jie (LKK Auto)
Subject: SMH3445J - FINALIZATION
Importance: High

Dear Veron / Hwee Jie,

We enclosed the total final repair costs for,

Vehicle No.	SMH3445J
Final Repair Costs (exclude GST)	\$ 8627.13
Repair Period* (Days)	6 days

****Note: Repair period does include Sunday and Public Holiday.***

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.


In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg

From: Printer Service <printservice@honda.com.sg>
Sent: Monday, 24 June, 2019 4:13 PM
To: Anikka Lai <anikkalai@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 18 June 2019 2:49 PM
To: 'Eileen Lee'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19003800MFSH/1
Attachments: SMH 3445J - Preli Advise .pdf

Dear Eileen,

Enclosed preliminary revised of vehicle SMH 3445J.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 14 June 2019 10:45 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003800MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer arrange on 17/06/2019.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 13 June 2019 5:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003800MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003800MFSH

Date: 18 June 2019

Our Ref: CS/FCI19010552/Jsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMH 3445J .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/06/2019 at the premises of M/s Kah Motor Co. Sdn. Bhd. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>15,793.65</u> .
Revised Estimate Amount	: S\$ <u>13,243.36</u> .
"Check" Items Amount	: S\$ <u>2,146.28</u> .
Total	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 6 days

Yours faithfully,
Ong Hwee Jie
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/06/2019 10:21
Date Of Accident	08/06/2019 14:45
Exact Location Of Accident	COMMONWEALTH AVE W SLIP RD TO CLEMENTI AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH3445J
Insured/Policyholder	
Name Of Registered Owner	HASLINDA BINTI ABDULLAH
NRIC No	S1619280E
Email Address	HASLINDA_ABD@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-82885854
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.3 CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3009481900
Cover Note Number	

Driver

Name of Driver	MUHAMMAD FIRMAN BIN JUMARI
NRIC No	S9441146G
Date Of Birth	30/10/1994
Occupation	INDOOR
Date Of Driving Pass	04/02/2017
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83187225
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	437 FAJAR RD #02-362
Postcode	670437
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : HASLINDA BINTI ABDULLAH GENDER: : FEMALE
Passenger 2	NAME: : JUMARI BIN SELAMAT GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 08/06/2019 AT AROUND 1145HRS, I WAS TRAVELLING ALONG COMMONWEALTH AVE WEST TO CLEMENTI AVE 4. WHILE DRIVING TO THE SLIP RD AND I STOP AS THERE ARE ON COMING VEHICLE ALONG THE ROAD BUT SUDDENLY I FELT AN IMPACT ON MY REAR THEN I WENT DOWN TO CHECK AND FOUND THAT VEHICLE B HAD HIT ONTO MY REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC2698M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	MOHAMED LATIFF BIN MOHAMED SALLEH
NRIC/Passport Number	S0110412H
Contact Number	97692831

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Accident Circumstances.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

☐ Claim own policy
☐ Claim third party
☒ Claim OD / TP at other works hop Kah motor
☐ For record purpose
Policy No. 01MPLN2009681900
Insurer Chubb Veh. No. SHAF34457



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

17/6-18 QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMH3445J
Chassis No : JHMGK3850HX200216
Model : JAZZ 1.3LXR CVT 17YM
Owner's Name : HASLINDA BINTI ABDULLAH
Ins Policy No. :
Date of Accident : 8/6/2019

Document No. : SQT19002584
Date : 12. Jun 2019
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L13B11020136
Date | Time : 12. Jun 2019 11:54:24 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: HASLINDA BINTI ABDULLAH OWNER INSURER: CHINA TAIPING ACC DATE: 08/06/2019 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL TP VEH: SHC2698M						
68100-T5A-U10ZZ	TAIL GATE COMP BUC ✓	1	730.60	25	547.95	38.36	586.31
68210-T5A-J03ZZ	HINGE COMPTAILGATE nux	2	30.80	25	46.20	3.23	49.43
74440-T5A-003	WEATHERSTRIPTAILGATE 1 CVT ✓	1	92.30	25	69.22	4.85	74.07
74801-T5A-013	LOCK ASSYTAILGATE Jam ✓	1	176.70	25	132.52	9.28	141.80
74810-S6A-003	HANDLETAILGATE nux	1	60.40	25	45.30	3.17	48.47
74813-T5A-003	STRIKER ASSYTAILGATE ? nux	1	24.70	25	18.52	1.30	19.82
74820-T5A-003	STAY ASSYR.TAILGATE OPEN nux	1	94.00	25	70.50	4.94	75.44
74870-T5A-003	STAY ASSY,L.TAILGATE OPEN nux	1	94.00	25	70.50	4.94	75.44
74830-T5A-000	CABLETAILGATE OPENER nux	1	25.80	25	19.35	1.35	20.70
75722-T5L-T01	EMBLEMRR. nlc ✓	1	10.90	25	8.17	0.57	8.74
74890-T5A-A11	GARNISH ASSY,RR LICENCE nux def	1	105.50	25	79.12	5.54	84.66
75701-T5A-000	EMBLEMH nlc ✓	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM nlc ✓	2	2.10	25	3.15	0.22	3.37
33500-T5A-J02	TAILLIGHT ASSY,R. ?	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL. ? } nux	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYR.LID ?	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID ?	1	81.70	25	61.27	4.29	65.56
73225-TF0-000	RUBBER A WSHIELD DAM nlc X n	1	37.00	25	27.75	1.94	29.69
73226-TF0-000	RUBBER B WSHIELD nlc X n	1	32.10	25	24.07	1.68	25.75

Printed on 12/6/2019 5:49:43 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SMH3445J

Chassis No : JHMGK3850HX200216

Model : JAZZ 1.3LXR CVT 17YM

Owner's Name : HASLINDA BINTI ABDULLAH

Ins Policy No. :

Date of Accident : 8/6/2019

Document No. : SQT19002584 **Page** 2

Date : 12. Jun 2019

Customer No. : WZF002

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L13B11020136

Date | Time : 12. Jun 2019 11:54:24 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73228-TF0-000	RUBBER D WSHIELD DAM not nux	2	4.90	25	7.35	0.51	7.86
75717-SNB-E01	STICKER I-VTEC not nux	1	12.60	25	9.45	0.66	10.11
04731-SAA-000	RUBBER, W/SHIELD not nux	1	24.70	25	18.52	1.30	19.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) not	2	60.00		120.00	8.40	128.40
04715-T5A-000ZZ	FACERR.BUMPER DEF	1	492.70	25	369.52	25.87	395.39
71593-T5A-000	SPACERR.RR.BUMPER not	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER not	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER not	10	2.30	25	17.25	1.21	18.46
71502-T5A-000	GARNISHR.RR.BUMPER not	1	14.30	25	10.72	0.75	11.47
71507-T5A-000	GARNISHL.RR.BUMPER not	1	14.30	25	10.72	0.75	11.47
90107-S9V-A01	BOLTRR.BUMPER STOPPER not	2	4.40	25	6.60	0.46	7.06
90149-SAA-003	BOLTBUMPER not nux	1	3.20	25	2.40	0.17	2.57
66100-TAR-T00ZZ	PANEL COMPRR. ? DD	1	320.40	25	240.30	16.82	257.12
04655-TAS-310ZZ	PANEL SET,RR.FLOOR ? nux	1	697.00	25	522.75	36.59	559.34
72841-SH3-315	OILSHEET ? nux	3	40.70	25	91.57	6.41	97.98
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER ? nux	1	53.70	25	40.27	2.82	43.09
84441-T5A-003ZB	POCKETTAILGATE LINING PULL ? nux	1	5.10	25	3.82	0.27	4.09
84521-T5A-901ZA	LID ASSYSPARE TIRE ? nux	1	189.80	25	142.35	9.96	152.31
84550-T5L-Q00	BOX ASSYCARGO FLOOR ? DEF	1	80.00	25	60.00	4.20	64.20
84640-T5A-003ZA	LINING ASSYRR.PANEL ? nux	1	60.80	25	45.60	3.19	48.79
84651-TAR-Z03ZA	LINING ASSYL.TRUNK ? nux	1	169.00	25	126.75	8.87	135.62
84601-TAR-Z03ZA	LINING ASSYR.TRUNK ? nux	1	169.00	25	126.75	8.87	135.62
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR Shorted	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) nux	1	45.00		45.00	3.15	48.15
Sum Item					3983.65	278.84	4,262.49

BOSUN	SUNDRIES	1	40	100.00	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT Tailgate	1	80	100.00	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT End Panel	1	80	100.00 ?	100.00	7.00	107.00

Printed on 12/6/2019 5:49:43 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SMH3445J

Chassis No : JHMGK3850HX200216

Model : JAZZ 1.3LXR CVT 17YM

Owner's Name : HASLINDA BINTI ABDULLAH

Ins Policy No. :

Date of Accident : 8/6/2019

Document No. : SQT19002584 Page 3

Date : 12. Jun 2019

Customer No. : WZF002

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L13B11020136

Date | Time : 12. Jun 2019 11:54:24 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOJSE	BODY JOINT SEALANT. <i>Floor Panel</i>	1	100.00 <i>80</i>	<i>?</i>	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00 <i>120</i>		150.00	10.50	160.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00 <i>280</i>		350.00	24.50	374.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	350.00 <i>280</i>		350.00	24.50	374.50
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00	<i>✓</i>	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00 <i>320</i>		800.00	56.00	856.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00 <i>560</i>		800.00	56.00	856.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00 <i>150</i>		250.00	17.50	267.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	150.00 <i>100</i>		150.00	10.50	160.50
BKRP21B	CUT OFF & RENEW RR FLOOR PANEL, RR PANEL & DAMAGE <i>(3 Penal)</i>	1	4500.00 <i>2240</i>		4500.00	315.00	4815.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. <i>(6P) (4 Penal)</i>	1	3500.00 <i>1800</i>		3500.00	245.00	3745.00
Sum Labor					11810.00	826.70	12,636.70

Survey By Huse Jie-LKK

Date & Time 17/6/19

Excess —

Status P/P 6days.

Signature *[Signature]*

[Signature]
18/6/19

Total Amount 15,793.65 1,105.54 16,899.19

Total (Inclusive of GST) **16,899.19**

15818.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/6/2019 5:49:43 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK3850HX200216
License No: SMH3445J
Mileage: 18083
Engine No: L13B11020136

Document No: SVO19038214
Printed By: ANIKKALAI
Order Date: 17. June 2019
Order Time: 1:53:41 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: HASLINDA BINTI ABDULLAH OWNER INSURER: CHINA TAIPING ACC DATE: 08/06/2019 SURVEYED BY: HWEE JIE / LKK DATE: 17/06/2019 REF NO: TP INSURER: MS FIRST CAPITAL TP VEH: SHC2698M						
68100-T5A-U10ZZ	TAIL GATE COMP <i>BUC -</i>	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE <i>CVT -</i>	1	92.30	25	69.22	4.85	74.07
74801-T5A-013	LOCK ASSYTAILGATE <i>Jan -</i>	1	176.70	25	132.52	9.28	141.80
75722-T5L-T01	EMBLEMRR. <i>nec -</i>	1	10.90	25	8.17	0.57	8.74
74890-T5A-A11	GARNISH ASSY,RR LICENCE <i>DEF -</i>	1	105.50	25	79.12	5.54	84.66
75701-T5A-000	EMBLEMH <i>nec -</i>	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM <i>nec -</i>	2	2.10	25	3.15	0.22	3.37
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>nec -</i>	2	60.00		120.00	8.40	128.40
04715-T5A-000ZZ	FACERR.BUMPER <i>DEF -</i>	1	492.70	25	369.52	25.87	395.39
71593-T5A-000	SPACERR.RR.BUMPER <i>nec -</i>	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER <i>nec -</i>	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER <i>nec -</i>	10	2.30	25	17.25	1.21	18.46
66100-TAR-T00ZZ	PANEL COMPRR. <i>DD -</i>	1	320.40	25	240.30	16.82	257.12
84550-T5L-Q00	BOX ASSYCARGO FLOOR <i>DEF -</i>	1	80.00	25	60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR SENSOR <i>shunted</i>	1	320.00		320.00	22.40	342.40
73127-TY0-000	A RUBBER CWINDOWSHIELD DAMPER <i>nec -</i>	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	A RUBBERWINDOWSHIELD DAMPER <i>nec -</i>	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	A DAMPERSTD 5X5 <i>nec -</i>	1	8.50	25	6.37	0.45	6.82
	SUM PARTS:				2,017.13	141.21	2,158.34
BOSUN		1	40.00	✓	40.00	2.80	42.80
	SUNDRIES						
BOJSE	1718	1	80.00	✓	80.00	5.60	85.60
	BODY JOINT SEALANT <i>Tailgate</i>						
BOJSE	1718	1	80.00	✓	80.00	5.60	85.60
	BODY JOINT SEALANT. <i>End panel</i>						
BA02R	1466	1	120.00	✓	120.00	8.40	128.40
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BC012R		1	280.00	✓	280.00	19.60	299.60
	RESET VEHICLE SMART ENTRY SYSTEM						
BC011R	1466	1	280.00	✓	280.00	19.60	299.60
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BG02R	1438	1	560.00	✓	560.00	39.20	599.20
	REPLACE RR. WINDSCREEN.(N)						
BKTG02R	1466	1	320.00	✓	320.00	22.40	342.40
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK3850HX200216
License No: SMH3445J
Mileage: 18083
Engine No: L13B11020136

Document No: SVO19038214
Printed By: ANIKKALAI
Order Date: 17. June 2019
Order Time: 1:53:41 PM
Service Advisor: ANIKKA LAI SWEE KAM

BMI03D	1438 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	560.00	/	560.00	39.20	599.20
BP00R	1438 APPLY BODY UNDERSIDE COATING (N).	1	150.00	/	150.00	10.50	160.50
BML02I	1438 INSPECT RR LIGHTING MECHANISMS, PERFORM WATER TEST.(N)	1	100.00	/	100.00	7.00	107.00
BKRP21B	1466 CUT OFF & RENEW RR FLOOR PANEL, RR PANEL & DAMAGE & FENDERS. STRAIGHTEN MAIN FRAME INCLUDING FITTING	1	2,240.00	/	2,240.00	156.80	2,396.80
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	1,800.00	/	1,800.00	126.00	1,926.00
SUM LABOUR:					6,610.00	462.70	7,072.70
TOTAL SGD					8,627.13	603.91	9,231.04

Total Payable (SGD)

9,231.04

(GST Amount) is indicated from individual line(s)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19010552/Jsd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-07-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2698M	Veh. Inspected	SMH 3445J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003800MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	13/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ	c.c	1318	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMGK3850HX200216	Colour	GREY	
Odometer	18083	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	175/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	175/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	175/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/06/2019	Inspection Date	17/06/2019	
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 3445J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE COMP (SN)	BUCKLED	547.95	547.95
2	HINGE COMPTAILGATE (SN)	NOT NECESSARY	46.20	-
1	WEATHERSTRIPTAILGATE (SN)	CUT	69.22	69.22
1	LOCK ASSYTAILGATE (SN)	JAMMED	132.52	132.52
1	HANDLETAILGATE (SN)	NOT NECESSARY	45.30	-
1	STRIKER ASSYTAILGATE (SN)	NOT NECESSARY	18.52	-
1	STAY ASSYR.TAILGATE OPEN (SN)	NOT NECESSARY	70.50	-
1	STAY ASSY,L.TAILGATE OPEN (SN)	NOT NECESSARY	70.50	-
1	CABLETAILGATE OPENER (SN)	NOT NECESSARY	19.35	-
1	EMBLEMRR. (SN)	NECESSARY	8.17	8.17
1	GARNISH ASSY, RR LICENCE (SN)	DEFORMED	79.12	79.12
1	EMBLEMH (SN)	NECESSARY	8.02	8.02
2	NUTPUSH 3MM (SN)	NECESSARY	3.15	3.15
1	TAILLIGHT ASSY,R. (SN)	NOT NECESSARY	167.92	-
1	TAILLIGHT ASSYL. (SN)	NOT NECESSARY	167.92	-
1	LIGHT ASSYR.LID (SN)	NOT NECESSARY	61.27	-
1	LIGHT ASSYL.LID (SN)	NOT NECESSARY	61.27	-
1	RUBBER A WSHIELD DAM (SN)	NOT NECESSARY	27.75	-
1	RUBBER B WSHIELD (SN)	NOT NECESSARY	24.07	-
2	RUBBER D WSHIELD DAMP (SN)	NOT NECESSARY	7.35	-
1	STICKER I-VTEC (SN)	NOT NECESSARY	9.45	-
1	RUBBER, W/SHIELD (SN)	NOT NECESSARY	18.52	-
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00
1	FACERR.BUMPER (SN)	DEFORMED	369.52	369.52
1	SPACERR.RR.BUMPER (SN)	NECESSARY	8.62	8.62
1	SPACERL.RR.BUMPER (SN)	NECESSARY	8.62	8.62
10	CLIP, BUMPER (SN)	NECESSARY	17.25	17.25
1	GARNISHR.RR.BUMPER (SN)	NOT NECESSARY	10.72	-
1	GARNISHL.RR.BUMPER (SN)	NOT NECESSARY	10.72	-
2	BOLTRR.BUMPER STOPPER (SN)	NOT NECESSARY	6.60	-
1	BOLTBUMPER (SN)	NOT NECESSARY	2.40	-

Report Ref No. CS/FCI19010552/Jsd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PANEL COMPRR. (SN)	DENTED	240.30	240.30
1	PANEL SET, RR.FLOOR (SN)	NOT NECESSARY	522.75	-
3	OILSHEET (SN)	NOT NECESSARY	91.57	-
1	LINING ASSYTAILGATE LOWER (SN)	NOT NECESSARY	40.27	-
1	POCKETTAILGATE LINING PULL (SN)	NOT NECESSARY	3.82	-
1	LID ASSYSPARE TIRE (SN)	NOT NECESSARY	142.35	-
1	BOX ASSYCARGO FLOOR (SN)	DEFORMED	60.00	60.00
1	LINING ASSYRR.PANEL (SN)	NOT NECESSARY	45.60	-
1	LINING ASSYL.TRUNK (SN)	NOT NECESSARY	126.75	-
1	LINING ASSYR.TRUNK (SN)	NOT NECESSARY	126.75	-
4	ACT RR.SENSOR (SN)	SHORTED	320.00	320.00
1	NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	45.00	-
1	SUNDRIES (SN)	NECESSARY	100.00	40.00
1	RUBBER CWINDSHIELD DAMPER (SN) (ADDITIONAL)	NECESSARY	8.55	8.55
2	RUBBERWINDSHIELD DAMPER (SN) (ADDITIONAL)	NECESSARY	9.75	9.75
1	DAMPERSTD 5X5 (SN) (ADDITIONAL)	NECESSARY	6.37	6.37
			4,108.32	2,057.13
	LABOUR			
	BODY JOINT SEALANT. (TAILGATE)		100.00	80.00
	BODY JOINT SEALANT. (END PANEL)		100.00	80.00
	BODY JOINT SEALANT. (FLOOR PANEL)	NOT NECESSARY	100.00	-
	REMOVE & RENEW REVERSE SENSORS - 4PCS.		150.00	120.00
	RESET VEHICLE SMART ENTRY SYSTEM.		350.00	280.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		350.00	280.00
	REPLACE RR.WINDSCREEN.		560.00	560.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &		800.00	320.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		800.00	560.00
	APPLY BODY UNDERSIDE COATING.		250.00	150.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		150.00	100.00
	CUT OFF & RENEW RR FLOOR PANEL, RR PANEL & DAMAGE.		4,500.00	2,240.00

Report Ref No. CS/FCI19010552/Jsd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)		3,500.00	1,800.00
			11,710.00	6,570.00
GRAND TOTAL			15,818.32	8,627.13
RECOMMENDED COST OF REPAIRS				8,627.13

Report Ref No. CS/FCI19010552/Jsd3e2

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.