

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5426L**AAD1906-120***Not Authorized
1 Sing @ 4000*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5426L

VF1ABL15AUC279847

RENAULT

LATITUDE

12.6.19

AXA

19/11/2014

	PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42	✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75	X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68	X
1	BUMPER RETAINER FRT LH	\$	<i>DR</i> 151.41	✓
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88	X
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83	X
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80	X
1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21	X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	X
1	HEADLAMP LH	\$	<i>SL</i> 1,184.43	X
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	X
1	FENDER PANEL FRT LH	\$	<i>B</i> 783.83	✓
1	WHEELARCH FRT LH	\$	<i>SL</i> 278.84	} X
1	FENDER BRACKET LOWER LH	\$	<i>SL</i> 15.79	
1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84	
1	FRONT BRACE PANEL	\$	<i>R</i> 177.22	
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36	
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75	
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90	
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
1	BONNET	\$	<i>B</i> 1,941.63	
1	BONNET INSULATOR	\$	<i>SL</i> 405.73	} X
1	BONNET STRUT LH	\$	<i>L</i> 88.61	
1	BONNET STRUT RH	\$	<i>L</i> 88.61	
1	BONNET HINGE LH	\$	<i>L</i> 348.31	
1	BONNET HINGE RH	\$	<i>L</i> 348.31	
1	BONNET LOCK	\$	<i>L</i> 305.48	
1	BONNET CABLE	\$	<i>L</i> 119.19	

Trans-cab Auto Services Pte Ltd

AAD1906-120

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5426L

1	BONNET CABLE COVER	\$	161.03	} PUCX
1	BONNET SEAL OUTER	\$	92.36	
1	BONNET SEAL INNER	\$	157.28	
1	AIR CLEANER BOX	\$	464.20	
1	AIR CLEANER HOSE	\$	175.85	
1	AIR CLEANER LOWER	\$	271.26	
1	AUTO COMPUTER	\$	5,032.17	
1	INJECTION COMPUTER	\$	4,706.30	
1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	5,154.52	
1	STEERING PUMP ELECTRIC L70Y	\$	2,306.90	
1	STEERING PINION RACK L70Y	\$	4,413.11	
1	LOWER ARM LH L70Y	\$	685.76	
1	KNUCKLE ARM LH L70Y	\$	846.98	
1	ABSORBER FRT LH L70Y	\$	360.54	
1	DRIVESHAFT LH	\$	1,747.45	
1	STABILIZER BAR FRT	\$	604.65	
1	DOOR PANEL FRT LH	\$	2,844.66	
1	DOOR MIRROR ASSY LH	\$	1,483.40	
1	WHEEL HOUSING PANEL FRNT LH	\$	4,682.09	
TOTAL		\$	50,524.11	
10%		\$	5,052.41	
		\$	45,471.69	

Special Nett

1	BUMPER CLIP FRT	\$	na 66.00	} X
1	BUMPER BRACKET CLIP FRT LH	\$	na 12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	na 10.50	
1	BUMPER GRILLE LOWER CLIP	\$	na 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na 30.00	
1	WHEELARCH CLIP FRT LH	\$	na 30.50	
1	FRONT LEFT TYRE	\$	sh 300.00	
1	FRONT LEFT TYRE RIM	\$	sh 380.00	
1SET	Front licence plate with holder	\$	sh 80.00	
1	WINDSCREEN SEALANT	\$	na 253.80	
1	FRONT WINDSCREEN MOULDING	\$	na 120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na 100.00	

Trans-cab Auto Services Pte Ltd

AAD1906-120

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5426L

6	BONNET INSULATOR CLIP L70Y	\$	<i>na</i>	7.30	} X
2	BONNET STRUT L70Y	\$	<i>ln</i>	88.61	
2	BONNET CABLE CLIP L70Y	\$	<i>na</i>	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	<i>na</i>	10.85	
1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>na</i>	52.00	
1SET	RADIATOR GRILLE SCREW	\$	<i>na</i>	16.00	
1	FRONT LH DOOR STICKER 'Trans-Cab'	\$	<i>na</i>	80.00	
1	FRONT LH DOOR STICKER 'Classic'	\$	<i>na</i>	80.00	
TOTAL		\$		1,882.88	
TOTAL PARTS		\$		47,354.57	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	<i>5000</i>
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X
To transfer of front windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	<i>6000</i>
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1906-120

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5426L

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i> 440.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>15%</i>
To rust-proofing of the affected areas.	\$	170.00	<i>60%</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	<i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>4</i> 380.00	<i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>4</i> 380.00	<i>X</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>4</i> 380.00	<i>X</i>
TOTAL	\$	16,760.00	
Over All Total	\$	64,114.57	

LUMP SUM (REPAIR DAY)*20 days*
2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: