

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel: 6844 2475

E-mail: claims@teamworkgarage.com

Register number : 201015366H 3RD PARTY CLAIM ESTIMATION

Vehicle number SLC493C
Make / Model KIA FORTE
Chassis number KNAFZ411MG5601188
Accident date 11/6/19

Accident date 11/6/19 Reference 1906-47

| | V / | ejerence | 1900-47 |
|-----|---|-------------|--------------------|
| Qty | Particulars | | Unit Price - SGD S |
| | PARTS REPLACEMENT - LIST ITEMS | | |
| 1 | BOOTLID X | | |
| 2 | BOOTLID HINGE X | | |
| 1 | BOOTLID EMBLEM | | |
| 1 | BOOTLID EMBLEM - FORTE X | | |
| 1 | BOOTLID EMBLME -1.6 [⋈] | | |
| 1 | BOOTLID INSULATOR ✓ | | |
| 1 | BOOTLID WEATEHRSTRIP X | | |
| 2 | BOOTLID INNER LAMP X | 14344 | |
| 21 | TAILLAMP RHX LH? | | |
| 2 | TAILAMP PANEL X | | |
| 2 | TAILLAMP INNER SEAL X | | |
| 1 | END PANEL | | |
| 1 | END PANEL TOP GARNISH | | |
| 1. | SPARE TRYE TOP BOARD X | | |
| 1 | FLOOR COMPARTMENT PANEL X | | |
| 1 | REAR BUMPER / DR | | |
| 2 | REAR BUMPER RETAINER | | |
| 2 | REAR BUMPER INNER SPONGE | | |
| 1 | REAR BUMPER REINFORCEMET | | |
| 1 | REAR BUMPER LOWER GANRISH | | |
| 2 | REAR FENDER INNER TRIM X | | |
| 1 | REAR EXHAUST SILENCER × | | |
| 2 | REAR EXHAUST MOUNTING V | | |
| 1 | REAR KEYLESS SENSOR ? | | |
| 4 | PDC SENSOR | | |
| 4 | PDC HOLDR ? | | |
| 0 | | - | 0.00 |
| Rev | LH Reflector som? | Less 20% | 0.00 |
| | | Subtotal | 0.00 |
| | | Balance C/F | |
| | PARTS REPLACEMENT - SPECIAL NETT ITEM: | | 0.00 |
| | TAKTS KET EACEMENT - SPECIAL NETT TIEM. | Balance B/F | 0.00 |
| | | balance B/F | 0.00 |
| 1 | REAR NUMBER PLATE X | | 70.00 |
| | REAR BUMPER CLIP | | 70.00 30 40.00 |
| | REAR FENDER INNER TRIM CLIP | | |
| | JOINT SEALANT | | 30.00 |
| 1 | REAR REVERSE CAMERA X | | 150.00 |
| | ILAN NEVERSE CAMERA X | Subtatal | 500.00 |
| | | Subtotal | 790.00 |
| | | Balance C/F | 790.00 |

| S/No | LABOUR AND MISCELLANEOUS CHARGES | |
|------|--|--------------|
| | Balance B/F | 790.00 |
| 1 | CHECK REAR WIRING AND LIGHTNING SYSTEM | 70.00 30 |
| 2 | REMOVE, REFIT REAR LINING, TRIM AND GARNISH | 200.00 30 |
| 3 | REMOVE AND RENEW REAR REVERSE SENSOR | 150.00 20 |
| 4 | REMOVE AND RENEW REAR EXHAUST SILENCER | 150.00 × |
| 5 | TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW | 200.00 × |
| 6 | PANEL BEATING ON AFFECTED AREAS | 1500.00 300 |
| 7 | SPRAY PAINTING ON AFFECTED AREAS | 1400.00 300 |
| 8 | APPLY ANTI RUST ON AFFECTED AREAS | 150.00 30 |
| | Subt | otal 3820.00 |
| | Grand t | otal 4610.00 |

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
 No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: