



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H

REPAIR PERFORMANCE INVOICE

Vehicle number	SLC493C
Make / Model	KIA FORTE
Chassis number	KNAFZ411MG5601188
Accident date	11/6/19
Reference	1906-47

AIG INSURANCE

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	BOOTLID X R	1072.95
2	BOOTLID HINGE X NAI	156.40
1	BOOTLID EMBLEM X NAI	42.55
1	BOOTLID EMBLEM - FORTE X NAI	54.10
1	BOOTLID EMBLME -1.6 X NAI	39.50
1	BOOTLID INSULATOR X NAI	94.30
1	BOOTLID WEATEHRSTRIP X NAI	115.00
2	BOOTLID INNER LAMP X NAI	1633.00
2	TAILLAMP RH X NAI LH / BR	1812.40 772 /
2	TAILAMP PANEL X NAI	282.90
1	END PANEL X R	378.00
1	END PANEL TOP GARNISH / BR	174.00 /
1	SPARE TRYE TOP BOARD X NAI	190.80
1	FLOOR COMPARTMENT PANEL X NAI	692.30
1	REAR BUMPER / DO	883.20 601 /
2	REAR BUMPER RETAINER / BR	75.90 /
2	REAR BUMPER INNER SPONGE X NAI	131.20
1	REAR BUMPER REINFORCEMET / BR	414.00 304 /
1	REAR BUMPER LOWER GARNISH / CUT	269.10 /
2	REAR FENDER INNER TRIM X NAI	386.40
1	REAR EXHAUST SILENCER X NAI	838.35
2	REAR EXHAUST MOUNTING X NAI	60.00
1	REAR KEYLESS SENSOR / BR	103.50 /
2	PDC SENSOR / Short 1pc - \$172	814.20 344 /
4	PDC HOLDR / NAI 1pc - \$15	598.00 60 /
		9499.65
		Less 20%
		Subtotal 7599.72
		Balance C/F 7599.72
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
		Balance B/F 7599.72
1	REAR NUMBER PLATE	70.00 X NAI
1 SET	REAR BUMPER CLIP	40.00 30 NAI
1 SET	REAR FENDER INNER TRIM CLIP	30.00 X NAI
1	JOINT SEALANT	150.00 X NAI
1	REAR REVERSE CAMERA	500.00 X NAI
		Subtotal 790.00
		Balance C/F 8389.72

2703.50
 - 20%
 2162.80

S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	8389.72
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	70.00 30
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	200.00 30
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 30
4	REMOVE AND RENEW REAR EXHAUST SILENCER	150.00 X
5	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 X
6	PANEL BEATING ON AFFECTED AREAS	1500.00
7	SPRAY PAINTING ON AFFECTED AREAS	1400.00 530
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	3820.00
	Grand total	12209.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK) with Arjun 14/6/19, 4.30pm

3 chys

L/S

Ry AFL spray

P - 2162.80

Supp - 61.60

A - 30

L 1060

3314.40

L/S - 2651.52

= 2659



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
REPAIR PERFORMA INVOICE

AIG INSURANCE

(Supp)

Vehicle number	SLC493C
Make / Model	KIA FORTE
Chassis number	KNAFZ411MG5601188
Accident date	11/6/19
Reference	1906-47

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR LH BUMPER REFLECTOR / BR	98.10 77/- -20
		98.10 61.69
	Less 20%	19.62
	Subtotal	78.48
	Balance C/F	78.48