

# XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 13/06/19

Address : ANG ZHIWEN CHRISTOPHER  
33 JALAN BINCHANG

SINGAPORE 578536

Reference : TP 1204/06/19

Vehicle No : SKS 8073G

Make/Model : M/BENZ A180

Insurance Co. : FWD

## RE : QUOTATION TO SKS 8073G FOR THIRD PARTY CLAIMS.

| PARTS REQUIRED              |                                           | QTY          | AMT \$                    |
|-----------------------------|-------------------------------------------|--------------|---------------------------|
| 1)                          | FRONT BUMPER <i>de</i>                    | 1            | \$ 1,195.00               |
| 2)                          | FRT BUMPER CLIPS <i>re</i>                | 10           | \$ 60.00                  |
| 3)                          | FRONT BUMPER RETAINER <i>re</i>           | 1            | \$ 145.00                 |
| 4)                          | FRONT BUMPER HEADLAMP WASHER              | 1            | \$ 195.00                 |
| 5)                          | FRONT BUMPER HEADLAMP WAS.COVER <i>ms</i> | 1            | \$ 115.00                 |
| 6)                          | FENDER FRONT RH <i>bt</i>                 | 1            | \$ 610.00                 |
| 7)                          | FENDER COWLING X                          | 1            | \$ 195.00                 |
| 8)                          | FENDER COWLING CLIPS <i>re</i>            | 20           | \$ 160.00                 |
| 9)                          | FRONT RH DOOR <i>bt</i>                   | 1            | \$ 1,387.00               |
| 10)                         | FRONT RH DOOR HINGES X                    | 2            | \$ 250.00                 |
| 11)                         | FRONT RH DOOR WEATHERSTRIPE <i>re</i>     | 1            | \$ 250.00                 |
| 12)                         | REAR RH DOOR <i>reper</i>                 | 1            | \$ 1,443.00               |
| 13)                         | REAR RH DOOR WEATHERSTRIPE X              | 1            | \$ 250.00                 |
| 14)                         | REAR BUMPER <i>reper</i>                  | 1            | \$ 1,205.00               |
| 15)                         | REAR BUMPER CLIPS/RIVET X                 | 10           | \$ 60.00                  |
| 16)                         | TYRE RIM RH <i>re</i>                     | 2            | \$ 1,600.00 <i>prize?</i> |
| 17)                         | DOORS INNER BOARD RIVET ?                 | 20 <i>40</i> | \$ 240.00                 |
| LIST PRICE TOTAL            |                                           |              | \$ 9,360.00               |
| LESS DISCOUNT 10%           |                                           |              | \$ 936.00                 |
| LIST PRICE TOTAL AFTER LESS |                                           |              | \$ 8,424.00               |

NETT PRICE TOTAL

\$0.00

TOTAL PARTS COST

**\$8,424.00**

## LABOUR AND MISCELLANEOUS CHARGES

- |    |                                                                                                          |                                    |
|----|----------------------------------------------------------------------------------------------------------|------------------------------------|
| 1) | TO REMOVE & REPLACE FRONT BUMPER, HEADLAMP, FENDER, BOTH RH DOOR & REAR BUMPER AND TO PANEL BEAT & ALIGN | \$ 1,200.00 <i>800</i><br>(6 DAYS) |
|----|----------------------------------------------------------------------------------------------------------|------------------------------------|

- 2) TO PUTTY & SPRAY PAINT FRONT BUMPER & REAR BUMPER, BOTH RH FENDERS & DOORS. \$ ~~1,400.00~~ 1200 (7 PANEL)
- 3) TO REMOVE & REFIT BOTH DOOR GLASS, MECHANISM PARTS & OTHERS AND TRANSFER TO NEW DOOR. \$ ~~400.00~~ 80
- 4) TO REMOVE & REPLACE TYRE RIMS & BALANCING. \$ ~~100.00~~ 60
- 5) COMPLETE WHEEL ALIGNMENT \$ ~~180.00~~ 60
- 6) TUFF KOTE \$ ~~250.00~~ 100

**LABOUR TOTAL**

**\$ 3,530.00**

**TOTAL ESTIMATED REPAIR COST**

**\$ 11,954.00**

*Pass*

*Up 90010068*

*10 days*

*43*

*18/01/19 @ 1235*

*Resurvey after repair*

Auto Consultants hence notify

the Repairer of the following:

- To resurvey before ~~after~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: