

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 158719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 13/06/19

Address : ANG ZHIWEN CHRISTOPHER
33 JALAN BINCHANG

SINGAPORE 578536

Reference : TP 1204/06/19
Vehicle No : SKS 8073G
Make/Model : M/BENZ A180
Insurance Co. : FWD

RE : QUOTATION TO SKS 8073G FOR THIRD PARTY CLAIMS.

PARTS REQUIRED		QTY	AMT \$
1)	FRONT BUMPER <i>de</i>	1	\$ 1,195.00
2)	FRT BUMPER CLIPS <i>ae</i>	10	\$ 60.00
3)	FRONT BUMPER RETAINER <i>ae</i>	1	\$ 145.00
4)	FRONT BUMPER HEADLAMP WASHER <i>? X sue</i>	1	\$ 195.00 X
5)	FRONT BUMPER HEADLAMP WAS COVER <i>ae</i>	1	\$ 115.00
6)	FENDER FRONT RH <i>bt</i>	1	\$ 610.00
7)	FENDER COWLING <i>X sue</i>	1	\$ 195.00 X
8)	FENDER COWLING CLIPS <i>ae</i>	20	\$ 160.00
9)	FRONT RH DOOR <i>bt</i>	1	\$ 1,387.00
10)	FRONT RH DOOR HINGES <i>X sue</i>	2	\$ 250.00 X
11)	FRONT RH DOOR WEATHERSTRIPE <i>ae</i>	1	\$ 250.00
12)	REAR RH DOOR <i>repair</i>	1	\$ 1,443.00 X
13)	REAR RH DOOR WEATHERSTRIPE <i>X sue</i>	1	\$ 250.00 X
14)	REAR BUMPER <i>repair</i>	1	\$ 1,205.00 X
15)	REAR BUMPER CLIPS/RIVET <i>X sue</i>	10	\$ 60.00 X
16)	TYRE RIM RH <i>ae</i>	2	\$ 1,600.00 <i>price? (800) S/N</i>
17)	DOORS INNER BOARD RIVET <i>? X sue 20</i>	20	\$ 240.00 X
LIST PRICE TOTAL			\$ 9,360.00
LESS DISCOUNT 10%			\$ 936.00
LIST PRICE TOTAL AFTER LESS			\$ 8,424.00
NETT PRICE TOTAL			\$0.00
TOTAL PARTS COST			\$8,424.00

LABOUR AND MISCELLANEOUS CHARGES

- 1) TO REMOVE & REPLACE FRONT BUMPER, HEADLAMP, FENDER, BOTH RH DOOR & REAR BUMPER AND TO PANEL BEAT & ALIGN \$ 1,280.00 *800 900*
(6 DAYS)

2)	TO PUTTY & SPRAY PAINT FRONT BUMPER & REAR BUMPER, BOTH RH FENDERS & DOORS.	\$	1,400.00 (7 PANEL)	1200	1300
3)	TO REMOVE & REFIT BOTH DOOR GLASS, MECHANISM PARTS & OTHERS AND TRANSFER TO NEW DOOR.	\$	400.00	80	
4)	TO REMOVE & REPLACE TYRE RIMS & BALANCING.	\$	100.00	60	2550
5)	COMPLETE WHEEL ALIGNMENT	\$	180.00	60	
6)	TUFF KOTE	\$	250.00	150	
LABOUR TOTAL		\$	3,530.00		
TOTAL ESTIMATED REPAIR COST		\$	11,954.00		

Panel
 Hp 900/m288
 10 days
 48
 18/01/19 @ 1235
 Resurvey after work

3529.80
 800.00
 2550.00
 6879.80
 20%
 5,503.84
 48-5500
 10 days

Consultants hence notify
 owner of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: