



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L		NAME : Mr Ong Kah Pieng		WIP : 54353	
64 CECIL STREET		ADDRESS : 146 Lorong 2 Toa Payoh		EXCESS :	
#04-#05 IOB BUILDING		#05-318		DATE: 11-Jun-19	
SINGAPORE 049711		Singapore 310146		3dy 19/6/19	
ATTN : MOTOR CLAIMS		TEL : 93697723			
FAX :					
VEH NO :	SMA2399C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GL1071J0136791	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	28-Mar-18	POLICY NO. :	

NATURE OF WORKS				
Parts Description				
NO	QTY		REVISED	PRICES
1	REAR BUMPER	1	MGJS1-50-221ABB	\$ 1,266.60
2	BRACKET CENTER	1	MKD53-50-251	\$ 5.40
3	TOWING COVER LHS	1	MG4YL-50-EL1 E4	\$ 24.90
4	TOWING COVER RHS	1	MG4YL-50-EK1 E4	\$ 23.10
5	REAR REINFORCEMENT	1	MGHK1-50-260	\$ 538.30
6	RETAINER CENTER, SENSOR	2	MKD45-67-UC5AE4	\$ 31.00
7	SENSOR CENTER, ULTRASONIC	2	MGMK6-67-UC1 E4	\$ 361.80
8	TAPE PROTECTOR, SENSOR	4	MGS1D-50-EM1A	\$ 34.40
9	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 6.00
10	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.80
11	CLIP, REAR BUMPER	4	MC274-50-133	\$ 14.80
12	FASTENER, REAR BUMPER	6	MB45A-56-146A	\$ 18.00
13	GASKET LHS, TAILLAMP	1	MGJA1-51-163	\$ 27.70
14	GASKET RHS, TAILLAMP	1	MGJA1-51-153	\$ 27.70
TOTAL PARTS				\$ 2,390.50
LESS 10%				\$ 239.05
TOTAL PARTS COST				\$ 2,151.45

Labour Description				
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 1,650.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND REAR END PANEL.	945	\$ 1,575.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	200	NETT \$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	na	X \$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	net 30	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 4,505.00
TOTAL PARTS	\$ -	\$ 2,151.45
TOTAL	\$ -	\$ 6,656.45
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: