



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

r/p 83898.07

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Ong Kah Pieng <i>Not Present</i> ADDRESS: 146 Lorong 2 Toa Payoh #05-318 Singapore 310146 TEL: 93697723		WIP: 54353 EXCESS: DATE: 11-Jun-19 <i>3dy 19/6/19</i>	
VEH NO:	SMA2399C	DATE IN:		CONTACT PERSON:	Ronald 63957875
CHASSIS NO:	JM6GL1071J0136791	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA6	DATE REG.:	28-Mar-18	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MGJ51-50-221ABB	20/22	\$ 1,266.60
2	BRACKET CENTER	1	MKD53-50-251	11	\$ 5.40
3	TOWING COVER LHS	1	MG4YL-50-EL1 E4	22	\$ 24.90
4	TOWING COVER RHS	1	MG4YL-50-EK1 E4	22	\$ 23.10
5	REAR REINFORCEMENT	1	MGHK1-50-260	20	\$ 538.30
6	RETAINER CENTER, SENSOR	2	MKD45-67-UCSAE4	11	\$ 31.00
7	SENSOR CENTER, ULTRASONIC	2	MGMK6-67-UC1 E4	11	\$ 361.80
8	TAPE PROTECTOR, SENSOR	4	MGS1D-50-EM1A	22	\$ 34.40
9	GROMMET, REAR BUMPER	2	M9991-00-501	22	\$ 6.00
10	GROMMET, REAR BUMPER	4	MBHN1-50-021A	22	\$ 10.80
11	CLIP, REAR BUMPER	4	MC274-50-133	22	\$ 14.80
12	FASTENER, REAR BUMPER	6	MB45A-56-146A	22	\$ 18.00
13	GASKET LHS, TAILLAMP	1	MGJA1-51-163	22	\$ 27.70
14	GASKET RHS, TAILLAMP	1	MGJA1-51-153	22	\$ 27.70
TOTAL PARTS					\$ 2,390.50
LESS 10%					\$ 239.05
TOTAL PARTS COST					\$ 2,151.45
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.			660 \$ 1,650.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND REAR END PANEL.			945 \$ 1,575.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.			200 NETT \$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			111 X \$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	net 30	NETT \$ 100.00
TOTAL LABOUR				\$ - \$ 4,505.00
TOTAL PARTS				\$ - \$ 2,151.45
TOTAL				\$ - \$ 6,656.45
LESS EXCESS				\$ - \$ -
TOTAL AFTER EXCESS				\$ -
GST 7%				\$ - \$ -
GRAND TOTAL				\$ - \$ -

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

 Authorised Signature

TRANS EUROKARS PTE LTD hereby notifies the following: • The repair work is now pending • The repair work is now pending resurvey • Parts are being sent to confirmation • The repair work is being done on a "Without Prejudice" basis • No further claim is allowed • Supply of parts must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX :		NAME : Mr Ong Kah Pieng ADDRESS : 146 Lorong 2 Toa Payoh #05-318 Singapore 310146 TEL : 93697723		WIP : 54353 EXCESS : DATE: 11-Jun-19	
VEH NO :	SMA2399C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GL1071J0136791	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	28-Mar-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	REAR BUMPER	1			
2	BRACKET CENTER	1	MGJS1-50-221ABB	\$ 1,266.60	\$ 1,266.60
3	TOWING COVER LHS	1	MKD53-50-251		\$ 5.40
4	TOWING COVER RHS	1	MG4YL-50-EL1 E4	\$ 24.90	\$ 24.90
5	REAR REINFORCEMENT	1	MG4YL-50-EK1 E4	\$ 23.10	\$ 23.10
6	RETAINER CENTER, SENSOR	1	MGHK1-50-260	\$ 538.30	\$ 538.30
7	SENSOR CENTER, ULTRASONIC	2	MKD45-67-UC5AE4		\$ 31.00
8	TAPE PROTECTOR, SENSOR	2	MGMK6-67-UC1 E4		\$ 361.80
9	GROMMET, REAR BUMPER	4	MGS1D-50-EM1A	\$ 34.40	\$ 34.40
10	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 6.00	\$ 6.00
11	CLIP, REAR BUMPER	4	MBHN1-50-021A	\$ 10.80	\$ 10.80
12	FASTENER, REAR BUMPER	4	MC274-50-133	\$ 14.80	\$ 14.80
13	GASKET LHS, TAILLAMP	6	MB45A-56-146A	\$ 18.00	\$ 18.00
14	GASKET RHS, TAILLAMP	1	MGJA1-51-163	\$ 27.70	\$ 27.70
		1	MGJA1-51-153	\$ 27.70	\$ 27.70
TOTAL PARTS				\$ 1,992.30	\$ 2,390.50
LESS 10%				\$ 199.23	\$ 239.05
TOTAL PARTS COST				\$ 1,793.07	\$ 2,151.45
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR AREAS AFFECTED BY THE ACCIDENT.		\$ 660.00	\$ 1,650.00
2		TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.		\$ 945.00	\$ 1,575.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.		\$ 200.00	\$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
			TOTAL LABOUR	\$ 2,105.00 \$ 4,505.00
			TOTAL PARTS	\$ 1,793.07 \$ 2,151.45
			TOTAL	\$ 3,898.07 \$ 6,656.45
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 3,898.07
			GST 7%	\$ 272.86 \$ -
			GRAND TOTAL	\$ 4,170.93 \$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)