

ASS. REC. BY:

REF: CS/CTI190105731 Kvd3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Ong chin Kiat

of CTI

Date/Time: 14.6.19 14:46 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGC 5959C

Insured: GBJ 3068J

at Workshop m/s Ah Lim Motor

Tel: 648 31244

of 10 Amp Industrial Park 2A #01-09

Policy No: DMCSN1912719000

Claim No: SRM 19D20266602

Sum Insured:

Excess:

Make of Veh:

D.O.A. 10.6.2019

(Client's Record)

18.6.2019 10.4am

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14.6.19 2:51 p.m

Person Contacted: zila

Vehicle IN / OUT

Date/Time

Action/Instruction (V) Estimate

SGC 5959C - (CTI) AIG 130161121 (A 34)

D.O.A - 30/08/2013

GBJ 3068J - X

18/7 8625.00 Calfron (Red 4189.46, 8790)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ing Auth'd	Status
Main	14 Jun 2019		14 Jun 2019 14:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		AGRO TECHNIC PTE LTD, Co. Reg. No.: 198102315E							
Main Claimant:		YAP CHIP SING, ID: S16132651							
Vehicle Reg. No.:		SGC5959C	Date of Loss:	10/06/2019 08:00 - :59 [41 Months and 12 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / SNM19D202566C02	Policy/Cover Note No.:	DMCVSN19122719000					
Vehicle Reg. No. (Insured):		GBJ3068J	Policy No. (Claimant):	PNPV2016-00000460-02					
			Excess:	\$0.00					
Repairer:		Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]							
Claimant's Insurer:		FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/06/2019]							
Driver/Custodian (Insured):		IRWAN BIN KAMIL (44 / Male), NRIC: S7510787J Email:							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 3265I

Vehicle Details

Vehicle No.: SGC5959C
Vehicle to be Exported: Yes
Intended Deregistration Date: 10 Jun 2019
Vehicle Make: TOYOTA
Vehicle Model: TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour: Grey
Manufacturing Year: 2015
Engine No.: 1ZRY236353
Chassis No.: MR053REH104542524
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$19,589.00
Original Registration Date: 29 Dec 2015
First Registration Date: 29 Dec 2015
Transfer Count: 0
Actual ARF Paid: \$19,589.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Dec 2025
PARF Rebate Amount: \$14,691.00

Intended COE Rebate Details

COE Expiry Date: 28 Dec 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$56,001.00
COE Rebate Amount: \$36,671.00
Total Rebate Amount: \$51,362.00

The information contained herein is correct as at 10 Jun 2019

OK

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : YAP CHIP SING
BLK 227B COMPASSVALE DRIVE
#10-214
SINGAPORE 542227

Estimate No: MC1900432
Date: 10 Jun 2019
Policy No: PNPV2016-00000460-02
Veh Reg No: SGC5959C
Make/Model: TOYOTA COROLLA
ALTIS

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/06/2019
TP Veh Reg No: GBJ3068J

SURVEYOR COPY

Estimate Repair Cost to Vehicle No :SGC5959C

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 HEADLAMP	1 PC	2,816.10	X
2 FRONT BUMPER	1 PC	541.20	X
3 FRONT BUMPER SIDE RETAINER LH	1 PC	65.80	X
4 FRONT BUMPER CLIPS	15 PC	58.35	X
5 SPORT RIM LHF	1 PC	1,644.50	X
		5,125.95	
	Less 25%	1,281.49	3,844.46
LABOUR			
6 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
7 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	60/
8 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR FRONT FENDER LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	150/
9 TO SPRAY FRONT BUMPER, FRONT FENDER LH	1 PC	450.00	400/
		970.00	970.00
Total			S\$ 4,814.46
Add GST @ 7%			337.01
Total Amount Payable			S\$ 5,151.47

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND ONE HUNDRED FIFTY ONE AND CENTS FORTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

Not Withstand
Repair After Paint
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after repair painting
- To display damaged parts, during resurvey
- Parts prices are subject to resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification or tampering
- Supplier's name is subject to resurvey and to be written on the repair order

Approved by: [Signature]

For AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
[Signature]
AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19010573/KVD3N2

Date: 24/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19122719000	
Claimant Vehicle No :	SGC5959C	Insured Vehicle No :	GBJ3068J	
Date of Loss:	10/06/2019	Nature of Claim:	TP	Claim No: SNM19D202566C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC5959C	Engine No:	1ZRY236353
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104542524
Reg. Date:	29/12/2015 (Man. Year: 2015)	Odometer:	79481 km
Colour:	Metallic Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,844.46	0.00	3,844.46	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	970.00	625.00	345.00	35.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,814.46	625.00	4,189.46	87.02
+ GST 7.00/7.00% (\$\$)	337.01	43.75	293.26	87.02
Nett Amount (\$\$)	5,151.47	668.75	4,482.72	87.02

INSPECTION

Date of Assignment:	14/06/2019	
Date Inspected:	18/06/2019	Inspected At: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 23 Jul 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGC5959C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Serviceable	2,816.10 FL	*- FL
2	1		*FRONT BUMPER	Repair	541.20 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	65.80 FL	*- FL
4	1		*FRONT BUMPER CLIPS	Not Necessary	58.35 FL	*- FL
5	1		*SPORT RIM LHF	Repair	1,644.50 FL	*- FL
					Sub Total (S\$)	5,125.95
					- List Item Discount on L Items 25.00/25.00% (S\$)	0.00
					Total Parts (S\$)	0.00

F=Franchise part. L=List/ItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	60.00
3	TO DISMANTLE ALL DAMAGED PARTS.TO KNOCK & REPAIR FRONT FENDER LH,INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	400.00	150.00
4	TO SPRAY FRONT BUMPER,FRONT FENDER LH	New	450.00	400.00
Gross Labour Cost (\$\$)			970.00	625.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >