

18/6/2010

INS. CASE OWNER:

CC 6/CTI1901 0583, Udab32

LKK:

IDAC:

Surveyor:

marcus

DOI:

ASSIGNMENT

14/6/19

Date / Time:

14/6/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKL 5900P

Name of Insured:

MDM ALICE HO ONG ENG

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

17/6/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES) NO

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

Smj 5797 h



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

28/6/19

called OZ to inform TP claim

12/2/19

FILE PAS TO TYPE MANDATE

13/2/19

FILE PAS TO LIP TO CLOSE

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

20/6/19 - 020 - 020

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 12/2/19

Confirm with: Jason

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

Repair Cost: (w/631)

SS 6420.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

360.00 (S 60 x 6 days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS 6780.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

6780.00

Name 1:

Fastech Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$400

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D SMJ 57974

NJP Auto and
Mak
2/5 \$ 6000
5 day
14/6/19

List Item:

1 PCS	REAR WINDSCREEN MOULDING	
1 PCS	TAILGATE	753.00
1 PCS	TAILGATE OUTER HANDLE GARNISH	
1 PCS	TAILGATE 'H' LOGO	
2 PCS	TAILGATE REFLECTORS @\$280	
1 PCS	TAILGATE 'VEZEL' EMBLEM	
1 PCS	TAILGATE INNER LOCK	
1 PCS	TAILGATE LOCK STRIKER	
1 PCS	TAILGATE INNER TRIM BOARD	
1 SET	TAILGATE INNER TRIM BOARD CLIPS	
1 PCS	TAILGATE WEATHERSTRIP	
1 PCS	TAILGATE KEYLESS SENSOR	
1 PCS	REAR BUMPER CENTRE	
2 PCS	REAR BUMPER SIDES @\$235.10	
2 PCS	REAR BUMPER SIDE RETAINERS @\$35.20	
2 PCS	REAR BUMPER SCREW SPACERS @\$12	
2 PCS	REAR BUMPER REFLECTORS @\$151.20	
2 PCS	TAILLAMPS @\$460.60	
2 PCS	TAILLAMP HOUSING PANELS @\$195	
1 PCS	REAR END PANEL	
1 PCS	REAR END PANEL TOP GARNISH	
1 PCS	REAR BUMPER LOWER DIFFUSER	
1 SET	REAR BUMPER LOWER DIFFUSER CLIPS	
1 PCS	REAR EXHAUST	
2 PCS	REAR EXHAUST MOUNTINGS @\$45	
1 PCS	REAR EXHAUST HEAT SHIELD	
2 PCS	REAR FENDER INNER TRIMS @\$295.30	
1 SET	REAR FENDER INNER TRIM CLIPS	
2 PCS	REAR FENDER OUTER GARNISH @\$195.80	
1 PCS	REAR FLOOR PANEL top board	365.50
1 PCS	REAR FLOOR PANEL TOOLS Tray	
2 PCS	REAR FENDERS @\$1100	

List Item Total:

Special Nett Item:

1 SET	REAR BUMPER REVERSE SENSOR
1 PCS	REAR REVERSE CAMERA
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR FLOOR PANEL INSULATOPR

Special Nett Total:

Labour Charge:

TO CHECK WIRING

rear	\$	121.30	/
body	\$	1,100.90	/
11	\$	285.30	X
11	\$	35.80	X
o/s cr	\$	560.00	pc
rear	\$	56.20	/
twi	\$	198.50	/
11	\$	25.50	X
before	\$	321.70	/
rear	\$	50.00	/
twi	\$	135.70	/
11	\$	180.00	X
7/5	\$	762.70	/
o/s cr	\$	470.20	pc
11	\$	70.40	X
11	\$	24.00	X
o/s cr	\$	302.40	cc
o/s cr	\$	921.20	pc
cr	\$	390.00	/
20/24	\$	514.00	/
twi	\$	125.00	/
twi	\$	348.20	/
rear	\$	50.00	/
cr	\$	899.20	X
11	\$	90.00	X
11	\$	98.30	X
o/s cr	\$	590.60	pc
11	\$	50.00	X
twi	\$	391.60	pc
wired/re	\$	912.30	/
twi	\$	685.00	/
cr	\$	2,200.00	X
	\$	12,966.00	

shud	\$	280.00	200
11	\$	500.00	X
rear	\$	50.00	40
rear	\$	50.00	/
11	\$	180.00	X
	\$	1,060.00	

630480
202
504384

\$ 80.00 30

TO DISMANTLE & REPLACE REVERSE SENSOR	\$ 80.00	50
TO TRANSFER TAILGATE MECHANISM	\$ 100.00	60
TO DISMANTLE & REFIX REAR WINDSCREEN	\$ 150.00	120
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$ 150.00	80
TO DISMANTLE & REPLACE REAR EXHAUST	\$ 100.00	60
TO SPRAY RUST PROOFING	\$ 150.00	60
TO MOUNT VEHICLE ON CAR O-LINER	\$ 17 380.00	X
TO DISMANTLE & REFIX PETROL TANK	\$ 17 100.00	X
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS	\$ 2,000.00	700
TO PUTTY & SPRAY PAINTING	\$ 2,000.00	1050
Labour Charge Total:	\$ 5,290.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 19,316.00x

7547.84
6035

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Points photo are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal third (party) is allowed
- Supplier (party) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1891H

Vehicle Details

Vehicle No.: SMJ5797U

Vehicle to be Exported: No

Intended Deregistration Date: 14 Jun 2019

Vehicle Make: HONDA

Vehicle Model: VEZEL HYBRID 1.5X AUTO

Primary Colour: White

Manufacturing Year: 2018

Engine No.: LEB6728875

Chassis No.: RU31308866

Maximum Power Output: 112.0 kW (150 bhp)

Open Market Value: \$26,341.00

Original Registration Date: 12 Mar 2019

First Registration Date: 12 Mar 2019

Transfer Count: 0

Actual ARF Paid: \$18,878.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 11 Mar 2029

PARF Rebate Amount: \$14,158.00

Intended COE Rebate Details

COE Expiry Date: 11 Mar 2029

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$36,961.00

COE Rebate Amount: \$35,992.00

Total Rebate Amount: \$50,150.00

The information contained herein is correct as at 14 Jun 2019

OK

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19010583/Udb3s2

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 26-12-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKC 5999P	Veh. Inspected	SMJ 5797U
Policy No.	DMPCSN3017991804	Coverage (\$)	0.00
Claim No.	SNM19D202774C02	Excess (\$)	0.00
Assign From		Assign Date	14/06/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL HYBRID (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	RU31308866	Colour	WHITE
Odometer	021446	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	DUNLOP	6 mm
L/H Front Tyre	205/60 R16	DUNLOP	6 mm
R/H Rear Tyre	205/60 R16	DUNLOP	6 mm
L/H Rear Tyre	205/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/06/2019	Inspection Date	14/06/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 5797U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING	NECESSARY	121.30	121.30
1	TAILGATE	BADLY DENTED	1,100.90	953.00
1	TAILGATE OUTER HANDLE GARNISH	NOT NECESSARY	285.30	-
1	TAILGATE 'H' LOGO	NOT NECESSARY	35.80	-
2	TAILGATE REFLECTORS @ \$280.00	O/S CRACKED	560.00	280.00
1	TAILGATE 'LOGO' EMBLEM	NECESSARY	56.20	56.20
1	TAILGATE INNER LOCK	TWISTED	198.50	198.50
1	TAILGATE LOCK STRIKER	NOT NECESSARY	25.50	-
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	321.70	321.70
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE WEATHERSTRIP	TWISTED	135.70	135.70
1	TAILGATE KEYLESS SENSOR	NOT NECESSARY	180.00	-
1	REAR BUMPER CENTRE	DISTORTED	762.70	762.70
2	REAR BUMPER SIDES @ \$235.10	O/S DEFORMED	470.20	235.10
2	REAR BUMPER SIDE RETAINER @ \$35.20	NOT NECESSARY	70.40	-
2	REAR BUMPER SCREW SPACERS @ \$12.00	NOT NECESSARY	24.00	-
2	REAR BUMPER REFLECTORS @ \$151.20	O/S CRACKED	302.40	151.20
2	TAILLAMPS @ \$460.60	O/S CRACKED	921.20	460.60
2	TAILLAMP HOUSING PANELS @ \$195.00	TO REPAIR SEE LABOUR	390.00	-
1	REAR END PANEL	DENTED / BENT	514.00	514.00
1	REAR END PANEL TOP GARNISH	TWISTED	125.00	125.00
1	REAR BUMPER LOWER DIFFUSER	TORN	348.20	348.20
1	SET REAR BUMPER LOWER DIFFUSER CLIPS	NECESSARY	50.00	50.00
1	REAR EXHAUST	TO REPAIR SEE LABOUR	899.20	-
2	REAR EXHAUST MOUNTINGS @ \$45.00	NOT NECESSARY	90.00	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	98.30	-
2	REAR FENDER INNER TRIMS @ \$295.30	O/S TORN	590.60	295.30
1	SET REAR FENDER INNER TRIM CLIPS	NOT NECESSARY	50.00	-
2	REAR FENDER OUTER GARNISH @ \$195.80	TORN	391.60	195.80

Report Ref No. CC6/CTI19010583/Udb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL TOP BOARD	WARPED / DEFORMED	912.30	365.50
1	REAR FLOOR PANEL TOOLS TRAY	TWISTED	685.00	685.00
2	REAR FENDERS @ \$1100.00	TO REPAIR SEE LABOUR	2,200.00	-
	LESS 20% DISCOUNT		-	-1,260.96
			12,966.00	5,043.84
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	500.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	180.00	-
			1,060.00	290.00
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACE REVERSE SENSOR.		80.00	50.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	60.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSETRY.		150.00	80.00
	TO DISMANTLE & REPLACE REAR EXHAUST.		100.00	60.00
	TO SPRAY RUST PROOFING.		150.00	60.00
	TO MOUNT VEHICLE ON CAR-O-LINER.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS, REAR EXHAUST AND REAR FENDERS.		2,000.00	700.00
	TO PUTTY & SPRAY PAINTING.		2,000.00	1,050.00
			5,290.00	2,210.00
	GRAND TOTAL		19,316.00	7,543.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,000.00

Report Ref No. CC6/CTI19010583/Udb3s2



Report Ref No. CC6/CTI19010583/Udb3s2

A handwritten signature in black ink, appearing to be 'Ch' followed by a stylized flourish.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.