

25/03/2019

A.S. REC. BY:

REF: CS/MSG 19010598

Tl Vd3⁵⁷

Special Instruction:

Surveyor

TAN KKH

ASSIGNMENT (Office)

From (Person): Christina Wong

of MSG

Date/Time: 14.6.19 16.32p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGL 3969P

Insured: GBE 2847K

at Workshop m/s Torque 5

Tel: 8 1316518

of 8 Kaki Bukit Ave 4, #01-49/50

Policy No: 2863205 MCC

Claim No:

Sum Insured:

Excess:

D.O.A. 12.6.2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

my

H.O.D. Endorsement:

Date/Time: 14.6.19 4.37p.m

Person Contacted:

Lucas

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGL 3969P - CS/MSG 1701599 2/Auber D.O.A - 14/08/2017
	GBE 2847K - NA/MSG 18011800164 D.O.A - 04/12/2018
19/6/19	Send preli revised via merimen, pending parts prices from repairer
23/7/19	@ 4.19pm Lucas will check and call back
24/7/19	@ 3.45pm Lucas said vehicle has not send in for repair

(08/11/13)

ASS. REC. BY: Tan Jhu

REF

MSIG

ASSIGNMENT

From:

Date:

18.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGL 3969Pat Workshop m/s Torque 5

of 8 kaki Bukit Ara 4 #01-49

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

1-30p-h owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$15K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

my

Date:

Person Contacted:

Vehicle: IN / OUT

LUL

Veh No:

SGL 3969P

Yr Regn:

2006 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi L200

c.c

1499

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

28675

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMYLT223W02000679

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /

TOYO / YOKO or

Dayton

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18/6/19

Survey held at

Torque 5

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/8/19 Repair limit \$3000. inform insurer.

21/8/19 45 \$ 3000, 5 days

22/8/19 LS \$3000 confirmed by email (Recd 15,091 To, 831)

23/8/19 Send preli revised via merimen

RECEIVED 26 AUG 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

23/8 - typist

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format:

merimen

Lump Sum / I.B.I. (\$

3000/-

19

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jun 2019		14 Jun 2019 16:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Aliff's Puffs N Such, Co. Reg. No.: 53114478W		
Main Claimant:	LIM YEW SAN, ID: S7409238A		
Vehicle Reg. No.:	SGL3969P	Date of Loss:	12/06/2019 19:00 - :59 [152 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28832025MKC (Comprehensive) Coverage: 16/10/2016 - 15/10/2019
Vehicle Reg. No. (Insured):	GBE2847K	Policy No. (Claimant):	
		Excess:	
Repairer:	Torque 5 Bodyworks Pte Ltd (HQ) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/06/2019]		
Adj Asg. Remarks:	on WP. Veh in 18/06/2019. Liab: dispute (OI NR) . TP Agree on SJE- assign Marcus Chua from LKK Auto Consultants. Contact: Lucas (8131 6518)		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 12 / 06 / 2019 (dd/mm/yy) Time of Accident: 19 : 30 (24-HR-FORMAT)

Vehicle No.: SGL3969P Vehicle Make & Model: Mitsubishi CoH Plus

Exact location of Accident: M Yishun Central Road

Policyholder's Name / IC No.: Earvin Lim Yew San (S7409238A)

Driver's Name / IC No.: _____ (As Above) ☒

Driver's Contact No.: 9277 1680 Company Contact No.: _____

Driver's Address: Blk 37A Yishun Ave 11 #12-519 S (761347)

Insurance Company: NIC Email address (if any): _____

Relationship between Owner & Driver: (Please CIRCLE one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: _____

What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

**Exact purpose for which the vehicle
was being used at time of accident?**

☒ Private use / ☐ Work purpose

Occupation (nature of job) ☒ Indoor / ☐ Outdoor

No. of Passengers (Including Driver): 1

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No.: _____ Vehicle No: GBE 2847 K

Driver's Contact No.: _____ Insurance Company (If any): _____

2. Driver's Name / IC No.: _____ Vehicle No: _____

Driver's Contact No.: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I (Vehicle A: SGL 3969 P) was stationary in my lane at the above mentioned venue as the traffic light was red. All of a sudden, I felt an impact from my rear portion & realised that Vehicle B (GBE 2847 K) had collided into my vehicle due to unable to stop in time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 23 Aug 2019

Preliminary Advice

Insured Vehicle No	: GBE2847K	Accident Date	: 12/06/2019
TP Vehicle No	: SGL3969P	Assignment Date	: 14/06/2019
Make	: MITSUBISHI COLT	Est. Duration of Repair	: 5
Date of Inspection	: 18/6/2019		
Inspection At	: TORQUE 5 PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,091.70
Revised Amount	:S\$	3,000.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,000.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Christina Wong	Date: 19 Jun 2019
Preliminary Advice	

Insured Vehicle No	: GBE2847K	Accident Date	: 12/06/2019
TP Vehicle No	: SGL3969P	Assignment Date	: 14/06/2019
Make	: MITSUBISHI COLT	Est. Duration of Repair	: 5
Date of Inspection	: 18/6/2019		
Inspection At	: TORQUE 5 BODYWORKS PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,165.00 (LABOUR ONLY)
Revised Amount	:S\$	2,275.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,275.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.
Pending parts prices from repairer.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9238A
Vehicle Details	
Vehicle No.:	SGL3969P
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	COLTPLUSPRT
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	4A910027984
Chassis No.:	JMYLTZ23W6Z000679
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$16,484.00
Original Registration Date:	14 Sep 2006
First Registration Date:	14 Sep 2006
Transfer Count:	0
Actual ARF Paid:	\$18,133.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,227.00
COE Rebate Amount:	\$9,432.00
Total Rebate Amount:	\$9,432.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Jun 2019

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 9238A

Vehicle Details

Vehicle No.: SGL3969P
Vehicle to be Exported: Yes
Intended Deregistration Date: 13 Jun 2019
Vehicle Make: MITSUBISHI
Vehicle Model: COLTPLUSPRT
Primary Colour: Black
Manufacturing Year: 2006
Engine No.: 4A910027984
Chassis No.: JMYLTZ23W6Z000679
Maximum Power Output: 77.0 kW (103 bhp)
Open Market Value: \$16,484.00
Original Registration Date: 14 Sep 2006
First Registration Date: 14 Sep 2006
Transfer Count: 0
Actual ARF Paid: \$18,133.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$23,227.00
COE Rebate Amount: \$9,510.00
Total Rebate Amount: \$9,510.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Jun 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

The Most Comfortable 2+2 Seat Supercar In The World!



F12 Facelift, More Than \$120K Of Extras And Ferrari Original Replaced Parts.
Direct Owner [See Ad](#)

AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

[Browse by Category](#)
[Sort by Date Posted](#)
[40 results/page](#)

4 vehicles

Colt Plus 1.5A

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Colt Plus 1.5A		Any	Any	Any	Any	Any	Any	Available
	Mitsubishi	Colt Plus 1.5A (COE till 01/2024)	\$28,800	\$6,300 /yr	07-Jan-2009	1,499 cc	91,000 km	Hatchback	Available
"One Year In-House Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, Bank & In-House Loan Available, Purchase Comes With Official Warranty Certificate For A Peace Of Mind, Fu...									
Carway									
Posted: 11-Jun-2019 Tags: 2009 Mitsubishi Colt, 2009 mitsubishi colt, Mitsubishi Colt, mitsubishi colt, Mitsubishi, Colt, colt, Used Mitsubishi									
	Mitsubishi	Colt Plus 1.5A (COE till 04/2024)	\$29,800	\$6,100 /yr	06-May-2009	1,499 cc	110,000 km	Hatchback	Available
"One Year In-House Warranty", Beautiful White Colt Plus, High Loan Available, Price Stated Above Is Actual Selling Price, New Paintwork Done, Bank And In-House Loan Available, Purchase Comes With Offi...									
Carway									
Posted: 13-Jun-2019 Tags: 2009 Mitsubishi Colt, 2009 mitsubishi colt, Mitsubishi Colt, mitsubishi colt, Mitsubishi, Colt, colt, Used Mitsubishi									
	Mitsubishi	Colt Plus 1.5A (New 5-yr COE)	\$29,800	\$5,950 /yr	26-Jun-2009	1,499 cc	-	Hatchback	Available
AA Trust Certified Quality Pre-Owned Vehicle! Well Maintained By Previous Owner! Low Fuel Consumption And Low Maintenance Cost! Smooth And Responsive Engine! Huge Cabin And Boot Space! Flexible Bank/1...									
AA Trust Automotive									
Posted: 09-Jun-2019 Tags: 2009 Mitsubishi Colt, 2009 mitsubishi colt, Mitsubishi Colt, mitsubishi colt, Mitsubishi, Colt, colt, Used Mitsubishi									
	Mitsubishi	Colt Plus 1.5A	\$20,300	\$8,740 /yr	30-Sep-2010	1,499 cc	79,000 km	Hatchback	Available
Most Of The Wear And Tear Has Been Done Up. Drive With A Peace Of Mind For The Next 12 Months. Arrange An Appointment With Us To Now. Loan And Insurance Packages.									
Posted: 16-May-2019 Tags: 2010 Mitsubishi Colt, 2010 mitsubishi colt, Mitsubishi Colt, mitsubishi colt, Mitsubishi, Colt, colt, Used Mitsubishi									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

40 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Colt Plus 1.5A, Colt Plus 1.5A Singapore comprising parallel importers, authorised car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT**Vehicle No** : SGL3969P**Estimation No.** : E19060010**Make & Model** :**DOA**

: 13/06/2019

MITSUBISHI, COLT PLUS SPRT, JMYLTZ23W6Z000679

**Year of
Manufacture**

: 2006

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper <i>de✓</i>	1.00	0.00	0.00
2	Rear bumper retainer (LH) <i>de✓</i>	1.00	0.00	0.00
3	Rear bumper retainer (RH) <i>de✓</i>	1.00	0.00	0.00
4	Rear bumper reflector (LH) <i>X</i>	1.00	0.00	0.00
5	Rear bumper reflector (RH) <i>X</i>	1.00	0.00	0.00
6	Rear bumper bracket (LH) <i>?</i>	1.00	0.00	0.00
7	Rear bumper bracket (RH) <i>?</i>	1.00	0.00	0.00
8	Auto tailgate <i>bt✓</i>	1.00	0.00	0.00
9	Tailgate lock & motor assy <i>?</i>	1.00	0.00	0.00
10	Tailgate lock switch <i>X</i>	1.00	0.00	0.00
11	Tailgate inner push button <i>X</i>	1.00	0.00	0.00
12	Tailgate hinge (LH) <i>X</i>	1.00	0.00	0.00
13	Tailgate hinge (RH) <i>X</i>	1.00	0.00	0.00
14	Tailgate damper (LH) <i>X</i>	1.00	0.00	0.00
15	Tailgate damper (RH) <i>X</i>	1.00	0.00	0.00
16	Tailgate lamp (LH) <i>?</i>	1.00	0.00	0.00
17	Tailgate lamp (RH) <i>?</i>	1.00	0.00	0.00
18	License lamp garnish <i>?</i>	1.00	0.00	0.00
19	License lamp (LH) <i>X</i>	1.00	0.00	0.00
20	License lamp (RH) <i>X</i>	1.00	0.00	0.00
21	Tailgate inner trim board <i>?</i>	1.00	0.00	0.00
22	Tailgate inner side garnish (LH) <i>X</i>	1.00	0.00	0.00
23	Tailgate inner side garnish (RH) <i>X</i>	1.00	0.00	0.00
24	Tailgate inner centre garnish <i>X</i>	1.00	0.00	0.00
25	Tailgate inner pull handle garnish <i>X</i>	1.00	0.00	0.00
26	Tailgate rubber beading <i>?</i>	1.00	0.00	0.00
27	Tailgate wiper motor <i>X</i>	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGL3969P
Make & Model : MITSUBISHI, COLT PLUS SPT, JMYLTZ23W6Z000679
Year of Manufacture : 2006

Estimation No. : E19060010
DOA : 13/06/2019

No	Description	Qty	U/P	Amt
28	Tailgate wiper arm ✕	1.00	0.00	0.00
29	Rear windscreen ✕	1.00	0.00	0.00
30	Rear windscreen moulding <i>nc</i>	1.00	0.00	0.00
31	Auto tailgate motor assy ✕	1.00	0.00	0.00
32	End panel <i>Rx</i>	1.00	0.00	0.00
33	End panel top garnish ?	1.00	0.00	0.00
34	Tail lamp (LH) ?	1.00	0.00	0.00
35	Tail lamp (RH) ✕	1.00	0.00	0.00
36	Tail lamp inner panel (LH) ✕	1.00	0.00	0.00
37	Tail lamp inner panel (RH) ✕	1.00	0.00	0.00
38	Spare tyre panel ✕	1.00	0.00	0.00
39	Spare tyre panel top board ✕	1.00	0.00	0.00
40	Rear fender inner trim (LH) ✕	1.00	0.00	0.00
41	Rear fender inner trim (RH) ✕	1.00	0.00	0.00
42	Rear speaker panel top board ✕	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

43	Reverse sensor set	1.00	250.00	250.00 <i>200 new</i>
44	Reverse camera	1.00	500.00	500.00 ✕
45	Tailgate emblem	1.00	120.00	120.00 <i>nc</i>
46	Rear number plate & casing	1.00	45.00	45.00 <i>bt</i>
47	Rear bumper clip set	1.00	50.00	50.00 <i>30 new</i>
48	Tailgate inner trim board clip set	1.00	50.00	50.00 ✕
49	End panel top garnish clip set	1.00	30.00	30.00 <i>910 new</i>
50	Tail lamp clip set	1.00	30.00	30.00 ✕
51	End panel sealant	1.00	50.00	50.00 ✕

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGL3969P

Estimation No. : E19060010

Make & Model :

DOA

: 13/06/2019

MITSUBISHI, COLT PLUS SPT, JMYLTZ23W6Z000679

Year of
Manufacture

: 2006

No	Description	Qty	U/P	Amt
52	Spare tyre panel sealant	1.00	50.00	50.00
53	Spare tyre panel insulator matt	1.00	280.00	280.00
54	Rear windscreen sealant	1.00	50.00	50.00
55	Rear windscreen tinted	1.00	200.00	200.00

Amt S\$ 1,705.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 1,705.00

Section: Labour Items

56	To R&R rear bumper reverse sensor	1.00	80.00	80.00
57	To check wiring and lighting system	1.00	80.00	80.00
58	To supply undercoating / putty on affected areas	1.00	80.00	80.00
59	To R&R rear windscreen	1.00	60.00	60.00
60	To R&R tailgate mechanism	1.00	200.00	200.00
61	To R&R rear trims, garnish and seats assy	1.00	200.00	200.00
62	To R&R fuel tank to cut & weld	1.00	250.00	250.00
63	To repair, replace & realign damaged areas	1.00	350.00	350.00
64	To spray painting on affected areas	1.00	1,200.00	1,200.00
65	To perform water seepage test after repair	1.00	1,100.00	1,100.00
66	Sundries	1.00	160.00	160.00

Amt S\$ 3,760.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 3,760.00

Tanjilun 17495749
 - WP
 18/6/19 @ 130pm
 Resurvey after repair
 sur@lkkauto.com

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal	S\$ 0.00
Special Nett Items	S\$
Subtotal	1,705.00
Labour Items Subtotal	S\$
	3,760.00
Total	S\$
	5,465.00

PAGE 3 OF 3

5165



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGL3969P

Make & Model :

MITSUBISHI, COLT PLUS SPRT, JMYLTZ23W6Z000679

Year of

: 2006

Manufacture

Estimation No. : E19060010

DOA

: 13/06/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper <i>de✓</i>	1.00	✓ 0.00 722.00	0.00 <i>681</i>
2	Rear bumper retainer (LH) <i>ne✓</i>	1.00	✓ 0.00 40.00	0.00
3	Rear bumper retainer (RH) <i>ne✓</i>	1.00	✓ 0.00 40.00	0.00
4	Rear bumper reflector (LH) <i>X</i>	1.00	0.00 45.00	0.00
5	Rear bumper reflector (RH) <i>X</i>	1.00	0.00 45.00	0.00
6	Rear bumper bracket (LH) <i>X u- n</i>	1.00	0.00 76.00	0.00
7	Rear bumper bracket (RH) <i>?</i>	1.00	0.00 76.00	0.00
8	Auto tailgate <i>bt✓</i>	1.00	✓ 0.00 894.00	0.00
9	Tailgate lock & motor assy <i>? bt✓</i>	1.00	✓ 0.00 492.00	0.00 <i>166</i>
10	Tailgate lock switch <i>X u</i>	1.00	0.00 132.00	0.00
11	Tailgate inner push button <i>X u</i>	1.00	0.00 127.00	0.00
12	Tailgate hinge (LH) <i>X</i>	1.00	0.00 95.00	0.00
13	Tailgate hinge (RH) <i>X u</i>	1.00	0.00 95.00	0.00
14	Tailgate damper (LH) <i>X</i>	1.00	0.00 135.00	0.00
15	Tailgate damper (RH) <i>X</i>	1.00	0.00 135.00	0.00
16	Tailgate lamp (LH) <i>* ? ana✓</i>	1.00	✓ 0.00 220.00	0.00
17	Tailgate lamp (RH) <i>* ? ana✓</i>	1.00	✓ 0.00 220.00	0.00
18	License lamp garnish <i>? ana✓</i>	1.00	✓ 0.00 98.00	0.00
19	License lamp (LH) <i>X u</i>	1.00	0.00 62.00	0.00
20	License lamp (RH) <i>X u</i>	1.00	0.00 62.00	0.00
21	Tailgate inner trim board <i>* ? ana✓</i>	1.00	✓ 0.00 240.00	0.00
22	Tailgate inner side garnish (LH) <i>X u</i>	1.00	0.00 92.30	0.00
23	Tailgate inner side garnish (RH) <i>X u</i>	1.00	0.00 92.30	0.00
24	Tailgate inner centre garnish <i>X u</i>	1.00	0.00 102.30	0.00
25	Tailgate inner pull handle garnish <i>X u</i>	1.00	0.00 43.60	0.00
26	Tailgate rubber beading <i>? ana✓</i>	1.00	✓ 0.00 210.00	0.00
27	Tailgate wiper motor <i>X u</i>	1.00	0.00 513.60	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGL3969P

Make & Model :

MITSUBISHI, COLT PLUS SPRT, JMYLTZ23W6Z000679

Year of Manufacture :

2006

Estimation No. : E19060010

DOA

: 13/06/2019

No	Description	Qty	U/P	Amt
28	Tailgate wiper arm <i>x un</i>	1.00	0.00 137.20	0.00
29	Rear windscreen <i>x un</i>	1.00	0.00 873.60	0.00
30	Rear windscreen moulding <i>acc</i>	1.00	✓ 0.00 115.00	0.00
31	Auto tailgate motor assy <i>x un</i>	1.00	0.00 1315.30	0.00
32	End panel <i>Rx</i>	1.00	0.00 450.00	0.00
33	End panel top garnish <i>? cut</i>	1.00	✓ 0.00 219.00	0.00
34	Tail lamp (LH) <i>? cut</i>	1.00	✓ 0.00 380.00	0.00 325
35	Tail lamp (RH) <i>x un</i>	1.00	0.00 380.00	0.00 325
36	Tail lamp inner panel (LH) <i>x</i>	1.00	0.00 115.30	0.00
37	Tail lamp inner panel (RH) <i>x</i>	1.00	0.00 115.30	0.00
38	Spare tyre panel <i>x</i>	1.00	0.00 1058.60	0.00
39	Spare tyre panel top board <i>x</i>	1.00	0.00 210.00	0.00
40	Rear fender inner trim (LH) <i>x</i>	1.00	0.00 590.00	0.00
41	Rear fender inner trim (RH) <i>x</i>	1.00	0.00 590.00	0.00
42	Rear speaker panel top board <i>x</i>	1.00	0.00 326.30	0.00

3088

11 976.70 Amt
Discount (0.00%)
Subtotal

S\$ 0.00 3464
S\$ 0.00 10% 3117.60
S\$ 0.00

Section: Special Nett Items

43	Reverse sensor set	1.00	250.00	250.00 <i>200 un</i>
44	Reverse camera	1.00	500.00	500.00 <i>x un</i>
45	Tailgate emblem	1.00	120.00	120.00 <i>acc</i>
46	Rear number plate & casing	1.00	45.00	45.00 <i>bt</i>
47	Rear bumper clip set	1.00	50.00	50.00 <i>3 one</i>
48	Tailgate inner trim board clip set	1.00	50.00	50.00 <i>x un</i>
49	End panel top garnish clip set	1.00	30.00	30.00 <i>910 un</i>
50	Tail lamp clip set	1.00	30.00	30.00 <i>x un</i>
51	End panel sealant	1.00	50.00	50.00 <i>x un</i>

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGL3969P
Make & Model : MITSUBISHI, COLT PLUS SPRT, JMYLTZ23W6Z000679
Year of Manufacture : 2006

Estimation No. : E19060010
DOA : 13/06/2019

No	Description	Qty	U/P	Amt
52	Spare tyre panel sealant	1.00	50.00	50.00
53	Spare tyre panel insulator matt	1.00	280.00	280.00
54	Rear windscreen sealant	1.00	50.00	50.00
55	Rear windscreen tinted	1.00	200.00	200.00
				Amt S\$ 1,705.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,705.00

Section: Labour Items

56	To R&R rear bumper reverse sensor	1.00	80.00	80.00
57	To check wiring and lighting system	1.00	80.00	80.00
58	To supply undercoating / putty on affected areas	1.00	80.00	80.00
59	To R&R rear windscreen	1.00	60.00	60.00
60	To R&R tailgate mechanism	1.00	200.00	200.00
61	To R&R rear trims, garnish and seats assy	1.00	200.00	200.00
62	To R&R fuel tank to cut & weld	1.00	250.00	250.00
63	To repair, replace & realign damaged areas	1.00	350.00	350.00
64	To spray painting on affected areas	1.00	1,200.00	1,200.00
65	To perform water seepage test after repair	1.00	1,200.00	1,200.00
66	Sundries	1.00	160.00	160.00
				Amt S\$ 3,760.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 3,760.00

parts = 4038 - 20% AAA Tanjilun 17495749
= 3230.40

S/N = 555

Labour = 1720

P + S + L = 5505.40 - 20% L/S

= #4400

Limit Repair #3K.

Amt S\$ 3,760.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 3,760.00

3117.60

555

1720

5392.60

4300

limit repair \$3000 * 18,091.70

List Items Subtotal	S\$ 0.00
Special Nett Items	S\$
Subtotal	1,705.00
Labour Items Subtotal	S\$
	3,760.00
Total	S\$
	5,465.00

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 23 August 2019 4:23 PM
To: Torque 5 Assessment
Cc: claims@torque5.com; sam.chang@torque5.com; SUR
Subject: RE: SGL 3969 P - Finalisation & After Repair Photo -DOA: 12/6/2019

Dear Lucas,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to MSIG INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Torque 5 Assessment <assessment@torque5.com>
Sent: Thursday, 22 August 2019 4:33 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: 'Torque 5 Assessment' <assessment@torque5.com>; claims@torque5.com; sam.chang@torque5.com
Subject: RE: SGL 3969 P - Finalisation & After Repair Photo -DOA: 12/6/2019

Dear Veron ,



We hereby confirm the COR \$3000 with 05 days .

Thank you .

Warmest Regards,

Lucas Chow

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Mobile (65) 8131 6518

Email lucas.chow@torque5.com

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com





From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, August 22, 2019 11:31 AM
To: Torque 5 Assessment; SUR
Cc: claims@torque5.com; sam.chang@torque5.com
Subject: RE: SGL 3969 P - Finalisation & After Repair Photo -DOA: 12/6/2019

Dear Lucas,

WITHOUT PREJUDICE

Offer limit repair Lump Sum \$3000 @ 5 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email
:sur@lkkauto.com | fax: 6256-



4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Torque 5 Assessment <assessment@torque5.com>
Sent: Wednesday, 7 August 2019 2:35 PM
To: SUR <sur@lkkauto.com>
Cc: 'Torque 5 Assessment' <assessment@torque5.com>; claims@torque5.com; sam.chang@torque5.com
Subject: SGL 3969 P - Finalisation & After Repair Photo .

Dear All ,



Kindly check the attach and confirm the finalise amount .

Thank you .

Warmest Regards,

Lucas Chow

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Mobile (65) 8131 6518

Email lucas.chow@torque5.com

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jun 2019		14 Jun 2019 16:32 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Aliff's Puffs N Such, Co. Reg. No.: 53114478W		
Main Claimant:	LIM YEW SAN, ID: S7409238A		
Vehicle Reg. No.:	SGL3969P	Date of Loss:	12/06/2019 19:00 - :59 [152 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 596766	Policy/Cover Note No.:	28832025MKC (Comprehensive) Coverage: 16/10/2016 - 15/10/2019
Vehicle Reg. No. (Insured):	GBE2847K	Policy No. (Claimant):	
		Excess:	
Repairer:	Torque 5 Bodyworks Pte Ltd (HQ) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/07/2019]		
Adj Asg. Remarks:	on WP. Veh in 18/06/2019. Liab: dispute (OI NR) , TP Agree on SJE- assign Marcus Chua from LKK Auto Consultants. Contact: Lucas (8131 6518)		

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGL3969P (596766)**
[GBE2847K]
TP
LIM YEW SAN
Jun 12 2019 7:00PM
[Aliff's Puffs N Such]
Torque 5 Bodyworks Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser ▼](#)

Assessment Reports

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page ▼	Thumbnail	Print
1	19/06/19 12:45	Adjuster Immediate Advice	1	Load HTM	
2	23/08/19 16:30	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	22/08/19 11:25	General View	1	Load JPG	✓
2	22/08/19 11:25	General View	1	Load JPG	✓
3	22/08/19 11:25	General View	1	Load JPG	✓
4	22/08/19 11:25	General View	1	Load JPG	✓
5	22/08/19 11:25	General View	1	Load JPG	✓
6	22/08/19 11:25	General View	1	Load JPG	✓
7	22/08/19 11:25	General View	1	Load JPG	✓
8	22/08/19 11:25	General View	1	Load JPG	✓
9	22/08/19 11:25	General View	1	Load JPG	✓
10	22/08/19 11:25	General View	1	Load JPG	✓
11	22/08/19 11:25	General View	1	Load JPG	✓
12	22/08/19 11:25	General View	1	Load JPG	✓
13	22/08/19 11:25	General View	1	Load JPG	✓
14	22/08/19 11:25	General View	1	Load JPG	✓
15	22/08/19 11:25	General View	1	Load JPG	✓
16	22/08/19 11:25	General View	1	Load JPG	✓
17	22/08/19 11:25	General View	1	Load JPG	✓
18	22/08/19 11:25	General View	1	Load JPG	✓
19	22/08/19 11:25	General View	1	Load JPG	✓
20	22/08/19 11:25	General View	1	Load JPG	✓
21	22/08/19 11:25	General View	1	Load JPG	✓
22	22/08/19 11:25	General View	1	Load JPG	✓
23	22/08/19 11:25	General View	1	Load JPG	✓
24	22/08/19 11:25	General View	1	Load JPG	✓
25	22/08/19 11:25	General View	1	Load JPG	✓
26	22/08/19 11:25	General View	1	Load JPG	✓
27	22/08/19 11:25	General View	1	Load JPG	✓
28	22/08/19 11:25	General View	1	Load JPG	✓
29	22/08/19 11:25	General View	1	Load JPG	✓
30	22/08/19 11:25	General View	1	Load JPG	✓
31	22/08/19 11:25	General View	1	Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
32	22/08/19 11:25	General View	 Load JPG	✓
33	22/08/19 11:25	General View	 Load JPG	✓
34	22/08/19 11:25	General View	 Load JPG	✓
35	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
36	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
37	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
38	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
39	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
40	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
41	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
42	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
43	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
44	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
45	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
46	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
47	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
48	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
49	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
50	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
51	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
52	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
53	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
54	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
55	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
56	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
57	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
58	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
59	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
60	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
61	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
62	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
63	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
64	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
65	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
66	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
67	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
68	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
69	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
70	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
71	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
72	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
73	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
74	22/08/19 11:26	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/06/19 09:54	PRI	 Load PDF	
2	14/06/19 09:54	SGL3969P - GIA REPORT	 Load PDF	
3	14/06/19 10:05	TP agree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010598/T1VD3S2
Date: 28/08/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28832025MKC
Claimant Vehicle No :	SGL3969P	Insured Vehicle No :	GBE2847K
Date of Loss:	12/06/2019	Nature of Claim:	TP
		Claim No:	596766

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL3969P	Engine No:	4A910027984
Make & Model:	MITSUBISHI COLT, 1.6 (M)	Chassis No:	JMYLTZ23W6Z000679
Reg. Date:	14/09/2006 (Man. Year: 2006)	Odometer:	286913 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Dayton 6 mm	Rear Left Side:	Dayton 6 mm
Front Right Side:	Dayton 6 mm	Rear Right Side:	Dayton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,841.70	3,692.60	10,149.10	73.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	1,700.00	2,550.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,091.70	5,392.60	12,699.10	70.19
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	18,091.70	3,000.00	15,091.70	83.42
+ GST 7.00/7.00% (S\$)	1,266.42	210.00	1,056.42	83.42
Nett Amount (S\$)	19,358.12	3,210.00	16,148.12	83.42

INSPECTION

Date of Assignment:	14/06/2019	Torque 5 Bodyworks Pte Ltd (HQ)
Date Inspected:	18/06/2019 Inspected At:	8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @
Estimated Period of Repair:	5.0 days	Kaki Bukit
		Singapore 415875

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2019)
Parts:	144	MITSUBISHI COLT 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGL3969P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	722.00 F	*681.00 FL
2	1		*REAR BUMPER RETAINER (LH)	Necessary	40.00 F	*40.00 FL
3	1		*REAR BUMPER RETAINER (RH)	Necessary	40.00 F	*40.00 FL
4	1		*REAR BUMPER REFLECTOR (LH)	Not Necessary	45.00 F	*- FL
5	1		*REAR BUMPER REFLECTOR (RH)	Not Necessary	45.00 F	*- FL
6	1		*REAR BUMPER BRACKET (LH)	Not Necessary	76.00 F	*- FL
7	1		*REAR BUMPER BRACKET (RH)	Not Necessary	76.00 F	*- FL
8	1		*AUTO TAILGATE	Bent	890.00 F	*890.00 FL
9	1		*TAILGATE LOCK & MOTOR ASSY	Bent	492.00 F	*166.00 FL
10	1		*TAILGATE LOCK SWITCH	Not Necessary	132.00 F	*- FL
11	1		*TAILGATE INNER PUSH BUTTON	Not Necessary	127.00 F	*- FL
12	1		*TAILGATE HINGE (LH)	Not Necessary	95.00 F	*- FL
13	1		*TAILGATE HINGE (RH)	Not Necessary	95.00 F	*- FL
14	1		*TAILGATE DAMPER (LH)	Not Necessary	135.00 F	*- FL
15	1		*TAILGATE DAMPER (RH)	Not Necessary	135.00 F	*- FL
16	1		*TAILGATE LAMP (LH)	Cracked	220.00 F	*220.00 FL
17	1		*TAILGATE LAMP (RH)	Cracked	220.00 F	*220.00 FL
18	1		*LICENSE LAMP GARNISH	Cracked	98.00 F	*98.00 FL
19	1		*LICENSE LAMP (LH)	Not Necessary	62.00 F	*- FL
20	1		*LICENSE LAMP (RH)	Not Necessary	62.00 F	*- FL
21	1		*TAILGATE INNER TRIM BOARD	Cracked	240.00 F	*240.00 FL
22	1		*TAILGATE INNER SIDE GARNISH (LH)	Not Necessary	92.30 F	*- FL
23	1		*TAILGATE INNER SIDE GARNISH (RH)	Not Necessary	92.30 F	*- FL
24	1		*TAILGATE INNER CENTRE GARNISH	Not Necessary	102.30 F	*- FL
25	1		*TAILGATE INNER PULL HANDLE GARNISH	Not Necessary	43.60 F	*- FL
26	1		*TAILGATE RUBBER BEADING	Cut	210.00 F	*210.00 FL
27	1		*TAILGATE WIPER MOTOR	Not Necessary	513.60 F	*- FL
28	1		*TAILGATE WIPER ARM	Not Necessary	137.20 F	*- FL
29	1		*REAR WINDSCREEN	Not Necessary	873.60 F	*- FL
30	1		*REAR WINDSCREEN MOULDING	Necessary	115.00 F	*115.00 FL
31	1		*AUTO TAILGATE MOTOR ASSY	Not Necessary	1,315.30 F	*- FL
32	1		*END PANEL	Repair	450.00 F	*- FL
33	1		*END PANEL TOP GARNISH	Cracked	219.00 F	*219.00 FL
34	1		*TAIL LAMP (LH)	Cracked	380.00 F	*325.00 FL
35	1		*TAIL LAMP (RH)	Not Necessary	380.00 F	*- FL
36	1		*TAIL LAMP INNER PANEL (LH)	Not Necessary	115.30 F	*- FL
37	1		*TAIL LAMP INNER PANEL (RH)	Not Necessary	115.30 F	*- FL
38	1		*SPARE TYRE PANEL	Not Necessary	1,058.60 F	*- FL
39	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	210.00 F	*- FL
40	1		*REAR FENDER INNER TRIM (LH)	Not Necessary	590.00 F	*- FL
41	1		*REAR FENDER INNER TRIM (RH)	Not Necessary	590.00 F	*- FL
42	1		*REAR SPEAKER PANEL TOP BOARD	Not Necessary	326.30 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
44	1		*REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
45	1		*TAILGATE EMBLEM	Necessary	120.00 FS	*120.00 FS
46	1		*REAR NUMBER PLATE & CASING	Bent	45.00 FS	*45.00 FS
47	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
48	1		*SET TAILGATE INNER TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
49	1		*SET END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
50	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
51	1		*END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
52	1		*SPARE TYRE PANEL SEALANT	Not Necessary	50.00 FS	*- FS
53	1		*SPARE TYRE PANEL INSULATOR MATT	Not Necessary	280.00 FS	*- FS
54	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
55	1		*REAR WINDSCREEN TINTED	Necessary	200.00 FS	*100.00 FS
56	1		*SUNDRIES	Necessary	160.00 FS	*20.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	13,841.70	4,039.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	346.40
Total Parts (S\$)	13,841.70	3,692.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R REAR BUMPER REVERSE SENSOR.	New	80.00	30.00
2	TO CHECK WIRING AND LIGHTING SYSTEM.	New	80.00	30.00
3	TO SUPPLY UNDERCOATING / PUTTY ON AFFECTED AREAS.	New	80.00	30.00
4	TO R&R REAR WINDSCREEN.	New	60.00	60.00
5	TO R&R TAILGATE MECHANISM.	New	200.00	60.00
6	TO R&R REAR TRIMS, GARNISH AND SEATS ASSY.	New	200.00	60.00
7	TO R&R FUEL TANK TO CUT & WELD.	New	250.00	0.00
8	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS.	New	1,000.00	700.00
9	TO SPRAY PAINTING ON AFFECTED AREAS.	New	1,200.00	700.00
10	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR.	New	1,100.00	30.00
Gross Labour Cost (S\$)			4,250.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >