



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGL3969P

Make & Model :

Year of Manufacture : 2006

Estimation No. : E19060010

DOA

: 13/06/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper <i>de✓</i>	1.00	0.00 <i>722.00</i>	0.00
2	Rear bumper retainer (LH) <i>ne✓</i>	1.00	0.00 <i>40.00</i>	0.00
3	Rear bumper retainer (RH) <i>ne✓</i>	1.00	0.00 <i>40.00</i>	0.00
4	Rear bumper reflector (LH) X	1.00	0.00 <i>45.00</i>	0.00
5	Rear bumper reflector (RH) X	1.00	0.00 <i>45.00</i>	0.00
6	Rear bumper bracket (LH) <i>gun✓</i>	1.00	0.00 <i>76.00</i>	0.00
7	Rear bumper bracket (RH) ?	1.00	0.00 <i>76.00</i>	0.00
8	Auto tailgate <i>bt✓</i>	1.00	0.00 <i>890.00</i>	0.00
9	Tailgate lock & motor assy ? <i>bt✓</i>	1.00	0.00 <i>492.00</i>	0.00
10	Tailgate lock switch X	1.00	0.00 <i>132.00</i>	0.00
11	Tailgate inner push button X	1.00	0.00 <i>127.00</i>	0.00
12	Tailgate hinge (LH) X	1.00	0.00 <i>95.00</i>	0.00
13	Tailgate hinge (RH) X	1.00	0.00 <i>95.00</i>	0.00
14	Tailgate damper (LH) X	1.00	0.00 <i>135.00</i>	0.00
15	Tailgate damper (RH) X	1.00	0.00 <i>135.00</i>	0.00
16	Tailgate lamp (LH) ? <i>ena✓</i>	1.00	0.00 <i>220.00</i>	0.00
17	Tailgate lamp (RH) ? <i>ena✓</i>	1.00	0.00 <i>220.00</i>	0.00
18	License lamp garnish ? <i>ena✓</i>	1.00	0.00 <i>98.00</i>	0.00
19	License lamp (LH) X	1.00	0.00 <i>62.00</i>	0.00
20	License lamp (RH) X	1.00	0.00 <i>62.00</i>	0.00
21	Tailgate inner trim board ? <i>ena✓</i>	1.00	0.00 <i>240.00</i>	0.00
22	Tailgate inner side garnish (LH) X	1.00	0.00 <i>92.30</i>	0.00
23	Tailgate inner side garnish (RH) X	1.00	0.00 <i>92.30</i>	0.00
24	Tailgate inner centre garnish X	1.00	0.00 <i>102.30</i>	0.00
25	Tailgate inner pull handle garnish X	1.00	0.00 <i>43.60</i>	0.00
26	Tailgate rubber beading ? <i>ena✓</i>	1.00	0.00 <i>210.00</i>	0.00
27	Tailgate wiper motor X	1.00	0.00 <i>513.60</i>	0.00

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGL3969P
Make & Model :
Year of Manufacture : 2006

Estimation No. : E19060010
DOA : 13/06/2019

MITSUBISHI, COLTPLUS PRT, JMYLTZ23W6Z000679

No	Description	Qty	U/P	Amt
28	Tailgate wiper arm ✕	1.00	0.00 137.20	0.00
29	Rear windscreen ✕	1.00	0.00 873.60	0.00
30	Rear windscreen moulding <i>acc</i>	1.00	0.00 115.00	0.00
31	Auto tailgate motor assy ✕	1.00	0.00 1315.30	0.00
32	End panel <i>R</i>	1.00	0.00 450.00	0.00
33	End panel top garnish <i>? car</i>	1.00	0.00 219.00	0.00
34	Tail lamp (LH) <i>? car</i>	1.00	0.00 380.00	0.00
35	Tail lamp (RH) ✕	1.00	0.00 380.00	0.00
36	Tail lamp inner panel (LH) ✕	1.00	0.00 115.30	0.00
37	Tail lamp inner panel (RH) ✕	1.00	0.00 115.30	0.00
38	Spare tyre panel ✕	1.00	0.00 1058.60	0.00
39	Spare tyre panel top board ✕	1.00	0.00 210.00	0.00
40	Rear fender inner trim (LH) ✕	1.00	0.00 590.00	0.00
41	Rear fender inner trim (RH) ✕	1.00	0.00 590.00	0.00
42	Rear speaker panel top board ✕	1.00	0.00 326.30	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

43	Reverse sensor set	1.00	250.00	250.00 <i>200</i>
44	Reverse camera	1.00	500.00	500.00 ✕
45	Tailgate emblem	1.00	120.00	120.00 <i>acc</i>
46	Rear number plate & casing	1.00	45.00	45.00 <i>bt</i>
47	Rear bumper clip set	1.00	50.00	50.00 <i>30 new</i>
48	Tailgate inner trim board clip set	1.00	50.00	50.00 ✕
49	End panel top garnish clip set	1.00	30.00	30.00 <i>20 new</i>
50	Tail lamp clip set	1.00	30.00	30.00 ✕
51	End panel sealant	1.00	50.00	50.00 ✕

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGL3969P
Make & Model : MITSUBISHI, COLT PLUS SPRT, JMYLTZ23W6Z000679
Year of Manufacture : 2006

Estimation No. : E19060010
DOA : 13/06/2019

No	Description	Qty	U/P	Amt
52	Spare tyre panel sealant	1.00	50.00	50.00
53	Spare tyre panel insulator matt	1.00	280.00	280.00
54	Rear windscreen sealant	1.00	50.00	50.00
55	Rear windscreen tinted	1.00	200.00	200.00

Amt S\$ 1,705.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,705.00

Section: Labour Items

56	To R&R rear bumper reverse sensor	1.00	80.00	80.00
57	To check wiring and lighting system	1.00	80.00	80.00
58	To supply undercoating / putty on affected areas	1.00	80.00	80.00
59	To R&R rear windscreen	1.00	60.00	60.00
60	To R&R tailgate mechanism	1.00	200.00	200.00
61	To R&R rear trims, garnish and seats assy	1.00	200.00	200.00
62	To R&R fuel tank to cut & weld	1.00	250.00	250.00
63	To repair, replace & realign damaged areas	1.00	350.00	350.00
64	To spray painting on affected areas	1.00	1,200.00	1,200.00
65	To perform water seepage test after repair	1.00	1,100.00	1,100.00
66	Sundries	1.00	160.00	160.00

Amt S\$ 3,760.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 3,760.00

parts = 4038 - 20% AAA Tanjilun 17095749
= 3230.40
S/N = 555
Labour = 1720
P + S + L = 5505.40 - 20% L/S
= #4400

18/6/19 @ 130pm
Resumy after repair.
sur @ 11k auto.com
5 days
Limit Repair #3K.

List Items Subtotal S\$ 0.00
Special Nett Items S\$
Subtotal 1,705.00
Labour Items Subtotal S\$
3,760.00
Total S\$
5,465.00