

ASS. REC. BY:

Kenneth
MunnenREF: CS-1A1G19010601/K9d3/n2
Special Instruction:

ASSIGNMENT (Office)

From (Person): Hor Finnul of A1G Date/Time: 14/6/19 @ 3.26pm

Estimated Cost: Bill to:

OD / FD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 4566 E Insured: SJQ 878B

at Workshop m/s Ah Cheng Motor Tel: 64835434

of Blk 10 Amk Ind. park 2A #03-16

Policy No: Claim No: 687433682085

Sum Insured: Excess:

Make of Veh: D.O.A. 7/6/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 3:50pm @ 14/6/19 Person Contacted: Jena Vehicle: IN/OUT

Date/Time	Action/Instruction	Initials (✓)
	SLB 4566E - CS/FI/8009814/K9d3n2	DDA: 23/5/2018
	SJQ 878B - CS/1A1G10017998/A4/1k2	DDA: 27/8/2010
27/6	11 Lp 841001 email lca firm (Red @ 15755.70, 79%)	

ASSIGNMENT

From:

Date:

17/6/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLB 4566E

at Workshop m/s

Ah cheng Motor

of Bk 10 Amk Ind. park 2A # 03-16

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

imp

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLB 4566E

Yr Regn:

04, 16

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

C.C

1491

Colour:

N. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

29900

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RUI

1106732

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD Air Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

7/6/19

D.O.I.

17/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 28 JUN 2019

Date/Time: File Pass to?

☐

Preli. Report

128/6 MFIS

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

7

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Other:

TOTAL

Report Format:

MER-TP

Lump Sum / TP Fee:

4100

250

11

261

PRE-REPAIR INSPECTION REQUEST – SLB4566E vs SJQ878B (OI) on D.O.A.: 07/06/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tor
Sent: 6/14/2019 3:26:57 PM
Attachments: 0014_001.pdf; 0014_001.pdf

Hi,

Please refer to the enclosed request from Cheonghoh Law Corporation.

Claim no : 6874336820SG003
Case Owner : Bernard Ler Ji Qian

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinrul.Hor@aig.com | www.aig.sg

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Friday, June 14, 2019 2:46 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJQ878B AND SLB4566E ON 07/06/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

We refer to the above matter.

Our client hereby nominate surveyor Kenneth Kong from LKK Auto Consultants Pte Ltd for the pre-repair survey ("PRS") of the damages to our client's vehicle.

Please be informed that our client's vehicle, SLB 4566 E is currently laying at our client's workshop, Ah Chang Motor Service Centre, Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo Kio Point #03-16 Singapore 568047. Kindly proceed to do the needful and you may contact the person in charge Mr Ng/Diana at 64835434 before your surveyor attend at the said workshop.

Kindly proceed to do the needful.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 14 Jun 2019, at 1:51 PM, Hor, Yinrul <Yinrul.Hor@aig.com> wrote:

<logo.jpeg>

<lock.gif>

This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2019-06-21 00:51 CDT to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved

<SecureMessageAtt.html>

From: Yinrul.Hor@aig.com
To: mail@cheonghoh.sg
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariessa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashni.Subramaniam@aig.com, Wahxin.Tong@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJQ878B AND SLB4566E ON 07/06/2019
Date: Fri, 14 Jun 2019 05:51:00 +0000
Without Prejudice

Your Reference : LCH.my/AMK10-90433.19
Our Reference : 6874336820SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL Claims Operations – Auto
Yinrul.Hor@aig.com | www.aig.sg

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Friday, June 14, 2019 12:15 PM
To: Supramaniam, Darshene
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene; Chin, Lee-Ying
Subject: [EXTERNAL] Re: PRS for SLB 4566 E accident involving vehicle SJQ 878 B on 7 June 2019 along Dalmedia Street (Our ref: LCH.my/AMK10-90433.19)

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

We append below our letter of PR
Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: roaming26@singtel.com.sg
Subject: Attached Image
Date: 14 June 2019 at 12:04:37 PM SGT

To: "mail@cheonghoh" <mail@cheonghoh.sg>

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply please quote our Reference Number

Our Ref: LCH.my/AMK10-90433.19

12.06.19

BY FAX NO. 68357416 AND BY HAND
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120



BY CERTIFICATE OF POSTING
Lee Hwee Wang
16 West Coast View
Singapore 127186

BY CERTIFICATE OF POSTING

Dear Sirs

We are instructed by Tan Sze Yen, Eileen (chen Siyan, Eileen) to notify you of a road traffic accident on 07.06.19 at about 7:40 am at D'Almeida Street involving our client's vehicle registration number SLB 4566 E and vehicle registration number SJQ 878 B driven by your insured driver/you/your driver at the material time. A copy of the Singapore accident statement filed is available.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

For the avoidance of doubt, our client will be claiming for compensation for loss of use/rental of a replacement vehicle in the instances enumerated in the State Courts Practice Direction Amendment No. 1 of 2016 paragraphs 7.1 and 7.2 of the Appendix C of the Pre-action Protocol for Non-Injury Motor Accident Cases which compensation is additional to any other claim for loss of use/rental of a replacement vehicle which our client may make against your insured and/or your insured's driver and or you/your driver.

Yours faithfully

Cheonghoh Law Corporation

encls:

This is a computer-generated document and requires no signature

cc: client (via e-mail/fax only) - SLB 4566 E

Enquire Vehicle & Owner Information (Vehicle No. SJQ878B As At 07 Jun 2019 / 07:40:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: AMK10-90433.19/MY

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S1605170E

Owner Name: LEE HWEE WANG

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 16

Registered Street Name: WEST COAST VIEW

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 127186

Current Vehicle Details

Vehicle No.: SJQ878B

Make Description/Model: AUDI / Q3 1.4 TFSI S TRONIC

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/06/2019 09:13
Date Of Accident	07/06/2019 07:40
Exact Location Of Accident	D'ALMEIDA STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB4566E
Insured/Policyholder	
Name Of Registered Owner	TAN SZE YEN, EILEEN
NRIC No	S8328250I
Email Address	MUSEONMULES@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91996448
Alternative Phone No	OTHERS-91996448

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108488503
Cover Note Number	

Driver

Name of Driver	TAN SZE YEN, EILEEN
NRIC No	S8328250I
Date Of Birth	21/09/1983
Occupation	INDOOR
Date Of Driving Pass	14/12/2002
Driving Experience	16 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91996448
Fax Number	
Contact Number	OTHERS-91996448
EMail Address	MUSEONMULES@GMAIL.COM

Address	BLK 3 TANJONG PAGAR PLAZA #23-30
Postcode	081003
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN. WILL REPAIR AND CLAIM AT ACM SERVICE CENTER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ878B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE HWEE WANG
NRIC/Passport Number	
Contact Number	62101134
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 11/1/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I have just turned into D'Almeida Street at 7:43am on 7/6/2019 and
 changing to the left lane. At a sudden I felt an impact from behind and
 hit my head on my steering wheel. I immediately stopped the car and
 looked back to find SJ0878B from the right lane had attempted to run on
 red and because the driver was not looking nor indicated to change lanes,
 they had rammed into the back right side of my car.
 I had then stopped the car to exchange particulars with the driver. She had
 then willingly agreed to pay out of pocket for my damages and requested
 that the accident is ~~not~~ her fault. After some discussions, she has
 informed that she will claim against her insurance, hence the report is
 made on 7/6/2019 after a call with Alan Lee on 10/6/2019 at 13:55pm.

With report and claim at ACM Service Centre

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 7/6/2019

Driver's Signature


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



AH CHANG MOTOR SERVICE CENTRE


Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

*Not Noted
C/Lump B?
Assembly After Paint
4 days*

SLB4566E Honda Vezel

Accident Date:

No	Qty	Parts Description	Estimated Parts Price
1	1	Front right door panel	<i>N B</i> \$ 1,628.00 <i>X</i>
2	1	Front right door lock mechanism	\$ <i>N</i> 225.00 <i>X</i>
3	1	Front right door glass outer moulding	\$ <i>Sn</i> 176.00 <i>X</i>
4	1	Front right door outer handle	\$ <i>Sn</i> 178.00 <i>X</i>
5	1	Front right door regulator with motor assy	\$ <i>N</i> 478.00 <i>X</i>
6	1	Front right door inner board	\$ <i>Sn</i> 328.00 <i>X</i>
7	1	Rear bumper assy	\$ <i>N</i> 1,209.00 <i>X</i>
8	1	Rear right fender	\$ <i>N</i> 2,098.00 <i>X</i>
9	1	Rear right fender side protector	<i>Nett/wh</i> 195.00 <i>✓</i>
10	1	Rear right door panel	<i>R1</i> \$ 1,620.00 <i>✓</i>
11	1	Rear right door lock mechanism	\$ <i>N</i> 225.00 <i>X</i>
12	1	Rear right door glass outer moulding	\$ <i>Sn</i> 176.00 <i>X</i>
13	1	Rear right door regulator with motor assy	\$ 478.00 <i>?</i>
14	1	Rear right door inner board	\$ <i>nn</i> 328.00 <i>X</i>
15	1	Rear right shock absorber assy	\$ <i>nn</i> 640.00 <i>X</i>
16	1	Rear right wheel hub bearing	\$ <i>nn</i> 457.00 <i>X</i>
17	1	Right side sill panel	\$ <i>N</i> 1,680.00 <i>X</i>
18	1	Rear lower torsion bar	<i>Sn</i> \$ 2,800.00 <i>X</i>
			\$ 14,919.00
		Less 20%	\$ 2,983.80
			\$ 11,935.20
<u>Special Nett Items</u>			
1	10	Front right door inner board clips	\$ <i>nn</i> 30.00 <i>X</i>
2	1	Rear right sport rim	\$ 850.00 <i>?</i>
3	1	Rear right tyre	\$ <i>Sn</i> 350.00 <i>X</i>
4	1	Rear right fender sealant	\$ <i>nn</i> 80.00 <i>X</i>
5	6	Rear right fender side protector clips	\$ <i>N</i> 20.00 <i>✓</i>
6	10	Rear right door inner board clips	\$ 30.00 <i>?</i>
7	1	Rear right lower skirting <i>P1?</i>	<i>Nett/wh</i> \$ 2,400.00 <i>✓</i>
8	12	Rear right lower skirting clips	\$ <i>N</i> 40.00 <i>✓</i>
9	1	Rear right lower skirting sealant	\$ <i>nn</i> 80.00 <i>X</i>
			\$ 3,880.00
Total parts			\$ 15,815.20



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SLB4566E Honda Vezel

Accident Date:

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front right, rear right affected area and replace front right and rear right damaged parts.	\$ 1,200.00 <i>500</i>
2	To putty and spray painting front right and rear right affected portion.	<i>660</i> 1,200.00
3	To apply anti rust proofing to front right and rear right affected area.	\$ <i>30</i> 120.00
4	To remove and install front right door lock mechanism.	\$ <i>60</i> 80.00
5	To transfer front right door glass to new door.	\$ <i>nn</i> 80.00 X
6	To remove and install rear right door lock mechanism.	\$ <i>nn</i> 80.00
7	To transfer rear right door glass to new door.	\$ <i>nn</i> 80.00 X
8	To conduct wheel alignment.	\$ <i>60</i> 120.00
9	To balance rear right wheel.	\$ 50.00 ?
10	To check door central locking for function.	\$ <i>nn</i> 80.00 X
11	To remove and install rear right undercarriage part.	\$ <i>nn</i> 350.00 X
12	Towing service.	\$ <i>nn</i> 100.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total labour : \$ 3,540.00

Total parts : \$ 15,815.20

Total labour : \$ 3,540.00

Total repair cost : \$ 19,355.20

Not Notified
Lump @ 4100/-
Assembly After Paint

5 days

SLB4566E Honda Vezel

Accident Date:


No	Qty	Parts Description	Estimated Parts Price
1	1	Front right door panel <i>1801n L.N B4</i>	\$ 1,628.00 <i>5</i>
2	1	Front right door lock mechanism	\$ <i>n</i> 225.00 <i>i</i>
3	1	Front right door glass outer moulding	\$ <i>sn</i> 176.00 <i>x</i>
4	1	Front right door outer handle	\$ <i>sn</i> 178.00 <i>x</i>
5	1	Front right door regulator with motor assy	\$ <i>n</i> 478.00 <i>x</i>
6	1	Front right door inner board	\$ <i>sn</i> 328.00 <i>x</i>
7	1	Rear bumper assy	\$ <i>n</i> 1,209.00 <i>x</i>
8	1	Rear right fender	\$ <i>sn</i> 2,098.00 <i>x</i>
9	1	Rear right fender side protector <i>165.00</i>	<i>Not/Not</i> 195.00 <i>L</i>
10	1	Rear right door panel <i>930.60</i>	<i>R1</i> \$ 1,620.00 <i>L</i>
11	1	Rear right door lock mechanism	\$ <i>n</i> 225.00 <i>x</i>
12	1	Rear right door glass outer moulding	\$ <i>sn</i> 176.00 <i>x</i>
13	1	Rear right door regulator with motor assy	<i>Dis/Not</i> 478.00 <i>2</i>
14	1	Rear right door inner board	\$ <i>sn</i> 328.00 <i>x</i>
15	1	Rear right shock absorber assy <i>330</i>	<i>R1</i> \$ <i>new</i> 640.00 <i>x</i>
16	1	Rear right wheel hub bearing <i>387.50</i>	<i>ne</i> \$ <i>new</i> 457.00 <i>x</i>
17	1	Right side sill panel	\$ <i>sn</i> 1,680.00 <i>x</i>
18	1	Rear lower torsion bar <i>AxL P1? 1513.60</i>	<i>R1</i> \$ <i>sn</i> 2,800.00 <i>x</i>
			\$ 14,919.00
Less 20%			\$ 2,983.80
			\$ 11,935.20

Special Nett Items

1	10	Front right door inner board clips	\$ <i>sn</i> 30.00 <i>x</i>
2	1	Rear right sport rim	\$ <i>R</i> 850.00 <i>x</i>
3	1	Rear right tyre	\$ <i>sn</i> 350.00 <i>x</i>
4	1	Rear right fender sealant	\$ <i>sn</i> 80.00 <i>x</i>
5	6	Rear right fender side protector clips	\$ <i>ne</i> 20.00 <i>L</i>
6	10	Rear right door inner board clips	\$ <i>sn</i> 30.00 <i>x</i>
7	1	Rear right lower skirting <i>bumper P1? 456.90</i>	<i>Not/Not</i> \$ 2,400.00 <i>L (4)</i>
8	12	Rear right lower skirting clips	<i>nn</i> \$ <i>ne</i> 40.00 <i>x</i>
9	1	Rear right lower skirting sealant	\$ <i>nn</i> 80.00 <i>x</i>
			\$ 3,880.00

Total parts

\$ 15,815.20



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SLB4566E Honda Vezel

Accident Date:

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front right, rear right affected area and replace front right and rear right damaged parts.	\$ 1,200.00 500
2	To putty and spray painting front right and rear right affected portion.	\$ 1,200.00 600
3	To apply anti rust proofing to front right and rear right affected area.	\$ 120.00 300
4	To remove and install front right door lock mechanism.	\$ 80.00 60
5	To transfer front right door glass to new door.	\$ 80.00 X n
6	To remove and install rear right door lock mechanism.	\$ 80.00 X n
7	To transfer rear right door glass to new door.	\$ 80.00 X n
8	To conduct wheel alignment.	\$ 120.00 60
9	To balance rear right wheel.	\$ 50.00 X n
10	To check door central locking for function.	\$ 80.00 X n
11	To remove and install rear right undercarriage part.	200/ \$ 350.00 ✓ n
12	Towing service.	\$ 100.00 X n
Total labour :		\$ 3,540.00
Total parts :		\$ 15,815.20
Total labour :		\$ 3,540.00
Total repair cost :		\$ 19,355.20

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19010601/KQD3N2

Date: 04/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
 Claimant: SLB4566E Insured Vehicle No: SJQ878B
 Vehicle No: SLB4566E Nature of Claim: TP Claim No: 6874336820SG
 Date of Loss: 07/06/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB4566E Engine No: L15B4026757
 Make & Model: HONDA VEZEL, 1.5 X (A) Chassis No: RU11106752
 Reg. Date: 08/04/2016 (Man. Year: 2015) Odometer: 29900 km
 Colour: Metallic Blue
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,815.20	3,609.28	12,205.92	77.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	1,510.00	2,030.00	57.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,355.20	5,119.28	14,235.92	73.55
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	19,355.20	4,100.00	15,255.20	78.82
+ GST 7.00/7.00% (S\$)	1,354.86	287.00	1,067.86	78.82
Nett Amount (S\$)	20,710.06	4,387.00	16,323.06	78.82

INSPECTION

Date of Assignment: 14/06/2019

Date Inspected: 17/06/2019 Inspected At:

Ah Chang Motor Service Centre (HQ)
 10 ANG MO KIO INDUSTRIAL PARK
 2A, ANG MO KIO POINT #03-16
 Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT DOOR LOCK MECHANISM	Repair	225.00 FL	*- FL
2	1		*FRONT RIGHT DOOR GLASS OUTER MOULDING	Serviceable	176.00 FL	*- FL
3	1		*FRONT RIGHT DOOR OUTER HANDLE	Serviceable	178.00 FL	*- FL
4	1		*FRONT RIGHT DOOR REGULATOR WITH MOTOR ASSY	Repair	478.00 FL	*- FL
5	1		*FRONT RIGHT DOOR INNER BOARD	Serviceable	328.00 FL	*- FL
6	1		*REAR BUMPER ASSY	Repair	1,209.00 FL	*- FL
7	1		*RAER RIGHT FENDER	Repair	2,098.00 FL	*- FL
8	1		*RAER RIGHT FENDER SIDE PROTECTOR	Dented/Cut	195.00 FL	*165.00 FL
9	1		*REAR RIGHT DOOR PANEL	Bent	1,620.00 FL	*930.60 FL
10	1		*REAR RIGHT DOOR LOCK MECHANISM	Repair	225.00 FL	*- FL
11	1		*REAR RIGHT DOOR GLASS OUTER MOULDING	Serviceable	176.00 FL	*- FL
12	1		*REAR RIGHT DOOR REGULATOR WITH MOTOR ASSY	Distorted/Jammed	478.00 FL	*478.00 FL
13	1		*REAR RIGHT DOOR INNER BOARD	Not Necessary	328.00 FL	*- FL
14	1		*REAR RIGHT SHOCK ABSORBER ASSY	Bent	640.00 FL	*330.00 FL
15	1		*REAR RIGHT WHEEL HUB BEARING	Necessary	457.00 FL	*387.50 FL
16	1		*RIGHT SIDE SILL PANEL	Repair	1,680.00 FL	*- FL
17	1		*REAR AXLE	Bent	2,800.00 FL	*1,513.60 FL
18	1		*FRONT RIGHT DOOR PANEL (LOCAL REPAIR)	Dented	1,302.40 FS	*180.00 FS
19	10		*FRONT RIGHT DOOR INNER BOARD CLIPS	Not Necessary	30.00 FS	*- FS
20	1		*REAR RIGHT SPORT RIM	Repair	850.00 FS	*- FS
21	1		*REAR RIGHT TYRE	Serviceable	350.00 FS	*- FS
22	1		*REAR RIGHT FENDER SEALANT	Not Necessary	80.00 FS	*- FS
23	1		*REAR RIGHT FENDER SIDE PROTECTOR CLIPS (6 Pcs)	Necessary	20.00 FS	*20.00 FS
24	10		*REAR RIGHT DOOR INNER BOARD CLIPS	Not Necessary	30.00 FS	*- FS
25	1		*REAR BUMPER	Dented/Cut	2,400.00 FS	*365.52 FS
26	12		*REAR RIGHT LOWER SKIRTING CLIPS	Not Necessary	40.00 FS	*- FS
27	1		*REAR RIGHT LOWER SKIRTING SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **18,473.40** **4,370.22**
 - List Item Discount on L Items 20.00/20.00% (\$\$) 2,658.20 760.94

Total Parts (\$\$) 15,815.20 3,609.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT RIGHT,REAR RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT AND REAR RIGHT DAMAGED PARTS	New	1,200.00	500.00
2	TO PUTTY AND SPRAY PAINTING FRONT RIGHT AND REAR RIGHT AFFECTED PORTION	New	1,200.00	660.00
3	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AND REAR RIGHT AFFECTED AREA	New	120.00	30.00
4	TO REMOVE AND INSTALL FRONT RIGHT DOOR LOCK MECHANISM	New	80.00	60.00
5	TO TRANSFER FRONT RIGHT DOOR GLASS TO NEW DOOR	New	80.00	0.00
6	TO REMOVE AND INSTALL REAR RIGHT DOOR LOCK MECHANISM	New	80.00	0.00
7	TO TRANSFER REAR RIGHT DOOR GLASS TO NEW DOOR	New	80.00	0.00
8	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
9	TO BALANCE REAR RIGHT WHEEL	New	50.00	0.00
10	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION	New	80.00	0.00
11	TO REMOVE AND INSTALL REAR RIGHT UNDERCARRIAGE PART	New	350.00	200.00
12	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			3,540.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >