

ASS. REC. BY:

REF:

es/asm19010605/TH d312

(Special Instructions)

Surveyor: Taufer

ASSIGNMENT (Office)

From (Person): Peter Wong of ASM (AXA) Date/Time: 14/6/19

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

Q1 / 4 WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFQ 57B Insured: \_\_\_\_\_

at Workshop n/w: Hin Tung Workshop Tel: 6858 3000

of BLK 1008 Bkt Merah Lane 3 # 01-20

Policy No: \_\_\_\_\_ Claim No: S9M0104P

Sum Insured: \_\_\_\_\_ Excess: NIL

Make of Veh: \_\_\_\_\_ D.O.A. 20/5/2019  
(Client's Record)

17/6/19 @ 5pm

H.O.D. Endorsement: \_\_\_\_\_

CA / REV / REP. / REV 24 HRS

Date/Time: 4:37pm @ 14/6/19 Person Contacted: Susan Vehicle IN/OUT: OUT

Date/Time	Action/Instruction
	<u>SFQ 57B - CCA/ASM19009482 / Cmb2</u>

6/7/19 5:08pm Revert via smart claim not authorize

Repairer is asking part by part as there 2nd not available

6/19/19 @ 11:19am Email inform Peter Wong, repair on 4/5 authorize repair

Tanp

REF

AXIT

ASSIGNMENT

Cof 2020 March

2010 March

Date:

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

of Workshop no

of

Insured

Policy No

Claim No

Sum Insured

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

IDAC Accident Report

CSA / PR Doc

Est. Repairs

Lump Sum

REV / REP / 24 HRS

Date

Person Contacted

Vehicle: IN / OUT

Veh No

Type: M/Cat / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Colour

Sp. Reading

Eng/No

C/Mo

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / 2Rim / STD A/Rim or

Tyre Size

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Rtl

L/Rtl

D.O.A

Survey held at

Des. of Damages: Frt / Rear / O/S / W / UC / Roodtop or

The UC / Chassis frame / Body Structure affected due to collision

SFQ57B

Wagon

Mercedes Benz

1796

Blue

AK Insured / Std / Nil / NA

171624

171624 Insured / Std / Nil / NA

WDD2042492A 360074

Good / Fair / Poor / Burnt

Inorder / Jammed / Leaked / Burnt or

Inorder / Jammed / Leaked / Burnt or

Nil / 2Rim / STD A/Rim or

F

225/40R17

R

h

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Rtl

L/Rtl

D.O.A

Survey held at

Des. of Damages: Frt / Rear / O/S / W / UC / Roodtop or

The UC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

19/6/19 - email authorise repair on lump sum @/-

lump sum \$2400 (red: 4864.90:66%)

RECEIVED 30 JUL 2019

Date/Time: FRI Pass 1/1

3017 Typist

Date/Time: FRI Repass 1/1

☐

Preli. Report

☒

Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Insp. \$

☐

Workhand \$

Report Format

Lump Sum / L.B. /

OD

2400

Survey Fee

Inspection

100

100

100

100

100

100

100




## Service Request Details

Claim

S9M01O4P

Reference

None 

Loss Date

May 20, 2019

Report Date

May 21, 2019 12:00:00 AM

Request Date

June 14, 2019

Due Date

June 21, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SFQ57B

INSURED

C180 CGI

## Service Address

...

## Primary Contact/Insured

YANG JIAO @ YANG QIAO

27B WEST COAST PARK, #04-07, 127722, Singapore

uncyqi@gmail.com

## Claim Handler

WANG Peter

peter.wang@axa.com.sg

## Additional Instructions

Wkshop: Hin Lung OD Excess: Nil (waived due to 50% NCD) Pls authorize if damage is consistent.

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

✚ Upload Documents

NAME

 Policy Schedule.pdf

TYPE

Forms / Claim Documents

SUB-TYPE

Policy Schedule / Covernote / Certificate of insurance

AUTHOR

WANG Peter

DATE UPLOADED




June 14, 2019


NAME


 ADVISE.jpg

TYPE

Forms / Claim Documents

<div> <div>  </div> <div> LKK AUTO CONSULTANTS PTE LTD (OD) <div>Menu</div> </div> </div>	
AUTHOR	HIN LUNG WORKSHOP
DATE UPLOADED	June 14, 2019
NAME	 DL.jpg
TYPE	Forms / Claim Documents
SUB-TYPE	Driver's License / IDP
AUTHOR	HIN LUNG WORKSHOP
DATE UPLOADED	June 14, 2019
NAME	 SAS2617220.pdf
TYPE	Reports & Statement
SUB-TYPE	GIA Report
AUTHOR	HIN LUNG WORKSHOP
DATE UPLOADED	June 14, 2019
NAME	 AUDATEX - 14 JUN 2019.pdf
TYPE	Reports & Statement
SUB-TYPE	Estimate / Quotation
AUTHOR	HIN LUNG WORKSHOP
DATE UPLOADED	June 14, 2019
NAME	 od pri from workshop.pdf
TYPE	Letters and Correspondence

<div>  <div> <div>LKK AUTO CONSULTANTS PTE LTD (ODI) </div> <div>Menu</div> </div> </div>	
<div> <div> <div></div> <div></div> </div> </div>	
DATE UPLOADED	June 14, 2019
NAME	 GIA REPORT OF SFQ57B (INSD).PDF
TYPE	Reports & Statement
SUB-TYPE	GIA Report
AUTHOR	KADRI Mateen
DATE UPLOADED	May 27, 2019
NAME	 GIA REPORT OF SJN3033T (TP).PDF
TYPE	Reports & Statement
SUB-TYPE	GIA Report
AUTHOR	KADRI Mateen
DATE UPLOADED	May 27, 2019



## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 19 June 2019 11:17 AM  
**To:** hlungws  
**Cc:** SUR  
**Subject:** SFQ 57B / OD / AXA / EXCESS NIL

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SFQ 57B(Excess /-). Repair on lump sum.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

Date: 19/6/2019

To : AXA Insurance Pte Ltd

### Survey details

Date of loss	20-May-19
Date of appointment	14-Jun-19
Date of survey	17-Jun-19
Location of survey	Hin Lung

### Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SFQ 57B
Make and Model	HONDA VEZEL
Date of registration	31/3/2010
Excess	0.00
Market Value	\$28,000
Part Rebate	\$20,033
Nett Loss	\$7,967

### Repair details

Initial Estimate	\$7,265
------------------	---------

### Proposed/Revised repair cost:

Parts	\$1,340
Check item	\$1,080
Labour	\$1,740
Total	\$4,160
Lump Sum(if applicable)	

Number of days of repair	4
--------------------------	---

Remarks:

Damage Consistent  
We have authorise repair



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

Date: 17/6/2019

To : AXA Insurance Pte Ltd

### Survey details

Date of loss	20-May-19
Date of appointment	14-Jun-19
Date of survey	17-Jun-19
Location of survey	K KIM HIN

### Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SFQ57B
Make and Model	MERCEDES - BENZ C 180
Date of registration	31/3/2010
Excess	0.00
Market Value	\$28,000
Part Rebate	\$20,033
Nett Loss	\$7,967

### Repair details

Initial Estimate	\$7,265
------------------	---------

### Proposed/Revised repair cost:

Parts	\$1,340
Check item	\$1,080
Labour	\$1,740
Total	\$4,160
Lump Sum(if applicable)	

Number of days of repair	4
--------------------------	---

### Remarks:

Damage Consistent  
We did not authorise repair

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	2997F
<b>Vehicle Details</b>	
Vehicle No.:	SFQ57B
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jun 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 CGI
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	27182030026736
Chassis No.:	WDD2040492A360074
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$37,054.00
Original Registration Date:	31 Mar 2010
First Registration Date:	31 Mar 2010
Transfer Count:	0
Actual ARF Paid:	\$37,054.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2020
PARF Rebate Amount:	\$18,527.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Mar 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,889.00
COE Rebate Amount:	\$1,506.00
<b>Total Rebate Amount:</b>	<b>\$20,033.00</b>

The information contained herein is correct as at 17 Jun 2019

OK





## DHAKAL Raghav

---

**From:** hlungws <hlungws@singnet.com.sg>  
**Sent:** Friday, June 14, 2019 12:43 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Subject:** Re : SFQ57B , AD 20/05/2019 - OD Claim , Appointment for Survey

**Categories:** Raghav

Dear Sirs,

We refer to the above subject and please arrange for survey.

Kindly take note that the vehicle is not in our workshop and need to arrange with owner.

As for your information, we have already submitted Estimate repair through Audatex System on 14/06/2019.

Thank you and please let us hear from you.

Thanks & Regards,  
Anna  
Hin Lung Workshop  
Tel: 6858 3000 Fax: 6476 0075  
Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/05/2019 17:16
Date Of Accident	20/05/2019 16:55
Exact Location Of Accident	CTE (NEAR CUPPAGE ROAD)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFQ57B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YANG JIAO @ YANG QIAO
NRIC No	S6882997F
Email Address	UNCYQI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98563658
Alternative Phone No	OFFICE-NOPHONE
<b>Vehicle Particulars</b>	
Manufacturer	MERCEDES-BENZ
Model	C180-1.6 CGI (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1718754
Cover Note Number	
<b>Driver</b>	
Name of Driver	YANG JIAO @ YANG QIAO
NRIC No	S6882997F
Date Of Birth	14/04/1968
Occupation	INDOOR
Date Of Driving Pass	12/11/2004
Driving Experience	14 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98563658
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	UNCYQI@GMAIL.COM

Address	27B WEST COAST PARK #04-07
Postcode	127722
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : LI XIN GENDER: : FEMALE
Passenger 2	NAME: : DIRA GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN3033T
Vehicle Make/Model/Colour	MAZDA
Details Of Properties	REFER TO PHOTOS ATTACH
Vehicle Category	PRIVATE CAR
Name of Driver	BRIAN DAVID JAMES
NRIC/Passport Number	S9241172I
Contact Number	97328518
Address	
Postcode	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

21/05/2019 15:30

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Suban Tan

CTE near Gurnage Road



On 20 May 2019, I was driving in CTE, kept in lane 2 without change. around 16:54, near the Cuppage Road in CTE, Suddenly the Car B (SJN3033T) from behind hit on my car rear and caused the damage. Nobody injured in this incident.

杨峰

杨峰 21/05/2019

Policyholder's Signature \_\_\_\_\_  
Date & Time: 21/05/2019

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Susan Tan  
NRIC/FIN No:



[Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

J4403

## Vehicle Details

Vehicle No:

07Q270

Vehicle Licence Category:

PM

Licence Validity Expiry Date:

29 Apr 2025

Vehicle Make:

HONDA (HONDA)

Vehicle Model:

Civic 1.8i

Previous Colour:

Blue

Manufacturing Year:

2009

Engine No:

2714278020270

Chassis No:

JH2G040092A200274

Maximum Power Output:

150kW (204hp)

Open Market Value:

\$30,554.00

Original Registration Date:

11 Mar 2010

First Registration Date:

11 Mar 2010

Transfer Count:

0

Actual MSRP Price:

\$33,054.00

## Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligible Expiry Date:

31 Mar 2025

PARF Rebate Amount:

\$10,621.00

## Intended COE Rebate Details

COE Expiry Date:

30 Mar 2025

COE Category:

D - Green Category

COE Premium Amount:

0

COE Fee:

\$33,054.00

COE Rebate Amount:

\$1,254.00

Total Rebate Amount:

\$10,621.00

The information presented herein is correct as of 24 Apr 2023.

OK

Enquire Transfer Fee

Vehicle No.:	SFQ57B
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 CGI
Chassis No.:	WDD2040492A360074
Propellant:	Petrol
Engine No.:	27182030026736
Engine Capacity:	1796 cc
Maximum Power Output:	115.0 kW ( 154 bhp )
Maximum Laden Weight:	2000 kg
Unladen Weight:	1495 kg
Year Of Manufacture:	2009
Original Registration Date:	31 Mar 2010

Lifespan Expiry Date :	-
COE Category :	E - Open Category
Quota Premium :	\$19,889.00
COE Expiry Date :	30 Mar 2020
Road Tax Expiry Date :	30 Sep 2019
PARF Eligibility Expiry Date :	30 Mar 2020
Inspection Due Date :	30 Mar 2021

Intended Transfer Date :	28 May 2019	\$20,261.00
CO2 Emission :	-	\$1,764.00
CO Emission :	-	\$19,889.00
HC Emission :	-	10
NOx Emission :	-	E - Open Category
PM Emission :	-	

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Before GST	\$37,054.00
(GST)	2,527.00
Transfer Fee:	
<b>Total Amount Payable:</b>	

You may print this page for reference.

Enquire PARF/COE Rebate for Registered Vehicle

[> Back to OneMotoring](#)

Page 1

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference:  
Assessment number: HLW00050  
Version: 1810  
Date calculated: 14/06/2019 11:23 AM

Full Report  
Registration: SFQ57B OD  
Printed: 14/06/2019 11:24 AM

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	JOON LIAN TAN	Currency:	SGD
Claim Reference:		Date of Incident:	20/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer:	MERCEDES-BENZ
Model:	C-CLASS (W204)
Sub Model:	C 63 AMG
Model Sheet Number:	03 04 81
Registration:	SFQ57B OD
VIN number:	WDD2040492A360074
Odometer:	170421

**Model Specs**

FR A359./F451./R126.	TECH CHANGE 09/02	MODEL 2010	RAIN SENSOR
DIPPING MIRROR	FOLDING DOOR MIRRORS	AUDIO SYSTEM 20 CD	LEATHER UPHOLSTERY
ALU DESIGN PARTS	EQUIPMENT AVANTGARDE	STRG WHEEL LEATHER	LEATHER STRG WHEEL
H/DUTY ALTERNATOR	ENGINE PROTECTION	AUTO GEARBOX 5 SPEED	PARAMETER STEERING
CRUISE CONTROL	TYRES 225/45 WR 17	WHEELS 7.5J X 17 ALU	SPARE WHEEL
RIGHT HAND DRIVE	CLEAR COAT HARD	TWO COAT PEARL/MICA	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tanflm 17495749

Ex: NIL

Revert  
Not Authorise  
17/6/19 @ 1045am  
8400 Hk auto loan  
3-4 days 3-4 days ✓  
Repair part by part  
Resurvey before paint

# HIN LUNG WORKSHOP

## 1008 Bukit Merah Lane 3, #01-20

### 159722

Claim Reference:  
Assessment number: HLW00050  
Version: 1810  
Date calculated: 14/06/2019 11:23 AM

Full Report  
Registration: SFQ57B OD  
Printed: 14/06/2019 11:24 AM


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
60-2180 01	R + R ATTACHED PARTS AT REAR COVER PANEL TO REPLACE R/R WING INCLUDES: REAR PANEL TRIMS, BOOT COMPART, INTERIOR IN REAR, ON ENTRANCE, REAR BUMPER, TAILLAMP, PARTITION PANEL UNDER WING, HEADLINING, SEAT BELT AND REAR PANEL-WINDOW REMOVE AND REFIT	61.0	61.0	274.50
60-2155 ZAX	R + R ATT/PARTS OF THE REAR PANELLING FOR RENEWAL OF THE CENTRE REAR SECTION (WHEN RENEWING REAR WING) INCLUDES: R + R TAILLAMP AND ATTACHED PARTS IN THE REPAIR SECTION	12.0	12.0	54.00
63-1890 01	RENEW R/R WING	107.0	107.0	481.50
64-1042 01	RENEW REAR END PANEL CPL (WHEN RENEWING REAR WING)	41.0	41.0	184.50

# HIN LUNG WORKSHOP

## 1008 Bukit Merah Lane 3, #01-20

### 159722

Claim Reference:

Assessment number: HLW00050

Version: 1810

Date calculated: 14/06/2019 11:23 AM

Full Report

Registration: SFQ57B OD

Printed: 14/06/2019 11:24 AM

Code	Description	WU	Price SGD
88-6976 01)	R + R L/R LOWER WING PARTITION (WHEEL REMOVED)	2.0	9.00
88-8806 ZAX	RENEW REAR BUMPER	3.0	13.50
88-8905 01	ADD TO RENEW REAR BUMPER CPL (LUXURY VERSION VEHICLE)	3.0	13.50
88-8956 03	R + R REAR LOWER BUMPER CROSSMEMBER (BUMPER REMOVED)	10.0	45.00
88-1052 01	R + R REAR NUMBER PLATE	2.0	9.00
82-4971 01	RENEW L/TAILLAMP CARRIER (COMP WORK)	2.0	9.00
60-1624 01	R + R COMPLETE REAR SEAT AND CARPETS AND PLACE IN STORAGE	7.0	31.50
54-7989 02	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	9.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		<b>25.20</b>	<b>252.0</b>
<b>Total of Labour</b>			<b>1,134.00</b>

## Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	LWR REAR CENTRE PART NEW PART PAINTING	19.0
	R/R WING NEW PART PAINTING	26.0
	FRONT BUMPER COVER NEW PART PAINT K1R	10.0
	REAR BUMPER COVER NEW PART PAINT K1R	12.0

## Paint Material Per Part

Code	Description	Price SGD
2711	LWR REAR CENTRE PART NEW PART PAINTING	22.00
3482	R/R WING NEW PART PAINTING	34.10
0283	FRONT BUMPER COVER NEW PART PAINT K1R	44.28
2583	REAR BUMPER COVER NEW PART PAINT K1R	60.52

# HIN LUNG WORKSHOP

## 1008 Bukit Merah Lane 3, #01-20

### 159722

Claim Reference:

Assessment number: HLW00050

Version: 1810

Date calculated: 14/06/2019 11:23 AM

Full Report

Registration: SFQ57B OD

Printed: 14/06/2019 11:24 AM

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		67.0	
Preparation Main Work Metal	2.10	21.0	94.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
<b>Total</b>	<b>10 WU/h</b>	<b>93.0</b>	<b>418.50</b>

Material Cost - Paint	Price SGD
New Part Painting	56.10
New Part Painting - Plastic K1R	104.80
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	<b>188.00</b>

### Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
2583	REAR BUMPER COVER	204 885 2925 9999		de ✓	950.00 ✓
2593	L/R GUIDE	204 880 0330		de ✓	30.00 ✓
2594	R/R GUIDE	204 880 0430		de ✓	30.00 ✓
2598	TOWING EYE COVER	204 885 0823 9999		de ✓	32.00 ✓
2615	CTR REAR BUMPER	204 885 0421		de ✓	70.00 ✓
	MLDG				
2617	L/R BUMPER MOULDING	204 885 0921		de ✓	65.00 ✓
2618	R/R BUMPER MOULDING	204 885 1021		de ✓	65.00 ✓
2621	REAR BUMPER BRACKET	204 880 0414		de ✓	25.00 ✓
2640	REAR BUMPER C-MEMBER	204 610 0214		de ✓	420.00 ✓
2641	RR INNER BUMPER PART	204 885 0565		de ✓	85.00 ✓
2711	LWR REAR CENTRE PART	204 640 1771		de ✓	760.00 ✓
3282	R/R LAMP ASSY	204 906 8802		de ✓	325.00 ✓
3305	L/R LAMP CARRIER	204 820 1500 05		de ✓	46.00 ✓
3482	R/R WING	204 630 1021		de ✓	1,265.00 ✓
3686	R/R VENT INSERT	212 830 0242		de ✓	20.00 ✓
4910	R/SIDE PANEL TRIM	204 693 1633		de ✓	22.00 ✓
1000	R EXHAUST SHIELDING	204 690 0307		de ✓	32.00 ✓
1001	TAIL LAMP TOP C CLIP	000 991 5940		de ✓	6.00 30
1002	REAR WINDSCREEN SEAL	204 671 0050		de ✓	30.00 ✓
1003	R/R LAMP CARRIER	204 880 0203		de ✓	46.00 ✓
1004	R/FENDER SIDE PANEL	204 630 0660		de ✓	185.00 ✓

# HIN LUNG WORKSHOP

## 1008 Bukit Merah Lane 3, #01-20

### 159722

Claim Reference:

Assessment number: HLW00050

Version: 1810

Date calculated: 14/06/2019 11:23 AM

Full Report

Registration: SFQ57B OD

Printed: 14/06/2019 11:24 AM

Code	Description	Part Number	Supplier	Price SGD
1005	REAR LAMP PANEL RH	204 637 2644		<del>RM</del> 95.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			4,604.00
u: Used parts	Addition(+10.00%)			460.40
	Total			5,064.40

#### Extras

Code	Description	Price SGD
1006	R/WINDSCREEN SEALANT	<sup>#4</sup> 60.00*
1007	REAR PARKING SENSOR	<sup>dis/100</sup> 400.00*
	Total Extras	460.00

#### Final Calculation

	SGD	SGD
<b>Parts</b>	4,604.00	
Addition(+10.00%)	460.40	
<b>Total Parts</b>		5,064.40
<b>Labour Time Base 10 WU/h</b>		
Total 252.0 WU X 45.00 SGD/h	1,134.00	<sup>189</sup>
<b>Total of Labour</b>		1,134.00
<b>Total Of Extras</b>	<sup>200</sup>	460.00
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 93.0 WU X 45.00 SGD/h	418.50	
Material Cost	188.00	
<b>Total Paint Including Material</b>		606.50
<b>Repair Cost Excludes GST</b>		7,264.90
GST (+7.00%)		508.54
<b>Repair Cost Included GST</b>		7,773.44

<sup>3291</sup> 30

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference:

Assessment number: HLW00050

Version: 1810

Date calculated: 14/06/2019 11:23 AM

Full Report

Registration: SFQ57B OD

Printed: 14/06/2019 11:24 AM

---

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference: S9M0104P

Assessment number: HLW00050

Version: 1810

Date calculated: 06/07/2019 10:01 AM

**Full Report**

**Registration: SFQ57B OD**

**Printed: 06/07/2019 10:01 AM**

---

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	JOON LIAN TAN	Currency:	SGD
Claim Reference:	S9M0104P	Date of Incident:	20/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

**Vehicle Details**

**Vehicle**

Manufacturer:	MERCEDES-BENZ
Model:	C-CLASS (W204)
Sub Model:	C 63 AMG
Model Sheet Number:	03 04 81
Registration:	SFQ57B OD
VIN number:	WDD2040492A360074
Odometer:	170421

**Model Specs**

FR A359./F451./R126.	TECH CHANGE 09/02	MODEL 2010	RAIN SENSOR
DIPPING MIRROR	FOLDING DOOR MIRRORS	AUDIO SYSTEM 20 CD	LEATHER UPHOLSTERY
ALU DESIGN PARTS	EQUIPMENT AVANTGARDE	STRG WHEEL LEATHER	LEATHER STRG WHEEL
H/DUTY ALTERNATOR	ENGINE PROTECTION	AUTO GEARBOX 5 SPEED	PARAMETER STEERING
CRUISE CONTROL	TYRES 225/45 WR 17	WHEELS 7.5J X 17 ALU	SPARE WHEEL
RIGHT HAND DRIVE	CLEAR COAT HARD	TWO COAT PEARL/MICA	

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference: S9M0104P  
Assessment number: HLW00050  
Version: 1810  
Date calculated: 06/07/2019 10:01 AM

Full Report  
Registration: SFQ57B OD  
Printed: 06/07/2019 10:01 AM


**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
Date of Inspection:

**Damage Areas**

All ☐  
Underbody ☐



**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
88-6976 01)	R + R L/R LOWER WING PARTITION (WHEEL REMOVED)		2.0	9.00
88-8802 01	R + R REAR BUMPER		7.0	31.50
88-8806 ZAX	RENEW REAR BUMPER		3.0	13.50
88-8905 01	ADD TO RENEW REAR BUMPER CPL (LUXURY VERSION VEHICLE)		3.0	13.50
88-9247 01	R + R RIGHT REAR AIR VENT GRILLE		1.0	4.50
88-8956 03	R + R REAR LOWER BUMPER CROSSMEMBER (BUMPER REMOVED)		10.0	45.00
88-8225 01	R + R R/R COVER		2.0	9.00
88-1052 01	R + R REAR NUMBER PLATE		2.0	9.00
82-4903 02	R + R R/R LAMP UNIT, RENEW IF NECESSARY		3.0	13.50
82-4971 01	RENEW L/TAILLAMP CARRIER (COMP WORK)		2.0	9.00
40-1580 01	R + R REAR WHEEL (WHEELS)		3.0	13.50
1000	R EXHAUST SHIELDING 204 690 0307			
1002	REAR WINDSCREEN SEAL 204 671 0050			

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference: S9M0104P  
 Assessment number: HLW00050  
 Version: 1810  
 Date calculated: 06/07/2019 10:01 AM

Full Report  
 Registration: SFQ57B OD  
 Printed: 06/07/2019 10:01 AM

Code	Description	WU	Price SGD
1004	R/FENDER SIDE PANEL 204 630 0660		
1005	REAR LAMP PANEL RH 204 637 2644		
1006	R/WINDSCREEN SEALANT REMOVE&REFIT		
3482	R/R WING REPAIR	4.0*	18.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		4.20	42.0
<b>Total of Labour</b>			189.00

**Paint**

Paint Work		SYSTEM AZT		Time Basis 10WU/h	
Code	Description - TWO COAT PEARL/MICA	WU	Price SGD		
	LWR REAR CENTRE PART NEW PART PAINTING	19.0			
	R/R WING NEW PART PAINTING	26.0			
	FRONT BUMPER COVER NEW PART PAINT K1R	10.0			
	REAR BUMPER COVER NEW PART PAINT K1R	12.0			

**Paint Material Per Part**

Code	Description	Price SGD
2711	LWR REAR CENTRE PART NEW PART PAINTING	22.00
3482	R/R WING NEW PART PAINTING	34.10
0283	FRONT BUMPER COVER NEW PART PAINT K1R	44.28
2583	REAR BUMPER COVER NEW PART PAINT K1R	60.52

<b>Labour Cost - Paint</b>		<b>Hrs</b>	<b>WU</b>	<b>Price SGD</b>
Factor		45.00 SGD/h		
Time Paint			67.0	
Preparation Main Work Metal		2.10	21.0	94.50
Preparation Comp. Work Plastic		0.50	5.0	22.50
<b>Total</b>		10 WU/h	9.30	93.0

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference: S9M0104P  
 Assessment number: HLW00050  
 Version: 1810  
 Date calculated: 06/07/2019 10:01 AM

Full Report  
 Registration: SFQ57B OD  
 Printed: 06/07/2019 10:01 AM

Material Cost - Paint	Price SGD
New Part Painting	56.10
New Part Painting - Plastic K1R	104.80
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	<b>188.00</b>

**Spare Parts**

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER COVER	204 885 2925 9999		950.00
2593	L/R GUIDE	204 880 0330		30.00
2594	R/R GUIDE	204 880 0430		30.00
2598	TOWING EYE COVER	204 885 0823 9999		32.00
2615	CTR REAR BUMPER	204 885 0421		70.00
	MLDG			
2617	L/R BUMPER MOULDING	204 885 0921		65.00
2618	R/R BUMPER MOULDING	204 885 1021		65.00
2641	RR INNER BUMPER PART	204 885 0565		85.00
3282	R/R LAMP ASSY	204 906 8802		325.00
3305	L/R LAMP CARRIER	204 820 1500 05		46.00
3686	R/R VENT INSERT	212 830 0242		20.00
4910	R/SIDE PANEL TRIM	204 693 1633		22.00
1001	TAIL LAMP TOP C CLIP	000 991 5940		30.00
1003	R/R LAMP CARRIER	204 880 0203		46.00

f: OEM Parts	<b>Savings</b>	0.00
n: Non-OEM Parts	<b>Subtotal</b>	1,816.00
u: Used parts	<b>Addition(+10.00%)</b>	181.60
	<b>Total</b>	<b>1,997.60</b>

**Extras**

Code	Description	Price SGD
1007	REAR PARKING SENSOR	200.00*
	<b>Total Extras</b>	<b>200.00</b>

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference: S9M0104P  
Assessment number: HLW00050  
Version: 1810  
Date calculated: 06/07/2019 10:01 AM

Full Report  
Registration: SFQ57B OD  
Printed: 06/07/2019 10:01 AM

**Final Calculation**

	SGD	SGD
<b>Parts</b>	1,816.00	
Addition(+10.00%)	181.60	
<b>Total Parts</b>		<b>1,997.60</b>
<b>Labour Time Base 10 WU/h</b>		
Total 42.0 WU X 45.00 SGD/h	189.00	
<b>Total of Labour</b>		<b>189.00</b>
<b>Total Of Extras</b>		<b>200.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 93.0 WU X 45.00 SGD/h	418.50	
Material Cost	188.00	
<b>Total Paint Including Material</b>		<b>606.50</b>
<b>Repair Cost Excludes GST</b>		<b>2,993.10</b>
GST (+7.00%)		<b>209.52</b>
<b>Repair Cost Included GST</b>		<b>3,202.62</b>

**Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference:  
Assessment number: HLW00050  
Version: 1810  
Date calculated: 14/06/2019 11:23 AM

Full Report  
Registration: SFQ57B OD  
Printed: 14/06/2019 11:24 AM

**Summary Information**

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	JOON LIAN TAN	Currency:	SGD
Claim Reference:		Date of Incident:	20/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

<b>Vehicle</b>			
Manufacturer:	MERCEDES-BENZ		
Model:	C-CLASS (W204)		
Sub Model:	C 63 AMG		
Model Sheet Number:	03 04 81		
Registration:	SFQ57B OD		
VIN number:	WDD2040492A360074		
Odometer:	170421		
<b>Model Specs</b>			
FR A359./F451./R126.	TECH CHANGE 09/02	MODEL 2010	RAIN SENSOR
DIPPING MIRROR	FOLDING DOOR MIRRORS	AUDIO SYSTEM 20 CD	LEATHER UPHOLSTERY
ALU DESIGN PARTS	EQUIPMENT AVANTGARDE	STRG WHEEL LEATHER	LEATHER STRG WHEEL
H/DUTY ALTERNATOR	ENGINE PROTECTION	AUTO GEARBOX 5 SPEED	PARAMETER STEERING
CRUISE CONTROL	TYRES 225/45 WR 17	WHEELS 7.5J X 17 ALU	SPARE WHEEL
RIGHT HAND DRIVE	CLEAR COAT HARD	TWO COAT PEARL/MICA	

Tanplm 17495749

EX: NIL

Revert ~~As per~~ 17/6/19 @ 17/6/19 1045.  
Not Authorise

sure 1/11/2016

3-4 days 3-4 days ✓

Repair part by part to keep car

Resumey before paint

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference:  
Assessment number: HLW00050  
Version: 1810  
Date calculated: 14/06/2019 11:23 AM

Full Report  
Registration: SFQ57B OD  
Printed: 14/06/2019 11:24 AM

**Vehicle Condition**


**Vehicle Status**

Pre-Accident Damage:

Date of Inspection:

**Damage Areas**

All ☐  
Underbody ☐



**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
60-2180 01	R + R ATTACHED PARTS AT REAR COVER PANEL TO REPLACE R/R WING INCLUDES: REAR PANEL TRIMS, BOOT COMPART, INTERIOR IN REAR, ON ENTR- ANCE, REAR BUMPER, TAILLAMP, PARTITION PANEL UNDER WING, HEAD- LINING, SEAT BELT AND REAR PANEL- WINDOW REMOVE AND REFIT		61.0	274.50
60-2155 ZAX	R + R ATT/PARTS OF THE REAR PANELLING FOR RENEWAL OF THE CENTRE REAR SECTION (WHEN RENEWING REAR WING) INCLUDES: R + R TAILLAMP AND ATTACHED PARTS IN THE REPAIR SECTION		12.0	54.00
63-1890 01	RENEW R/R WING		107.0	481.50
64-1042 01	RENEW REAR END PANEL CPL (WHEN RENEWING REAR WING)		41.0	184.50

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference:  
 Assessment number: HLW00050  
 Version: 1810  
 Date calculated: 14/06/2019 11:23 AM

Full Report  
 Registration: SFQ57B OD  
 Printed: 14/06/2019 11:24 AM

Code	Description	WU	Price SGD
88-6976 01)	R + R L/R LOWER WING PARTITION (WHEEL REMOVED)	2.0	9.00
88-8806 ZAX	RENEW REAR BUMPER	3.0	13.50
88-8905 01	ADD TO RENEW REAR BUMPER CPL (LUXURY VERSION VEHICLE)	3.0	13.50
88-8956 03	R + R REAR LOWER BUMPER CROSSMEMBER (BUMPER REMOVED)	10.0	45.00
88-1052 01	R + R REAR NUMBER PLATE	2.0	9.00
82-4971 01	RENEW L/TAILLAMP CARRIER (COMP WORK)	2.0	9.00
60-1624 01	R + R COMPLETE REAR SEAT AND CARPETS AND PLACE IN STORAGE	7.0	31.50
54-7989 02	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	9.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		<b>25.20</b>	<b>252.0</b>
<b>Total of Labour</b>			<b>1,134.00</b>

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	LWR REAR CENTRE PART NEW PART PAINTING	19.0
	R/R WING NEW PART PAINTING	26.0
	FRONT BUMPER COVER NEW PART PAINT K1R	10.0
	REAR BUMPER COVER NEW PART PAINT K1R	12.0

**Paint Material Per Part**

Code	Description	Price SGD
2711	LWR REAR CENTRE PART NEW PART PAINTING	22.00
3482	R/R WING NEW PART PAINTING	34.10
0283	FRONT BUMPER COVER NEW PART PAINT K1R	44.28
2583	REAR BUMPER COVER NEW PART PAINT K1R	60.52

# HIN LUNG WORKSHOP

## 1008 Bukit Merah Lane 3, #01-20

### 159722

Claim Reference:  
Assessment number: HLW00050  
Version: 1810  
Date calculated: 14/06/2019 11:23 AM

Full Report  
Registration: SFQ57B OD  
Printed: 14/06/2019 11:24 AM

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		67.0	
Preparation Main Work Metal	2.10	21.0	94.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
<b>Total</b>	10 WU/h	93.0	418.50

Material Cost - Paint	Price SGD
New Part Painting	56.10
New Part Painting - Plastic K1R	104.80
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	188.00

### Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
2583	REAR BUMPER COVER	204 885 2925 9999		de	950.00
✓ 2593	L/R GUIDE	204 880 0330		com X	30.00
2594	R/R GUIDE	204 880 0430		de	30.00
2598	TOWING EYE COVER	204 885 0823 9999		mis	32.00
2615	CTR REAR BUMPER*	204 885 0421		com	70.00
	MLDG				
2617	L/R BUMPER MOULDING	204 885 0921		de	65.00
2618	R/R BUMPER MOULDING	204 885 1021		com	65.00
2621	REAR BUMPER BRACKET	204 880 0414		mis	25.00
2640	REAR BUMPER C-MEMBER	204 610 0214		mis	420.00
✓ 2641	RR INNER BUMPER PART	204 885 0565		de	85.00
2711	LWR REAR CENTRE PART	204 640 1771		mis	760.00
3282	R/R LAMP ASSY	204 906 8802		com	325.00
✓ 3305	L/R LAMP CARRIER	204 820 1500 05		de	46.00
✓ 3482	R/R WING	204 630 1021		4 WU Rx	1,265.00
✓ 3686	R/R VENT INSERT	212 830 0242		de	20.00
✓ 4910	R/SIDE PANEL TRIM	204 693 1633		de	22.00
1000	R EXHAUST SHIELDING	204 690 0307		mis	32.00
1001	TAIL LAMP TOP C CLIP	000 991 5940	-5 PCS	30.00 de	6.00
1002	REAR WINDSCREEN SEAL	204 671 0050		mis	30.00
✓ 1003	R/R LAMP CARRIER	204 880 0203		com X	46.00
1004	R/FENDER SIDE PANEL	204 630 0660		mis	185.00

*Signature* 26/6

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference:

Assessment number: HLW00050

Version: 1810

Date calculated: 14/06/2019 11:23 AM

Full Report

Registration: SFQ57B OD

Printed: 14/06/2019 11:24 AM

Code	Description	Part Number	Supplier	Price SGD
1005	REAR LAMP PANEL RH	204 637 2644		11 x 95.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			4,604.00
u: Used parts	Addition(+10.00%)			460.40
	<b>Total</b>			<b>5,064.40</b>

**Extras**

Code	Description	Price SGD
1006	R/WINDSCREEN SEALANT	11 x 60.00*
1007	REAR PARKING SENSOR	200 11 x ? 400.00*
	<b>Total Extras</b>	<b>460.00</b>

**Final Calculation**

	SGD	SGD
<b>Parts</b>		
Addition(+10.00%)	4,604.00	
<b>Total Parts</b>	460.40	<b>5,064.40</b>
<b>Labour Time Base 10 WU/h</b>		
Total 252.0 WU X 45.00 SGD/h	1,134.00	
<b>Total of Labour</b>		<b>1,134.00</b>
<b>Total Of Extras</b>		<b>460.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 93.0 WU X 45.00 SGD/h	418.50	
Material Cost	188.00	
<b>Total Paint Including Material</b>		<b>606.50</b>
<b>Repair Cost Excludes GST</b>		<b>7,264.90</b>
GST (+7.00%)		508.54
<b>Repair Cost Included GST</b>		<b>7,773.44</b>

**HIN LUNG WORKSHOP**  
**1008 Bukit Merah Lane 3, #01-20**  
**159722**

Claim Reference:

Assessment number: HLW00050

Version: 1810

Date calculated: 14/06/2019 11:23 AM

Full Report

Registration: SFQ57B OD

Printed: 14/06/2019 11:24 AM

---

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS



redefining / insurance

### SATISFACTION VOUCHER / WORKSHOP'S WARRANTY

To: AXA Insurance Pte Ltd

I/We Yang Jiao & Yang Qiao hereby confirm that I/we have taken delivery of my/our vehicle of registration number SFQ 518 from the Workshop, Messrs Hin Lung Workshop and that all necessary and reasonable repairs arising from the accident involving my/our vehicle that occurred on 20/05/2019 have been effected to my/our entire satisfaction. Save for my/our rights under the Warranty set out below, I/we confirm that I/we have no further claims against the Workshop in respect of such repairs.

I/We hereby authorise my/our insurer, AXA Insurance Pte Ltd, to pay the costs of such repairs (less the excess) which amounts to S\$ 2,568.00 directly to the said Workshop and I/we confirm that such payment shall wholly discharge any and all liability on the part of AXA Insurance Pte Ltd to indemnify me/ us for all damage to my/our said vehicle arising from the said accident.

Dated: 02/07/2019

Signature of the Policyholder or duly authorized representative and company stamp where applicable.

### WORKSHOP'S WARRANTY

Subject to provisions (a) to (d) below, the repairs effected to the abovementioned vehicle are warranted good by the Workshop for twelve (12) months from the date of this Satisfaction Voucher and during this period, rectification of repairs effected by the Workshop which prove to be faulty shall be undertaken by the Workshop free of charge.

This Warranty shall be inapplicable to:

- (a) faults arising out of abnormal usage of the vehicle;
- (b) faults due to attempts to correct any defect in the repairs effected by the Workshop or the mishandling of rectification work to the vehicle by persons other than the Workshop;
- (c) manufacturing defects in any parts replaced that could not reasonably have been detected by the Workshop at the time the repairs were effected;
- (d) faults or defects arising out of normal wear and tear, misuse, neglect, accident, flood, acts of God, or use in violation of the specifications relevant to the vehicle.

Signature and stamp of the Workshop

**TAX INVOICE**

M/s AXA INSURANCE PTE LTD  
8 SHENTON WAY, #24-01 AXA TOWER  
SINGAPORE 068811  
ATTN.: MR PETER WANG

INVOICE NO. : OD531  
Acc/Rep Date: 20/05/2019  
Policy No. : P1718754  
Model : C180 CGI 0  
Veh Reg. No.: SFQ57B  
Invoice Date: 30/07/2019 Page: 1

<u>REPLACEMENT OF PARTS</u>	
1 LUMP SUM REPAIR PARTS AND LABOURS.	2,400.00
-----	
Nett Total Before GST	2,400.00
Add GST @ 7%	168.00
=====	
Nett Total After GST (CLAIM:S9M0104P)	2,568.00
=====	

(Two Thousand Five Hundred Sixty-Eight Only)



HIN LUNG WORKSHOP  
(Workshop Manager)



**POLICYHOLDER ACKNOWLEDGEMENT FORM**

Date: 21/05/2019

To: Owner of Vehicle Number: SF057B

The following has been advised to you via your workshop, HIN LUNG WORKSHOP through their staff,  
Susan Tan


Please tick the applicable box if you had been advised on any of the following:

- (☒) You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- (☒) You had been advised by the workshop on the liability and merits of the case accordingly.
- (☒) You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- (☒) There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ( ) There will be no cancellation/withdrawal of the Own Damage claim once the order of spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ( ) The estimated waiting time for the spare parts to arrive is \_\_\_\_\_. The estimated arrival time does not include the repair period.
- (☒) You will be driving the vehicle out despite being advised by the workshop mechanic/ personnel that the vehicle may not be road worthy.
- (☒) For vehicles below three (3) years old or under warranty with a local distributor, your insurance company will use only original parts to repair your vehicle.
- For vehicles above three (3) years old and no longer under warranty with a local distributor, your insurance company will be carrying out repairs where any damaged part that can be repaired will be repaired and any part that needs to be replaced will be replaced using **any combination** of original parts and/or original equipment manufacturer (OEM) parts and/or second-hand parts.
- (☒) You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ( ) For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ( ) Others \_\_\_\_\_

Signed and acknowledged by:

Name and signature of policyholder/ authorized driver\* and company stamp (where applicable)

\*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.



Name and signature of workshop personnel including company stamp