



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2009 MERCEDES BENZ C180 CGI (SFQ57B)

Date of Loss 20 May 2019

Time of Loss 16.55

Loss Description SFQ57B (INSD) C/W SJN3033T (TP)

Comment

Workshop Details

Total Rebate Amount 20033

Nett Loss Amount \$7,967.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SFQ57B

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

31/03/2010



Mileage

171624

Age of Vehicle

9

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2009

2009

Make

MERCEDES BENZ

MERCEDES BENZ

Model

C180 CGI

C 180 CGI

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

YANG JIAO @ YANG QIAO

Date of Birth

14 April 1968

dd/mm/yy



Age

51

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	WDD2040492A360074	WDD2040492A3
Engine No	27182030026736	27182030026736
Engine Capacity		1796
Sum Insured	0	0
Market Value	0	28000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	13	
Driver License #		
License Type		
License Issue Date		dd/mm/yy 
License Expiration Date		dd/mm/yy 
Address	27B WEST COAST PARK, #04-07, 127722, Singapore	
Address type	Residential	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Married	
Identification #	S6882997F	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

17/06/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
named Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/45R17

Rear Tyre Size

225/45R17

Front left side

GOODYEAR6mm

Rear left side

GOODYEAR6mm

Front right side

GOODYEAR6mm

Rear right side

GOODYEAR6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add Approve Deny Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
☐		0	1		REAR BUMPER COVER (WCP) (10%)	Deformed	0	1045	No					1045	Reviewing	
☐		0	1		L/R GUIDE (WCP) (10%)	Deformed	0	33	No					33	Reviewing	
☐		0	1		R/R GUIDE (WCP) (10%)	Necessary	0	33	No					33	Reviewing	
☐		0	1		TOWING EYE COVER (WCP) (10%)	Missing	0	35.2	No					35.2	Reviewing	
☐		0	1		CTR REAR BUMPER MLDG (WCP) (10%)	Cracked	0	77	No					77	Reviewing	
☐		0	1		L/R BUMPER MOULDING (WCP) (10%)	Necessary	0	71.5	No					71.5	Reviewing	
☐		0	1		R/R BUMPER MOULDING (WCP) (10%)	Cracked	0	71.5	No					71.5	Reviewing	
☐		0	1		REAR BUMPER BRACKET	Serviceable	0	0	No					0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		REAR BUMPER C-MEMBER	Serviceable	0	0	No					0	Deny	
		0	1		RR INNER BUMPER PART (WCP) (10%)	Deformed	0	93.5	No					93.5	Reviewing	
		0	1		LWR REAR CENTRE PART	Serviceable	0	0	No					0	Deny	
		0	1		R/R LAMP ASSY (WCP) (10%)	Cracked	0	357.5	No					357.5	Reviewing	
		0	1		L/R LAMP CARRIER (WCP) (10%)	Damaged	0	50.6	No					50.6	Reviewing	
		0	1		R/R WING	Repair	0	0	No					0	Deny	
		0	1		R/R VENT INSERT (WCP) (10%)	Necessary	0	22	No					22	Reviewing	
		0	1		R/SIDE PANEL TRIM (WCP) (10%)	Deformed	0	24.2	No					24.2	Reviewing	
		0	1		R EXHAUST SHIELDING	Serviceable	0	0	No					0	Deny	
		0	1		TAIL LAMP TOP C CLIP (WCP) (10%)	Necessary	0	33	No					33	Reviewing	
		0	1		REAR WINDSCREEN SEAL	Serviceable	0	0	No					0	Deny	
		0	1		R/R LAMP CARRIER (WCP) (10%)	Damaged	0	50.6	No					50.6	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		R/FENDER SIDE PANEL	Serviceable	0	0	No					0	Deny	
		0	1		REAR LAMP PANEL RH	Serviceable	0	0	No					0	Deny	

Labour

Add	Approve	Deny	Submit All							
EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
		0	252.0 WU X 45.00 SGD/H	0	189	0	0	Reviewing		
		0	LABOUR COST 93.0 WU X 45.00 SGD/H	0	418.5	0	0	Reviewing		
		0	MATERIAL COST	0	188	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
☐		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
☐		0	R/WINDSCREEN SEALANT	Deny		0	NOT NECESSARY	
☐		0	REAR PARKING SENSOR	Reviewing		200	DISTORTED	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$2,993.10

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$1,997.60

Labour

\$0.00

\$795.50

Miscellaneous

\$0.00

\$200.00

[Submit for Review](#)



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

2400





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$2,400.00

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

\$0.00

\$2,400.00

Submit for Review