

ASS. REC. BY:

REF: CS/FCI19010609/040312

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

check with marcus

From (Person): Henry Kao

of

FCI

Date/Time: 13.6.2019 5.04pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SMC 1021M

Insured: SHA 0400D

at Workshop m/s Fastech Auto

Tel: 67465405

of 1 Kian Bukit Ave 6 # 01-46

Policy No:

Claim No: D19003894MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 12.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

rup

H.O.D. Endorsement:

Date/Time: 14.6.19 5.30pm

Person Contacted: nancy

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMC 1021M - KA/INV 19010471/64 DOA - 12/06/2019
	SHA 0400D - X
	11/6@1:58pm - Pending estimate via email.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

CIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC102/M Yr Regn: 6.18

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make:

Toyota Sienta c.c. 1496

Colour:

Steel A/C: Insured / Std / NI / NA

Sp. Reading:

61435 T/Radio: Insured / Std / NI / NA

Eng/No:

NHP170 7123964

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F: 185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

12/6/19

D.O.I.

13/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/7/19 1/5 # 4800 confirmed with Alan (red: 8617.60:64%)

RECEIVED 23 JUL 2019

Date/Time, File Pass to?



Preli. Report



Final Report

1) 23/7 Typist

Date/Time, File Return to?

2)

Report Format:

TP

Lump. Sum / I.B.I.: (\$ 4800/-)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

3x15=45

170+45

50

5050

81

446

MOTOR SURVEY ASSIGNMENT

Date	14-06-2019	Our Ref No. D19003894MFSH
Accident Date	12-06-2019	Claim Type. Third Party
Insured Vehicle	SHA0400D	Third Party Vehicle. SMC1021M
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 17 June 2019 1:58 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003894MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle **SMC 1021M** on 13/6/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 14 June 2019 5:40 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003894MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 14 June 2019 5:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003894MFSH/1



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Boxster S at the Price of a Boxster!



Latest 718 Boxster S, Cheapest
in the Market, Immaculate
Condition
StarAd


Browse by Category

Sort by Date Posted 20 results/page

2 vehicles

Sienta Hybrid 1.5A

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Sienta Hybrid 1.5A		Any	Any	2018	Any	Any	Any	Available
	Toyota	Sienta Hybrid 1.5A G	\$89,900	\$9,320 /yr	26-Jun-2018	1,496 cc	-	MPV	Available
Fuel Type: Petrol-Electric Elegant Blue MPV, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.									
Prime Motor & Leasing Posted: 05-Jun-2019 Tags: 2018 Toyota Sienta, 2018 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota									
	Toyota	Sienta Hybrid 1.5A G	\$90,000	\$9,520 /yr	27-Jun-2018	1,496 cc	-	MPV	Available
Fuel Type: Petrol-Electric Elegant Yellow MPV, Low Fuel Consumption With Hybrid, Easy Financing, Flexible In-House Loan Packages Available.									
Prime Motor & Leasing Posted: 08-May-2019 Tags: 2018 Toyota Sienta, 2018 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Sienta Hybrid 1.5A, Sienta Hybrid 1.5A Singapore, used Sienta Hybrid 1.5A Singapore, used Sienta Hybrid 1.5A, used vehicles Singapore or even buy used Sienta Hybrid 1.5A Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 3500X

Vehicle Details

Vehicle No.: SMC1021M

Vehicle to be Exported: No

Intended Deregistration Date: 14 Jun 2019

Vehicle Make: TOYOTA

Vehicle Model: SIENTA HYBRID 1.5X AUTO

Primary Colour: Black

Manufacturing Year: 2018

Engine No.: 1NZ8528714

Chassis No.: NHP1707123964

Maximum Power Output: 73.0 kW (97 bhp)

Open Market Value: \$23,015.00

Original Registration Date: 26 Jun 2018

First Registration Date: 26 Jun 2018

Transfer Count: 0

Actual ARF Paid: \$14,221.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Jun 2028

PARF Rebate Amount: \$10,665.00

Intended COE Rebate Details

COE Expiry Date: 25 Jun 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$36,890.00

COE Rebate Amount: \$33,313.00

Total Rebate Amount: \$43,978.00

The information contained herein is correct as at 14 Jun 2019

OK

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
date
13/6/19
4/5 & 4800 Hdy.

VEHICLE NO: SMC 1021M

QTY	PARTICULAR			
1 PCS	FRONT DOOR O/S	1288.10	50650	\$1,685.10
1 PCS	FRONT DOOR GLASS O/S	620.50	shuttered	\$866.50
1 PCS	FRONT DOOR GLASS OUTER MOULDING O/S		3erf	\$199.20
1 PCS	FRONT DOOR OUTER HANDLE O/S	288.20	cut/fin	\$311.50
1 PCS	FRONT DOOR INNER LOCK O/S		shuttered	\$366.20
1 PCS	FRONT DOOR INNER TRIM BOARD O/S	711.90	re 10.1	\$845.10
1 SET	FRONT DOOR INNER TRIM BORAD CLIPS O/S		ur	\$50.00
1 PCS	FRONT DOOR INNER RUBBER O/S		ur	\$166.50
1 PCS	FRONT DOOR GLASS REGULATOR O/S		ur	\$311.20
1 PCS	FRONT DOOR GLASS REGULATOR MOTOR O/S		eye/3erf	\$450.10
1 SET	FRONT DOOR FRAME BLACK STICKER O/S	65.00	ur	\$125.00
1 PCS	FRONT DOOR VIEW MIRROR ASSY O/S		ur	\$866.10
1 PCS	FRONT DOOR INNER LOCK BRACKET O/S		ur	\$121.50
1 PCS	CENTRE PILLAR O/S		ur	\$899.10
1 PCS	SLIDING DOOR O/S	1485.10	ur/3erf	\$1,885.10
1 PCS	SLIDING DOOR INNER LOCK O/S		ur	\$399.50
1 PCS	SLIDING DOOR RUBBER O/S		ur	\$266.50
1 SET	SLIDING DOOR FRAME BLACK STICKER O/S	85.00	ur	\$128.00
1 PCS	SLIDING DOOR OUTER HANDLE O/S	285.50	ur	\$305.10
1 PCS	SLIDING DOOR OUTER HANDLE KNOCK O/S		ur	\$60.00
1 PCS	SLIDING DOOR GLASS OUTER MOULDING O/S		ur	\$188.20
1 PCS	SLIDING DOOR OUTER PROTECTOR O/S		ur	\$422.10
				\$10,917.60

LABOUR CHARGES
TO CHECK WIRING
TO SPRAY RUST PROOFING
TO TRANSFE FRONT DOOR MECHANISM
TO TRNAFER SLIDING DOOR MECHANISM
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$80.00 20
\$100.00 60
\$120.00 60
\$120.00 60
\$800.00 400
\$1,280.00 650
TOTAL \$13,417.60

Warranty
The Repairer shall be responsible for:
• To maintain the vehicle in good condition
• To provide the vehicle in good condition
• To provide the vehicle in good condition
• To provide the vehicle in good condition
• To provide the vehicle in good condition
• To provide the vehicle in good condition
• To provide the vehicle in good condition
Authorized by Repairer
Signature:
Date:

6370.40
252
477780
6027.8



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19010609/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 400D	Veh. Inspected	SMC 1021M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003894MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	13/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	NHP1707123964	Colour	BLACK	
Odometer	61435	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	TOYO	7 mm	
L/H Front Tyre	185/60 R15	TOYO	7 mm	
R/H Rear Tyre	185/60 R15	TOYO	7 mm	
L/H Rear Tyre	185/60 R15	TOYO	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/06/2019	Inspection Date	13/06/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 1021M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR O/S	BADLY DENTED	1,685.10	1,288.10
1	FRONT DOOR GLASS O/S	SHATTERED	866.50	620.50
1	FRONT DOOR GLASS OUTER MOULDING O/S	BENT	199.20	199.20
1	FRONT DOOR OUTER HANDLE O/S	CUT / TWISTED	311.50	288.20
1	FRONT DOOR INNER LOCK O/S	SHORTED / JAMMED	366.20	366.20
1	FRONT DOOR INNER TRIM BOARD O/S	DEFORMED / TORN	845.10	711.90
1	SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	NECESSARY	50.00	50.00
1	FRONT DOOR INNER RUBBER O/S	NECESSARY	166.50	166.50
1	FRONT DOOR GLASS REGULATOR O/S	DAMAGED / BENT	311.20	311.20
1	FRONT DOOR GLASS REGULATOR MOTOR O/S	NOT NECESSARY	450.10	-
1	SET FRONT DOOR FRAME BLACK STICKER O/S	NECESSARY	125.00	65.00
1	FRONT DOOR VIEW MIRROR ASSY O/S	TO REPAIR SEE LABOUR	866.10	-
1	FRONT DOOR INNER LOCK BRACKET O/S	CRACKED	121.50	121.50
1	CENTRE PILLAR O/S	TO REPAIR SEE LABOUR	899.10	-
1	SLIDING DOOR O/S	DENTED / BENT	1,885.10	1,485.10
1	SLIDING DOOR INNER LOCK O/S	NOT NECESSARY	399.50	-
1	SLIDING DOOR RUBBER O/S	NECESSARY	266.50	266.50
1	SET SLIDING DOOR FRAME BLACK STICKER O/S	NECESSARY	128.00	85.00
1	SLIDING DOOR OUTER HANDLE O/S	CUT	305.10	285.50
1	SLIDING DOOR OUTER HANDLE KNOCK O/S	CUT	60.00	60.00
1	SLIDING DOOR GLASS OUTER MOULDING O/S	NOT NECESSARY	188.20	-
1	SLIDING DOOR OUTER PROTECTOR O/S	NOT NECESSARY	422.10	-
	LESS 25% DISCOUNT		-	-1,592.60
			10,917.60	4,777.80
LABOUR				
	TO CHECK WIRING.		80.00	20.00
	TO SPRAY RUST PROOFING.		100.00	60.00
	TO TRANSFER FRONT DOOR MECHANISM.		120.00	60.00

Report Ref No. CS/FCI19010609/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER SLIDING DOOR MECHANISM.		120.00	60.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR VIEW MIRROR ASSY O/S AND CENTRE PILLAR O/S.		800.00	400.00
	TO PUTTY & SPRAY PAINTING.		1,280.00	650.00
			2,500.00	1,250.00
GRAND TOTAL			13,417.60	6,027.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,800.00

Report Ref No. CS/FC119010609/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.