

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
 SHD9578A -

ROEL

*Not Authored*  
*1-B.1*  
*\$ 5791.45*

|                       |                         |
|-----------------------|-------------------------|
| Vehicle No.:          | <b>SHD 9578A - ROEL</b> |
| Chassis No.:          | LK1LA69RJBB098105*      |
| Vehicle Make:         | CHEVROLET               |
| Vehicle Model:        | CHEVROLET EPICA 2.0     |
| Date of Accident :    | 06.06.2013              |
| Third Party Insurer : | <i>AVG</i>              |

| PART |   |                                        | LIST |                          |
|------|---|----------------------------------------|------|--------------------------|
| 1    | 1 | Front Bumper ( Bumper A-Frt )          | \$   | <i>Bul/Dr</i> 1,202.00 ✓ |
| 2    | 1 | Front Bumper Lower Absorber            | \$   | <i>Sm</i> 180.00 X       |
| 3    | 1 | Front Bumper Reinforcement             | \$   | <i>R</i> 356.00 X        |
| 4    | 1 | Front Bumper Lower Stiffener           | \$   | <i>R</i> 134.37 X        |
| 5    | 1 | Front Bumper Retainer RH               | \$   | <i>Dr</i> 102.00 ✓       |
| 6    | 1 | Front Bumper Fog Lamp Outer Cover RH   | \$   | <i>Sm</i> 32.40 X        |
| 7    | 1 | Front Headlamp RH (Lamp A-Head RH)     | \$   | <i>CMS</i> 816.00 ✓      |
| 8    | 1 | Front Fender RH                        | \$   | <i>R</i> 837.60 ✓        |
| 9    | 1 | Front Fender Liner RH                  | \$   | <i>Dr</i> 47.00 ✓        |
| 10   | 1 | Front Side View Mirror Assy RH         | \$   | <i>Dr/CMS</i> 939.00 ✓   |
| 11   | 1 | Front Door RH (Panel A-Frt DR RH)      | \$   | <i>R</i> 1,133.00 ✓      |
| 12   | 1 | Front Door Hinge Upper ( Hinge A-Dr )  | \$   | <i>R</i> 20.67 X         |
| 13   | 1 | Front Door Hinge Lower ( Hinge A-Dr )  | \$   | <i>R</i> 20.67 X         |
| 14   | 1 | Centre Pillar Reinforcement ( Centre ) | \$   | <i>R</i> 596.00 X        |
| 15   | 1 | Rear Door RH ( Panel A-RR DR RH )      | \$   | <i>R</i> 1,133.00 X      |
| 16   | 1 | Rear Door Top Hinge LH                 | \$   | <i>R</i> 91.68 X         |
| 17   | 1 | Rear Door Bottom Hinge LH              | \$   | <i>R</i> 91.68 X         |
| 18   | 1 | Rear Door Check/ Arrestor LH           | \$   | <i>Sm</i> 145.68 X       |
| 19   | 1 | Rear Fender RH                         | \$   | <i>R</i> 1,145.00 X      |
| 20   | 1 | Rear Bumper (Bumper A-RR)              | \$   | <i>R</i> 1,202.00 X      |

|       |    |                  |
|-------|----|------------------|
| TOTAL | \$ | <b>10,225.75</b> |
| 25%   | \$ | <b>2,556.44</b>  |
|       | \$ | <b>7,669.31</b>  |

**Specical Nett**

|       |                                |    |                  |
|-------|--------------------------------|----|------------------|
| 1 Set | Front Bumper Fastener Clip     | \$ | <i>R</i> 24.00 ✓ |
| 1 Set | Front Fender Liner Clip        | \$ | <i>R</i> 20.00 ✓ |
| 1     | Front Door Sticker 'Trans-Cab' | \$ | <i>R</i> 60.00 ✓ |

**TRANS-CAB AUTO SERVICES PTE LTD****ROEL**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD9578A -

|   |                                   |    |             |
|---|-----------------------------------|----|-------------|
| 1 | Rear Door Sticker '6555-3333'     | \$ | Na 60.00 ✓  |
| 2 | Rear Windscreen Sealant           | \$ | na 100.00 X |
| 1 | Rear Windscreen Inner Sponge Seal | \$ | na 80.00 X  |

|       |    |               |
|-------|----|---------------|
| TOTAL | \$ | <u>344.00</u> |
|-------|----|---------------|

|             |    |          |
|-------------|----|----------|
| TOTAL PARTS | \$ | 8,013.31 |
|-------------|----|----------|

Panel Beating, Knocking And Straightening  
The Necessary Portion, Remove And  
Renewal Of Parts, Adjust And Realign The  
Same

|    |          |     |
|----|----------|-----|
| \$ | 2,500.00 | 600 |
|----|----------|-----|

To Rust-Proofing Of The Affected Areas.

|    |        |    |
|----|--------|----|
| \$ | 200.00 | 60 |
|----|--------|----|

To Check Electrical Lighting Concerned.

|    |        |    |
|----|--------|----|
| \$ | 100.00 | 20 |
|----|--------|----|

Putty and Spray Painting Of The Affected  
Portion.

|    |          |      |
|----|----------|------|
| \$ | 1,800.00 | 1080 |
|----|----------|------|

To Transfer Of Front Fender Fittings,  
Attachment And Perform Water Seepage  
Test.

|    |           |   |
|----|-----------|---|
| \$ | na 150.00 | X |
|----|-----------|---|

To Transfer Of Rear Fender Fittings,  
Attachment And Perform Water Seepage  
Test.

|    |           |   |
|----|-----------|---|
| \$ | na 150.00 | X |
|----|-----------|---|

To Remove And Refit Rear W/ Screen Glass  
To Facilitate Bodywork Repair.

|    |           |   |
|----|-----------|---|
| \$ | na 150.00 | X |
|----|-----------|---|

To Reseal Sealant On Gap

|    |           |   |
|----|-----------|---|
| \$ | na 100.00 | X |
|----|-----------|---|

To Transfer Of Door Fittings, Attachment  
And Perform Water Seepage Test.

|    |        |    |
|----|--------|----|
| \$ | 300.00 | 60 |
|----|--------|----|

Towing Fee

|    |           |   |
|----|-----------|---|
| \$ | na 100.00 | X |
|----|-----------|---|

To Remove And Replace Corporate Sticker

|    |           |   |
|----|-----------|---|
| \$ | na 300.00 | X |
|----|-----------|---|

TRANS-CAB AUTO SERVICES PTE LTD  
NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346  
TEL NO.6287 6666 FAX NO.6366 8862  
CO/GST REG NO.201019626G  
SHD9578A -

ROEL

|              |           |                 |
|--------------|-----------|-----------------|
| <i>TOTAL</i> | <i>\$</i> | <u>5,850.00</u> |
|--------------|-----------|-----------------|

|                       |           |                  |
|-----------------------|-----------|------------------|
| <i>Over All Total</i> | <i>\$</i> | <i>13,863.31</i> |
|-----------------------|-----------|------------------|

*( Part By Part )*