

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

ASIA TONG

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 4212
Date Estimated : 13/06/2019
Prepared By : Simon Koh Eng Aun

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Ng En Cher (Huang Enze)
50J Faber Height
#03-68

Singapore 129203

- ACCOUNT - 2000

CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SIM2448T	VF38E5GZTGL016134	24/03/2017	508SW1.6 Allure	0

DESCRIPTION

TO CONDUCT TP CLAIM - AXA (DOA:09/06/2019)

VALUE

0.00

SUNDRIES

LABOUR TO REMOVE, REPLACE AND REPAIR REAR BUMPER, END PANEL, TAILGATE EXTERIOR PANEL AND ALL AFFECTED PARTS

30 150.00

1250 2,500.00

LABOUR TO PUTTY AND RESPRAY REAR BUMPER, REAR TAILGATE PANEL AND ALL AFFECTED AREA

1250 1,500.00

LABOUR TO REMOVE, REPLACE AND REPAIR FRONT BUMPER, FRONT LH WING, FRONT LH HEADLAMP AND ALL AFFECTED AREA

750 1,500.00

LABOUR TO PUTTY AND RESPRAY FRONT BUMPER, FRONT LH WING, AND ALL AFFECTED AREA

1000 1,500.00

TUFF KOTE, ANTI RUST PRESERVATION, BODY CAVITY PRESERVATIONS (\$60 NETT PER PANEL)

X 240.00

SEALANT FOR BODY PANEL (\$90 NETT PER PANEL)

X 360.00

ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING (NETT)

150.00

TO REMOVE AND REFIX/REPLACE REAR BUMPER REVERSE SENSOR. CONDUCT DISTANCE SETTING (NETT)

150.00

HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME HEADLAMP CORRECTOR (NETT)

200.00

TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES, RESTORE ALL PROGRAMME MODULES (NETT)

600.00

Total Labour 1: 8,850.00

PART NUMBER DESCRIPTION

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1611916580	REAR BUMPER de	1	956.00	10.00	860.40
1612092480	RR BPR DETECTION SENSOR SUPPORT ?	1	75.00	10.00	67.50
1612092580	RR BPR DETECTION SENSOR HOLDER ?	1	75.00	10.00	67.50
745386	REFLECTOR ca	1x	61.00	10.00	54.90

AUTOFRANCE

(A Division of Vantage Automotive Limited)
Business Registration No. 52907220C GST Registration No. M2-0000551-1
305 Alexandra Road
159942, Singapore
Tel : 6376 2288
Fax : 6477 7373



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 4212
Date Estimated : 13/06/2019
Prepared By : Simon Koh Eng Aun

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SIM2448T	VF38E5GZTGL016134	24/03/2017	508SW1.6 Allure	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1611901580	SET PROXIMITY SENSOR RINGS ?	1	65.00	10.00	58.50
7243GN	REAR PANEL repair	1	225.00	10.00	202.50
1606393880	TAILGATE PANEL repair	1	615.00	10.00	553.50
8666CX	BADGE new	1	32.00	10.00	28.80
9809004580	BADGE 508 SW new	1	55.00	10.00	49.50
1612221980	FRT BUMPER - P508 repair	1	1,114.00	10.00	1,002.60
98076314XT	GRILLE ?	1	150.00	10.00	135.00
1612223080	SET PROXIMITY SENSOR SUPPORTS X	1	95.00	10.00	85.50
9807844980	RANGE SUPPORT X	1	127.00	10.00	114.30
98076283XT	BUMPER RANGE new	1	120.00	10.00	108.00
7422Z6	BUMPER ABSORBER new (S)	1	152.00	10.00	136.80
7840CA	FRONT WING repair	1	345.00	10.00	310.50
1612495580	BARE HEADLAMP LH new	1	1,950.00	10.00	1,755.00
1608321780	SENSOR-OBSTACLE DETECTION FRT/REAR ?	1	99.00	10.00	89.10
1608472280	SENSOR-OBSTACLE DETECTION FRT/REAR ?	1	180.00	10.00	162.00

Total Parts : 5,841.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resue
Hp 20010068
6 days
18/06/19 @ 1030
Resurvey before paint

Customer Name & Signature / Company Stamp

Date

Labour 1	:	8,850.00
Parts	:	5,841.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,028.43
Grand Total	:	15,720.33

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

305 Alexandra Road

Vantage Automotive Centre

Singapore 159942

Service Booking: 6477 7377

Parts: 6477 7420

Vantage 24-Hour Assist: 6473 8588

Fax: 6477 7300

**PEUGEOT****FINALIZATION REPORT**

REPAIR ORDER NO. BP 115022	Date IN 24/06/2019 Payment Term 30 Days From Invoice Customer Service Advisor Simon Koh Eng Aun	Invoice Number Invoice Date Invoice By Simon Koh Eng Aun	Page No. 1 of 2
--------------------------------------	---	--	------------------------

CUSTOMER INFORMATION	INVOICE TO 77
Ng En Cher (Huang Enze) 503 Faber Height #03-68 Singapore 129203	Axa Insurance Pte Ltd No. 8 Shenton Way #24-01 Axa Tower Singapore 068811

REGISTRATION No. SLM2448T	CHASSIS No. VF38E5GZTGL016134	STOCK No. 209537	REGISTRATION DATE 24/03/2017	MODEL 508SW1.6 Allure	MILEAGE 35809
-------------------------------------	---	----------------------------	--	---------------------------------	-------------------------

CODE	DESCRIPTION	UNITS	DISC %	NETT
	TO CONDUCT TP CLAIM - AXA (DOA:09/06/2019)	0	0.00	0.00
	SUNDRIES	1	0.00	30.00 ✓
	LABOUR TO REMOVE, REPLACE AND REPAIR REAR BUMPER, END PANEL, TAILGATE EXTERIOR PANEL AND ALL AFFECTED PARTS	1	0.00	1,250.00 ✓
	LABOUR TO PUTTY AND RESPRAY REAR BUMPER, REAR TAILGATE PANEL AND ALL AFFECTED AREA	1	0.00	1,250.00 ✓
	LABOUR TO REMOVE, REPLACE AND REPAIR FRONT BUMPER, FRONT LH WING, FRONT LH HEADLAMP AND ALL AFFECTED AREA	1	0.00	750.00 ✓
	LABOUR TO PUTTY AND RESPRAY FRONT BUMPER, FRONT LH WING, AND ALL AFFECTED AREA	1	0.00	1,000.00 ✓
	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING (NETT)	1	0.00	150.00 ✓
	TO REMOVE AND REFIX/REPLACE REAR BUMPER REVERSE SENSOR. CONDUCT DISTANCE SETTING (NETT)	1	0.00	150.00 ✓
	HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME HEADLAMP CORRECTOR (NETT)	1	0.00	200.00 ✓
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES, RESTORE ALL PROGRAMME MODULES (NETT)	2	0.00	600.00 ✓
Sub-Total :				5,380.00
CODE	DESCRIPTION	UNITS	DISC %	NETT
00007422W9	RR BUMPER REINFORCEMENT - P508SW (S)	1	10.00	451.80 ✓
0000742163	BUMPER BRACKET LH (S)	1	10.00	72.00 ✓
0000745386	REFLECTOR - LH REAR BUMPER SKIRTING	1	10.00	54.90 ✓
00008666CX	PEUGEOT EMBLEM	1	10.00	28.80 ✓
1606393880	TAILGATE PANEL	1	10.00	553.50 ✓
1612495580	BARE HEADLAMP LH	1	10.00	1,755.00 ✓
98076283XT	BUMPER RANGE	1	10.00	108.00 ✓
9809004580	BADGE 508 SW	1	10.00	49.50 ✓
00007422W6	BUMPER ABSORBER (S)	1	10.00	136.80 ✓
1611916580	REAR BUMPER	1	10.00	860.40 ✓
Sub-Total :				4,070.70
Attending CSO : Simon Koh				
Should you require further explanation, please reach me at				

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1



305 Alexandra Road

Vantage Automotive Centre

Singapore 159942



Service Booking: 6477 7377

Parts: 6477 7420

Vantage 24-Hour Assist: 6473 8588

Fax: 6477 7300

**PEUGEOT****FINALIZATION REPORT**

REPAIR ORDER NO. BP 115022	Date IN	Invoice Number	Page No.
	24/06/2019		2 of 2
	Payment Term	Invoice Date	
	30 Days From Invoice		
	Customer Service Advisor	Invoice By	
	Simon Koh Eng Aun	Simon Koh Eng Aun	

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	9,450.70
Labour Charges	5,380.00	Less Insurance Excess	S\$	0.00
Parts Charges	4,070.70	GST @ 7%	S\$	661.55
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	10,112.25
		Less Deposit/Voucher	S\$	0.00
Computer generated invoice. No signature is required.		Amount Payable	S\$	10,112.25
All amounts are in Singapore Dollars.				
Work was carried out subject to the Company's Terms and Conditions of Service.				
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.				
For credit purchases, interest @1% per month will be debited on overdue amounts.				

Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Car Reg No: SLM2448T

RO Number: BP115022

Date: 24/06/2019

No.	Supplementary / Check Items Parts	Part Number	Qty	U / Price	Disc %	Ext Price
1	BUMPER ABSORBER <i>cra</i>	00007422W6	1	\$152.00	10%	\$136.80
2	RR BUMPER REINFORCEMENT <i>bt</i>	00007422W9	1	\$502.00	10%	\$451.80
3	BUMPER BRACKET LH <i>cra</i>	*0000742163	1	\$80.00	10%	\$72.00
Parts Total:						\$660.60

No.	Supplementary Labour Charges	Price
Total Labour:		\$0.00
Total Parts & Labour:		\$660.60
GST @ 7%:		\$46.24
Grand Total:		\$706.84

Raised By Technician	Approved By CSA SIMON KOH	Acknowledge By Parts Assistant	BO Parts: Yes / No ETA: _____
-------------------------	-------------------------------------	-----------------------------------	--------------------------------------