

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Jun-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6102 P

|       |   |   |    |        |
|-------|---|---|----|--------|
| 1 pc  | Bootlid emblem                                    | X | \$ | 27.00  |
| 1 pc  | Bootlid CRDi                                      | - | \$ | 29.00  |
| 1 pc  | End panel inner garnish                           | X | \$ | 74.00  |
| 1 pc  | Rear bumper                                       | - | \$ | 696.00 |
| 1 pc  | Rear bumper lower cover                           | - | \$ | 206.00 |
| 2 pcs | Rear bumper side bracket o/s & n/s @ \$29.00      | X | \$ | 58.00  |
| 1 pc  | Rear bumper inner sponge                          | X | \$ | 114.00 |
| 1 pc  | Rear bumper reinforcement                         | X | \$ | 607.00 |
| 2 pcs | Rear bumper stay o/s & n/s @ \$53.00              | X | \$ | 108.00 |
| 2 pcs | Rear bumper reinforcement lower bracket @ \$18.00 | X | \$ | 36.00  |
| 2 pcs | Rear bumper reinforcement upper bracket @ \$18.00 | X | \$ | 36.00  |
| 2 pcs | Rear bumper reflector n/s & o/s @ \$46.00         | X | \$ | 92.00  |

\$ 2,083.00  
\$ 208.30  
\$ 1,874.70

**S/NETT**

|       |                               |   |    |        |
|-------|-------------------------------|---|----|--------|
| 1 set | Rear bumper clips             | ✓ | \$ | 48.00  |
| 1 set | End panel inner garnish clips | X | \$ | 30.00  |
| 1 set | Bootlid stickers              | - | \$ | 100.00 |
| 1 set | Reverse sensor                | X | \$ | 280.00 |
| 1 pc  | Rear bumper top protector     | - | \$ | 80.00  |

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_  
 is subject to final approval from Insurance Company  
 Less 10%  
 • No illegal modifications(s) is allowed  
 • Third party survey is on a "Without Prejudice" basis  
 • Parts prices are subject to confirmation  
 • To display damaged part(s) during resurvey  
 • To resurvey before/after part(s) during painting  
 the Repairer of the following:  
 LKK Auto Corporation's hereby notify

*Kalin LKK*

*14/6/19 17:55h*

*3 Days*

*4s*

*Adha Repro pth*

|   |  |    |          |     |
|---|--|----|----------|-----|
| Sundry  |  | \$ | 50.00    | 20  |
| Towing Fee  |  | \$ | 50.00    | X   |
| To dismantle / replace reverse sensor to new bumper and reset to the same   |  | \$ | 120.00   | 30  |
| To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.                                  |  | \$ | 180.00   | X   |
| To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc. |  | \$ | 850.00   | 200 |
| To putty and spray painting on bootlid lower garnish, rear bumper, end panel  |  | \$ | 600.00   | 360 |
| To apply rustproofing on the repaired and replaced panels.  |  | \$ | 120.00   | X   |
|   |  | \$ | 4,382.70 |     |

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

CASH SALE/WORK ORDER

No: AE 4408



**PEOPLE'S VEHICLE SERVICE PTE LTD**

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 ( 3 LINES ) FAX : 6743 0013

Reg No: 200415052W

Date, 14.6.19

寶號 Premier  
Messrs: Premier

車號 SHC6102P 車型 OPTIMA  
Vehicle No: SHC6102P Model No: OPTIMA

由 CGH taxi stand.  
From: CGH taxi stand.

到 Omega  
To: Omega

其他 1 key  
Remark: 1 key

時間 01:32:02:12:02:52 AMOUNT: \$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人 [Signature]   
Authorised by: [Signature]

收貨人 [Signature]   
Received by: [Signature]