

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0749/2019/TG
Date : 14-Jun-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. : **SHD 134 G**

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Thaw Tint
Address : Blk 348C Yishun Avenue 11
#10-583
Singapore 763348
Telephone : (HP)+65 93200417
Type of Claim : Third Party Claims
Policy No. : 1700065489-01
Vehicle No : **SLT 258 B**
Model Code : A5 SPORTBACK 2.0 TFSI
Model / Year : Oct-17
Engine No : CVK 047182
Chassis No : WAUZZZF51JA034302
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jun-19
Place of Accident : Clementi Ave Entering AYE (Tuas)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLP 1056 G

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00 S 00 ✓
3	To rep spray rear bumper.	\$ 1,000.00 S 00 ✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 2,752.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 258 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Rehnd</i>	\$ 2,311.00	✓
2	REAR BUMPER FIXING SETS <i>men</i>	\$ 150.00	+
3	REAR BUMPER ATTACHEMENT PARTS <i>men</i>	\$ 203.00	+
4	REAR BUMPER TRIM MOULDING <i>lit</i>	\$ 928.00	✓
5	REAR LIGHT REFLECTOR - REAR <i>men</i>	\$ 38.00	+
6	REAR BUMPER CARRIER <i>?</i>	\$ 819.00	+
7	REAR GUIDE SECTION - LH <i>men</i>	\$ 20.00	+
8	REAR GUIDE SECTION - RH <i>?</i>	\$ 20.00	+
9	REAR PARKING AID SENSOR <i>men</i>	2 \$ 462.00	+
10	SEAL RING	4 \$ 12.00	+
11	CONTROL UNIT FOR OPENING BOOT LID <i>men</i>	\$ 381.00	+
12	SUNDRIES <i>?</i>	\$ 200.00	?
TOTAL SPARE PARTS CHARGES		: \$ 5,544.00	
TOTAL LABOUR CHARGES		\$ 2,752.00	
GRAND TOTAL		<u>\$ 8,296.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim,
Surveyed Date : 14/06/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days.

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant