

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2972/11/19 Your Ref: \_\_\_\_\_ Date: 27th NOV 2019

MR TAN KOK HOW  
BLK 127, #10-387  
PASIR RIS STREET 11  
SINGAPORE 51017

Estimate cost of repair to HONDA VEZEL 1.5X (A) Hybrid S/Wgn - SIQ 5157 S

1 pc o/s tail lamp assy	<i>cm</i>	SGD S\$	463.90	SGD	<i>✓</i>
2 pcs o/s tail lamp clips & stopper	<i>cm @ \$ 6.50</i>		13.00	"	<i>✓</i>
1 pc tail gate door o/s reflector	<i>^^</i>		272.30	"	<i>X</i>
1 pc rear bumper o/s side pad	<i>DD</i>		284.50	"	<i>✓</i>
1 pc rear bumper o/s side pad side retainer	<i>But</i>		26.00	"	<i>✓</i>
1 pc rear bumper o/s side pad top retainer	<i>But</i>		42.00	"	<i>✓</i>
14 pcs rear bumper top & low clips	<i>cm @ \$ 3.90</i>		46.80	"	<i>✓</i>
1 pc rear o/s fender	<i>✓</i>		709.80	"	<i>X</i>
8 pcs rear o/s fender inner trim board clips	<i>@ \$ 6.50 ^^</i>		52.00	"	<i>✓</i>
1 pc rear o/s fender wheel guard shield	<i>^^</i>		263.40	"	<i>X</i>
10 pcs rear o/s fender wheel guard clips stopper	<i>@ \$ 8.50 ^^</i>		85.00	"	<i>X</i>

S\$ 2,258.70 SGD  
Less 20% S\$ 451.74 SGD  

---

SGD S\$ 1,806.96 SGD

To wiring check up for affected wiring system. 50.00 *20*

To remove & refix carpet, floor mat, garnish, floor board cover, fender inner shield & necessary parts, to enable repair rear o/s fender, tail lamp panel & necessary parts. 150.00 *60*

To respray Tuff-Kote on all affected accident parts. *^^* 60.00 *X*

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s fender, o/s tail lamp panel & necessary parts, to weld, renew & align above parts. 750.00 *280*

To putty & respray painting on all affected accident parts. 1,000.00 *400*

SGD : S\$ 3,816.96 (SGD)  
=====

Singapore Dollars : Three Thousand Eight Hundred Sixteen Dollars And Cents Ninety Six Only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display **HUP MOTOR TRADING & SERVICE**
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal communication(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*Not done*

*hkn*

*Wong H. Seking*

*3 Oct 2019*

*202*  
*700.96*  
*1460.96*

*P/P \$ 1460.96*

*Reer o/s.*